

22/03/2007

ASS. R.C. BY:

REF: CS3/CTI/8019042/Gcd3et Special Instruction:

Surveyor:

Momen

From (Person):

Chong Boon Sen

ASSIGNMENT (Office)

of

CTI

Date/Time:

19/10/18 @ 2:13pm

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJB 9482D

Insured:

GBC 2704A

at Workshop m/s

T. W. Lim Motor

Tel:

97409067

of

160 Sin Ming Drive # 08-12

Policy No:

DMCVSN1665851701

Claim No:

8NM18D04946C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/10/2018

CA / REV / REP. / REV 24 HRS

1up

22/10/18 @ after 10am

H.O.D. Endorsement:

Date/Time:

3:06pm @ 19/10/18

Person Contacted:

Mr. Lim

Vehicle IN/

OUT

Date/Time	Action/Instruction (X) Estimate
	SJB 9482D - NS/INC17023506/K/rbn 2 Don: 8/12/17
	GBC 2704A - CCG/AG/16015276/R/pg 3s2 Dia: 14/08/16
	Dismantle: 23/10/2018

Survivor

147  
Xnd.

REF: CTI

# ASSIGNMENT

From: Date: 22/10/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJB 9482D  
at Workshop m/s T.W. Lim Motor  
of 160 Sin Ming Drive # 08-12

Insured:

Policy No.

Claims No.


Sum Insured: Excess:

(Client's Record)

Make of Veh: Mr. Lim @ 97409067

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 5 \* days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJB 9482D Yr Regn: Jan / 08

Type: M.C. / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Verna C.C. 1399

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 175162 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: KMH CM 41AR 74 144277

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65 R14

R: 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. D.O.I. 22-10-18

Survey held at W/S 3pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

\$3000 - \$4000

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format: PRS.

Lump Sum / I.B.I. (\$ )

150

150

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Oct 2018		19 Oct 2018 14:13 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	AH KWANG EGGS DEALER, Co. Reg. No.: 53040603M		
Main Claimant:	PROPERTY SALESPERSON, Co. Reg. No.: 53360191J		
Vehicle Reg. No.:	SJB9482D	Date of Loss:	16/10/2018 13:00 - :59
Claim Type:	TP / SNM18D04946C02	Policy/Cover Note No.:	DMCVSN1665851701 (Comprehensive)
Vehicle Reg. No. (Insured):	GBC2704A	Policy No. (Claimant):	5090059934-01
		Excess:	S\$0.00
Repairer:	T.w. Lim Motor (HQ) 160 Sin Ming Drive, #08-12, Sin Ming Auto City, 575722 Sin Ming - Tel: 97409067		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/10/2018]		
Driver/Custodian (Insured):	LEE CHYE CHENG (57 / Male), NRIC: S1491050F, Tel: +6597356395		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire Transfer Fee**

Vehicle Details

Vehicle No. :	SJB9482D		
Vehicle Type :	Z10 - Private Hire (Chauffeur) Motor Car		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	HYUNDAI		
Vehicle Model :	VERNA 1.4 AUTO		
Chassis No. :	KMHCM41AR7U144277		
Propellant :	Petrol		
Engine No. :	G4EE7714546		
Engine Capacity :	1399 cc		
Maximum Power Output :	69.9 kW ( 93 bhp )		
Maximum Laden Weight :	1600 kg		
Unladen Weight :	1263 kg		
Year Of Manufacture :	2007		
Original Registration Date :	29 Jan 2008		
Lifespan Expiry Date :	-		
COE Category :	A - Car (1600cc & below)		
PQP Paid :	\$21,485.00		
COE Expiry Date :	28 Jan 2023		
Road Tax Expiry Date :	28 Jan 2019		
Inspection Due Date :	28 Jan 2019		
Intended Transfer Date :	24 Oct 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00
Message			
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.			

You may print this page for reference.

[OK](#)[Print](#)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Business
Owner ID:	0191J
<b>Vehicle Details</b>	
Vehicle No.:	SJB9482D
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	VERNA 1.4 AUTO
Primary Colour:	Red
Manufacturing Year:	2007
Engine No.:	G4EE7714546
Chassis No.:	KMHCM41AR7U144277
Maximum Power Output:	69.9 kW (93 bhp)
Open Market Value:	\$10,485.00
Original Registration Date:	29 Jan 2008
First Registration Date:	29 Jan 2008
Transfer Count:	1
Actual ARF Paid:	\$11,534.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	28 Jan 2023
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$21,485.00
COE Rebate Amount:	\$18,308.00
<b>Total Rebate Amount:</b>	<b>\$18,308.00</b>
<b>Message</b>	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 24 Oct 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/10/2018 12:46
Date Of Accident	16/10/2018 13:55
Exact Location Of Accident	KEPPEL RD / CANTONMENT LINK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJB9482D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	PROPERTY SALESPERSON
Co Reg No	53360191J
Email Address	QUEEBON@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94556379
Alternative Phone No	Office-94556379

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	VERNA
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5090059934-01
Cover Note Number	

### Driver

Name of Driver	ONG QUEE BON
NRIC No	S1628860H
Date Of Birth	06/09/1964
Occupation	OUTDOOR
Date Of Driving Pass	28/04/1982
Driving Experience	36 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94556379

## . Fax Number

Contact Number	OFFICE-94556379
EMail Address	QUEEBON@GMAIL.COM
Address	APT BLK 329 ANG MO KIO AVENUE 3 #11-2042 SINGAPORE
Postcode	560329
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

**General Information of the Accident**

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

**Other Information**

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	Name: : NA Gender: : Male
Passenger 2	Name: : NA Gender: : Male
Passenger 3	Name: : NA Gender: : Male
Passenger 4	Name: : NA Gender: : Female

**Details of Police Action**

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

**Circumstances of Accident**

REFER TO ATTACHED

**Attachment(s)**

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	GBC2704A
Vehicle Make/Model/Colour	

## • Details Of Properties

Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	LEE CHYE CHENG
NRIC/Passport Number	
Contact Number	90278132
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	



## Sketch Plan

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

PROPERTY SALESPERSON  
Co Reg No: 53360191J

Policyholder's Signature  
Date & Time:


Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

GIA/ELC SketchPlanForm\_V3

Sketch Plan #2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

while stopped my vehicle at the traffic Junction. at Kappel Rd  
 & Cantonment Link, Sudden my vehicle been hit on ~~my~~ the  
 rear.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

PROPERTY SALESPERSON  
 Co Reg No: 53360191J

Policyholder's Signature  
 Date & Time:

Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

GENERAL DECLARATION FORM

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Oct 2018		19 Oct 2018 14:13 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured:	<b>AH KWANG EGGS DEALER</b> , Co. Reg. No.: 53040603M								
Main Claimant:	<b>PROPERTY SALESPERSON</b> , Co. Reg. No.: 53360191J								
Vehicle Reg. No.:	<b>SJB9482D</b>	Date of Loss:	16/10/2018 13:00 - :59 [128 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM18D04946C02</b>	Policy/Cover Note No.:	DMCVSN1665851701 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>GBC2704A</b>	Policy No. (Claimant):	5090059934-01						
		Excess:	S\$0.00						
Repairer:	<b>T.w. Lim Motor (HQ)</b> 160 Sin Ming Drive, #08-12, Sin Ming Auto City, 575722 Sin Ming - Tel: 97409067								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 30/10/2018]								
Driver/Custodian (Insured):	LEE CHYE CHENG (57 / Male), NRIC: S1491050F, Tel: +6597356395								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJB9482D (SNM18D04946C02)  
[GBC2704A]  
TP  
PROPERTY SALESPERSON  
Oct 16 2018 1:00PM  
[AH KWANG EGGS DEALER]  
T.w. Lim Motor

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

**View** View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	17/10/18 12:53	<b>STA INSPECTION PTE LTD (Sin Ming)</b> <b>Accident Statement</b>		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	17/10/18 12:51	<b>STA INSPECTION PTE LTD (Sin Ming)</b> <b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	17/10/18 12:51	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	17/10/18 12:51	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	17/10/18 12:51	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	17/10/18 12:51	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	17/10/18 12:51	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	17/10/18 12:51	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
8	17/10/18 12:51	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
9	17/10/18 12:51	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
10	17/10/18 12:51	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
11	17/10/18 12:51	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	<b>LKK Auto Consultants Pte Ltd (HQ)</b>		Thumbnail	Print
1	26/10/18 15:41	<b>General View</b>		Load PDF	
2	26/10/18 15:41	<b>Photographs of Damaged Parts</b>		Load PDF	

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	19/10/18 14:12	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> <b>PRS</b>		Load PDF	
2	19/10/18 14:12	<b>OI GIA</b>		Load PDF	
No	Finalized On	<b>STA INSPECTION PTE LTD (Sin Ming)</b>		Thumbnail	Print
1	17/10/18 12:52	<b>Sketch Plan</b> [Linked Accident Report Documents]		Load TIF	
2	17/10/18 12:52	<b>Sketch Plan #2</b> [Linked Accident Report Documents]		Load TIF	

## Linked Accident Report Documents

**View** View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On			Thumbnail	Print
1	17/10/18 12:53	<b>STA INSPECTION PTE LTD (Sin Ming)</b> <b>Accident Statement</b>		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
---------------	--	--	--	------------	-------------------------------------

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	17/10/18 12:51	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	17/10/18 12:51	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	17/10/18 12:51	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	17/10/18 12:51	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	17/10/18 12:51	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	17/10/18 12:51	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	17/10/18 12:51	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	17/10/18 12:51	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	17/10/18 12:51	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	17/10/18 12:51	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	17/10/18 12:51	Accident Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	17/10/18 12:52	Sketch Plan		Load TIF	
2	17/10/18 12:52	Sketch Plan #2		Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18019042/GCD3E2

Date: 30/10/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMCVSN1665851701

Claimant Vehicle  
No: SJB9482DInsured Vehicle  
No: GBC2704A

Date of Loss: 16/10/2018

Nature of Claim: TP

Claim  
No: SNM18D04946C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SJB9482D

Make &amp; Model: HYUNDAI VERNA, 1.4

Reg. Date: 29/01/2008 (Man. Year: 2007)

Colour: Red

Engine Capacity: 1399 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

Engine No: G4EE7714546

Chassis No: KMHCM41AR7U144277

Odometer: 175162 km

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	185/65 R14	Rear Tyre Size:	185/65 R14
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (\$\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 19/10/2018

Date Inspected: 22/10/2018 Inspected At:

T.w. Lim Motor (HQ)  
160 Sin Ming Drive, #08-12, Sin Ming Auto  
City  
Singapore 575722

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00



## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b> MRM-SG		Version: 1.0 (Last Synchronised: 30 Oct 2018)
<b>Parts:</b>	143	HYUNDAI VERNA 1.4 (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJB9482D)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >