

22/03/2002

ASS. REC. BY:

REF: CS3/CT18019056/ Gedzer

Special Instruction:

Survivor  
Mentor

G&amp;

ASSIGNMENT (Office)

From (Person): Elaine Cheong

of

CPI

Date/Time:

19/10/18 @ 4:33pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8LZ 3524G

Insured:

SLP 6145A

at Workshop m/s

SAT Motors

Tel:

9859 9677

of

24 Defu Lane 12

Policy No:

DMPCSN3057901801

Claim No:

8NM18D04972C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16/10/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

4:35pm @ 19/10/18

Person Contacted:

Jessie

Vehicle IN OUT

Date/Time	Action/Instruction (x) Estimate
	8LZ3524G-X
	SLP 6145A-X
	Dismantle: 23/10/2018.

Signature

Handwritten signature: *Kal*

REF:

87958 /

# ASSIGNMENT

(-2019)

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s *Sat Motor*  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)


Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: *\$16k*  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: *3* days Res.: Yes or No  
 Lum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT



Veh No: *SLZ 3524G* Yr Regn: *24 Aug 2009*  
 Type: *Motor* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: *Volkswagen New GOLF 1390*  
 Colour: *Red* A/C: Insured / Std / NI / NA  
 Sp. Reading: *1743ac* T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: *WVWZZZ1KZ AW004034*  
 Gen. Cond: *Good* / Fair / Poor / Burnt  
 Steering: *Order* / Jammed / Leaked / Burnt or  
 Brake: *Order* / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: *225/40 ZR18*  
 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or *Achilles*

Front		Rear
R/Bal. <i>6</i> mm		R/Bal. <i>6</i> mm
L/Bal. <i>6</i> mm		L/Bal. <i>6</i> mm
D.O.A.		D.O.I. <i>22-10-18</i>
Survey held at <i>W/S</i>		

Des. of Damages : Frt / *Rear* / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<i>\$1900 - \$2000</i>

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: *3*

Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

Report Format : *PRS*

Lump Sum / I.B.I. (\$)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

<i>190</i>
<i>150</i>

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Oct 2018		19 Oct 2018 16:33 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:			
Main Claimant:	CHUA SIEW MEI		
Vehicle Reg. No.:	SLZ3524G	Date of Loss:	16/10/2018 00:00 - :59
Claim Type:	TP / SNM18D04972C02	Policy/Cover Note No.:	DMPCSN3057901801
Vehicle Reg. No. (Insured):	SLP6145A	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Sat Motors (HQ) 24 Defu Lane 12, 539131 Defu Lane - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 30/10/2018]		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		


#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Satwant Singh  
Pritam Singh  
Khong Zi-Wei



CONVEYANCING OFFICE:  
450 Lorong 6 Toa Payoh  
#02-03 Harsing Centre  
Singapore 319394  
Tel: 6221 6114  
Fax: 6266 6925  
www.satwantlaw.com.sg  
(Fax not for service  
of documents)

*An Official Member of The Lawyer Network, an international network of law firms*

*(Please quote our Ref. when replying)*

Your Ref: To be advised  
Our Ref: PD/DL/1801785 (sp) – Toa Payoh Office  
(pri@satwantlaw.com)

19 October 2018

**China Taiping Insurance (Singapore) Pte. Ltd.**  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

**BY EMAIL ONLY**

**Attention: Motor Claims Department**

Dear Sir/Mdm,

**ACCIDENT INVOLVING SLZ3524G & SLP6145A ALONG YUAN CHING ROAD TOWARDS  
AYE ON 16/10/2018 @ 15:05**

We refer to your email dated 19 October 2018 confirming your intention to conduct a pre-repair survey on our client's vehicle SLZ3524G.

Please be informed that said vehicle can be inspected at:

Workshop name: Sat Motors  
Address: No. 24 Defu Lane 12 Singapore 539131  
Contact Person: Jessie (HP: 9859 9677), Jonathan (HP: 9126 9987)

In the event you fail to conduct the pre-repair survey within the next 2 working days, excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,

**SATWANT & ASSOCIATES**

cc client

For Surveyor: To initial after Completion

1<sup>st</sup> Inspection  
Appointed surveyor  
(Name & Signature)

Date & Time

2<sup>nd</sup> Inspection  
Appointed surveyor  
(Name & Signature)

Date & Time

3<sup>rd</sup> Inspection  
Appointed surveyor  
(Name & Signature)

Date & Time

**NB: Any Settlement of offer is on the express condition that this settlement is in respect of our client's claim for property related damaged only and shall not preclude our client from claiming injury-related damages arising from this accident.**  
This document is intended for the addressee(s) only and may contain confidential information and/or may be subject to legal privilege. If you have received this in error, please contact us immediately and destroy the original message.

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	9795Z

### Vehicle Details

Vehicle No.:	SLZ3524G
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Oct 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	NEW GOLF 1.4 TSI AT 5K14Q5
Primary Colour:	Blue
Manufacturing Year:	2009
Engine No.:	CAV090889
Chassis No.:	WVWZZZ1KZAW004034
Maximum Power Output:	118.0 kW (158 bhp)
Open Market Value:	\$25,506.00
Original Registration Date:	24 Aug 2009
First Registration Date:	24 Aug 2009
Transfer Count:	2
Actual ARF Paid:	\$25,506.00

### Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Aug 2019
PARF Rebate Amount:	\$12,753.00

### Intended COE Rebate Details

COE Expiry Date:	23 Aug 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$7,090.00
COE Rebate Amount:	\$590.00
<b>Total Rebate Amount:</b>	<b>\$13,343.00</b>

The information contained herein is correct as at 23 Oct 2018

OK

## ► Volkswagen New Used Vehicle List (20 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Available
<b>Volkswagen New Beetle 1.6A</b>	<b>\$14,500</b>	-	15-Jan-2009	1,595 cc	130,000 km		<b>Available</b>

A Well Maintained Car Worth Renewing COE! All Wear And Tear And Battery Replaced In August 2018! Definitely A Collector's Car! Grab Before It's Gone!

Office No. - -

Jenn Foo - 96836323

<b>Volkswagen New Beetle 1.6A</b>	<b>\$14,800</b>	\$8,860 /yr	24-Jun-2009	1,595 cc	160,000 km		<b>Available</b>
-----------------------------------	-----------------	-------------	-------------	----------	------------	--	------------------

Beautiful White New Beetle. Very Good Condition.

Office No. - -

Christina Lim - 94889822

<b>Volkswagen New Beetle 1.6A</b>	<b>\$15,000</b>	-	12-Jan-2009	1,595 cc	85,294 km		<b>Available</b>
-----------------------------------	-----------------	---	-------------	----------	-----------	--	------------------

RTS: Selling To Upgrade. More Than \$10k Worth Of Core Parts CHANGED. (Original: Engine Gaskets, VW Disc Rotors. Cam Arm Shaft, Wiper Motor. New Air Condition System Unit (Worth \$2k Alone). Timing Belt...

Office No. - -

Ng - 91510871

<b>Volkswagen New Beetle 1.6A</b>	<b>\$15,800</b>	\$13,310 /yr	04-May-2009	1,595 cc	122,000 km	High Speed Motor	<b>Available</b>
-----------------------------------	-----------------	--------------	-------------	----------	------------	------------------	------------------

Best Price In Town, 6 Months Road Tax Till Nov 2018, Sporty Light Green, Accident Free, Pristine Tip Top Condition, Gear Box Just Complete Overhaul As Good As New With Receipt To Show, Responsive Engi...

Office No. - 64568190

Harjinder Singh - 93386317 | Manjit Singh - 98581265

<b>Volkswagen New Beetle 1.6A</b>	<b>\$16,500</b>	\$9,490 /yr	12-Aug-2009	1,595 cc	102,000 km	Carro	<b>Available</b>
-----------------------------------	-----------------	-------------	-------------	----------	------------	-------	------------------

Very Well Maintenance Car As I Need Regular Servicing. The Maintenance Cost Is Very Low Compare To Other European Cars. Schedule A T Drive Today. Viewing Is Strictly By Appointment Only.

Office No. - 67146652

Jace - 81394200

<b>Volkswagen Caddy 2.0M</b> (New 5-yr COE) (Diesel)	<b>\$24,800</b>	\$4,960 /yr	30-Jan-2009	1,968 cc	-	COE Auto Trading	<b>Available</b>
---	-----------------	-------------	-------------	----------	---	------------------	------------------

Dare To Compare, Cheapest Yet Affordable. The Best Panel Van In The Market. Well-Known For Its Power And Fuel Efficiency. 2 Owner Only Full 5 Years COE Guaranteed. Give Us A Call Before Heading Down.

Office No. - 64589833 / 64571902

Mr Liauw - 96718933 | Mr Chua - 98181643

<b>Volkswagen Caddy 2.0M</b> (New 5-yr COE) (Diesel)	<b>\$26,800</b>	\$5,360 /yr	25-Feb-2009	1,968 cc	115,870 km	Quality Auto Hub	<b>Available</b>
---	-----------------	-------------	-------------	----------	------------	------------------	------------------

New 5 Years COE. Well Kept And Accident Free., Loan Available.

Office No. - -

Yap - 90662292

<b>Volkswagen New Beetle 1.6A</b> (New 5-yr COE)	<b>\$28,800</b>	\$5,760 /yr	02-Jan-2009	1,595 cc	79,100 km	Jia Leong Trading Enterprise	<b>Available</b>
---	-----------------	-------------	-------------	----------	-----------	------------------------------	------------------

Beautiful Metallic Green, 1 Careful Owner, New 5 Years COE. Well Maintained, Very Seldom Used, Per Year 7,900KM Only, Accident Free, Just Serviced, Undergone A 120 Points Safety Check By Our In House ...

Office No. - 68415997

John - 97595778 | Jackson - 96863331 | Latiff - 97310560

<b>Volkswagen New Beetle 1.6A</b> (New 5-yr COE)	<b>\$28,800</b>	\$5,760 /yr	09-Jan-2009	1,595 cc	164,000 km	AA Trust Automotive	<b>Available</b>
---	-----------------	-------------	-------------	----------	------------	---------------------	------------------

Pre-Owned Vehicle! Extremely Well Maintained By Previous Owner! Beautiful Metallic Silver Beetle With Matching Red Lush Leather Interior! Make The Car Stand Out! Regularly Service And Maintained B...

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	17/10/2018 17:16
Date Of Accident	16/10/2018 15:05
Exact Location Of Accident	YUAN CHING ROAD TOWARDS AYE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ3524G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHUA SIEW MEI
NRIC No	S8429795Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88666153
Alternative Phone No	OTHERS-88666153

### Vehicle Particulars

Manufacturer	VOLKSWAGEN
Model	GOLF
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5100678112
Cover Note Number	

### Driver

Name of Driver	KOH FOO SING
NRIC No	S8416017B
Date Of Birth	03/06/1984
Occupation	INDOOR
Date Of Driving Pass	10/08/2010
Driving Experience	8 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88666153
Fax Number	
Contact Number	OTHERS-88666153
EMail Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Oct 2018		19 Oct 2018 16:33 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<a href="#">[Created by insurer]</a>							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	<b>CHUA SIEW MEI</b>								
Vehicle Reg. No.:	<b>SLZ3524G</b>	Date of Loss:	16/10/2018 00:00 - :59 [109 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM18D04972C02</b>	Policy/Cover Note No.:	DMPCSN3057901801						
Vehicle Reg. No. (Insured):	<b>SLP6145A</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Sat Motors (HQ)</b> 24 Defu Lane 12, 539131 Defu Lane - Tel:								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Elaine Cheong</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 30/10/2018]</b>								
Adj Asg. Remarks:	NO EST, CASE W/O SJE.								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
<b>Due Date</b>	<b>Priority</b>	<b>Type</b>	<b>Task Group</b>	<b>Subject</b>	<b>Handler</b>	<b>Assigned By</b>	<b>Completed On</b>	<b>Created On</b>	<b>Done?</b>
No results.									

## Claim Documents

**\*SLZ3524G (SNM18D04972C02)**  
**[SLP6145A]**  
**TP**  
**CHUA SIEW MEI**  
**Oct 16 2018 12:00AM**  
**[-]**  
**Sat Motors**

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a> <input type="button" value="v"/>	
<b>Photos/Images</b>			3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		<b>Thumbnail</b> <b>Print</b>
1	26/10/18 15:48	<b>General View</b>	 Load PDF	
2	26/10/18 15:48	<b>Photographs of Damaged Parts</b>	 Load PDF	
<b>Documentation</b>			1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		<b>Thumbnail</b> <b>Print</b>
1	19/10/18 16:33	<b>PRS</b>	 Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>   <a href="#">Save</a>   <a href="#">Print</a>
There are no document checklists configured.	
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>	
<div></div>	
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18019056/GCD3E2

Date: 01/11/2018

## REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN3057901801

Claimant Vehicle  
No: SLZ3524GInsured Vehicle  
No: SLP6145A

Date of Loss: 16/10/2018

Nature of Claim: TP

Claim  
No: SNM18D04972C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SLZ3524G

Make &amp; Model: VOLKSWAGEN NEW GOLF, 1.4 TSI 5K14Q5 (A)

Engine No: CAV090889

Reg. Date: 24/08/2009 (Man. Year: 2009)

Chassis No: WWWZZZ1KZAW004034

Colour: Red

Odometer: 174300 km

Engine Capacity: 1390 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

## CONDITION OF TYRES

Front Tyre Size: 225/40Z R18

Rear Tyre Size: 225/40Z R18

Front Left Side: Achilles 6 mm

Rear Left Side: Achilles 6 mm

Front Right Side: Achilles 6 mm

Rear Right Side: Achilles 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 19/10/2018

Date Inspected: 22/10/2018

Inspected At:

Sat Motors (HQ)  
24 Defu Lane 12  
Singapore 539131

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,000.00 -\$2,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 01 Nov 2018)
<b>Parts:</b>	144	VOLKSWAGEN NEW GOLF 1.4 TSI 5K14Q5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLZ3524G)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.


## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 16/10/18 at about 3:05pm, I was stationary at a traffic junction when suddenly vehicle B: SLP61115A hit on to the rear of my vehicle A: SLZ35246. This incident I would like to claim against the third party vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

\*

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



Address	BLK 675A YISHUN AVENUE 4 #03-746
Postcode	761675
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	AFTER RAIN
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO WITH DRIVER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP6145A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	83385562
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	