

ASS. REC. BY:

REF: CS/AIG18019061/Kg d352

Special Instruction:

Surveyor

Mumen

ASSIGNMENT (Office)

From (Person):

Azlan Syazairudin

of

AIG

Date/Time:

19/10/18 @ 3:25pm

Estimated Cost:

Bill to:

OD/REP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SKA 86462

Insured:

SLC 8547D

at Workshop m/s

AI Motor Holdings

Tel:

69262677 / 81889819

of

160 Sin Ming Drive #05-12

Policy No:

2100468334

Claim No:

53368311854

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

17/10/2018

CA / REV / REP. / REV 24 HRS

22/10/18

H.O.D. Endorsement:

Date/Time:

4:25pm @ 19/10/18

Person Contacted:

Ms-Grace

Vehicle:

IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SKA 86462 - CS/AIG14022171/Gwa 3q2
	SLC 8547D
26/10/18 @ 2:56pm	checked with Grace, the estimate not yet ready.
8/11	61 Lp @ 2200 enal

ASS. REC. BY:

REF:

A/G/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKA 86467

Yr Regn:

Apr, 2011

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Citroen C5

c.c

1598

Colour:

M.D. Blue

A/C:

Insured / Std / Nil / NA

Sp. Reading

143507

T/Radio:

Insured / Std / Nil / NA

Eng/No:

C/No:

VF7RD 5EV AAE574588

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kumho

Front

Rear

R/Bal.

2

mm

R/Bal.

2

mm

L/Bal.

2

mm

L/Bal.

2

mm

D.O.A.

1/18

D.O.I.

19/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

110 File pass to Catherine, GIA & EN not ready

11 Jan 8 2200 to Summit (Red & 73675, 90%)

RECEIVED 10 JAN 2013

Date/Time, File Pass to?

11/11/11

Date/Time, File Return to?

2)

☐

: Prel. Report

☐

: Final Report

Days Of Repair:

3

Resurvey No. of Trip:

1

Survey Fee:

250

Transportation:

S + RS, SI

Fixturs

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format:

MER-TP

Lump Sum / I.B.I. (\$

2200

250
20

- Pre repair inspection request - SKA8646Z VS SLC8547D (OI) DOA 17/10/2018

From: Azlan, Syazairdina
To: admin-a@lkkauto.com; assignments@lkkauto.com
Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa, Md Ishak, Mohd Imran, Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit
Sent: 19/10/2018 3:25:12 PM

Hi,

Please refer to the enclosed request from **Hin Tat Augustine & Partners**.

Claim no : 53368311185G003
Case Owner : MING YAO LEE

If you have any queries/concerns, please let us know.
Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Anil Kumar [mailto:anil@htapartners.com.sg]

Sent: Friday, October 19, 2018 3:07 PM

To: Azlan, Syazairdina

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi; Kaur, Baljit; AI Car Holdings; Tang Chi Loong; Marilyn Ho; sur@lkkauto.com

Subject: NOTICE OF ACCIDENT & PRE-REPAIR SURVEY - YOUR REF: SLC8547D & OUR REF: TCL.MH.en.50398.1B.AIMH - ACCIDENT INVOLVING SKA8646Z & SLC8547D ON 17/10/18

Without Prejudice
Save As To Cost

Dear Ms Azlan,

We refer to your email dated even date.

Our client is agreeable to use Mr. Kenneth Kong of LKK Auto Consultants Pte Ltd from your list to conduct the joint pre-repair survey as a single joint expert for our client's vehicle SLC8547D as follows:

Kindly contact the person-in-charge to arrange for the inspection of the vehicle. Please be informed that the said vehicle can be inspected at: -

Venue : AI MOTOR HOLDINGS PTE LTD
160 Sin Ming Drive

#05-12 Sin Ming Autocity

Singapore 575722

Contact Person : Ms Grace : 69262677

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference.

Best regards,

Anil (Secretary)
M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext.256
Direct Fax: 63383536
Fax : 6533 0313

From: Azlan, Syazairdina [mailto:Syazairdina.Azlan@aig.com]

Sent: Friday, October 19, 2018 9:33 AM

To: Anil Kumar <anil@htapartners.com.sg>

Cc: Fong, Andy-SY <Andy-SY.Fong@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Mithoosingh, Aashweenjeetkaur <Aashweenjeetkaur.Mithoosingh@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLC8547D AND SKA8646Z ON 17/10/2018

Importance: High

This is a secure, encrypted message. To read it, open the attachment.

这是安全加密信息。如要阅读此信息，请开启附件。

นี่คือการรักษาความปลอดภัยของข้อมูลที่เข้ารหัสลับ เพื่ออ่านมันโปรดเปิดไฟล์แนบมา

이것은 안전하고 암호화된 메시지입니다. 그것을 읽으려면 첨부 파일을 엽니다.

Ini adalah pesan, aman terenkripsi. Untuk membacanya, membuka attachment.

[Click here](#) by 2018-10-26 09:32 +08 to read your message.
After that, open the attachment.

[More info](#)

Disclaimer: This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2017 Proofpoint, Inc. All rights reserved.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Syazairina Azlan@aiig.com
To: anil@htapartners.com.sg
Cc: Andy-SY.Fong@aiig.com, Lee-Ying.Chin@aiig.com, NoorMariessa.AbuKassim@aiig.com, Imran.Ishak@aiig.com, ShengYang.Lim@aiig.com, Aashweenjeetkaur.Mithoosingh@aiig.com, Yokeshi.Chan@aiig.com, Baljit.Kaur@aiig.com
Subject: AIGENCRYPT - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLC8547D AND SKA8646Z ON 17/10/2018
Date: Fri, 19 Oct 2018 01:32:46 +0000
Without Prejudice

Your Reference : TCL.MH.an.50398.18.AIMH
Our Reference : 5336831118SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks and regards,

Syaza Irdina Azlan
AIG
Express Claims Adjuster II
SG Claims Operations | AIG Shared Services

From: Chan, Yoke Shi
Sent: Friday, October 19, 2018 7:36 AM
To: Azlan, Syazairina
Subject: FW: NOTICE OF ACCIDENT & PRE-REPAIR SURVEY - YOUR REF: SLC8547D & OUR REF: TCL.MH.an.50398.18.AIMH - ACCIDENT INVOLVING SKA8646Z & SLC8547D ON 17/10/18
Importance: High

From: Anil Kumar [mailto:anil@htapartners.com.sg]
Sent: Thursday, October 18, 2018 5:38 PM
To: Tan, Lily (AIG); Fong, Andy-SY; Kaur, Baljit; Chin, Lee-Ying; Lim, Sheng Yang; Md Ishak, Mohd Imran; Chan, Yoke Shi; Supramaniam, Darshene; Abu Kassim, Noor Mariessa
Subject: NOTICE OF ACCIDENT & PRE-REPAIR SURVEY - YOUR REF: SLC8547D & OUR REF: TCL.MH.an.50398.18.AIMH - ACCIDENT INVOLVING SKA8646Z & SLC8547D ON

17/10/18

Importance: High

Dear Sirs,

CLAIMANT: AI CAR HOLDINGS PTE LTD

ACCIDENT INVOLVING SKA8646Z & SLC8547D ALONG / AT CARPARK LEVEL 5B AT HARBOURFRONT ON 17/10/18 @ TIME: 18:30 HRS

We are instructed by AI Car Holdings Pte Ltd to notify you of the above-mentioned road traffic accident which involves our client's vehicle registration number **SKA8646Z** and vehicle registration number **SLC8547D** driven by your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Best regards,

Anil (Secretary)

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

Tel : 6533 0212 ext.256

Direct Fax: 63383536

Fax : 6533 0313

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	18/10/2018 12:32
Date Of Accident	17/10/2018 18:30
Exact Location Of Accident	CARPARK LEVEL 5B AT HARBOURFRONT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA8646Z
Insured/Policyholder	
Name Of Registered Owner	AI CAR HOLDINGS PTE LTD
Co Reg No	201733662W
Email Address	AICARHOLDINGSPTELTD@GMAIL.COM
Mobile Phone No	
Alternative Phone No	OFFICE-81889819

Vehicle Particulars

Manufacturer	CITROEN
Model	C5
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	QBE INSURANCE (SINGAPORE) PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	
Cover Note Number	2017/AGY/2388

Driver

Name of Driver	JEREMY CHANG YUAN JIE
NRIC No	S9734640B
Date Of Birth	02/10/1997
Occupation	INDOOR
Date Of Driving Pass	18/08/2016
Driving Experience	2 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97997878
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	23 JALAN TARI PAYONG
Postcode	799269
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - AUTHORISED DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : JIE MIN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC8547D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


ALCAR HOLDINGS PTE LTD
UEN NO: 201Y33662W

Policyholder's Signature

Date & Time:

18 OCT 2018

12:32hs


Printed Name of Policyholder


Driver's Signature
(If driver is not the policyholder)

Date & Time:

18 OCT 2018

12:32hs


Reporting Centre Personnel's Signature

Name:

Poh Kwee Choo

NRIC/FIN No.:

S6840583A

SKETCH PLAN

See Attached

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 17 Oct 2018, I, Jeremy Chang Yuan Jie
 S9734640B authorised driver of Vehicle SKA8646Z
 was at harbourfront Centre Carpark Level 5B.
 I was waiting for a silver toyota in front to
 park. At around 1830-1835, my car SKA8646Z
 was being bang from the back by SLC8547D
 driver Cheah Chee Chung S6932933J.
 SLC8547D had banged the back right bumper
 of my car with his left fender of SLC8547D.
 Cheah Chee Chung got out of his car and
 apologised to me before stating that he was looking
 straight ahead while making the left turn up after
 the slope and thus collided with my car.

I will send to AI MOTOR HOLDINGS PTE LTD @
 SIN MING AUTOCITY #05-12 for repair. - END of Report -

DECLARATION

I/We declare that the particulars are true in every respect.

AI CAR HOLDINGS PTE LTD

UEN NO: 201733662W

Policyholder's Signature

Date & Time:

18 OCT 2018

CHANG YUAN JIE

Zhang

Driver's Signature

(If driver is not the policyholder)

Date & Time: 18 OCT 2018

REPORTING CENTRE PERSONNEL'S SIGNATURE

Reporting Centre Personnel's Signature

Name: Poh Kwee Choo

NRIC/FIN No.: S6840583A

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3662W
Vehicle Details	
Vehicle No.:	SKA8646Z
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Nov 2018
Vehicle Make:	CITROEN
Vehicle Model:	C5 1.6 THP BVA AT ABS D/AB 2WD 4DR
Primary Colour:	Blue
Manufacturing Year:	2010
Engine No.:	10FJBK1017498
Chassis No.:	VF7RD5FVAAL574588
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$25,259.00
Original Registration Date:	11 Apr 2011
First Registration Date:	11 Apr 2011
Transfer Count:	1
Actual ARF Paid:	\$25,259.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Apr 2021
PARF Rebate Amount:	\$15,155.00
Intended COE Rebate Details	
COE Expiry Date:	10 Apr 2021
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$42,600.00
COE Rebate Amount:	\$10,330.00
Total Rebate Amount:	\$25,485.00

The information contained herein is correct as at 07 Nov 2018

OK

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details

Vehicle No.:	SKA8646Z
Vehicle Type:	P10 - Passenger Motor Car
Vehicle Attachment 1:	No Attachment
Vehicle Scheme:	Normal
Vehicle Make:	CITROEN
Vehicle Model:	C5 1.6 THP BVA AT ABS D/AB 2WD 4DR
Chassis No.:	VF7RD5FVAAL574588
Propellant:	Petrol
Engine No.:	10FJBK1017498
Engine Capacity:	1598 cc
Maximum Power Output:	115.0 kW (154 bhp)
Maximum Laden Weight:	2026 kg
Unladen Weight:	1515 kg
Year Of Manufacture:	2010
Original Registration Date:	11 Apr 2011
Lifespan Expiry Date:	-
COE Category:	A - Car (1600cc & below)
Quota Premium:	\$42,600.00
COE Expiry Date:	10 Apr 2021
Road Tax Expiry Date:	10 Apr 2019
PARF Eligibility Expiry Date:	10 Apr 2021
Inspection Due Date:	10 Apr 2020
Intended Transfer Date:	07 Nov 2018
CO2 Emission:	-
CO Emission:	-
HC Emission:	-
NOx Emission:	-
PM Emission:	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Total Amount Payable:			25.00

You may print this page for reference.

OK

Print

Post FREE Ad to Sell Your Used Items!

Have preloved items cluttering around your house?
Sell it on Marketplace. Posting an advertisement is FREE!

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

New 5 Years Coe Renewal Toyota Picnic 2.0A



2.80% P.A. Lowest Interest @ Gv
Cars Financing \$2000
Downpayment Monthly From
\$688
GV Credit Pte Ltd StarAd



Browse by Category

Sort by Date Posted

20 results/page

3 vehicles

CITROEN C5

Advanced Search



Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	CITROEN C5	Any	Any	2011	Any	Any	Any	Available
	Citroen C5 1.6A THP Exclusive	\$35,800	\$8,940 /yr	07-Feb-2011	1,598 cc	-	Luxury	Available
Rare-Grab This Beautiful 3-Digit Num Plate Today! Attractive Price! Only \$3,880 Drive Away. Up To 100% Flexible Loan, We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Pa...								
Classic Credit Pte Ltd								
Posted: 30-Oct-2018 Tags: 2011 Citroen C5, 2011 citroen c5, Citroen C5, citroen c5, Citroen, C5, c5, Used Citroen								
	Citroen C5 1.6A THP	\$39,800	\$8,470 /yr	10-Aug-2011	1,598 cc	-	Luxury	Available
Well Taken Care Luxury Sedan With Huge Boot Space, Low Depreciation For A Conti Sedan, Warranty On Engine And Gearbox, Certified With Assurance And Quality By STA Evaluation, Buy It From Us With A Pea...								
Dickson Automobile								
Posted: 17-Oct-2018 Tags: 2011 Citroen C5, 2011 citroen c5, Citroen C5, citroen c5, Citroen, C5, c5, Used Citroen								
	Citroen C5 1.6A THP Exclusive	\$39,999	\$8,050 /yr	22-Sep-2011	1,598 cc	88,735 km	Luxury	Available
End Mth Scrap If Not Sold! Low KM! Full Agent Servicing Records! New Bridgestone Tyres In Aug 18! Meticulous Owner Does What The Agent Suggests. Expect All Creature Comforts In A Mercedes But Pay A Fr...								
Hua Yang Credit Pte Ltd								
Posted: 12-Oct-2018 Tags: 2011 Citroen C5, 2011 citroen c5, Citroen C5, citroen c5, Citroen, C5, c5, Used Citroen								

Save this search criteria, to get email alerts whenever a match is found.

Make Model Price Depreciation Reg Date Eng Cap Mileage Veh Type Status

For old advertisements, view Expired ads

20 results/page

Home | New Cars | Used Cars | Sell My Car | Directory | Products | Insurance | Article | Forum | Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used CITROEN C5, CITROEN C5 Singapore, used CITROEN C5 Singapore, used CITROEN C5, used vehicles Singapore or even buy used CITROEN C5 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2018 sgCarMart. All rights reserved.

BIL NO	PARTS	QTY	REMARK	TOTAL PRICE
1	Rear bumper top 1pc	1	need order 3 months + airfreight	5100
2	Rear bumper side retainer 2 pcs	2	need order 3 months + airfreight	3300
3	Rear bumper clips	2		120
4	Rear bumper side chrome garnish right 1pc	1	need order 3 months + airfreight	1200
5	Rear bumper lower	1	need order 3 months + airfreight	1200
6	Rear bumper lower reflector right 1pc	1		135
7	Rear bumper parking sensor 1 set	1		2040
8	Rear lamp right 1pc	1		720
9	Rear lamp holder right 1pc	1	need order 3 months + airfreight	900
10	Rear lamp side cover right 1pc	1	need order 3 months + airfreight	960
11	Rear end panel 1pc	1	need order 3 months + airfreight	5400
12	Rear end panel inner trim 1pc	1	need order 3 months + airfreight	1200
13	Rear bumper clips 10pcs	1	need order 3 months + airfreight	300
TOTAL PARTS				22575

LAROUR CHARGE			
14	CHECK REAR WIRING & LIGHTING SYSTEM		120
15	REMOVE & REFIT TAIL LAMP & GASKET (RIGHT)		120
16	REMOVE & REFIT REAR REVERSE SENSOR		120
17	REMOVE & REFIT Rear bumper top		120
18	REMOVE & REFIT Rear bumper side retainer 2-pcs		120
19	REMOVE & REFIT Rear bumper clips 2-pcs		120
20	REMOVE & REFIT Rear bumper side chrome garnish right 1pc		120
21	REMOVE & REFIT Rear bumper lower		120
22	REMOVE & REFIT Rear bumper lower reflector right 1pc		120
23	REMOVE & REFIT Rear bumper parking sensor 1-set		120
24	REMOVE & REFIT Rear lamp right 1pc		120
25	REMOVE & REFIT Rear lamp holder right 1pc		120
26	REMOVE & REFIT Rear lamp side cover right 1pc		120
27	REMOVE & REFIT Rear end panel 1pc		120
28	REMOVE & REFIT Rear end panel inner trim 1pc		120
29	REMOVE & REFIT Rear bumper clips 10pcs		120
30	PANEL BEATING ON AFFECTED AREA		500
31	SPARY PAINTING ON AFFECTED AREA		800
32	APPLY ANTI RUST ON AFFECTED AREA		80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

3 days

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Oct 2018 Edit Reg		19 Oct 2018 00:00 Edit Adj Rpt	S\$2,200.00 Edit Estimates	S\$2,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	CHAW MEE YENG (CAO MEIYAN), ID: S7119797B		
Main Claimant:	-		
Vehicle Reg. No.:	SKA8646Z	Date of Loss:	17/10/2018 00:00 - :59 [90 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 5336831118SG	Policy/Cover Note No.:	2100468337 (Comprehensive)
Vehicle Reg. No. (Insured):	SLC8547D	Policy No. (Claimant):	
		Excess:	
Repairer:	- Not Applicable - (-)		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Lee, Ming-Yao] MingYao.Lee@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 30/10/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AIG_SG (22/10/2018): Request to upload TP GIA Report

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKA8646Z (5336831118SG)**
[SLC8547D]

TP

-

Oct 17 2018 12:00AM
[CHAW MEE YENG (CAO MEIYAN)]

Upload Documents

Upload Photos

Compose New Letter

Upload Video

Upload Audio

View

View in Browser

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	18/01/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
2	18/01/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
3	18/01/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
4	18/01/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
5	18/01/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
6	18/01/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
7	18/01/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
8	18/01/19 09:44	General View		Load JPG	<input checked="" type="checkbox"/>
9	18/01/19 09:44	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
10	18/01/19 09:44	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
11	18/01/19 09:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
12	18/01/19 09:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
13	18/01/19 09:48	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation

1 per page

No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	22/10/18 10:00	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#)
[Save](#)
[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18019061/KQD3S2
Date: 21/01/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100468337
Claimant Vehicle No: SKA8646Z Insured Vehicle No: SLC8547D
Date of Loss: 17/10/2018 Nature of Claim: TP Claim No: 5336831118SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKA8646Z
Make & Model: CITROEN C5, 1.6 (A) Engine No: 10FJBK1017498
Reg. Date: 11/04/2011 (Man. Year: 2010) Chassis No: VF7RD5FVAAL574588
Colour: Metallic Dark Blue Odometer: 143527 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55R17 Rear Tyre Size: 225/55R17
Front Left Side: Kumho 8 mm Rear Left Side: Kumho 8 mm
Front Right Side: Kumho 8 mm Rear Right Side: Kumho 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	22,575.00	2,171.00	20,404.00	90.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	680.00	2,620.00	79.39
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	25,875.00	2,851.00	23,024.00	88.98
Approved Total (Overridden) (\$\$)		2,200.00		
Nett Amount (\$\$)	25,875.00	2,200.00	23,675.00	91.50

INSPECTION

Date of Assignment: 19/10/2018
Date Inspected: 19/10/2018 Inspected At: AI MOTOR HOLDINGS PTE LTD
160 SIN MING DRIVE #05-12
SINGAPORE 575722
Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER TOP	Bent	5,100.00 F	*980.00 F
2	1		*REAR BUMPER SIDE RETAINER	O/s Distorted	3,300.00 F	*98.00 F
3	2		*REAR BUMPER CLIPS	Necessary	120.00 F	*50.00 F
4	1		*REAR BUMPER CHROME GARNISH RIGHT	Scratched	1,200.00 F	*138.00 F
5	1		*REAR BUMPER LOWER	Dented / Cut	1,200.00 F	*520.00 F
6	1		*REAR BUMPER LOWER REFLECTOR RIGHT	Scratched	135.00 F	*135.00 F
7	1		*SET REAR BUMPER PARKING SENSOR	Serviceable	2,040.00 F	*- F
8	1		*REAR LAMP RIGHT	Cracked	720.00 F	*250.00 F
9	1		*REAR LAMP HOLDER RIGHT	Serviceable	900.00 F	*- F
10	1		*REAR LAMP SIDE COVER RIGHT	Serviceable	960.00 F	*- F
11	1		*REAR END PANEL	Repair	5,400.00 F	*- F
12	1		*REAR END PANEL INNER TRIM	Serviceable	1,200.00 F	*- F
13	1		*SET REAR BUMPER CLIPS	Repeated	300.00 F	*- F
F=Franchise part.						
Total Parts (S\$)					22,575.00	2,171.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING & LIGHTING SYSTEM.	New	120.00	20.00
2	REMOVE & REFIT TAIL LAMP & GASKET (RIGHT)	New	120.00	0.00
3	REMOVE & REFIT REAR REVERSE SENSOR.	New	120.00	60.00
4	REMOVE & REFIT REAR BUMPER TOP. }	New	120.00	300.00
5	REMOVE & REFIT REAR BUMPER SIDE RETAINER. }	New	120.00	0.00
6	REMOVE & REFIT REAR BUMPER CLIPS. }	New	120.00	0.00
7	REMOVE & REFIT REAR BUMPER SIDE CHROME GARNISH RIGHT. }	New	120.00	0.00
8	REMOVE & REFIT REAR BUMPER LOWER. }	New	120.00	0.00
9	REMOVE & REFIT REAR BUMPER LOWER REFLECTOR RIGHT. }	New	120.00	0.00
10	REMOVE & REFIT REAR BUMPER PARKING SENSOR. }	New	120.00	0.00
11	REMOVE & REFIT REAR LAMP RIGHT. }	New	120.00	0.00
12	REMOVE & REFIT REAR LAMP HOLDER RIGHT. }	New	120.00	0.00
13	REMOVE & REFIT REAR LAMP SIDE COVER RIGHT. }	New	120.00	0.00
14	REMOVE & REFIT REAR END PANEL. }	New	120.00	0.00
15	REMOVE & REFIT REAR END PANEL INNER TRIM. }	New	120.00	0.00
16	REMOVE & REFIT REAR BUMPER CLIPS. }	New	120.00	0.00
17	PANEL BEATING ON AFFECTED AREA. }	New	500.00	0.00
18	SPRAY PAINTING ON AFFECTED AREA.	New	800.00	300.00
19	APPLY ANTI RUST ON AFFECTED AREA.	New	80.00	0.00
Gross Labour Cost (S\$)			3,300.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >