

27/03/2002

ASS. REC. BY:

REF:

CS/SPF18019101/Kobez

Special Instruction:

Surveyor

ASSIGNMENT (Office)

From (Person): Frankie Tay of SPF Date/Time: 22-10-2018

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SKT8924X Insured: Qx 590K

at Workshop m/s Tan Chong Motor Tel: 63570757

of 17 Lorong 8 Toa Payoh

Policy No: \_\_\_\_\_ Claim No: AMND / 105 / 101 / 2018 / 148

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 15.10.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp' 23.10.2018 @ 10am - 12pm H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 22.10.2018 1.49pm Person Contacted: Affendi Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SKT 8924X - X
	Qx 590K - X
3/1	Vehicle has not send in for repair. Pending for liability.
4/1	Submit preli report. (Repair range R3K-R5K)

ASSIGNMENT

From: \_\_\_\_\_ Date: 23-10-2018

Estimated Cost: \_\_\_\_\_

OD: (TP) / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKT 8924X

at Workshop m/s Tan Chong

of 17 Lorong 8 Tou Payoh

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: Mr. Affendi

(Policy Condition) 10am - 12pm

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rport: \_\_\_\_\_ Consistent?: Yes or No


GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 4-5 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT



Veh No: SKT 8924X Yr Regn: 06 / 15

Type: (C) M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: NIS Qashqai c.c. 1197

Colour: M. Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 85175 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: STNFEAJ11U1405401

Gen. Cond: (Good) / Fair / Poor / Burnt

Steering: (In order) / Jammed / Leaked / Burnt or

Brake: (In order) / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / (STD) A/Rim or

Tyre Size: F: 215/60R17  
R: \_\_\_\_\_

(BS) DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R/Bal. <u>9</u> mm	R/Bal. <u>9</u> mm
L/Bal. <u>9</u> mm	L/Bal. <u>9</u> mm
D.O.A. <u>15/10/18</u>	D.O.I. <u>23/10/18</u>

Survey held at \_\_\_\_\_

Des. of Damages: Frt / (Rear) / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Do not finalize</u>
<u>24/10</u>	<u>File pass to Catherine (3-9K)</u>

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format: TP

Lump Sum / I.B.I. (\$) \_\_\_\_\_

Days Of Repair: 5

Resurvey No. of Trip: -

Add Fee:  : Site Insp (\$)  : Interview (\$)  : Tech. Invs (\$)  : Weekend (\$)

Survey Fee: 280

Transportation: \_\_\_\_\_ \$ + RS, \_\_\_\_\_ \$

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL 280



# SINGAPORE POLICE FORCE

SPF Accidents Claims Section  
Automotive Engg & Mgmt Div  
Police Logistics Department  
No. 1 Mount Pleasant Road  
Block 8 Old Police Academy  
#02-12 Singapore 298333

Your Ref : SKT8924X

Our Ref : AEMD/105/09/2018/148

Date : 22 October 2018

Tel: 64784841

Fax: 64784848

LKK Auto Consultants Pte Ltd  
Paya Ubi Industrial Park  
51 Ubi Avenue 1 # 01/02-25  
Singapore 408933

**Via Fax only: 62564315**

Dear Sir,

## **ACCIDENT INVOLVING GOVERNMENT VEHICLE QX590K AND OTHER VEHICLE SKT8924X ON 15 OCTOBER 2018**

We refer to the above matter.

- 2 Kindly arrange for a Pre-Repair Inspection for Vehicle SKT8924X at Tan Chong Motor Sales Pte Ltd, Auto World Building, 17 Lorong 8, Toa Payoh, Singapore 319254.
- 3 Please contact Mr Affendi at 63570757 for appointment.
- 4 Thank you.

Yours faithfully,

Frankie Thay  
Safe Driving Manager  
for ASSISTANT DIRECTOR

**A FORCE FOR THE NATION**

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6705I
Vehicle Details	
Vehicle No.:	SKT8924X
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Jan 2019
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR
Primary Colour:	Brown
Manufacturing Year:	2015
Engine No.:	HRA2152137A
Chassis No.:	SJNFEAJ11U1405401
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$19,084.00
Original Registration Date:	25 Jun 2015
First Registration Date:	25 Jun 2015
Transfer Count:	0
Actual ARF Paid:	\$9,084.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jun 2025
PARF Rebate Amount:	\$6,813.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jun 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,000.00
COE Rebate Amount:	\$39,497.00
<b>Total Rebate Amount:</b>	<b>\$46,310.00</b>

The information contained herein is correct as at 03 Jan 2019

OK

# CERTIFICATE OF INSURANCE

Name of Policyholder : CHEW CHYE GUAN  
 Period of Insurance : 25 Jun 2018 To 24 Jun 2019  
 Engine No. : HRA2152137A  
 Chassis No. : SJNFEAJ11U1405401

Vehicle No. : SKT8924Z  
 Policy No. : 1800036298  
 Endorsement No. :  
 Issued Date : 27 Apr 2018

## ABOUT THE COVER

Make/Model : NISSAN Qashqai 1.2 DIG-Turbo  
 Engine Capacity/Tonnage : 1,197.00 CC  
 Driver Restriction : NA  
 Sum Insured : Market Value  
 Off Peak Car : No  
 First Year of Registration : 2015  
 Insuring with GOF/PARE : Yes

**Person or Classes of Persons Entitled to Drive :**

a) The Insured  
 b) Any other person who is driving on the Policyholder's order or with their permission  
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.  
 You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" (YIDEP) if you are a Young and/or Inexperienced Driver (YID) who has less than 2 years' driving experience.

Age Condition : All Age Condition

**Limitation as to use\***

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, or for any purpose in connection with the carriage of goods, or the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the above.

Loss of Use 1500cc - 1600cc Optional

\* Limitations rendered operative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 103) and Section 25 of the Road Transport Act, 1987 (Malaysia) and Section 10 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 103) and Section 25 of the Road Transport Act, 1987 (Malaysia) are not included under these headings.

## EXCESS

Section 1  
 Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0  
 Section 2  
 Property Damage - \$0  
 Windscreen : \$100

**Named Driver and Excess (where applicable)**

CHEW CHYE GUAN

## APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

Any accident repairs to the Vehicle must be carried out by one of our Authorised Repairers. Within the first 3 years of the first registration of the Vehicle in Singapore, you have the option of having the accident repairs carried out at the Sole Agent's workshop.  
 For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6739 8003. Alternatively, You may refer to AIG website [www.aig.com.sg](http://www.aig.com.sg) or the AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

## IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: NA

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 103) and Section 25 of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1958 (Malaysia)

0503487000  
 AAS INSURANCE AGENCY PTE LTD  
 535 KALLANG BAHRU #02-08 GS POINT  
 SINGAPORE 339351  
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

*M. Manile*  
 AIG Asia Pacific Insurance Pte. Ltd.  
 AUTHORISED REPRESENTATIVE

No. Rev. 18 27102015M. 1 Copy right © 2015. AIG Asia Pacific Insurance Pte. Ltd.

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S14667051



Name: CHEW CHYE GUAN

周財源

Race:

CHINESE

Date of Birth:

28-03-1961

Sex:

M

Country of Birth:

SINGAPORE

S14667051

REPUBLIC OF SINGAPORE DRIVING LICENCE



License Number: S14667051

Name: CHEW CHYE GUAN

Issue Date: 28 Mar 1961

Valid Until: 18 Jun 2003



900578757A



NRIC No. S14667051



Issue Class: Date of issue:

B+ 27-09-1991


Address:  
145 LENTOR STREET  
SINGAPORE 786840  
NRIC No: S14667051

Date: 07/11/2007 (R) No: 14667051

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S):

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

02 Sep 1982



License No. S14667051

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	16/10/2018 16:54
Date Of Accident	15/10/2018 07:55
Exact Location Of Accident	YIO CHU KANG ROAD ANG MO KIO AVE 8
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKT8924X
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHEW CHYE GUAN
NRIC No	S1466705I
Email Address	CHEWCG@OUTLOOK.COM
Mobile Phone No	(LOCAL) +65-98311218
Alternative Phone No	OFFICE-98311218
<b>Vehicle Particulars</b>	
Manufacturer	NISSAN
Model	QASHQAI-1.2 DIG-T CVT ABS 2WD 5DR (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800035289
Cover Note Number	
<b>Driver</b>	
Name of Driver	CHEW CHYE GUAN
NRIC No	S1466705I
Date Of Birth	28/03/1961
Occupation	INDOOR
Date Of Driving Pass	02/09/1982
Driving Experience	36 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98311218
Fax Number	
Contact Number	OFFICE-98311218
EEmail Address	CHEWCG@OUTLOOK.COM

Address 145 LENTOR STREET  
 Postcode 786840  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident 2  
 Was any body injured in the Accident? NO  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2  
 Passenger 1 NAME: : CHEW WEI KWANG  
 GENDER: : MALE

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE  
 Police Station Address ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-4849999 - FAX NO: 62181399  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

PLEASE REFER TO POLICE REPORT ATTACH. REPORT NO : T/20181015/2204

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number QX590K  
 Vehicle Make/Model/Colour HYUNDI  
 Details Of Properties SALOON CAR  
 Vehicle Category GOVERNMENT  
 Name of Driver ALAN KOH ZHENG YONG  
 NRIC/Passport Number S9825526E  
 Contact Number  
 Address  
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorized Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the IA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [Form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyer/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

TAN CHONG MOTOR SALES PTE LTD  
 17, Tanjong Pagar Road  
 Singapore 330214  
 Tel: 6357 0759 Fax: 6356 4922

Policyholder's Signature  
 Date & Time: 16/05/2015  
 12:00

Driver's Signature  
 (if driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name: [Signature]  
 NRIC/FIN No.: 973221800



POLICE REPORT Pg. 1



SINGAPORE  
POLICE FORCE



151010180755

1 of 5

Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

Report No: 15201810562903

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/10/2018 22:54	Video Report No.:	Station Diary No.: 119
--	-------------------	---------------------------

Informant's Particulars

Name of Informant: CHEW CHYE GUAN			Address: 145 LENTOR STREET SINGAPORE 786840		
ID Type / ID No.: NRIC NO / S14667051			Contact No.:		
Nationality: SINGAPORE CITIZEN			Home/Office: Mobile 98311218		
Email:					
Sex: Male	Age: 57	Date of Birth: 28/03/1961	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: UNEMPLOYED			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 15/10/2018 07:55	Type of Location: X-Junction
Location: Along Road 1 YIO CHU KANG ROAD ANG MO KIO AVENUE 6 Right form up lane of traffic light juncture of Yio Chu Kang Road, Ang Mo Kio Ave 6.				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Traffic Light - Working		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
QX590K	Car				Slightly Damaged	2
SKT8924X	Car	NISSAN	QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR	Brown	Slightly Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



SINGAPORE  
POLICE FORCE



F/20181015/0092

Police Station Of Origin  
Ang Mo Kio North N.P.C.  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No 1800-4849999

012-4

F/20181015/0092

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SKT8924X	AIG ASIA PACIFIC INSURANCE PTE LTD.	1800035289	25/06/2018	24/06/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	CHEW CHYE GUAN		ID No	S1466705I
Related Vehicle	SKT8924X (Car)		Contact No.	98311218
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
Passenger				
Name	CHEW WEI KWANG		ID No.	S9320083G
Related Vehicle	SKT8924X (Car)		Contact No.	92711328
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

**Brief Details.**

On 15/10/2018 at about 0755hrs, I was driving along Yio Chu Kang Road when I filtered out to the most right lane, in preparation to turn into Ang Mo Kio Avenue 6.

While filtering to the turn right lane, the turn right arrow was already blinking so I then prepared to stop my car at the traffic light junction. After stopping, my car SKT8924X was suddenly hit at the rear by a police vehicle with plate number QX590K. The other driver of the car was Alan Koh Zheng Yong. My car then jerked forward.

There was no injuries to anyone and traffic police then attended to the accident.

I have also given a SD card consisting of the front and rear camera footage of my car to Traffic Police. Report reference number F/20181015/0092.

I am lodging this report for record purposes.



SINGAPORE  
POLICE FORCE



12345678901234567890

Police Station of Origin  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No. 1800-4849999

Report No. 16200519102504

CONTINUATION OF REPORT



SINGAPORE  
POLICE FORCE



179319191502000

Police Station Of Origin  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
509784  
Tel No: 1800-4849999

R.F.A.

Report No: 179319191502000

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT. Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Staff Sgt MOHAMED SHA'ARI BIN MOHAMED <sup>W</sup> AYOB <i>ibni ismet, Palsamaran Mohd Ismet</i>
Signature Of Interpreter: Not applicable <i>[Signature]</i>
Officer In Charge Of Case: TP / GIT / SI MOHAMMAD ABDILLAH BIN PALIL Contact No.: 65476246

Signature Of Informant: <i>[Signature]</i>
Date/Time: 15/10/2018 22:54
Classification Of Case:

Authentication Stamp  
NP158

TC AUTOCLINIC PTE LTD  
1 SIXTH LOK YANG ROAD  
SINGAPORE 628099

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : 225/1C/TC/HO/2018

DATE : 18-OCT-2018

SPF ACCIDENT CLAIMS SECTION  
POLICE LOGISTICS DEPARTMENT  
NO.1 MOUNT PLEASANT ROAD  
BLK 8 OLD POLICE ACADEMY S(298333)  
TEL : 64784840  
FAX : 64784848  
MR QUEK SWEE CHOON

OWNER'S NAME : MR CHEW CHYE GUAN

ADDRESS : 145 LENTOR STREET

S(786840)

TELEPHONE NO : 83838812/98311218

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM  
POLICY NO : SINGAPORE POLICE FORCE 3RD PAR  
VEHICLE NO : SKT8924X  
MODEL CODE : FRLARB2J11UEA--A--  
MODEL/YEAR : NISSAN QASHQAI 1.2  
ENGINE NO : HRA2152137A  
CHASSIS NO : SJNFEAJ11U1405401  
MILEAGE : 1 KM  
DATE IN : 18/10/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : HO YUE MENG  
ACCIDENT DATE : 15/10/2018

TC AUTOCLINIC PTE LTD  
1 SIXTH LOK YANG ROAD  
SINGAPORE 628099

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SKT8924X

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	NP1	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS-REAR	60.00	X
2	RP1	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	120.00	?
3	RS1	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	110.00	601
4	SEAL1	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	100.00	?
5	ZZ/001	REMOVE/INSTALL REAR BUMPER, END PANEL AND AFFECTED PORTION. REPAIR BACK DOOR, LHR FENDER & RHR FENDER	1560.00	7801
6	ZZ/002	RESPRAY PAINT REAR BUMPER, END PANEL, BACK DOOR, LH REAR FENDER AND RH REAR FENDER	1500.00	5001
7	ZZ/003	REMOVE/INSTALL REAR SEAT AND CARPETS TO FACILITATE TEH REPAIR	240.00	?
8	ZZ/004	CHECK REAR LIGHTINGS AND WIRING SYSTEM	20.00	✓
TOTAL LABOUR CHARGES			3710.00	

TC AUTOCLINIC PTE LTD  
 1 SIXTH LOK YANG ROAD  
 SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SKTB924X

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	CLIP-LH REAR OVER FENDER @\$2.50EACH X3PCS	76847-JG00A	<i>me</i> 7.50	✓	
2	CLIP-LH REAR OVER FENDER @\$2.50EACH X3PCS	76847-4EA0A	7.50	?	
3	OVER FENDER-REAR,LH	93829-4EA0A	403.00	?	
4	CLIP-REAR LUGGAGE PLATE @\$1.20EACH X4PCS	01554-00181	<i>me</i> 4.80	X	
5	PLATE-LUGGAGE,REAR	84992-4EA0A	<i>me</i> 63.50	X	
6	DRAFTER-AIR @\$62.30EACH X2PCS	76804-JD00A	<i>su</i> 124.60	X	
7	WEATHER STRIP-BACK DOOR	90830-4EA0B	<i>su</i> 158.70	X	
8	EMBLEM-REAR	90892-4EA0A	<i>me</i> 87.00	X	
9	EMBLEM-REAR	90890-4EA0A	<i>me</i> 59.70	X	
10	LH REAR BUMPER STAY	H5211-4EAMA	126.00	?	
11	RH REAR BUMPER STAY	H5210-4EAMA	126.00	?	
12	REAR BUMPER REINFORCEMENT	H5030-4EAMA	619.20	?	
13	REAR BUMPER ENERGY ABSORBER	85090-4EA0B	126.40	?	
14	RH REAR BUMPER SIDE BRACKET	85220-4EA0A	35.90	?	
15	LH REAR BUMPER SIDE BRACKET	85221-4EA0A	35.90	?	
16	RETAINER-REAR BUMPER SIDE,LH	79185-4EA0A	<i>dit</i> 23.80	✓	
17	RETAINER-REAR BUMPER SIDE,RH	79184-4EA0A	<i>su</i> 23.80	X	
18	REAR BUMPER UPPER CLIP @\$7.40EACH X3PCS	85284-JD00A	<i>me</i> 22.20	✓	
19	CANOE RIVET-REAR BUMPER @\$6.50EACH X2PCS	76882-0M000	13.00	?	
20	REAR BUMPER LOWER CLIP @\$1.20EACH X4PCS	01553-05933	<i>me</i> 4.80	✓	
21	FINISHER-REAR BUMPER	85071-4EA0A	16.80	?	
22	REVERSE SENSOR(4EYE)	SENSOR-4-FUM			250.00 ?
23	REAR BUMPER FASCIA	85022-4EA0H	<i>net</i> 717.00	✓	
24	REAR END PANEL	G9110-4EAMA	<i>R</i> 482.60	?	
25	LAMP ASSY-REAR COMBI,RH	26550-4EA0A	<i>su</i> 323.70	X	

TC AUTOCLINIC PTE LTD  
 1 SIXTH LOR YANG ROAD  
 SINGAPORE 628099

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SETB924X

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
26	LAMP ASSY-REAR COMBI, LH	26555-4EA0A	<i>pu</i> 323.70		X
SUB TOTAL			4017.10	0.00	250.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			803.42	0.00	5.00
GRAND TOTAL			3213.68	0.00	250.00
OVERALL TOTAL			3463.68		

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

TC AUTOCLINIC PTE LTD  
1 SIXTH LOK YANG ROAD  
SINGAPORE 628099

SUMMARY OF ESTIMATE FOR VEHICLE REGH NO SFT0924X

TOTAL LABOUR CHARGES	3710.00
TOTAL SPARE PARTS CHARGES	3463.60
GRAND TOTAL	7173.60 *

\* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

*Not Authorized*  
*L.B.I*  
*Prep work B4 paint*  
*4-5 days*

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18019101/Kcbe2	
ACCIDENT CLAIM SECTION(SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333 ATTN : FRANKIE THAY		Date : 07-01-2019	
		Code : SPF	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	QX 590K	Veh. Inspected	SKT 8924X
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/009/2018/148	Excess (\$)	0.00
Assign From	FRANKIE THAY	Assign Date	22/10/2018
2. Vehicle Particulars & Condition			
Make & Model	NISSAN QASHQAI (A)	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	SJNFEAJ11U1405401	Colour	METALLIC MAROON
Odometer	85175	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R17	BRIDGESTONE	9 mm
L/H Front Tyre	215/60 R17	BRIDGESTONE	9 mm
R/H Rear Tyre	215/60 R17	BRIDGESTONE	9 mm
L/H Rear Tyre	215/60 R17	BRIDGESTONE	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	15/10/2018	Inspection Date	23/10/2018
Survey held at	TAN CHONG MOTOR SALES PTE LTD 17 LORONG 8 TOA PAYOH SINGAPORE 319254		
5a. Remarks			
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>5 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 8924X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
3	CLIP-LH REAR OVER FENDER @\$2.50 (N)	NECESSARY	7.50	7.50
3	CLIP-LH REAR OVER FENDER @\$2.50 (N)	* CHECK	7.50	-
1	OVER FENDER-REAR, LH (N)	* CHECK	483.00	-
4	CLIP-REAR LUGGAGE PLATE @\$1.20 (N)	NOT NECESSARY	4.80	-
1	PLATE-LUGGAGE, REAR (N)	NOT NECESSARY	63.50	-
2	DRAFTER-AIR @\$62.30 (N)	SERVICEABLE	124.60	-
1	WEATHER STRIP-BACK DOOR (N)	SERVICEABLE	158.70	-
1	EMBLEM-REAR (N)	NOT NECESSARY	87.00	-
1	EMBLEM-REAR (N)	NOT NECESSARY	59.70	-
1	LH REAR BUMPER STAY (N)	* CHECK	126.00	-
1	RH REAR BUMPER STAY (N)	* CHECK	126.00	-
1	REAR BUMPER REINFORCEMENT (N)	* CHECK	619.20	-
1	REAR BUMPER ENERGY ABSORBER (N)	* CHECK	126.40	-
1	RH REAR BUMPER SIDE BRACKET (N)	* CHECK	35.90	-
1	LH REAR BUMPER SIDE BRACKET (N)	* CHECK	35.90	-
1	RETAINER-REAR BUMPER SIDE, LH (N)	DISTORTED	23.80	23.80
1	RETAINER-REAR BUMPER SIDE, RH (N)	SERVICEABLE	23.80	-
3	REAR BUMPER UPPER CLIP @\$7.40 (N)	NECESSARY	22.20	22.20
2	CANOE RIVET-REAR BUMPER @\$6.50 (N)	* CHECK	13.00	-
4	REAR BUMPER LOWER CLIP @\$1.20 (N)	NECESSARY	4.80	4.80
1	FINISHER-REAR BUMPER (N)	* CHECK	16.80	-
1	REAR BUMPER FASCIA (N)	DENTED	717.00	717.00
1	REAR END PANEL (N)	* CHECK	482.60	-
1	LAMP ASSY-REAR COMBI, RH (N)	SERVICEABLE	323.70	-
1	LAMP ASSY-REAR COMBI, LH (N)	SERVICEABLE	323.70	-
	LESS 20% DISCOUNT		-803.42	-155.06
			3,213.68	620.24
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REVERSE SENSOR (4EYE) (SN)	* CHECK	250.00	-
			250.00	-
<b><u>LABOUR</u></b>				
	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS - REAR.	NOT NECESSARY	60.00	-

Report Ref No. CS/SPF18019101/Kcbe2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL.	* CHECK	120.00	-
	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST.		110.00	60.00
	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA.	* CHECK	100.00	-
	REMOVE / INSTALL REAR BUMPER, END PANEL AND AFFECTED PORTION, REPAIR BACK DOOR, LHR FENDER & RHR FENDER.		1,560.00	780.00
	RESPRAY PAINT REAR BUMPER, END PANEL, BACK DOOR, LH REAR FENDER AND RH REAR FENDER.		1,500.00	500.00
	REMOVE / INSTALL REAR SEAT AND CARPETS TO FACILITATE TEH REPAIR.	* CHECK	240.00	-
	CHECK REAR LIGHTINGS AND WIRING SYSTEM.		20.00	20.00
			3,710.00	1,360.00
	<b>GRAND TOTAL</b>		<b>7,173.68</b>	<b>1,980.24</b>
	<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$2,367.84 NETT)</b>			<b>1,980.24</b>

Report Ref No. CS/SPF18019101/Kcbe2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.