

Our Ref : CC18100648/ SHA 647J /WT(st)
Your Ref :
Date : 12-Nov-18

CDGE Taxi Claims Dept
59 Loyang Drive 4th Flr
Singapore 508969

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 199506048W

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Yishun
501 Yishun Industrial Park A
Singapore 768732

AXA Insurance Pte Ltd
8 Shenton Way
#24-01, AXA Tower
Singapore 068811

Attn : Motor Claims Department

WITHOUT PREJUDICE

Dear Sir

**ACCIDENT INVOLVING OUR TAXI SHA 647J YOUR INSURED FBE9644H
AND OTHER _____ ON 20.10.18**

We are the authorised repair workshop for Citycab Pte Ltd, the owner of motor Vehicle No : SHA 647J which was involved in the captioned accident with your insured vehicle.

The vehicle owner and the taxi driver concerned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving : FBE9644H we are submitting these claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 4,236.99
2	<u>5</u> days Loss of Rental @ \$ 117.00 per day	\$ 585.00
3	Survey Report Fees (Surveyed by M/s LKK)	\$ -
4	LTA Search Fees	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing Fees	\$ -
Sub Total :		\$ 4,829.48

HIRER'S CLAIM

7	<u>5</u> days Loss of Income @ \$ 80.00 per days	\$ 400.00
Total Claims :		\$ 5,229.48

We enclose herewith the following documents to support the claims: -

- a) Original repair bill and photocopies of photographs 9 pcs.
b) LTA search slip/s of : FBE9644H
c) GIA / Police report/s of : SHA 647J
d) Letter of authority from owner / hirer / operator
(X) Photocopies of Accident Scene Photo/s () Hirer's 3 Years IRAS
() Witness statement/s (x) Rental Rate letter (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

William Tan

CDGE Claims Department

Tel: 6214 8737 Fax : 6214 1843 Email : williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.

LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING
ALONGi 40 SHA647J , FBE9644H
YISHUN RING RD TOWARDS YISHUN AVE 4 JUNCTION

ON 20-Oct-18 04:00

I / We

CHANG CHIN WOH

(Hirer) NRIC No.: S1191324E

and/or

ONG HOCK CHUAN

(Relief) NRIC No.: S7107003D

Taxi Number

SHA647J

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

20-Oct-2018

Name of Hirer
Hirer NRICCHANG CHIN WOH
S1191324E

Signature :



Address

43 JALAN TIGA #17-24
390043

Contact No.

97397556

Name of Relief
Relief NRICONG HOCK CHUAN
S7107003D

Signature :



Address

50 LORONG 28 GEYLANG ROAD 08-03
398453

Contact No.

90698832

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W
Page: 1

8010010

AXA INSURANCE PTE LTD

8 SHENTON WAY AXA TOWER #24-01
SINGAPORE SG 068811

CONTACT NO: 63387288

VEHICLE NO
SHA 647J

INV. NO/DATE
91404737 30.10.2018

MAKE
HYUNDAI

JOB NO.
305228256

MODEL
I-40

ODOMETER READING

DATE OF REG
11.01.2017

DATE/TIME IN
20.10.2018 08:15

CHASSIS CODE
KMHLB41UMHU098298

Description : 3P 20.10.18/C

S/No	Part No.		Qty	Unit Price	%Disc	Net
PART REQUISITION						
0001	04-01-0103-0592	I40VC PANEL ASSY-FR DR RH	1	2,256.40	20.00	1,805.12
0002	04-01-0103-0594	I40VC MIRROR ASSY-RR VIEW	1	670.00	20.00	536.00
0003	04-01-0103-0658	I40VC CAP ASSY-WHEEL HUB	1	107.10	20.00	85.68
0004	28-01-0103-0003	(I40)FRT DOOR LOGO SONATA	1	75.00	0.00	75.00
0005	28-01-0103-2014	I40V3 APP LOGO REAR DOOR	1	80.00	0.00	80.00
0006	19-01-0103-2013	I40VC HANKOOK 205/60R16 H	1	216.00	50.00	108.00
SUB-TOTAL						2,689.80

JOB NATURE

0001	L	PANEL BEATING- FRT.	300.00	300.00
0002	23-502	SPRAYPAINT ON AFFECTED AREA	800.00	800.00

- WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED AT OWNERS' RISK.
- CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GIVE NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.
- INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.
- PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd
A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010010	91404737	4,236.99	

GST REG. NO. M2-8921817-3

TAX INVOICE

COMPANY REG. NO.: 199506048W
Page: 2

8010010

AXA INSURANCE PTE LTD

8 SHENTON WAY AXA TOWER #24-01
SINGAPORE SG 068811

CONTACT NO: 63387288

VEHICLE NO
SHA 647J

MAKE
HYUNDAI

MODEL
I-40

DATE OF REG
11.01.2017

CHASSIS CODE
KMHLB41UMHU098298

INV. NO/DATE
91404737 30.10.2018

JOB NO.
305228256

ODOMETER READING

DATE/TIME IN
20.10.2018 08:15

S/No	Part No.		Qty	Unit Price	%Disc	Net
0003	20-00	TUFF COAT ON AFFECTED PARTS.	20.00		20.00	
0004	20-05	RENEW ADVERTISEMENT STICKER-	100.00		100.00	
0005	L	TRANSFER DOOR PART	50.00		50.00	
SUB-TOTAL				:		1,270.00

Items total		3,959.80
Add GST @	7.000 %	277.19
Invoice amount		4,236.99

Issued by : KATHERINETAN 30.10.2018 14:47:32
Repair type : CFSO/57/57
Payment Type/Term: /Credit 30 days

- WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED AT OWNERS' RISK.
- CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GIVE NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.
- INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.
- PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd

A member of COMFORTDELGRO

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.
8010010	91404737	4,236.99	

Our Ref: CC18100648



Date: 30 October 2018

TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON 20/10/2018 @ 04:00 hrs
ALONG YISHUN RING RD > YISHUN AVE 4 JUNCTION
INVOLVING FBE9644H

We refer to the above-mentioned accident and wish to inform that **CityCab Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHA0647J** (the "Taxi"). The Taxi was hired to **CHANG CHIN WOH IC NO S1191324E** a registered hirer-operator of **CityCab Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate **\$117.00** per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay
Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

Enquire Vehicle Insurer

Vehicle No.	Incident Date/Time	Search Status	Insurance Company Code	Insurance Company Name
FBE9644H	20 Oct 2018 / 04:00:00	Successful	A12	AXA INSURANCE PTE LTD

[Previous](#)[OK](#)

SHA647J

