

22/03/2002

ASS. REC. BY:

REF:

CS3/ICS18019134/GCDB

Special Instruction:

Surveyor:

Guo Qing

ASSIGNMENT (Office)

From (Person):

Desmond Lee

of

ECICS

Date/Time:

19/10/18 @ 6.09

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FY 4117 T

Insured:

GX56764

at Workshop m/s

Wing Fung Trading

Tel:

67425588

of

81K 3020A Ubi Road 1 #01-37

Policy No:

Claim No:

DMCV18000814

Sum Insured:

Excess:

Make of Veh:

D.O.A.

16/10/18

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

9:02am @ 22/10/18

Person Contacted:

Eric

Vehicle IN/OUT

Date/Time

Action/Instruction

(X) Estimate

FY 4117 T - NA/INC18018904/k4

DOT: 16/10/2018

GX56764 - NA/INC18018904/k4

DOT: 16/10/2018



## Nivitha (LKK Auto)

---

**From:** Desmond Lee Ker Wen (ECICS, Claims) <Desmond\_Lee@ecics.com.sg>  
**Sent:** Friday, 19 October 2018 6:09 PM  
**To:** Mail office; SUR; assignments  
**Cc:** motorsurvey; ECICS Claims  
**Subject:** RE: PRS for FY4117T involving vehicle GX5676H on 16 October 2018 along Sungei Kadut Street 1 (Oref: GTW.ACC.10T172.18.wk)

Without Prejudice

Dear Sir

We are not agreeable to your proposed motor surveyors.

We are appointing LKK for the PRS.

Hi LKK

Kindly do the needful.

Thank you.

Best regards,  
Desmond Lee  
Claims Division  
DID: +65 6303 0167  
FAX: +65 6338 9267

ECICS Limited  
7 Temasek Boulevard  
#10-01 Suntec Tower One  
Singapore 038987

Our new address wef 6 August 2018

**ECICS Limited**  
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

**From:** Mail office [mailto:mail@gohjpwong.com]  
**Sent:** Friday, 19 October, 2018 5:55 PM  
**To:** Desmond Lee Ker Wen (ECICS, Claims)  
**Cc:** motorsurvey; ECICS Claims  
**Subject:** Re: PRS for FY4117T involving vehicle GX5676H on 16 October 2018 along Sungei Kadut Street 1 (Oref: GTW.ACC.10T172.18.wk)

Dear Sir

We are not agreeable to your proposed motor surveyors.

Our list of proposed Single Joint Expert ("SJE") as follows:-

1. Teo Liak Hoo of L H Teo Appraisal Services
2. Jayson Liaw Leong San of Pro-Option Services
3. Seah Kwang Boon of Absolute Appraisal Services
4. Oh Han Cheong of Oh Appraisal
5. Bok Jee Tan of Prudent Adjustors Services
6. Fong Kok Heng Stanley of Automax Survey
7. Sebastian Lim Yong Tian of Constant Appraiser Services
8. Lek Boon Hwee of Auto Performance Appraisal
9. Louis S C Ng Cae Amimi of Prestige Appraiser Services
10. Richard Wong Ah Kow of R W Automotive Appraiser Services

Lee Wee Ka  
for and on behalf of Goh Teck Wee  
Messrs Goh JP & Wong LLC  
Advocates & Solicitors  
Commissioner for Oath  
133 New Bridge Road #16-09  
Chinatown Point Singapore 059413  
Tel: 6538 5868  
Fax: 6538 4898

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 5 pm and we are closed on Saturday, Sundays and Public Holidays. UEN/GST Regn No: 201406078M

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender.

You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Fri, Oct 19, 2018 at 5:35 PM Desmond Lee Ker Wen (ECICS, Claims) <[Desmond\\_Lee@ecics.com.sg](mailto:Desmond_Lee@ecics.com.sg)> wrote:

## **Without Prejudice**

Dear Sir/Madam,

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop.

We propose to use one of the motor surveyors named in our list to conduct the joint pre-repair survey as a single joint expert.

Please let us know within 2 working days whether you are agreeable to the appointment of any these motor surveyors

provided to you as a single joint expert.

You may select one of our motor surveyors.

As our listed of the survey firms for your nomination:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please furnish us a copy of repair quotation/estimate to show the detail of cost of repair breakdown for each item together with the full detail

to show the names of the driver of the GIA reports and colour photographs of the damaged vehicle to evaluate transparency on the pre-repair

survey of this claim.

Thank you.

Best regards,

Desmond Lee

Claims Division

DID: +65 6303 0167

FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard

#10-01 Suntec Tower One

Singapore 038987

Our new address wef 6 August 2018

**ECICS Limited**

**10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600**

follow us on  facebook  follow us on twitter  visit our website [ecics.com.sg](http://ecics.com.sg) 

This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

**Nivitha (LKK Auto)**

---

**From:** Mail office <mail@gohjpwong.com>  
**Sent:** Monday, 22 October 2018 8:02 AM  
**To:** Desmond\_Lee@ecics.com.sg  
**Cc:** LKK Auto; assignments; motorsurvey@ecics.com.sg; claims@ecics.com.sg  
**Subject:** Re: PRS for FY4117T involving vehicle GX5676H on 16 October 2018 along Sungei Kadut Street 1 (Oref: GTW.ACC.10T172.18.wk)

Dear Sir

Our client's motorcycle FY 4117T is now at Wing Fuat Trading Co of Blk 3020A Ubi Road 1 #01-37 Singapore 408714 (Tel: 67425288 - Mr Eric).

Kindly proceed to conduct the pre-repair inspection forthwith and let us know once the pre-repair inspections has been conducted, failing which we shall assume that the pre-repair inspection is conducted within the next 2 working days

Lee Wee Ka  
for and on behalf of Goh Teck Wee  
Messrs Goh JP & Wong LLC  
Advocates & Solicitors  
Commissioner for Oath  
133 New Bridge Road #16-09  
Chinatown Point Singapore 059413  
Tel: 6538 5868  
Fax: 6538 4898

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 5 pm and we are closed on Saturday, Sundays and Public Holidays. UEN/GST Regn No: 201406078M

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender.  
You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Fri, Oct 19, 2018 at 6:08 PM Desmond Lee Ker Wen (ECICS, Claims) <Desmond\_Lee@ecics.com.sg> wrote:

Without Prejudice

> Back to OneMotoring

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	FY4117T		
Vehicle Type :	P01 - Passenger Scooter		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	PIAGGIO		
Vehicle Model :	VESPA GT200A		
Chassis No. :	ZAPM3120000018935		
Propellant :	Petrol		
Engine No. :	M312M19367		
Engine Capacity :	198 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	-		
Unladen Weight :	138 kg		
Year Of Manufacture :	2004		
Original Registration Date :	14 Sep 2004		
Lifespan Expiry Date :	-		
COE Category :	D - Motorcycle		
PQP Paid :	\$4,040.00		
COE Expiry Date :	31 Aug 2024		
Road Tax Expiry Date :	03 Oct 2019		
Inspection Due Date :	03 Oct 2019		
Intended Transfer Date :	26 Oct 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2665B
Vehicle Details	
Vehicle No.:	FY4117T
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Oct 2018
Vehicle Make:	PIAGGIO
Vehicle Model:	VESPA GT200A
Primary Colour:	Green
Manufacturing Year:	2004
Engine No.:	M312M19367
Chassis No.:	ZAPM3120000018935
Maximum Power Output:	-
Open Market Value:	\$3,257.00
Original Registration Date:	14 Sep 2004
First Registration Date:	14 Sep 2004
Transfer Count:	1
Actual ARF Paid:	\$489.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	31 Aug 2024
COE Category:	D - Motorcycle
COE Period(Years):	10
PQP Paid:	\$4,040.00
COE Rebate Amount:	\$2,384.00
Total Rebate Amount:	\$2,384.00

The information contained herein is correct as at 26 Oct 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	17/10/2018 16:42
Date Of Accident	16/10/2018 14:25
Exact Location Of Accident	SUNGEI KADUT STREET 1
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	FY4117T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	AHMAD BIN AMAT
NRIC No	S1252665B
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94525725
Alternative Phone No	OTHERS-94525725
<b>Vehicle Particulars</b>	
Manufacturer	PIAGGIO
Model	VESPA GT200A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	5001325403-14
Cover Note Number	
<b>Driver</b>	
Name of Driver	AHMAD BIN AMAT
NRIC No	S1252665B
Date Of Birth	24/10/1957
Occupation	OUTDOOR
Date Of Driving Pass	17/01/1985
Driving Experience	33 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94525725
Fax Number	
Contact Number	OTHERS-94525725
EEmail Address	NOEMAIL

Address	BLK 216 LORONG 8 TOA PAYOH #02-605
Postcode	310216
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	- - -
Insurance Company of Driver's Own Vehicle	- - -

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	DRIZZLING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ
Police Station Address	<b>ROAD:</b> 10 UBI AVENUE 3 , <b>POSTCODE:</b> 408865 , <b>COUNTRY:</b> SINGAPORE
Police Station Contact	<b>TEL NO:</b> 65470000 - <b>FAX NO:</b>
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

PLS REFER TO THE POLICE REPORT : T/20181017/2053 / T/20181017/2056

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GX5676H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	HAQUE MOHAMMAD FAZLUL
NRIC/Passport Number	G2296866T
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name AHMAD BIN AMAT

Approximate Age

Injuries Sustain SLIGHT

Injured person in which vehicle? FY4117T

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

## Sketch Plan


### SKETCH PLAN


#### IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature  
Date & Time:

  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

 17/10/2018  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan #2



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Pls Refer to the Police Report -  
T/20181017/2053  
T/20181017/2056

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

And  
Policyholder's Signature  
Date & Time:

And  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

17/10/2018  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

## Sketch Plan #3



**SINGAPORE  
POLICE FORCE**



T/20181017/2053

Police Station Of Origin:  
Traffic Police Division HQ  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20181017/2053

## CONTINUATION OF REPORT

<b>Details of Person Involved</b>			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
<b>Rider</b>			
Name	AHMAD BIN AMAT	ID No.	S1252665B
Related Vehicle	FY4117T (Motorcycle)	Contact No.	94525725
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	HAQUE MOHAMMAD FAZLUL	ID No.	G2296866T
Related Vehicle	GX5676H (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

ON 16/10/2018 AT ABOUT 1426HRS AT SUNGEU KADUT STREET 1.

I WAS TRAVELLING STRAIGHT AND I NOTICED A LORRY THAT WAS STATIONARY AT THE LEFT SIDE. BEFORE I PASSED THE LORRY, THE LORRY SUDDENLY MADE A RIGHT TURN AND COLLIDED INTO ME. I THINK THAT HE WAS TRYING TO MAKE A U TURN. AS I WAS APPROACHING THE LORRY, I DID NOT NOTICE ANY SIGNAL LIGHTS ON THE LORRY. I THEN FELL AND ROLLED SOME DISTANCE AWAY. I THEN ASKED SOME PASSERBY TO HELP ME TAKE SOME PICTURE OF THE LORRY AND WAS CONVEYED TO KHOO TECK PUAT HOSPITAL AFTERWARDS.



T/20181017/2056

2 of 3

Report No. T/20181017/2056

### Continuation of CSF For NP168

**Brief Facts.**

THIS CSF IS TO INCLUDE THE FOLLOWING INFORMATION,

I HAVE A PHOTO THAT SHOWS THE DAMAGE ON THE LORRY. IT SHOWS THAT THE LORRY HAD DAMAGES TO THE FRONT RIGHT PORTION OF THE VEHICLE NEAR THE HEADLIGHT AREA.



# ...CLAIM SUBFOLDER...(Pending for Survey Report)

Midnight Accident

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Nov 2018 16:13 <a href="#">Edit Reg</a>		19 Oct 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS**

Insured:

- , Co. Reg. No.: -, Email: EMAIL@EMAIL.COM

Main Claimant:

-

Vehicle Reg. No.:

FY4117T

Date of Loss:

16/10/2018 00:00 - :59  
[169 Months and 2 Days From LTA Reg Date (Man Yr)]

Claim Type:

TP

Policy/Cover Note No.:

Vehicle Reg. No. (Insured):

GX5676H

Policy No. (Claimant):

Excess:

Repairer:

Wing Fuat Trading Co ( ) Blk 3020A Ubi Road 1, #01-37, 408714 Ubi - Tel:

Handling Insurer:

ECICS Limited (HQ) - Tel: 63374779 /6303 0178

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 31/10/2018]

**ASSOCIATED MAIL RECEIVED**

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS**






































[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)



















Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*FY4117T  
[GX5676H]  
TP  
-

Oct 16 2018 12:00AM  
[-]  
Wing Fuat Trading Co

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
2	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
3	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
4	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
5	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
6	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
7	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
8	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
9	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
10	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
11	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
12	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
13	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
14	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
15	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
16	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
17	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
18	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
19	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
20	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
21	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
22	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
23	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
24	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
25	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
26	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
27	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
28	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
29	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
30	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
31	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
32	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
33	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
34	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
35	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
36	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
37	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
39	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
40	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
41	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
42	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
43	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
44	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
45	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
46	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
47	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
48	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
49	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
50	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
51	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
52	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
53	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
54	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>
55	26/10/18 11:34	General View	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/ICS18019134/GCD3E2

Date: 08/11/2018

## REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle  
No : FY4117T

Insured Vehicle No :

GX5676H

Date of Loss: 16/10/2018

Nature of Claim:

TP

Claim No:

N/A

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: FY4117T

Make &amp; Model: PIAGGIO VESPA GT200A, 198cc

Engine No: M312M19367

Reg. Date: 14/09/2004 (Man. Year: 2004)

Chassis No: ZAPM3120000018935

Colour: Yellow

Odometer: 67729 km

Engine Capacity: 198 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 120/70-12

Rear Tyre Size:

130/70-12

Front Left Side: IRC 4 mm

Rear Left Side:

IRC 4 mm

Front Right Side: 0 mm

Rear Right Side:

0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 19/10/2018

Date Inspected: 22/10/2018

Inspected At:

Wing Fuat Trading Co

Blk 3020A Ubi Road 1, #01-37

Singapore 408714

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 -\$4,000.00

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 08 Nov 2018)	
<b>Parts:</b>	N/A	PIAGGIO VESPA GT200A 198cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FY4117T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >