

ASS. REC. BY:

REF:

CS3/AIG1801946/Gcd302

Special Instruction:

Surveyor:

GUO CCand

ASSIGNMENT (Office)

Maimen

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

22/10/2018 @ 12:17pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SJW 8186E

Insured:

SLM 8459Y

at Workshop m/s:

Lek Chuan Autocraft

Tel:

9626 2911 / 6482 2911

of

5 Kim Chuan Lane

Policy No.:

0999994759

Claim No.:

480894469786

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/10/18

CA / REV / REP. / REV 24 HRS^{up}

H.O.D. Endorsement:

Date/Time:

1:54pm @ 22/10/18

Person Contacted:

Judy

Vehicle IN OUT

Date/Time

Action/Instruction (X) Estimate

SJW 8186E-CC4/AXA1502334/M/ug 3s2

Dom: 24/10/18

SLM 8459Y-X

Dismantle: 23/10/2018

After repair: 24/10/2018

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 22/10/2018 12:17:38 PM
Attachments:  tmpE13.tif

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

From: bonnie kwok [mailto:litigation@bonniekwok.com]

Sent: Monday, October 22, 2018 11:39 AM

To: Azlan, Syazairdina

Cc: Fong, Andy-SY; Chin, Lee-Ying; Abu Kassim, Noor Mariesa; Md Ishak, Mohd Imran; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur; Chan, Yoke Shi

Subject: Re: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLM8459Y AND SJW8186E ON 21/10/2018

Dear Sirs,

Your list of surveyors is rejected.

Our proposed list of surveyors for Single Joint Expert are as follows: -

1. Patrick Ng Kong Beng;
2. Sim Siak Tong;
3. Choo Beng Hai;
4. Leslie Lim;
5. Tan Chin Suan;
6. Fong Kok Heng;
7. Matthew Yong Chin Ng;
8. Ong Hock Leng;
9. Andrew How; and
10. William Ng.

Kindly contact the repairers, M/s Lek Chuan Autocraft Pte Ltd at 9011 6452 / 9626 2911 for pre-repair inspection arrangements.

Regards,
Ms. Tan

--

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 9 am to 6 pm and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

BONNIE KWOK LLC
Advocates & Solicitors

101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358

Tel : (65) 6536 6026
Fax : (65) 6536 2279
[Not for service of court documents]
GST Reg No. 201203347Z

Your Vehicle: SLM 8459 Y
Our Vehicle: LekChuan-SJW 8186 E

Date : 22 October 2018

M/s **AIG Asia Pacific Insurance Pte. Ltd.**
78 Shenton Way
#07-16 AIG Building
Singapore 079120

By Fax 6835 7416 only

Dear Sirs,

ACCIDENT INVOLVING SJW 8186 E & SLM 8459 Y ON 21 OCTOBER 2018

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle SJW 8186 E at M/s Lek Chuan Autocraft Pte Ltd, 5 Kim Chuan Lane Singapore 537070.

Your faithfully


BONNIE KWOK
c.c. Client

00

00

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	3909C

Vehicle Details

Vehicle No.:	SJW8186E
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Oct 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 180 CGI
Primary Colour:	Black
Manufacturing Year:	2009
Engine No.:	27182030031437
Chassis No.:	WDD2040492A364364
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$37,054.00
Original Registration Date:	21 Apr 2010
First Registration Date:	21 Apr 2010
Transfer Count:	3
Actual ARF Paid:	\$37,054.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Apr 2020
PARF Rebate Amount:	\$20,379.00

Intended COE Rebate Details

COE Expiry Date:	20 Apr 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$21,899.00
COE Rebate Amount:	\$3,271.00
Total Rebate Amount:	\$23,650.00

The information contained herein is correct as at 23 Oct 2018

OK

▶ Mercedes-Benz C180 Used Vehicle List (13 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Mercedes-Benz C-Class C180K (New 10-yr COE)	\$68,000	\$6,790 /yr	29-Jan-2010	1,597 cc	140,444 km	AutoPrestige Gallery Pte Ltd	Availal

Free 3 Year Warranty! Lowest Depreciation In The Market! Flexible Loan With 100% Approval Rate Available! Head On Down Today For A No Obligated Viewing. Car Is Ready For Viewing Anytime From 10AM To ...

Office No. - 69098044

Chris - 88689696 | Andy - 82233641 | Ben - 88773030 | Alex - 98533834

Mercedes-Benz C-Class C180K	\$34,800	\$12,560 /yr	10-Feb-2010	1,597 cc	160,000 km		Availal
------------------------------------	-----------------	--------------	-------------	----------	------------	--	---------

Well Maintained. No Repair Needed. Clean And Neat Interior.

Office No. - -

Ms Li - 97548093

Mercedes-Benz C-Class C180K	\$37,500	\$13,240 /yr	31-Mar-2010	1,597 cc	-	A1 Motoring Pte Ltd	Availal
------------------------------------	-----------------	--------------	-------------	----------	---	---------------------	---------

Sporty Mercedes Benz C180 Black On Black. Well Maintained. 100% Accident Free. Owner Upgraded To New CLA180. Arrange For Test Drive Now. 3K To 5K Drive Away!

Office No. - -

Roy - 87999711 | Steve - 81820249 | Lee - 93678860

Mercedes-Benz CLC-Class CLC180K	\$30,800	\$9,200 /yr	01-Apr-2010	1,796 cc	167,000 km	Quality Motor Trading Enterprise	Availal
--	-----------------	-------------	-------------	----------	------------	----------------------------------	---------

Flexible Repayment In-House Financing! Come With Nice Number Plate 5755. C&C Unit. Extremely Fuel Friendly For A Luxury Car. Spacious, Quiet And Comfortable Cabin For 4 Passengers To Travel In Top Not...

Office No. - 64738668

Sharon - 97882224 | Dominic - 86685757

Mercedes-Benz C-Class C180 CGI	\$42,800	\$13,830 /yr	01-Jul-2010	1,796 cc	-	ST Carz Pte Ltd	Availal
---------------------------------------	-----------------	--------------	-------------	----------	---	-----------------	---------

Cheapest In The Market! CGI Facelifted Model! Very Well Maintained By Previous Owner! Excellent Condition! Warranty Provided! STA Evaluation Welcome! View To Believe! High Trade In For Your Used Car! ...

Office No. - 64654747

Chris - 83565566 | Ryan - 90778009 | Daven - 88225151

Mercedes-Benz C-Class C180 Avantgarde	\$45,800	\$13,890 /yr	15-Sep-2010	1,796 cc	-	38 Karz Station LLP	Availal
--	-----------------	--------------	-------------	----------	---	---------------------	---------

The Most Fuel Efficiency In Its Own Class With Powerful Drive Among The Same Group! Interior And Exterior Very Well Taken Care Of With Mileage Done, Healthy Engine And Gearbox With No Oil Leak, No...

Office No. - 69247738

Tony Lim - 91700981 | Gabriel Lin - 81814692 | Javier Chua - 91692347 | QH - 81570208

Mercedes-Benz C-Class C180 CGI	\$45,000	\$13,450 /yr	16-Sep-2010	1,796 cc	105,000 km		Availal
---------------------------------------	-----------------	--------------	-------------	----------	------------	--	---------

Rare 1.8L C&C Unit, High OMV \$20K Mi N. Takeback, Only 1owner Due To Carplate Transfer Bet. Cars. Why Buy A 2nd Car No Peace Of Mind Confident Enough To Offer 1 Month Warranty If You Find Anything ...

Office No. - -

Derrick - 93678688

Mercedes-Benz C-Class C180 CGI	\$43,800	\$12,800 /yr	17-Sep-2010	1,796 cc	94,000 km	Juzt Carz Auto	Availal
---------------------------------------	-----------------	--------------	-------------	----------	-----------	----------------	---------

C&C Unit! New Arrival! Owned By A Careful Lady Owner And Service Regularly Without Fail. Accident Free, Non Smoker Unit Yet Stylish, Spacious To Fit Your Family Size. Dream Of Owning It? Grab It Now B...

Office No. - 63383813

James Li - 88588866 | Joey Lim - 97898277 | Shawn Zheng - 97520620 | Philip Koh - 82338484

Mercedes-Benz C-Class C180 CGI	\$43,800	\$12,710 /yr	22-Sep-2010	1,796 cc	140,159 km		Availal
---------------------------------------	-----------------	--------------	-------------	----------	------------	--	---------

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	22/10/2018 09:09
Date Of Accident	21/10/2018 12:05
Exact Location Of Accident	BUYONG ROAD & ORCHARD ROAD
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SJW8186E
Insured/Policyholder	
Name Of Registered Owner	ONG HAI LEE
NRIC No	S7113909C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97359771
Alternative Phone No	OTHERS-97359771
Vehicle Particulars	
Manufacturer	MERCEDES-BENZ
Model	C 180 CGI
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5104714619
Cover Note Number	
Driver	
Name of Driver	CHENG TECK MENG HAROLD THADDAEUS
NRIC No	S7008977G
Date Of Birth	14/03/1970
Occupation	INDOOR
Date Of Driving Pass	13/07/1995
Driving Experience	23 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98217132
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address 1 JALAN MAHIR
 Postcode 537803
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured SPOUSE
 Vehicle Registration Number of Driver's Own Vehicle -
 Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : CHENG ZHI-EN AARON
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name TRAFFIC POLICE DIVISION HQ
 Police Station Address ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 65470000 - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

AS PER POLICE REPORT No.T/2018021/2041

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLM8459Y
 Vehicle Make/Model/Colour TOYOTA PRIUS
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, store, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers/agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing claims; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time: 22/12/18

Driver's Signature
(If driver is not the policyholder)
Date & Time: 22/12/18

IDAC KAKI BUKIT (KAKI)
Reporting Centre
Name: Singapore 418933
NRIC/Telephone: 7416697 Fax: 67492305
Email: vackb@sinonet.com.sg

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS PER POLICE REPORT.

I GROPE WITH THE IO (FORS - 65476706) WHO HAD
 VIEWED THE IN-CAR VIDEO - DRIVER OF SEMI TRUCK
 HAD HIT SJWIBEE FROM THE LEFT REAR.



DECLARATION

We declare the foregoing particulars are true in every respect.

[Signature]
 Policyholder's Signature
 Date & Time: 27/10/13

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 27/10/13

IDAC KAKI BUKIT (P) LTD
 23 Kaki Bukit Ave 3
 Singapore 415933
 Name: *[Name]*
 Tel: 67416697 Fax: 67492303
 Email: wackb@sinonet.com.sg



**SINGAPORE
POLICE FORCE**



T/20181021/2041

1 of 3

Report No. T/20181021/2041

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
21/10/2018 14:50

Video Report No.:
E/20181021/0095

Station Diary No.:

Informant's Particulars

Name of Informant:
CHENG TECK MENG HAROLD
THADDAEUS

Address:
1 JALAN MAHIR SINGAPORE 537803

ID Type / ID No.:
NRIC NO / S7008977G

Contact No.:
Home/Office: Mobile: 98217132

Nationality:
SINGAPORE CITIZEN

Email:

Sex: Age: Date of Birth:
Male 48 14/03/1970

Type of Informant:
Driver

Institution / School Name:

Race:
Chinese

Language:

Occupation:
MANAGER

Driving Licence Information:
Class: Date of Expiry:

General Information of the Accident

Type of Accident:

Injury
Conveyed By Ambulance

Drink
Drive:
No

Date/Time of
Accident:
21/10/2018 12:05

Type of Location:

Location:
Junction of Road 1 and Road 2
BUYONG ROAD
ORCHARD ROAD

Weather:

Road Surface:

Road Speed Limit:

Traffic Flow:

Traffic Control:

Traffic Volume:

Type of Collision:

Anyone conveyed by
ambulance:
Yes

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passengers
SJW8186E	Car	MERCEDES BENZ	C 180 CGI	Black		1
SLM8458Y	Car	TOYOTA	PRIUS HYBRID 1.8 CVT	Silver		0



SINGAPORE
POLICE FORCE



T2018102172941

2018

Report No. T2018102172941

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 35470000

CONTINUATION OF REPORT

Brief Details.

ON 21/10/2018 AT ABOUT 1204HRS AT THE JUNCTION OF BUYONG ROAD AND ORCHARD ROAD.

I WAS ON THE EXTREME LEFT LANE OF BUYONG ROAD AND STOPPED AS IT WAS RED LIGHT AT THE JUNCTION. I WAS THE SECOND VEHICLE AT THE JUNCTION. A FEW MOMENTS LATER, ANOTHER CAR COLLIDED INTO THE REAR LEFT PORTION OF MY VEHICLE. AFTER COLLIDING INTO MY VEHICLE, HE SWERVED TO THE LEFT AND COLLIDED INTO A SIGNPOST BEFORE COLLIDING INTO A LAMPPOST. AFTER THE ACCIDENT, I MOVED MY VEHICLE SLIGHTLY FORWARD AS MY PASSENGER COULD NOT OPEN HIS DOOR. AFTER GETTING OUT, I CHECKED WITH THE OTHER DRIVER IF HE WAS OKAY. HE MENTIONED THAT HIS BACK WAS IN PAIN AND THAT HE COULD NOT GET OUT OF THE CAR. HENCE, I CALLED 995 FOR ASSISTANCE. AFTER ABOUT 15MINS. HE FELT WELL ENOUGH TO GET OUT OF THE VEHICLE. HE WAS THEN CONVEYED BY AMBULANCE. TRAFFIC POLICE THEN ARRIVED AT SCENE SHORTLY AFTER. I WOULD LIKE TO ADD THAT THERE IS A TRAFFIC CAMERA ALONG ORCHARD ROAD, BESIDE CONCORD HOTEL.



SINGAPORE
POLICE FORCE



T/2018/1021/2011

3443

Report No: T/2018/1021/2011

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
TP /
LEE KWANG HONG KENDRICK

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TF / GIT /
SI THABAGESH JEYATHESH
Contact No.: 65476232

Authentication Stamp
IP 382

Signature Of Informant:

Date/Time:
21/10/2018 14:50

Classification Of Case:

 SINGAPORE
POLICE FORCE
Signature

(01) Bent (2) Dented (3) Distorted (4) Cracked (5) Cut (6) Scratched
 (07) Deformed (08) Shifted (09) Buckled (10) Broken (11) Necessary
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (0) (3) Check (0)
 (4) Not Consistent (N/C)

Vehicle No: **STW 8186E**

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	DIS	2	
1149	993045	Rear Bumper Reinforcement	BT	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	RA	✓	
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding	NEC	✓	
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DM	✓	
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish	RA	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	CRA	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel	BVC	R	
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	BT	R	
1171	991328	Bootlid Emblem	NEC	✓	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Handwritten signature
 30/10/2018

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender	BVC	✓	
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield	CRA	✓	
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim	CRT	✓	
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding	NEC	✓	
1247	993955	Rear Windscreen Sealant	NEC	✓	
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille LH	DIS	✓	
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1136	990247	Sticker			

No of Items: _____ Assessor: _____

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Oct 2018 Edit Reg		22 Oct 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Main Claimant:	-								
Vehicle Reg. No.:	SJW8186E	Date of Loss:	21/10/2018 12:00 - :59 [102 Months From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 4808944697SG	Policy/Cover Note No.:	0999994759 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLM8459Y	Policy No. (Claimant):							
Repairer:	- Not Applicable - (-)								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Gan, Angie-GL] Angiegeokling.Gan@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 31/10/2018]								
Claimant's Solicitor:	BONNIE KWOK LLC - Tel: 65366026								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
<ul style="list-style-type: none"> AIG_SG (23/10/2018): Request to upload TP GIA Report AIG_SG (23/10/2018): No OI GIA Report 									
ALL ASSOCIATED TASKS <input type="checkbox"/>		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJW8186E (4808944697SG)
[SLM8459Y]
TP**

**Oct 21 2018 12:00PM
[LCRF PTE LTD]**

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <input type="button" value="View in Browser"/>		
Photos/Images												3 per page		<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print				
1	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
2	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
3	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
4	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
5	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
6	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
7	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
8	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
9	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
10	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
11	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
12	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
13	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
14	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
15	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
16	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
17	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
18	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
19	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
20	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
21	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
22	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
23	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
24	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
25	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
26	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
27	23/10/18 17:33	General View											Load JPG	<input checked="" type="checkbox"/>			
28	24/10/18 12:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>			
29	24/10/18 12:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>			
30	24/10/18 12:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>			
31	24/10/18 12:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>			
32	24/10/18 12:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>			
33	24/10/18 12:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>			
34	24/10/18 12:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>			
35	24/10/18 12:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>			
36	24/10/18 12:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>			
37	24/10/18 12:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>			
38	24/10/18 12:58	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>			

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
39	24/10/18 12:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	24/10/18 12:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	24/10/18 12:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	24/10/18 12:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
43	24/10/18 12:58	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	31/10/18 08:37	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
45	31/10/18 08:37	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
46	31/10/18 08:37	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
47	31/10/18 08:37	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
48	31/10/18 08:37	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
49	31/10/18 08:37	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
50	31/10/18 08:37	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
51	31/10/18 08:37	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
52	31/10/18 08:37	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
53	31/10/18 08:37	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
54	31/10/18 08:37	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
55	31/10/18 08:37	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
56	31/10/18 08:37	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
57	31/10/18 08:37	Photo After Spray	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	31/10/18 13:07	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<p>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</p> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<p>Show Remarks To: <input type="checkbox"/> Handling Insurer</p> <p><small>Note: Remarks are private unless you show it to other parties.</small></p>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18019146/GCD3E2

Date: 14/11/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999994759
Claimant Vehicle No : SJW8186E	Insured Vehicle No :	SLM8459Y
Date of Loss: 21/10/2018	Nature of Claim:	TP
		Claim No: 4808944697SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJW8186E	Engine No:	27182030031437
Make & Model:	MERCEDES-BENZ C180, 1.6 CGI (A)	Chassis No:	WDD2040492A364364
Reg. Date:	21/04/2010 (Man. Year: 2009)	Odometer:	114573 km
Colour:	Black		
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	22/10/2018	
Date Inspected:	22/10/2018 Inspected At:	5 KIM CHUAN LANE Repairer : LEK CHUAN AUTOCRAFT PTE LTD
Estimated Period of Repair:	7.0 days	

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
4	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
5	1		*REAR BUMPER SPONGE	Cracked	0.00 F	*- F
6	1		*REAR BUMPER MOULDING	Necessary	0.00 F	*- F
7	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
8	1		*REAR END PANEL	Dented	0.00 F	*- F
9	1		*REAR END PANEL TOP GARNISH	Cracked	0.00 F	*- F
10	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
11	1		*REAR LH TAILLAMP PANEL	Repair	0.00 F	*- F
12	1		*BOOTLID	Repair	0.00 F	*- F
13	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
14	1		*REAR LH FENDER	Buckled	0.00 F	*- F
15	1		*REAR LH FENDER INNER SHIELD	Cracked	0.00 F	*- F
16	1		*REAR LH WHEEL RIM	Cut	0.00 F	*- F
17	1		*REAR WINDSCREEN MOULDING	Necessary	0.00 F	*- F
18	1		*REAR WINDSCREEN SEALANT	Necessary	0.00 F	*- F
19	1		*REAR FENDER AIR GRILLE LH	Distorted	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >