



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18019177/Upa3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 30-09-2019



ATTN: SAW THENG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHD 237T	Veh. Inspected	SJR 608J
Policy No.	VPX/P1680520	Coverage (\$)	0.00
Claim No.	S8M00ZQS	Excess (\$)	0.00
Assign From	SAW THENG	Assign Date	19/10/2018

2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11113772	Colour	WHITE
Odometer	039183	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	6 mm
L/H Front Tyre	215/60 R16	DUNLOP	6 mm
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/10/2018	Inspection Date	22/10/2018
Survey held at	BLK 6 WOODLANDS RD 399F		
Repairer	YEW TEE AUTOMOBILE TECH PL		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------