

ASS. REC. BY:

REF: CS/MSA18019222 | Gcd3⁵²

Special Instruction:

Surveyor: Guo Cheng ASSIGNMENT (Office)

From (Person): Christina Wong of MSIG Date/Time: 23/10/18 @ 11:19am

Estimated Cost: _____ Bill to: _____

OD TP WS TP RES OD RES EVA INV MV CS

To Inspect Vehicle No: GBF 4096S Insured: GY 3877C

at Workshop m/s: Motor Intel Tel: 6261 0087

of 13/keki Bkt Rd 4 # 01-20

Policy No: MSD/vcft/18-000498 Claim No: _____

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 19/10/2018
(Client's Record)

CA / REV / REP. / REV 24 HRS up H.O.D. Endorsement: _____

Date/Time: 12:10pm @ 23/10/18 Person Contacted: Richard Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	<u>GBF 4096S - X</u>
	<u>GY 3877C - CC41A1G17003333 / T1eb3q2</u> <u>Dors 1/12/17</u>
	<u>Dismantle: 25/10/2018.</u>

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Oct 2018 15:20		23 Oct 2018 11:19 <input type="button" value="Assign"/>				New Assignment <input type="button" value="Cancel Case"/>

Main	Reference	Claim Details	Documents	<input type="button" value="Show All"/>					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	PROPELL INTEGRATED PTE LTD , Co. Reg. No.: 0								
Main Claimant:	ROYAL AUTOWORKZ PTE LTD , Co. Reg. No.: 201716451W								
Vehicle Reg. No.:	GBF4096S	Date of Loss:	19/10/2018 00:00 - :59 [23 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:	MSD/VCFT/18-000498 Coverage: 21/03/2018 - 20/03/2019						
Vehicle Reg. No. (Insured):	GY3877C	Policy No. (Claimant):							
		Excess:							
Repairer:	Motor Intel Automo Pte Ltd - Kaki Bukit (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 24/10/2018]								
Adj Asg. Remarks:	Liability unclear. Non Reporting. Contact Person: Mr Richard / 6281 0087. TP disagree with SJE llist. Proceed to appoint LKK Auto Consultants as the SJE.								
ASSOCIATED MAIL RECEIVED <input type="button" value="View All"/> <input type="button" value="Compose Case Mail"/>									
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="button" value="View All"/> <input type="button" value="Search Tasks"/> <input type="button" value="Create New Task"/> <input type="button" value="Complete"/>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/10/2018 17:04
Date Of Accident	19/10/2018 14:45
Exact Location Of Accident	WOODLANDS AVE 12 BEFORE AVE 5 JUNCT(FROM SLE)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF4096S
Insured/Policyholder	
Name Of Registered Owner	ROYAL AUTOWORKZ PTE LTD
Co Reg No	201716451W
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-86861286
Alternative Phone No	OFFICE-86861286

Vehicle Particulars

Manufacturer	TOYOTA
Model	HIACE 3.0 SUPER GL DARK PRIME AT
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5097168810
Cover Note Number	

Driver

Name of Driver	ERNEST SONG JIALONG
NRIC No	S9717930A
Date Of Birth	28/05/1997
Occupation	OUTDOOR
Date Of Driving Pass	23/04/2018
Driving Experience	0 YEAR AND 5 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-86867930
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 126 YISHUN STREET 11 #09-419
 Postcode 760126
 Was driver an employee of the Insured's Company YES
 If No, Relationship of the Driver with the Insured
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GY3877C
 Vehicle Make/Model/Colour NISSAN CABSTAR
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver SUBRAMANIAN VENKATESHVARAN
 NRIC/Passport Number G5047989M
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name ERNEST SONG JIALONG
 Approximate Age

Injuries Sustain

Injured person in which vehicle?

GBF4096S

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

Address

BLK 126 YISHUN STREET 11 #09-419

Postcode

760126

Accident Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all Insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be cited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


19 OCT 2018
lit

Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAL)
23 KAKI BUKIT AVE 4
Singapore 415933
Tel: 67416697
Fax: 67492305
Email: vackb@singnet.com.sg

Accident Sketch Plan Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Woodland Ave 12 from SLE on the right most lane of a 3-lane road. Somewhere before Junction of Woodland Ave 12 and Ave 5, I stopped at the traffic light due to traffic light turning red. Moments after I stopped, I suddenly felt a strong impact from the rear portion of my vehicle. After the accident, I managed to see that vehicle B front portion collided into the rear portion of my vehicle. Hence I was involved in an accident of 2 vehicles. My body hit against the dashboard and I experienced body pain from the accident and will be seeking medical attention. Veh A: GBF 4965. Veh B: GY 3877C.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature] 19 OCT 2018

[Signature]
 Policyholder's Signature
 Date & Time

[Signature]
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time

IDAC KAKI BUKIT (VAC)
 23 KAKI BUKIT AVE 4
 Singapore 415933

Reporting Centre Tel: 67416697
 Name: Fax: 67492305
 NRIC/Fin Email: vackb@singnet.com.sg

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6451W
Vehicle Details	
Vehicle No.:	GBF4096S
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE 3.0 SUPER GL DARK PRIME AT
Primary Colour:	Black
Manufacturing Year:	2016
Engine No.:	1KD2643889
Chassis No.:	KDH2010204032
Maximum Power Output:	-
Open Market Value:	\$45,864.00
Original Registration Date:	20 Oct 2016
First Registration Date:	20 Oct 2016
Transfer Count:	2
Actual ARF Paid:	\$2,294.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	19 Oct 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
COE Paid:	\$5,006.00
COE Rebate Amount:	\$4,078.00
Total Rebate Amount:	\$4,078.00

The information contained herein is correct as at 24 Oct 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Oct 2018		23 Oct 2018 11:19 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]							
Insured:	PROPELL INTEGRATED PTE LTD, Co. Reg. No.: 0								
Main Claimant:	ROYAL AUTOWORKZ PTE LTD, Co. Reg. No.: 201716451W								
Vehicle Reg. No.:	GBF4096S	Date of Loss:	19/10/2018 00:00 - :59 [23 Months and 29 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MSC/V/18-001411	Policy/Cover Note No.:	MSD/VCFT/18-000498 Coverage: 21/03/2018 - 20/03/2019						
Vehicle Reg. No. (Insured):	GY3877C	Policy No. (Claimant):							
		Excess:							
Repairer:	Motor Intel Automo Pte Ltd - Kaki Bukit (HQ) 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 417807 Kaki Bukit - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 24/10/2018]								
Adj Asg. Remarks:	Liability unclear. Non Reporting. Contact Person: Mr Richard / 6281 0087. TP disagree with SJE list. Proceed to appoint LKK Auto Consultants as the SJE.								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBF4096S (MSC/V/18-001411)
[GY3877C]

TP

ROYAL AUTOWORKZ PTE LTD

Oct 19 2018 12:00AM

[PROPELL INTEGRATED PTE LTD]

Motor Intel Automo Pte Ltd - Kaki Bukit

Upload Documents Upload Photos Compose New Letter			View	View in Browser ▾
Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	27/10/18 14:21	General View		Load JPG <input checked="" type="checkbox"/>
2	27/10/18 14:21	General View		Load JPG <input checked="" type="checkbox"/>
3	27/10/18 14:21	General View		Load JPG <input checked="" type="checkbox"/>
4	27/10/18 14:21	General View		Load JPG <input checked="" type="checkbox"/>
5	27/10/18 14:21	General View		Load JPG <input checked="" type="checkbox"/>
6	27/10/18 14:21	General View		Load JPG <input checked="" type="checkbox"/>
7	27/10/18 14:21	General View		Load JPG <input checked="" type="checkbox"/>
8	27/10/18 14:21	General View		Load JPG <input checked="" type="checkbox"/>
9	27/10/18 14:21	General View		Load JPG <input checked="" type="checkbox"/>
10	27/10/18 14:21	General View		Load JPG <input checked="" type="checkbox"/>
11	27/10/18 14:21	General View		Load JPG <input checked="" type="checkbox"/>
12	27/10/18 14:21	General View		Load JPG <input checked="" type="checkbox"/>
13	27/10/18 14:21	General View		Load JPG <input checked="" type="checkbox"/>
14	27/10/18 14:21	General View		Load JPG <input checked="" type="checkbox"/>
15	27/10/18 14:24	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
16	27/10/18 14:24	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
17	27/10/18 14:24	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
18	27/10/18 14:24	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
19	27/10/18 14:24	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
20	27/10/18 14:24	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
21	27/10/18 14:24	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
22	27/10/18 14:24	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
23	27/10/18 14:24	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
24	27/10/18 14:24	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
25	27/10/18 14:24	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
26	27/10/18 14:24	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
27	27/10/18 14:24	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
28	27/10/18 14:24	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
29	27/10/18 14:24	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
30	27/10/18 14:24	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
31	27/10/18 14:24	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
32	27/10/18 14:24	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
33	27/10/18 14:24	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
34	27/10/18 14:24	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
35	27/10/18 14:24	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
36	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
37	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
38	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
39	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
40	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
41	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
42	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
43	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
44	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
45	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
46	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
47	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
48	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>
49	27/10/18 14:24	Photographs of Damaged Parts	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	22/10/18 15:22	Notice of PRI	Load PDF	
2	22/10/18 15:23	Email - PRI	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18019222/GCD3S2

Date: 29/10/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VCFT/18-000498

Claimant Vehicle No: GBF4096S Insured Vehicle No: GY3877C

Date of Loss: 19/10/2018 Nature of Claim: TP Claim No: MSC/V/18-001411

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF4096S**
 Make & Model: TOYOTA HIACE, 3.0 (A) Engine No: 1KD2643889
 Reg. Date: 20/10/2016 (Man. Year: 2016) Chassis No: KDH2010204032
 Colour: Yellow Odometer: 85559 km
 Engine Capacity: 2982 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

<u>COST OF CLAIMS</u>	<u>Repairer's</u>	<u>Adjuster's</u>	<u>Difference</u>	<u>Diff %</u>
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 23/10/2018

Date Inspected: 23/10/2018 Inspected At:

Motor Intel Automo Pte Ltd - Kaki Bukit (HQ)
13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre
Singapore 417807

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000.00 - \$4,000.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Oct 2018)	
Parts:	N/A	TOYOTA HIACE 3.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBF4096S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >