

ASS. REC. BY:

REF: CS/SMO18019236/Alvd3⁹²

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

Merimen

From (Person): chan shu hui agnes of SMO

Date/Time: 23/10/18 29:23am

Estimated Cost:

Bill to:

OD ☒ TR / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJT 5719D

Insured:

GIBB 7905J

at Workshop m/s

Mora Automotive

Tel:

62723892

of

Blk 1008, 8ct Meruh lane 3 #01-04

Policy No:

DI8M1PCVGE000700

Claim No:

CMTD1804602

Sum Insured:

Excess:

Make of Veh:

D.O.A. 20/10/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

up

H.O.D. Endorsement:

Date/Time:

10:05am 23/10/18

Person Contacted:

Nabilah

Vehicle IN ☒ OUT

Date/Time	Action/Instruction (✓) Estimate
	SJT 5719D - CG/AIG 14013897 / K2a 3c3
	GIBB 7905J - X
	VNI
29/10/18	Send preli. revised via merimen

DOA: 18/7/2014

Signature: *P. Pau*

REF:

6086A


08 NOV 2019 / 04

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: **SET 5 7190**
at Workshop m/s **NOVA**
of **BUKIT MERAH**
Insured: **SMO**
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: _____ days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **SJT 57190** Yr Regn: **2009 / 04**
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: **HYUNDAI AVANTE 1.6 AT c.c. (571)**
Colour: **WHITE** A/C: Insured / Std / NI / NA
Sp. Reading: **69730** T/Radio: Insured / Std / NI / NA

Eng/No: _____
C/No: **KMHOU41BMAU892904**

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **195/60R15**
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front		Rear	
R/Bal. 5	mm	R/Bal. 5	mm
L/Bal. 5	mm	L/Bal. 5	mm
D.O.A. 20/10/18		D.O.I. 25/10/18	

Survey held at **NOVA**

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

8/11/18 @ 1140am Bo Bo said TP do cash job, withdraw TP claim
8/11/18 Submit preli report

RECEIVED 08 NOV 2018

Date/Time, File Pass to?



1)

Date/Time, File Return to?

2) **8/11 - typist**

Report Format: **merimen**

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: **3**

Resurvey No. of Trip: **-**

Add Fee: ☐ Site Insp (\$ _____)
☐ Interview (\$ _____)
☐ Tech. Invs (\$ _____)
☐ Weekend (\$ _____)

Survey Fee: **250**

Transportation: _____

_____ S + RS _____ SI

Photos _____

Others _____

TOTAL

10

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Inc Auth'd	Status
Main	22 Oct 2018 Sendback Est	22 Oct 2018 16:36 \$S\$1,490.40	23 Oct 2018 09:23 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	KH AIR.CON SYSTEM , Co. Reg. No.: 0		
Main Claimant:	CHONG WEI LUM , ID: S7676086A		
Vehicle Reg. No.:	SJT5719D	Date of Loss:	20/10/2018 11:00 - :59 [108 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1804602	Policy/Cover Note No.:	D18MTPCVE000700
Vehicle Reg. No. (Insured):	GBB7905J	Policy No. (Claimant):	2100204723-08
		Excess:	
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3, 159722 Bukit Merah - Tel: 62723892/64763333		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/11/2018]		
Adj Asg. Remarks:	PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#) [Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Sompso Insurance Singapore Pte. Ltd. 50 Raffles Place #05-01/06, Singapore Land Tower Singapore 048623	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: CHAN SHU HUI AGNES	Date: 29 Oct 2018

Preliminary Advice

Insured Vehicle No	: GBB7905J		
TP Vehicle No	: SJT5719D	Accident Date	: 20/10/2018
Make	: HYUNDAI AVANTE	Assignment Date	: 23/10/2018
Date of Inspection	: 25/10/2018	Est. Duration of Repair	: 3.00
Inspection At	: MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH) BLK 1008, #01-04/06/08/94, BUKIT MERAH LANE 3 SINGAPORE 159722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,490.40
Revised Amount	:S\$	1,130.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,130.80

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : The vehicle survey on "Without Prejudice" basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	22/10/2018 09:32
Date Of Accident	20/10/2018 11:30
Exact Location Of Accident	31A GHIM MOH EDGE MULTI-STOREY CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT5719D
Insured/Policyholder	
Name Of Registered Owner	CHONG WEI LUM
NRIC No	S7676086A
Email Address	KENNYSS76@GMAIL.COM
Mobile Phone No	(LOCAL) +65-98785210
Alternative Phone No	OTHERS-98785210

Vehicle Particulars

Manufacturer	HYUNDAI
Model	AVANTE 1.6 AT ABS D/AB 2WD 4DR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100204723-08
Cover Note Number	

Driver

Name of Driver	CHONG WEI LUM
NRIC No	S7676086A
Date Of Birth	20/08/1976
Occupation	INDOOR
Date Of Driving Pass	16/01/2010
Driving Experience	8 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98785210
Fax Number	
Contact Number	OTHERS-98785210
EEmail Address	KENNYSS76@GMAIL.COM

Address	BLK 32 GHIM MOH LINK #20-296
Postcode	271032
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO STATEMENT ON THE SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB7905J
Vehicle Make/Model/Colour	
Details Of Properties	KH AIR CON SYSTEM - 63392913 (MS VIVIAN)
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	AH HONG
NRIC/Passport Number	
Contact Number	90844697
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this {form} and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

22 Oct 2018
9:40 am

Driver's Signature:

(If driver is not the policyholder)

Date & Time:



Reporting Centre Person's Signature

Name:

NRIC/FIN No.:

Nabiah
22/10/2018

Sketch Plan Pg. 2

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT



LICENSE PLATE: <u>SJT5719D</u>	ACCIDENT DATE & TIME: <u>20 Oct 2018 11:30am</u>
CONTACT NUMBER: <u>98785210</u>	E-MAIL ADDRESS: <u>kennyss76@gmail.com</u>
LOCATION: <u>31A Ghim Moh Edge Multi-storey Car Park</u>	
<p>On 20 Oct 2018 at 11:30am, when I go to Car Park to look for my car. I noticed my car left bumper was full of scratches. Also, I noticed there is a postage indicate the Van belongs to KTH Aircon was knocked on my car bumper and the vehicle number is GBB7905J. I then contacted KTH Aircon and the Ms Vivian has confirmed the vehicle is belong to her company and she will check with his worker. The worker named Ah Hong called back at 12:27pm to confirm that he accidentally knocked my car and waited for 30mins before go off for other service appointment. He then sent me all the photos related to this accident. I had contacted Ms Vivian and she has acknowledged her staff knocked my car.</p>	
NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION	
Please state:	
<input type="checkbox"/> Claim Own Policy	<input checked="" type="checkbox"/> Claim Third Party
<input type="checkbox"/> Claim OD/TP at other workshop	
<input type="checkbox"/> Reporting Only	

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time: 22 Oct 2018
9:40am

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:



 Reporting Person's Signature
 Name: Nahlah
 NRIC/FIN No.: 22/10/2018

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	6086A
Vehicle Details	
Vehicle No.:	SJT5719D
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Oct 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	AVANTE 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	G4FC9U746245
Chassis No.:	KMH DU41BMAU892904
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,440.00
Original Registration Date:	20 Oct 2009
First Registration Date:	20 Oct 2009
Transfer Count:	1
Actual ARF Paid:	\$10,029.00
OPC Cash Rebate Details	
OPC Cash Rebate Eligibility:	No
OPC Cash Rebate Eligibility Expiry Date:	-
OPC Cash Rebate Amount:	-
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Oct 2019
PARF Rebate Amount:	\$5,014.00
Intended COE Rebate Details	
COE Expiry Date:	19 Oct 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$0.00
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$5,014.00

The information contained herein is correct as at 29 Oct 2018

OK



Main Office : No. 22, Jalan Klang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 1008, Bukit Merah Lane 3,
#01-04/06/08/115, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise in Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre
Hilton Auto Trading
Dealing in New/Used Cars, Hire Purchase & Insurance.



TP INSURER: **Sompo Insurance Singapore Pte. Ltd. (HQ)**
UNKNOWN
NIL
Singapore 0

Claimant Insurer: **AIG Asia Pacific Insurance Pte. Ltd.**

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	20/10/2018
Vehicle Reg. No.:	SJT5719D	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	CHONG WEI LUM		
Make/Model:	HYUNDAI AVANTE, 1.6 ABS AIRBAG 2WD 4DR (A)	Vehicle Reg. Date:	20/10/2009
Vehicle Colour:	WHITE		
Engine No:	G4FC9U746245	Chassis No:	KMH DU41BMAU892904
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	3		
Description of Accident/Loss	PLEASE REFER TO STATEMENT ON THE SKETCH PLAN.		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	490.40
Miscellaneous Items	0.00
Labour	1,000.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	1,490.40
+ GST 7.00% (\$)	104.33
Nett Amount (\$)	1,594.73

This claim is handled by: BOBO

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Oct 2018)**Parts:** 143 HYUNDAI AVANTE 1.6 ABS AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** (Unsubmitted, no print-code for SJT5719D)**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER - SUR ✓	20.00	0.00	*478.50 FL
2	1		*FRONT BUMPER RETAINER X nn	20.00	0.00	*29.00 FL
3	10		*FRONT BUMPER CLIPS nn ✓	20.00	0.00	*35.00 FL
4	1		*HEADLAMP BRACKET 2 X nn	20.00	0.00	*45.50 FL
5	1		*FRONT FENDER EMBLEM VVTI nn ✓	20.00	0.00	*25.00 FL
6	1		*HEADLAMP RH - CHECK nn	20.00	0.00	-
F=Franchise part. L=ListItemDisc. LH						
Sub Total (S\$)						613.00
- List Item Discount on L Items (S\$)						122.60
Total Parts (S\$)						490.40

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REPAIR FRONT FENDER LH. TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN AND REALIGN AFFECTED AREAS	New	300 400.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	400 600.00
Gross Labour Cost (\$\$)			1,000.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Rame
Hy 90010068
3 days
45
25/10/18 @ 1710
Resurvey after photo
29/10/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Oct 2018 Sendback Est	22 Oct 2018 16:36 S\$1,490.40	23 Oct 2018 09:23 Edit Adj Rpt	S\$1,130.80 Edit Estimates	S\$1,130.80 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	KH AIR.CON SYSTEM, Co. Reg. No.: 0		
Main Claimant:	CHONG WEI LUM, ID: S7676086A		
Vehicle Reg. No.:	SJT5719D	Date of Loss:	20/10/2018 11:00 - :59 [108 Months From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1804602	Policy/Cover Note No.:	D18MTPCVE000700
Vehicle Reg. No. (Insured):	GBB7905J	Policy No. (Claimant):	2100204723-08
		Excess:	
Repairer:	Mova Automotive Pte Ltd (Bukit Merah) Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3, 159722 Bukit Merah - Tel: 62723892/64763333		
Handling Insurer:	Sampo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 01/11/2018]		
Adj Asg. Remarks:	PLEASE BE INFORMED THAT OUR INSURED HAS NOT REPORTED THE ACCIDENT		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.


















Claim Documents

SJT5719D (CMTD1804602)
[GBB7905J]
TP
CHONG WEI LUM
Oct 20 2018 11:00AM
[KH AIR.CON SYSTEM]
Mova Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser ▼	
Assessment Reports			1 per page ▼	✓
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	22/10/18 11:47	Accident Statement	1 Load HTM	
2	22/10/18 16:36	Repairer Estimates	1 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/10/18 14:32	Adjuster Immediate Advice	1 Load HTM	
Photos/Images			3 per page ▼	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/11/18 11:46	General View	1 Load JPG	✓
2	08/11/18 11:46	General View	1 Load JPG	✓
3	08/11/18 11:46	General View	1 Load JPG	✓
4	08/11/18 11:46	General View	1 Load JPG	✓
5	08/11/18 11:46	General View	1 Load JPG	✓
6	08/11/18 11:46	General View	1 Load JPG	✓
7	08/11/18 11:46	General View	1 Load JPG	✓
8	08/11/18 11:46	General View	1 Load JPG	✓
9	08/11/18 11:46	General View	1 Load JPG	✓
10	08/11/18 11:46	General View	1 Load JPG	✓
11	08/11/18 11:46	General View	1 Load JPG	✓
12	08/11/18 11:46	General View	1 Load JPG	✓
13	08/11/18 11:46	General View	1 Load JPG	✓
14	08/11/18 11:46	General View	1 Load JPG	✓
15	08/11/18 11:46	General View	1 Load JPG	✓
16	08/11/18 11:46	General View	1 Load JPG	✓
17	08/11/18 11:46	General View	1 Load JPG	✓
18	08/11/18 11:46	General View	1 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	22/10/18 16:33	E-filed GIA report	1 Load PDF	

Linked Accident Report Documents

			View View in Browser ▼	
Assessment Reports			1 per page ▼	✓
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	22/10/18 11:47	Accident Statement	1 Load HTM	

Assessment Reports			1 per page ▼	✓
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
Photos/Images			3 per page ▼	✓
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	22/10/18 11:45	Accident Photo	 Load JPG	✓
2	22/10/18 11:45	Accident Photo	 Load JPG	✓
3	22/10/18 11:45	Accident Photo	 Load JPG	✓
4	22/10/18 11:45	Accident Photo	 Load JPG	✓
5	22/10/18 11:45	Accident Photo	 Load JPG	✓
6	22/10/18 11:45	Accident Photo	 Load JPG	✓
7	22/10/18 11:45	Accident Photo	 Load JPG	✓
8	22/10/18 11:45	Accident Photo	 Load JPG	✓
9	22/10/18 11:45	Accident Photo	 Load JPG	✓
10	22/10/18 11:45	Accident Photo	 Load JPG	✓
11	22/10/18 11:45	Accident Photo	 Load JPG	✓
12	22/10/18 11:46	ACCIDENT SCENE PHOTO	 Load JPG	✓
13	22/10/18 11:46	ACCIDENT SCENE PHOTO	 Load JPG	✓
14	22/10/18 11:46	ACCIDENT SCENE PHOTO	 Load JPG	✓
15	22/10/18 11:46	ACCIDENT SCENE PHOTO	 Load JPG	✓
16	22/10/18 11:46	ACCIDENT SCENE PHOTO	 Load JPG	✓
17	22/10/18 11:46	ACCIDENT SCENE PHOTO	 Load JPG	✓
18	22/10/18 11:46	ACCIDENT SCENE PHOTO	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Mova Automotive Pte Ltd (Bukit Merah)	Thumbnail	Print
1	22/10/18 11:44	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/SMO18019236/R1VD3S2
Date: 09/11/2018

REFERENCE

Handling Insurer: Somp Insurance Singapore Pte. Ltd. Policy No: D18MTPCVE000700
Claimant Vehicle No : SJT5719D **Insured Vehicle No :** GBB7905J
Date of Loss: 20/10/2018 **Nature of Claim:** TP **Claim No:** CMTD1804602

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJT5719D
Make & Model: HYUNDAI AVANTE, 1.6 ABS AIRBAG 2WD 4DR (A) **Engine No:** G4FC9U746245
Reg. Date: 20/10/2009 (Man. Year: 2009) **Chassis No:** KMHDU41BMAU892904
Colour: White **Odometer:** 69730 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair **Steering (Serviceable):** Yes **Footbrake (Serviceable):** Yes
Handbrake (Serviceable): Yes **Engine Modification:** No **Pre-accident Condition:** Yes

CONDITION OF TYRES

Front Tyre Size: 195/60R15 **Rear Tyre Size:** 195/60R15
Front Left Side: Yokohama 5 mm **Rear Left Side:** Yokohama 5 mm
Front Right Side: Yokohama 5 mm **Rear Right Side:** Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	490.40	430.80	59.60	12.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	700.00	300.00	30.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	1,490.40	1,130.80	359.60	24.13
+ GST 7.00/7.00% (\$\$)	104.33	79.16	25.17	24.13
Nett Amount (\$\$)	1,594.73	1,209.96	384.77	24.13

INSPECTION

Date of Assignment: 23/10/2018
Date Inspected: 25/10/2018 **Inspected At:** Mova Automotive Pte Ltd (Bukit Merah)
 Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3
 Singapore 159722
Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 Nov 2018)

Parts: 143 HYUNDAI AVANTE 1.6 ABS AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SJT5719D)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Scratched	478.50 FL	*478.50 FL
2	1		*FRONT BUMPER RETAINER	Not Necessary	29.00 FL	*- FL
3	10		*FRONT BUMPER CLIPS	Necessary	35.00 FL	*35.00 FL
4	1		*HEADLAMP BRACKET	Not Necessary	45.50 FL	*- FL
5	1		*FRONT FENDER EMBLEM VVTI	Necessary	25.00 FL	*25.00 FL
6	1		*HEADLAMP RH - CHECK	Not Necessary	-	-

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	613.00	538.50
- List Item Discount on L Items 20.00/20.00% (\$\$)	122.60	107.70
Total Parts (\$\$)	490.40	430.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR FRONT FENDER LH. TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN AND REALIGN AFFECTED AREAS	New	400.00	300.00
2	TO SPRAY PAINT ON AFFECTED AREAS	New	600.00	400.00
Gross Labour Cost (\$\$)			1,000.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >