

ASS. REC. BY:

REF: (CS / FWD) 18019250 / Bcb<sup>52</sup>

Special Instruction:

Surveyor  
Maimin

Mr. Lim

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

FWD

Date/Time:

19-10-2018 7:30pm

Estimated Cost:

Bill to:

OD / TI / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 7727Y

Insured:

SLE 2743H

at Workshop m/s

My Car Consultant

Tel:

8866 8832.

of

55 Ubi Ave 1 # 01-33

Policy No:

Claim No:

1201800013412 / CL

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 17-10-2018

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

23-10-2018 136pm

Person Contacted:

Elena

Vehicle (IN) OUT

| Date/Time | Action/Instruction ( X ) Estimate |
|-----------|-----------------------------------|
|           | SKW 7727Y - X                     |
|           | SLE 2743H - X                     |
|           | Dismantle: 26/10/2018             |
|           |                                   |
|           |                                   |
|           |                                   |
|           |                                   |

PRS

REF: FWD

ASSIGNMENT

From: Date: 23.10.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW 2727Y

at Workshop m/s of My Car Consultants 53 Ubi Ave 1 #01-33

Insured:

Policy No.:

Claims No.:


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Veh No: SKW 2727Y Yr Regn: 04/05/2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Honda HRV 1.5DX CVT c.c 1496

Colour: Red A/C: Insured / Std / NI / NA

Sp. Reading: 78805 T/Radio: Insured / Std / NI / NA

Eng/No: L15B4534093

C/No: JHMRU1810GX204092

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: 215/60R16

BS: SUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 17.10.18 D.O.I. 23/10/18 1630

Survey held at My Car Consultants

Des. of Damages: P / Rear O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction           |
|-------------|--------------------------------|
|             | MV 92k Range \$7,000 - \$8,500 |
|             | PV 50,526k                     |
|             | Net 41k                        |
|             | 25/10/2018                     |
|             | TGrim                          |
|             | 25/10/18                       |

Date/Time, File Pass to?  : Preli. Report

1)  : Final Report

Date/Time, File Return to?

2)

Report Format: PRS

Lump Sum / I.B.I: (\$ )

Days Of Repair: 8

Resurvey No. of Trip: 1

Survey Fee:

Transportation: \$ + RS \$

Photos

Others

Add Fee:  Site Insp (\$ )

Interview (\$ )

Tech. Invs (\$ )

Weekend (\$ )

TOTAL

## Catherine Chong (LKK Auto)

---

**From:** motorclaims.sg@fwd.com  
**Sent:** Friday, 19 October, 2018 7:20 PM  
**To:** assignments@lkkauto.com; sur@lkkauto.com  
**Cc:** clara.li@fwd.com; motorclaims.sg@fwd.com  
**Subject:** FW: CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 17 OCTOBER 2018 AT ABOUT 17:45HRS INVOLVING MOTOR VEHICLES NO(S). SLE2743H, SKW2727Y & SKZ7146A ALONG TPE TOWARDS PUNGGOL  
**Attachments:** RE: CLAIM ARISING FROM A ROAD TRAFFIC ACCIDENT ON 17 OCTOBER 2018 AT ABO... (89.9 KB)

Attn: LKK Team

Please attend to attached PRS notice.

Kindly create case in Merimen. Our Ref: 1201800013412/CL

Best Regards,

Lionel Tan  
Senior Executive, Claims



FWD Singapore Pte. Ltd.  
6 Temasek Boulevard, #18-01 Suntec Tower Four, Singapore 038986  
T (65) 6914 6824  
E [lionel.tan@fwd.com](mailto:lionel.tan@fwd.com)  
W [fwd.com.sg](http://fwd.com.sg)



### ATTENTION:

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

**Catherine Chong (LKK Auto)**

---

**From:** lia@aplp.com.sg  
**Sent:** Tuesday, 23 October, 2018 11:45 AM  
**To:** clara.li@fwd.com  
**Cc:** charles@aplp.com.sg  
**Subject:** Our reference: AP/2018/000261 Your reference: SLE2743H

Hi Clara,

We refer to our tele-conversation moments ago.

As requested, kindly find below the address of our client's workshop;

My Car Consultant  
53 Paya Ubi Industrial Park  
#01-33  
Singapore 408934

**Best regards,**

**Armelia**

**Secretary to Mr Charles Hoon**

**AP** Law Practice

9 Temasek Boulevard #09-01 Suntec Tower 2 Singapore 038989

T: 64071429 F: 64071427 E: [lia@aplp.com.sg](mailto:lia@aplp.com.sg)

Singapore UEN No.: 53380739E

=====

This email transmission is confidential and intended only for the addresses(s). It may contain information which is privileged as between solicitor and client or protected by litigation privilege. If you are not the intended recipient, please delete this message and all attachments and inform us by return email. No part of this message should be disclosed to any party, copied or used for any purpose. Thank you for your co-operation.

=====

**ATTENTION:**

The email and any attachments transmitted with it are private and confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error, please notify the sender immediately and delete this email and any attachments from your system. You should not use, disclose, copy or store this email and any attachments.

Messages and attachments are scanned for all viruses known. However, you are advised that you open any attachments at your own risk. If this message contains password-protected attachments, the files have NOT been scanned for viruses by our mail domain. Please always scan for viruses before opening any attachments.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                            |                    |
|----------------------------|--------------------|
| Date Of Report             | 18/10/2018 20:17   |
| Date Of Accident           | 17/10/2018 17:45   |
| Exact Location Of Accident | TPE TOWARD PUNGGOL |
| Country/State of Loss      | SINGAPORE          |

### DETAILS OF OWN VEHICLE

|  |                                     |
|--|-------------------------------------|
| Vehicle Registration Number  | SKW2727Y                            |
| <b>Insured/Policyholder</b>  |                                     |
| Name Of Registered Owner   | TAN SEE LENG                        |
| NRIC No  | S8432182F                           |
| Email Address  | ADMIN@MYCAR.SG                      |
| Mobile Phone No  | (LOCAL) +65-96426720                |
| Alternative Phone No   | OFFICE-96426720                     |
| <b>Vehicle Particulars</b>   |                                     |
| Manufacturer   | HONDA                               |
| Model  | HRV 1.5 DX CVT                      |
| Exact Purpose for which vehicle was being used at time of accident           | PRIVATE USE                         |
| Are you claiming under your own insurance policy for repair to your vehicle? | NO                                  |
| If No, Please state action to be taken                                       | THIRD PARTY                         |
| Vehicle Category   | PRIVATE CAR                         |
| <b>Insurance Company</b>   |                                     |
| Name of Insurance Company  | SOMPO INSURANCE SINGAPORE PTE. LTD. |
| Type Of Coverage   | COMPREHENSIVE                       |
| Fleet Policy   | NO                                  |
| Policy Number  | D18MTPV01007455                     |
| Cover Note Number  |                                     |
| <b>Driver</b>  |                                     |
| Name of Driver   | TAN SEE LENG                        |
| NRIC No  | S8432182F                           |
| Date Of Birth  | 23/10/1984                          |
| Occupation   | INDOOR                              |
| Date Of Driving Pass   | 03/03/2005                          |
| Driving Experience   | 13 YEARS AND 7 MONTHS               |
| Gender   | FEMALE                              |
| Mobile Number  | (LOCAL) +65-96426720                |
| Fax Number   |                                     |
| Contact Number   | OFFICE-96426720                     |
| Email Address  | ADMIN@MYCAR.SG                      |

Address THE ESTUARY, 99 YISHUN AVENUE 1 769139

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -  
-  
-

Insurance Company of Driver's Own Vehicle -  
-  
-

#### General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1 NAME: : ELYSIA GOH

GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

POLICE STATION NAME [OTHER] YISHUN SOUTH NPC

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

REFER TO THE POLICE REPORT NO : T/20181017/2019D LODGED AT YISHUN SOUTH NPC I WAS TRAVELLING ALONG TPE AND VEHICLE (SKZ7146A) IN FRONT OF ME CAME TO A STOP WHICH I STOPPED BEHIND, HOWEVER VEHICLE (SLE2743H) BEHIND, COLLIDED INTO THE REAR OF MY VEHICLE WHICH THEN CAUSED A CHAIN COLLISION WHICH INVOLVED 5 VEHICLES. AT THIS POINT OF TIME I HAD A PASSENGER WITH ME NAMELY ELYSIA GOH, C/N: 96961165. AFTER THE ACCIDENT HAPPENED I EXITED MY VEHICLE AND SOMEONE APPROACHED ME AND INFORMED THAT HE COULD REPAIR MY VEHICLE DAMAGES. I THEN LEFT IN MY VEHICLE WITH THE SAID PERSON TO THE WORKSHOP. I AM UNSURE IF ANYONE WAS CONVEYED BY THE AMBULANCE BUT I WAS INFORMED BY VEHICLE (SLE2743H) THAT TRAFFIC POLICE WERE AT SCENE AND I WAS GIVEN THE REPORT NUMBER TO LODGE A POLICE REPORT.

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: PENDING FROM INSURED

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLE2743H

Vehicle Make/Model/Colour NISSAN/ QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver LOO SHEK PENG

NRIC/Passport Number S2649373J

Contact Number 96181786  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number SKZ7146A  
Vehicle Make/Model/Colour MAZDA6 4-DOOR SEDAN 2.0L SP.6EAT  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver GANESAN  
NRIC/Passport Number S8007556A  
Contact Number 98197330  
Address  
Postcode  
Insurance Company Name  
Nature Of Damage  
No. Of Passenger (Including Driver)

Sketch Plan

**SKETCH PLAN**

*(Faint printed text describing the purpose and use of the sketch plan form is visible in the background.)*

**VERIFIED BY AJAX MARS  
REPORTING OFFICER  
MOHAMMAD SULHANDI BIN  
MOHD AFFANDI**

Policyholder's Signature / Date & Time: \_\_\_\_\_  
Driver's Signature (If driver is not the policyholder) / Date & Time: \_\_\_\_\_  
Witnessed by Reporting Centre Person(s): \_\_\_\_\_

Sketch Plan

TPE

↑   ↑   ↑

→ SKZ714UA  
→ SKW2727Y  
→ SLE2743H

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

| Vehicle Owner Particulars     |                                      |
|-------------------------------|--------------------------------------|
| Owner ID Type:                | Singapore NRIC                       |
| Owner ID:                     | 2182F                                |
| Vehicle Details               |                                      |
| Vehicle No.:                  | SKW2727Y                             |
| Vehicle to be Exported:       | No                                   |
| Intended Deregistration Date: | 23 Oct 2018                          |
| Vehicle Make:                 | HONDA                                |
| Vehicle Model:                | HRV 1.5 DX CVT                       |
| Primary Colour:               | Red                                  |
| Manufacturing Year:           | 2018                                 |
| Engine No.:                   | L15B4534093                          |
| Chassis No.:                  | JHMRU1810GX204092                    |
| Maximum Power Output:         | 96.0 kW (128 bhp)                    |
| Open Market Value:            | \$19,096.00                          |
| Original Registration Date:   | 04 May 2018                          |
| First Registration Date:      | 04 May 2018                          |
| Transfer Count:               | 0                                    |
| Actual ARF Paid:              | \$19,096.00                          |
| Intended PARF Rebate Details  |                                      |
| PARF Eligibility:             | Yes                                  |
| PARF Eligibility Expiry Date: | 03 May 2028                          |
| PARF Rebate Amount:           | \$14,322.00                          |
| Intended COE Rebate Details   |                                      |
| COE Expiry Date:              | 03 May 2028                          |
| COE Category:                 | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years):            | 10                                   |
| QP Paid:                      | \$38,000.00                          |
| COE Rebate Amount:            | \$36,204.00                          |
| <b>Total Rebate Amount:</b>   | <b>\$50,526.00</b>                   |

The information contained herein is correct as at 23 Oct 2018

OK

Dep 8,580/yr  
715/mo

MV 91K - 92K

lin.  
23/10/18

- 2016 Hyundai Elantra / Avante
- Right-hand exiting expressway to be replaced
- Instant Water Heater

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad Advertiser Login Ways of Selling

New 5 Years Coe Renewal Honda Stream 1.8A RSZ



\$2000 Development Monthly  
From \$638 Downward Lower!  
1.18% A SGV Car Financing  
GV Credit Pte Ltd

\* Free VICOM evaluation  
 \* Free grooming and 8 months maintenance  
 \* In-house workshop ensures quality service  
 \* Member of SVTA and hire purchase association  
 \* 100% deposit refund for unapproved loan

**YONG LEE SENG MOTOR PTE LTD**

Browse by Category

Sort by Date Posted 20 results/page

3 vehicles

Honda HR-V

| Make   | Model                     | Price    | Depreciation | Reg Date    | Eng Cap  | Mileage  | Veh Type | Status      |
|--|---------------------------|----------|--------------|-------------|----------|----------|----------|-------------|
| <b>Search Selection</b>  |                           |          |              |             |          |          |          |             |
| Honda  | HR-V                      | Any      | Any          | 2018        | Any      | Any      | Any      | All         |
|  | <b>Honda HR-V 1.5A LX</b> | -        | N.A          | 09-Jan-2018 | 1,496 cc | -        | SUV      | <b>SOLD</b> |
| At 1.99% Consignment Appointment Only Warranty Till Jan 2023 With Unlimited Mileage One Owner SUV Cheapest And Lowest Depreciation With Up To 90% Guaranteed HRV 1.5 LX In The Market With Fully Maintained A... |                           |          |              |             |          |          |          |             |
| Posted: 28-Aug-2018 Tags: 2018 Honda HR-V, 2018 honda HRV, Honda HR-V, honda HRV, Honda, HR-V, HRV, Used Honda   |                           |          |              |             |          |          |          |             |
|  | <b>Honda HR-V 1.5A LX</b> | \$90,800 | \$8,580 /yr  | 20-Feb-2018 | 1,496 cc | 2,486 km | SUV      | Available   |
| 1 Owner With Low Mileage. High Spec Edition In Showroom Condition. Agent Maintained With Warranty. Selling Cheap. Only \$9,080 Down Payment. Classic Credit Pte Ltd  |                           |          |              |             |          |          |          |             |
| Posted: 25-Aug-2018 Tags: 2018 Honda HR-V, 2018 honda HRV, Honda HR-V, honda HRV, Honda, HR-V, HRV, Used Honda   |                           |          |              |             |          |          |          |             |
|  | <b>Honda HR-V 1.5A DX</b> | -        | N.A          | 06-Mar-2018 | 1,496 cc | -        | SUV      | <b>SOLD</b> |
| 1 Owner Unit. Super Low Mileage.Flexibility In House Loan Up To 90%.Fully Maintained By Agent With 5 Years Warranty. As Good As Brand New. Beautiful And Well Maintained Call Now! Viewing Strictly By A...      |                           |          |              |             |          |          |          |             |
| Monster Motors Pte Ltd   |                           |          |              |             |          |          |          |             |
| Posted: 19-Aug-2018 Tags: 2018 Honda HR-V, 2018 honda HRV, Honda HR-V, honda HRV, Honda, HR-V, HRV, Used Honda   |                           |          |              |             |          |          |          |             |

Save this search criteria, to get email alerts whenever a match is found.

Make: Model: Price: Depreciation: Reg Date: Eng Cap: Mileage: Veh Type: Status:

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Honda, Honda Singapore, used Honda Singapore, used Honda, used vehicles Singapore or even buy used Honda Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

**Follow sgCarMart.com**

About Us | Careers | Contact Us | Sitemap | Terms of Service | Privacy Policy | Personal Data Protection Statement

©2004-2018 sgCarMart. All rights reserved.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

| CLAIM SUBFOLDER TRACKING |   |               |   |  |  |             |   |
|--------------------------|---|---------------|---|--|--|-------------|---|
| Case                     | Notified                                | Est Submitted | Adj Assigned                                      | Adj Rpt  | Adj Submitted                              | Ins Auth'ed | Status  |
| Main                     | 18 Oct 2018<br><a href="#">Edit Reg</a> |               | 19 Oct 2018 00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$0.00</b><br><a href="#">Edit Estimates</a> | <b>S\$0.00</b><br><a href="#">View Rpt</a> |             | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

|                      |                           |                               |                           |                          |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|
| <a href="#">Main</a> | <a href="#">Reference</a> | <a href="#">Claim Details</a> | <a href="#">Documents</a> | <a href="#">Show All</a> |
|----------------------|---------------------------|-------------------------------|---------------------------|--------------------------|

| CLAIM SUBFOLDER DETAILS   |  |                        | [Created by adjuster]   |         |         |             |              |            |       |
|---|--|------------------------|---|---------|---------|-------------|--------------|------------|-------|
| Insured:  | LOO SHEK PENG, ID: S2649373J   |                        |   |         |         |             |              |            |       |
| Main Claimant:  | TAN SEE LENG, ID: S8432182F  |                        |   |         |         |             |              |            |       |
| Vehicle Reg. No.:   | SKW2727Y   | Date of Loss:          | 17/10/2018 17:00 - :59<br>[5 Months and 13 Days From LTA Reg Date (Man Yr)] |         |         |             |              |            |       |
| Claim Type:   | TP / 1201800013412   | Policy/Cover Note No.: | PNPV2017-00005247-01 (Comprehensive)  |         |         |             |              |            |       |
| Vehicle Reg. No. (Insured):   | SLE2743H   | Policy No. (Claimant): |   |         |         |             |              |            |       |
|   |  | Excess:                | S\$500.00   |         |         |             |              |            |       |
| Repairer:   | My Car Consultant Pte Ltd (Ubi) 53 Ubi Ave 1, #01-24, Paya Ubi Industrial Park, 408934 Ubi - Tel:                |                        |   |         |         |             |              |            |       |
| Handling Insurer:   | FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong]                                  |                        |   |         |         |             |              |            |       |
| Adjuster:   | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Lim Teow Guan] ... [Final Rpt due 01/11/2018] |                        |   |         |         |             |              |            |       |
| <b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>   |  |                        |   |         |         |             |              |            |       |
| There are no mail for this case.  |  |                        |   |         |         |             |              |            |       |
| <b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span> |  |                        |   |         |         |             |              |            |       |
| Due Date  | Priority   | Type                   | Task Group  | Subject | Handler | Assigned By | Completed On | Created On | Done? |
| No results.   |  |                        |   |         |         |             |              |            |       |



## Claim Documents

**\*SKW2727Y (1201800013412)**  
**[SLE2743H]**  
**TP**  
**TAN SEE LENG**  
**Oct 17 2018 5:00PM**  
**[LOO SHEK PENG]**  
**My Car Consultant Pte Ltd**

[Upload Documents](#) | 
 [Upload Photos](#) | 
 [Compose New Letter](#)

**View** [View in Browser](#) ▼

| Photos/Images |                 |                                   | 3 per page ▼ | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail    | Print                               |
| 1             | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 2             | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 3             | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 4             | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 5             | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 6             | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 7             | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 8             | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 9             | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 10            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 11            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 12            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 13            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 14            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 15            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 16            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 17            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 18            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 19            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 20            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 21            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 22            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 23            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 24            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 25            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 26            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 27            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 28            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 29            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 30            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 31            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 32            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 33            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 34            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |
| 35            | 24/10/18 14:00  | <b>General View</b>               | Load JPG     | <input checked="" type="checkbox"/> |

| Photos/Images |                 |                                   | 3 per page   | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|--|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 36            | 24/10/18 14:00  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 37            | 24/10/18 14:00  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 38            | 24/10/18 14:00  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 39            | 24/10/18 14:00  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 40            | 24/10/18 14:00  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 41            | 24/10/18 14:00  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 42            | 24/10/18 14:00  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 43            | 24/10/18 14:00  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 44            | 24/10/18 14:00  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 45            | 24/10/18 14:00  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 46            | 24/10/18 14:00  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 47            | 24/10/18 14:00  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 48            | 24/10/18 14:00  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 49            | 24/10/18 14:00  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 50            | 24/10/18 14:00  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 51            | 24/10/18 14:00  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 52            | 24/10/18 14:00  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 53            | 24/10/18 14:00  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 54            | 24/10/18 14:00  | General View                      |  Load JPG   | <input checked="" type="checkbox"/> |
| 55            | 24/10/18 14:00  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 56            | 24/10/18 14:00  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 57            | 24/10/18 14:00  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 58            | 24/10/18 14:00  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 59            | 24/10/18 14:00  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 60            | 24/10/18 14:00  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 61            | 24/10/18 14:00  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 62            | 24/10/18 14:00  | General View                      |  Load JPG | <input checked="" type="checkbox"/> |
| 63            | 26/10/18 11:44  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 64            | 26/10/18 11:44  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 65            | 26/10/18 11:44  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 66            | 26/10/18 11:44  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 67            | 26/10/18 11:44  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 68            | 26/10/18 11:44  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 69            | 26/10/18 11:44  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 70            | 26/10/18 11:44  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 71            | 26/10/18 11:44  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 72            | 26/10/18 11:44  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 73            | 26/10/18 11:44  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 74            | 26/10/18 11:44  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 75            | 26/10/18 11:44  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 76            | 26/10/18 11:44  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 77            | 26/10/18 11:44  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 78            | 26/10/18 11:44  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 79            | 26/10/18 11:44  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 80            | 26/10/18 11:44  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 81            | 26/10/18 11:44  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 82            | 26/10/18 11:44  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |
| 83            | 26/10/18 11:44  | Photographs of Damaged Parts      |  Load JPG | <input checked="" type="checkbox"/> |

| Photos/Images |                 |                                   | 3 per page | <input checked="" type="checkbox"/> |
|---------------|-----------------|-----------------------------------|------------|-------------------------------------|
| No            | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail  | Print                               |
| 84            | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 85            | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 86            | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 87            | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 88            | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 89            | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 90            | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 91            | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 92            | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 93            | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 94            | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 95            | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 96            | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 97            | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 98            | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 99            | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 100           | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 101           | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 102           | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 103           | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 104           | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 105           | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 106           | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 107           | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 108           | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| 109           | 26/10/18 11:44  | Photographs of Damaged Parts      | Load JPG   | <input checked="" type="checkbox"/> |
| Documentation |                 |                                   | 1 per page | <input checked="" type="checkbox"/> |
| No            | Finalized On    | FWD Singapore Pte. Ltd. (HQ)      | Thumbnail  | Print                               |
| 1             | 24/10/18 12:08  | OI GIA Report                     | Load PDF   | <input type="checkbox"/>            |

## Documents Checklist

|  |   |
|--|---|
| <b>DOCUMENTS CHECKLIST</b>                   | <input type="button" value="Reset"/> <input type="button" value="Save"/> <input type="button" value="Print"/> |
| There are no document checklists configured. |   |

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer  
Note: Remarks are private unless you show it to other parties.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/FWD18019250/BCBS2  
**Date:** 29/10/2018

### REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2017-00005247-01  
**Claimant Vehicle No :** SKW2727Y **Insured Vehicle No :** SLE2743H  
 Date of Loss: 17/10/2018 Nature of Claim: TP Claim No: 1201800013412

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW2727Y**  
 Make & Model: HONDA HR-V, 1.5 DX CVT (A) Engine No: L15B4534093  
 Reg. Date: 04/05/2018 (Man. Year: 2018) Chassis No: JHMRU1810GX204092  
 Colour: Red Odometer: 78805 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16  
 Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7 mm  
 Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7 mm

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>    | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|--------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                    | 0.00              | 0.00              | 0.00              |               |
| Miscellaneous Items      | 0.00              | 0.00              | 0.00              |               |
| Labour                   | 0.00              | 0.00              | 0.00              |               |
| Paintwork Labour         | 0.00              | 0.00              | 0.00              |               |
| Towing                   | 0.00              | 0.00              | 0.00              |               |
| <b>Nett Amount (S\$)</b> | <b>0.00</b>       | <b>0.00</b>       | <b>0.00</b>       |               |

### INSPECTION

Date of Assignment: 19/10/2018  
 Date Inspected: 23/10/2018 Inspected At: My Car Consultant Pte Ltd (Ubi)  
 53 Ubi Ave 1, #01-24, Paya Ubi Industrial Park  
 Singapore 408934  
 Estimated Period of Repair: 8.0 days

**Adjuster:** Lim Teow Guan

**Manager:** CELINE FONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 - \$8,500.00

## REPAIR DETAILS

### Reference

|                            |  |
|----------------------------|--|
| <b>Part Source:</b> MRM-SG | Version: 1.0 (Last Synchronised: 29 Oct 2018)  |
| <b>Parts:</b> M1-SUV       | HONDA HR-V 1.5 DX CVT (A) (Catalogue:Merimen Singapore 1.0)  |
| <b>Labour:</b> Repairer's  | (Price-denominated Standard List)  |
| <b>Print Code:</b>         | (Unsubmitted, no print-code for SKW2727Y)  |
| <b>Validity:</b>           | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page |
| <b>Further Info:</b>       | Items/values not in reference catalogue are prefixed with an asterisk *.   |

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >