	laine cheong o	cti	Date	Time: 23/10/18@	2.13p
Estimated Cost:	Dill Chevry	Bill to:	240	Tame:	
OD THE WSTT	RES / OD RES / EVA /		**		
To Inspect Vehicle		49276x	Insured:	SDM 7838M1	
at Workshop m/s _		s Wagen Group	Tel:	3057176	
of		Alexandra Ro			
Policy No: DM	DCSN171441180	Claim	No: 3NM18	D05608C02	
Sum Insured:	86 ==10**(10**	Exc			
Make of Veh:			D.O.	A 20/10/2018	
(Client's Record)	,			20/11	
	P. / REV 24 HRS CW	(970)		D.D. Endorsement:	
Date/Time: 2.54	Pers	on Contacted:	ermeine Vehic	e_IN_OUT	
Date/Time Ac	ion/Instruction (	) Estimate			
	SKU 9276X-	X			
		Innia wal	12	20A:20110/20	18
	1 1 1 V 1 - 1 K - X V 1 V 1 - 1 T L	1AG18019092/C	lpu3		100
201 1 - 0	lla confirme	1 00 0 1	in find fin 1	K 21 W 16 2 1	1.42

\*

# ...CLAIM SUBFOLDER...(New Assignment)

	Carry Comments	DER TRA	Est Submitted	Adi Assigned	Adj Rpt	Adj Subi	nitted In	is Authled	Status		
Main		Oct 2018	La de Secretor de Const.	23 Oct 2018 14:13 Assign					New As Cancel	signment Case	
	Mai	n	Re	ference		Claim Details		Document	5	SI	IIA wor
CLATM S	URF	OLDER DE	ETAILS			A SAME AND A SAME ASSESSMENT	[Created	by insurer]			
Insured:			SAY SAI, ID: S1	558255G							
Main Claimant:			SEPH MURPHY								
Vehicle R	eg.	SKU927	6X			Date of Loss:	20/10/2018 10:00 - :59				
No.: Claim Typ	oe:	e: TP / SNM18D05008C02 Policy/Cover Note No.: DMPCSN1714411801 (Comprehensive)					e)				
Vehicle R		SDM7838	вм			Policy No. (Claimant):					
(Insured)	):					Excess:	\$\$0.00				
Repairer:		Volkswa	gen Group Singa	pore Pte Ltd (-	) 247 ALEXA	NDRA ROAD, 15	9934 Alexani	dra - Tel: 630572	293		
Handling Insurer:			iping Insurance						eong]		
Adjuster:	:	LKK Auto	Consultants Pto	Ltd (HQ) - Tel	: 6256-3561	[Final Rpt	due 01/11	/2018]			
Adj Asg. Remarks		EST \$848	0.75, CASE WITH	SJE,							
ASSOCI	ATE	MAIL R	ECEIVED						View All	Compose	Case Mail
There are	e no i	mail for thi	s case.								
ALL AS	SOC	IATED TA	sks⊟				View All	Search Tasks	Create N	New Task	Complete
Due D		Priority	y Type Task	Group Sul	bject Ha	ndler Assig	ned By	Completed Or	Cre	eated On	Done

## Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Friday, 23 November 2018 11:16 AM

To:

'Cheong, Pearlyn (VWG Singapore)'; SUR; Admin A; Admin-D (LKKAuto)

Cc:

Kong, Charmaine (VWG Singapore); Wong, Meiy (VWG Singapore); Foo, John (VWG

Singapore)

Subject:

RE: SKU9276X - FINALISE

Dear Pearlyn,

WITHOUT PREJUDICE

Confirm final fig \$3,476.45 before GST and 3 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Cheong, Pearlyn (VWG Singapore) <Pearlyn.cheong@vw.com.sg>

Sent: Thursday, 22 November 2018 9:06 AM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Admin-D

(LKKAuto) <admin-d@lkkauto.com>

Cc: Kong, Charmaine (VWG Singapore) <charmaine.kong@vw.com.sg>; Wong, Meiy (VWG Singapore)

<meiy.wong@vw.com.sg>; Foo, John (VWG Singapore) <John.Foo@vw.com.sg>

Subject: SKU9276X - FINALISE

Dear Rasul,

Please confirmed

COR \$3476.45 before GST

Total 3 working days repairs

Best regards,

Pearlyn Cheong Service Advisor

Aftersales Body & Paint Department

Volkswagen Group Singapore (Alexandra) 247 Alexandra Road Singapore 159934

Direct line:

+65 6305 7288

Mobile : +65 9236 1336

Main line: +65 6305 7299 Main Fax: +65 6474 3643

pearlyn.cheong@vw.com.sg

http://www.vw.com.sg

MVGS18136602 / Volksweigen Centre Singapore - HQ ENTRY DATE & TIME 22/10/2018 11:15 SUBMITTED BY: Pearlyn Cheong Pei Fang.

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

ACCI	DEN	IT STA	TEM	ENT

Date Of Report

22/10/2018 11:15

Date Of Accident

20/10/2018 10:55

Exact Location Of Accident

ECP

Country/State of Loss

SINGAPORE

## **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

SKU9276X

#### Insured/Policyholder

Name Of Registered Owner

BRIAN JOSEPH MURPHY

S2686416Z NRIC No.

Email Address

KPMLTM@YAHOO.COM.SG

(LOCAL) +65-96238009 Mobile Phone No

Alternative Phone No

OTHERS-96494546

#### Vehicle Particulars

Manufacturer

VOLKSWAGEN

Model

GOLF-1.2 (A7) TSI (A)

Exact Purpose for which vehicle was being used at

time of accident

PRIVATE

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No. Please state action to be taken

THIRD PARTY

Vehicle Category

PRIVATE CAR

#### Insurance Company

Name of Insurance Company

MSIG INSURANCE (SINGAPORE) PTE. LTD.

Type Of Coverage

COMPREHENSIVE

Fleet Policy

NO.

Policy Number

A 28811663 AVW

Cover Note Number

#### Driver

Name of Driver

EMILY CHUA HWEE GEOK

NRIC No

S1816660G

Date Of Birth Occupation

07/12/1967

Date Of Driving Pass

INDOOR

18/06/1993

Driving Experience

25 YEARS AND 4 MONTHS

Gender

FEMALE

Mobile Number

(LOCAL) +65-96494546

Fax Number

Contact Number

EMail Address

KPMLTM@YAHOO.COM.SG

Address

60 BAYSHORE ROAD #20-02

Postcode

469982

Was driver an employee of the Insured's Company NO

If No. Relationship of the Driver with the Insured

SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

8

#### General Information of the Accident

Type Of Accident

CHAIN COLLISION

Weather Conditions

CLEAR

Road Surface

DRY

#### Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

NO

Was any body injured in the Accident?

Was any injured conveyed to hospital by

NO

ambulance?

4,000

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

91

#### **Details of Police Action**

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

#### Circumstances of Accident

PLEASE REFER TO ATTACHEMENT

#### Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO.

Was there any audio recorded?

NO

### **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number

SDM7838M

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

FOO SAY SAI

NRIC/Passport Number

S1658255G

Contact Number

96485948

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### **DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number

SLK8843G

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category

Name of Driver

PRIVATE CAR

LEE CHANG THIA

NRIC/Passport Number

S0007419E

Contact Number

90612848

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

## **DETAILS OF OTHER VEHICLE PROPERTY 3**

Vehicle Registration Number

SKB9211H

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

WILSON KWEK WEI LOONG

NRIC/Passport Number

S85292601

Contact Number

94899049

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Sketch Plan

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of "
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders

Pearlyn Cheong

Policyholder's Signature Date & Time: Oriver's Signature (If driver is not the policyholder)

Date & Time:

15.00


Reporting Centre Personnel's Signature Name:

NRIC/FIN No.

2 2 OCT 2018

#### Sketch Plan #2

SKETCH PLAN



#### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ESCRIBE CIRCUMSTANCES OF THE ACCIDENT
I was driving along ECP at about 10.50 am (terrals changi
Arreste Before marine Vista The car stop broked suddenly
and I braked in time . Phanomen Moments later, a I heard a seed bung.
and the rear vehicle hot my car.
vaguely
Becas It happen in a spilt cound what I remembered is that
doften thoraken, the second car didn't not me immediately after
I brake (based in the real mirror).
The Court of the C

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Pearlyn Cheong

Policyholder's Signature Date & Time: Oriver's Signature

(If driver is not the policyholder)

Date & Time:

2 2 OCT 2018

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No...

2 2 OCT 2018



Insurance (Singapore) Pte. Ltd. 1301 Way, # 21-01, \$GX Centre 2, Singapore 068807 JS 5827 7888, Fax +65 6827 7800 ag, No. 2004122120, GST Rag, No. 20-04122120

VW DRIVEEASY

#### RENEWAL CERTIFICATE

Policy Number		Period of Insurance	Place of Issue		
A 28811663 AVW	21	/08/2018 to 20/08/2019	SINGAPORE		
Nam	Date of Issue				
Brian Joseph Murphy 60			15/08/2018		
Bayshore Road #20-02			Account Number		
Bayshore Park Singapore 469982	156346				
Premium	GST	国的 新在388 0 F1 G ()	Total Due		
SGD801.78	SGD56.12		SGD857.90		

RISK NUMBER

VW DRIVEEASY

OCCUPATION

Business Manager

FINANCIAL INTEREST

DBS Bank Ltd

as Hire Purchase Owners

SCOPE OF COVER Comprehensive

INTEREST INSURED

REGISTRATION NO. SKU9276X

SUM INSURED

MARKET VALUE

MAKE/MODEL Volkswagen Golf A7 1.2 TSI
ENGINE NUMBER CJZ608570
CHASSIS NUMBER WVWZZZAUZFWZ89584

INCL. COE/PARF

NO OFF-PEAK CAR

NO CLAIM DISCOUNT 50.00% (or F/D)

YEAR OF MFG 2015 CAPACITY 1197

GOOD DRIVER'S DISCOUNT

SGD42.20

1197 C.C. SEATING CAPACITY 5 (INCL. DRIVER)

NCD PROTECTOR COVERED

SGD500

WINDSCREEN UNLIMITED

EXCESS

ANNUAL PREMIUM SGD801.78

ACCESSORIES

Aircon, radio/cassette/compact disc player, in-vehicle unit, rust-proofing and other accessories that are factory fitted.

**AUTHORISED DRIVERS** 

Brian Joseph Murphy

#### **PDI TUAS**

PDI TUAS

BRIAN JOSEPH MURPHY 60 BAYSHORE ROAD #20-02 Singapore, 469982 Singapore

Phone No. Fax No. E-Mail

VAT Registration No. M20098505-2 199101494Z Tax No.

## Service Quote

Customer No.

CV030710

Quote No.

SER/QUO/1801766

QuoteDate Salesperson

22/10/18 Jose Chang

Page

1

THIS IS NOT AN OFFICIAL TAX INVOICE

Make

License No.

SKU9276X **Engine Code**  Model Description

Volkswagen Passeng GOLF A7 1.2 TSI TL BMT (DSG)

WVWZZZAUZFW289584

Labor Type

Mileage 30,928

Initial Registration 21/08/15

Engine No. CJZ 608570 Service Advisor Cheong Pearlyn Sales Advisor Jose Chang

Model Code 5G12DZ

	No.	Description	Qty.	UoM	Unit Price	Amount
-	DOD ALEY LADOUD	LABOUR	3	UNIT		840 2520.00
P	B&P ALEX LABOUR	SPRAY PAINT	3	UNIT		800 3,400.00
P	B&P ALEX PAINT		1	pcs		34/80.00
Р	B&P NUMBER PLATE	B&P NUMBER PLATE -NETT	- 8	11000		480.00
P	B&P DIAG	PROGRAMMING & CALIBRATION	1	Time Un		460.00
		COMPULSORY TO DO AFTER AC				
P	B&P MECH	CHECK WIRE HARNESS, ECU, S	1	Time Un		280.00
		Nett				0.72
		Sum Labor				5,760.00
Р	5G0807305B	BUMPER REINFORCEMENT	1	Pieces		( ? 629.03 )
10		Successor 5G0807305D-				1 2
Р	5G6807393	BUMPER BRACKETS LHS	1	Pieces		SUC 5 39.97 X
P	5G6807393A	BUMPER RETAINER LHS	1	Pieces		39.97
P	5G6807394	BUMPER BRACKETS RHS	1	Pieces		39.97
P	5G6807394A	BUMPER RETAINER LHS	1	Pieces		7 39.97
Р	5G6807417APGRU	REAR BUMPER	1	Pieces		996.45
		Predecessor 5G6807417ARGRU				V 17
P	5G6807568B 9B9	REAR LOWER SPOLIER RDIFFU	1	Pieces		Cuc ( = 322.45 ()
Р	5G6807863A	CENTER STRIP	1	Pieces		58.12
		Use Predecessor 5G6807863				

Sum carried forward

7,925.93

#### **PDI TUAS**

POI TUAS

BRIAN JOSEPH MURPHY 60 BAYSHORE ROAD #20-02

Singapore, 469982

Singapore

Phone No. Fax No. E-Mail

VAT Registration No. M20098505-2

199101494Z

Service Quote

Customer No.

CV030710

Quote No. QuoteDate SER/QUO/1801766 22/10/18

Salesperson

Jose Chang

Page

2

THIS IS NOT AN OFFICIAL TAX INVOICE

Make

Volkswagen Passeng

License No.

SKU9276X Engine Code Model Description

GOLF A7 1.2 TSI TL BMT (DSG)

WVWZZZAUZFW289584

Labor Type

Mileage 30,928

Initial Registration

21/08/15

Engine No. CJZ 608570

Service Advisor Cheong Pearlyn

Sales Advisor

Jose Chang Model Code

5G12DZ

Continued

7,925.93

2,165.93

5,760.00

Sum Item

Sum Labor Sum Item

2,165.93

Total 7% GST

SGD

7,925.93

7.925.93 554.82

Total SGD Incl. GST

8,480.75

Explanations

P = Proportionately Charged

**Payment Terms** 

No Credit

Rasul

4p 90010068 / 200118

3 days 29/0/18

25/10/18 @ 1030

Resurvey 64 paint

# Service Order Confirmation

SERVIC	CE ORDER	NO: 18/P2900	)								
CUSTO	MER NO.:	CV030710									
CUSTO	MER NAM	IE: BRIAN JOS	SEPH MURPHY								
TELEP	HONE NO	4									
ADDRE	ESS:	60 BAYSH	ORE ROAD #2	0-02							
		Singapore									
VE	H No.	: SKU	9276X								
Order	Date:	05/11/18									
Reg D	ate:	21/08/15		KM:	33,645					SA-	Cheong Pearlyn
VIN NO	0.:	WVWZZZAUZF	W289584	ENGINE	NO:					34.	Checking ( carry)
MODE	EL:	GOLF A7 1.2 TS	SI TL BMT (DSC	) MODEL	NO.: 5G12DZ						
	No.		DESCRIPT	ION			QTY	<u>uom</u>	UNIT PRICE	DISC %	AMOUNT
	Labor						1000	711	480		480
1	B&P DIA	AG.			ALIBRATION- NET		1	TU	280		280
2	B&P ME	CH			ESS, ECU, SENSO	R,SOCKET	1	UNIT	840		840
3	B&P AL	EX LABOUR	LABOUR				1	UNIT	800		800
4		EX PAINT	SPRAY F					ST	80		80
5	B&P NU	IMBER PLATE	B&P NU	MBER PLATI	E-NETT						
	item		REAR B	IMPER			1	PCS	996.45		996.45
6		417APGRU									
Rema	arks : CHIN	IA TAIPING DIRE	CT SETTLEME	NT:							
DOA	20.10.201	8									
SUR	VEYOR LK	K RASUL									
TPV	EHICLE S	DM7838M									
									OTAL		3,476.45
									ST AMOUNT		243.35
								OTAL AMOUNT		3,719.80	
								210	OTAL AMOUNT		
				o	n Behalf Of "COM	PANY"			Certified Goods	/Service receive	d:

Authorized Signature

Customer

## LKK Auto Consultants Pte Ltd (Co. Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/CTI18019266/R1QD3N2

Date:

26/11/2018

REFERENCE

Handling Insurer:

China Taiping Insurance

(Singapore) Pte. Ltd.

Policy No:

DMPCSN1714411801

Claimant Vehicle No:

Date of Loss:

SKU9276X

Insured Vehicle

SDM7838M

20/10/2018

No:

Nature of Claim:

TP

Claim No:

SNM18D05008C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKU9276X

Make & Model:

VOLKSWAGEN GOLF, 1.2 (A7) TSI (A)

Engine No: Chassis No: CJZ608570

Reg. Date:

21/08/2015 (Man. Year: 2015)

Odometer:

WWZZZAUZFW289584 32920 km

Colour:

Grey

Engine Capacity: Market Value/New Car

1197 cc

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable): No Pre-accident Condition:

Yes

Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

205/55R16 Pirelli 6 mm

Yes Engine Modification:

Rear Tyre Size: Rear Left Side: Rear Right Side: 205/55R16 Pirelli 6 mm

Pirelli 6 mm

Pirelli 6 mm Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts Miscellaneous Items	Repairer's 2,245.93 0.00	Adjuster's 1,076.45 0.00	Difference 1,169.48 0.00	Diff % 52.07
Labour Paintwork Labour	5,680.00 0.00	2,400.00 0.00	3,280.00 0.00	57.75
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,925.93	3,476.45	4,449.48	56.14
+ GST 7.00/7.00% (S\$)	554.82	243.35	311.47	56.14
Nett Amount (S\$)	8,480.75	3,719.80	4,760.95	56.14

INSPECTION

Date of Assignment:

23/10/2018

Date Inspected:

25/10/2018 Inspected At:

Volkswagen Group Singapore Pte Ltd (-

247 ALEXANDRA ROAD Singapore 159934

Estimated Period of Repair:

3.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 26 Nov 2018)

Parts:

144

VOLKSWAGEN GOLF 1.2 (A7) TSI (A) (Catalogue:Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKU9276X)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

Qty	Part No.	Particulars	Condition	Repairer's	Amount
1		*BUMPER REINFORCEMENT	Serviceable	629.03FS	*-FS
1			Serviceable	39.97 FS	*-FS
1		*BUMPER RETAINER LHS *BUMPER BRACKETS RHS	Serviceable Serviceable	39.97 FS 39.97 FS	*- FS *- FS
1		*BUMPER RETAINER LHS *REAR BUMPER	Serviceable Deformed	39.97 FS 996.45 FS	*- FS *996.45 FS
1		*REAR LOWER SPOILER RDIFFU *CENTER STRIP	Serviceable Serviceable	322.45 FS 58.12 FS	*- FS *- FS
1		*B&P NUMBER PLATE	Bent	80.00 FS	*80.00 FS
F=Franchise part. S=SpcNett.		ett.	Total Parts (S\$)	2 245 93	1,076.45
	1 1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1	*BUMPER REINFORCEMENT  *BUMPER BRACKETS LHS  *BUMPER RETAINER LHS  *BUMPER BRACKETS RHS  *BUMPER RETAINER LHS  *REAR BUMPER  *REAR BUMPER  *REAR LOWER SPOILER RDIFFU  *CENTER STRIP  *B&P NUMBER PLATE	*BUMPER REINFORCEMENT Serviceable  *BUMPER BRACKETS LHS Serviceable  *BUMPER RETAINER LHS Serviceable  *BUMPER BRACKETS RHS Serviceable  *BUMPER RETAINER LHS Serviceable  *BUMPER RETAINER LHS Serviceable  *REAR BUMPER  *REAR BUMPER Deformed  *REAR LOWER SPOILER RDIFFU Serviceable  *CENTER STRIP Serviceable  *B&P NUMBER PLATE  Bent	*BUMPER REINFORCEMENT Serviceable 629.03 FS  *BUMPER BRACKETS LHS Serviceable 39.97 FS  *BUMPER RETAINER LHS Serviceable 39.97 FS  *BUMPER BRACKETS RHS Serviceable 39.97 FS  *BUMPER RETAINER LHS Serviceable 39.97 FS  *BUMPER RETAINER LHS Serviceable 39.97 FS  *REAR BUMPER Deformed 996.45 FS  *REAR LOWER SPOILER RDIFFU Serviceable 322.45 FS  *CENTER STRIP Serviceable 58.12 FS  *B&P NUMBER PLATE Bent 80.00 FS

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended	Labour	-
Recommended	Labour	

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR	New	2,520.00	840.00
2	SPRAY PAINT	New	2,400.00	800.00
3	PROGRAMMING & CALIBRATION COMPULSORY TO DO AFTER AC	New	480.00	480.00
4	CHECK WIRE HARNESS, ECU.S	New	280.00	280.00
	Gross Labou	r Cost (S\$)	5,680.00	2,400.00
	Report was unsubmitted during	on this print-out		

< END OF ESTIMATES >