

23/03/2003

ASS. REC. BY:

REF: CS/CTI18019314/Nvd3h2

Special Instruction:

Surveyor:

Naz

ASSIGNMENT (Office)

Meinen

From (Person):

Elaine Cheong

of

CTI

Date/Time:

23/10/18 3:56pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKP 2229 E

Insured:

G8B 6918D

at Workshop m/s

Elite Automotive

Tel:

6339 7378

of

280 woodlands Ind. Park E5 #01-17

Policy No:

DMCVSN1404471804

Claim No:

SNM18D04950C02

Sum Insured:

Excess:

Make of Veh:

D.O.A.

15/10/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS ^{up}

H.O.D. Endorsement:

Date/Time:

10:00am 24/10/18

Person Contacted:

Christy

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

Christy agreed Naz to survey.

SKP 2229 E - CS3/AIG18000028/8be2

DOA: 30/12/2017

G8B 6918D - CA1AIG10008507/81

DOA: 3/5/2010

20/11/18

LS \$1950 confirmed by email (Ref 6952, 788)

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKP 2229E

Yr Regn: 25 AUG 2014

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MAZDA 3 1.5L

c.c. 1,496

Colour

GRBY

A/C: Insur. d / Std / NI / NA

Sp. Reading

89,436

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMBM42A8F0138122

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

4

mm

Rear

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

15/10/18

D.O.A.

24/10/18

Survey held at

ELITE AUTO

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 21 NOV 2018

Date/Time, File Pass to?

☐ : Preli: Report☐ : Final Report

1)

Date/Time, File Return to?

2)

21/11 - typist

Report Format:

merimen

Lump Sum / I.B.I. (\$

1950/-

Days Of Repair:

3

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Inv Auth'd	Status
Main	22 Oct 2018		23 Oct 2018 15:56 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	GOH & GOH ENGINEERING PTE LTD, Co. Reg. No.: 200802075D		
Main Claimant:	ANG KHENG OON, ID: S7424262F		
Vehicle Reg. No.:	SKP2229E	Date of Loss:	15/10/2018 11:00 - :59
Claim Type:	TP / SNM18D04950C02	Policy/Cover Note No.:	DMCVSN1404471804 (Comprehensive)
Vehicle Reg. No. (Insured):	GBB6918D	Policy No. (Claimant):	GA250346/1
		Excess:	S\$0.00
Repairer:	Elite Automotive Pte Ltd (HQ) 280 Woodlands Industrial Park E5, #01-17, Harvest@Woodlands, 757322 Woodlands - Tel: 9388 2885/8136 4741/63397378		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/11/2018]		
Driver/Custodian (Insured):	KALYANASUNDARAM RAJKAMAL (28 / Male), NRIC: G6520384M, Tel: +6584051172		
Adj Asg. Remarks:	EST \$8902, ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED
[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS
[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Elite Automotive <elite.automotive13@gmail.com>
Sent: Wednesday, 21 November 2018 9:13 AM
To: Veron Chen (LKKAUTO)
Subject: Re: SKP 2229E-DOA: 15/10/2018

Hi Veron,

Good day! We accept the offer. Thanks!

Regards,

Christy

On Tue, 20 Nov 2018 at 17:31, Veron Chen (LKKAUTO) <veronchen@lkkauto.com> wrote:

Dear Christy,

WITHOUT PREJUDICE

As spoken, confirmed Lump Sum \$1950 @ 3 working days.

Kindly send Final invoice and all supporting documents to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

From: Veron Chen (LKKAuto)
Sent: Tuesday, 20 November 2018 2:49 PM
To: elite.automotive13@gmail.com
Cc: SUR <sur@lkkauto.com>
Subject: SKP 2229E-DOA: 15/10/2018

Dear Christy,

WITHOUT PREJUDICE

Offer Lump Sum \$1900 @ 3 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

--
Regards,

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 20 November 2018 5:32 PM
To: elite.automotive13@gmail.com
Cc: SUR
Subject: RE: SKP 2229E-DOA: 15/10/2018

Dear Christy,

WITHOUT PREJUDICE

As spoken, confirmed Lump Sum \$1950 @ 3 working days.

Kindly send Final invoice and all supporting documents to CHINA TAIPING

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 20 November 2018 2:49 PM
To: elite.automotive13@gmail.com
Cc: SUR <sur@lkkauto.com>
Subject: SKP 2229E-DOA: 15/10/2018

Dear Christy,

WITHOUT PREJUDICE

Offer Lump Sum \$1900 @ 3 working days.

Please check and confirm.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	4262F
Vehicle Details	
Vehicle No.:	SKP2229E
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Oct 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Grey
Manufacturing Year:	2014
Engine No.:	P520224170
Chassis No.:	JM6BM42A8F0138122
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$15,740.00
Original Registration Date:	25 Aug 2014
First Registration Date:	25 Aug 2014
Transfer Count:	0
Actual ARF Paid:	\$5,740.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Aug 2024
PARF Rebate Amount:	\$4,305.00
Intended COE Rebate Details	
COE Expiry Date:	24 Aug 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$65,710.00
COE Rebate Amount:	\$38,295.00
Total Rebate Amount:	\$42,600.00

The information contained herein is correct as at 26 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/10/2018 11:38
Date Of Accident	15/10/2018 11:45
Exact Location Of Accident	SLE TOWARDS CTE AFTER MANDAI EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKP2229E
Insured/Policyholder	
Name Of Registered Owner	ANG KHENG OON
NRIC No	S7424262F
Email Address	KHENGGOON@SINGNET.COM.SG
Mobile Phone No	(LOCAL) +65-98383702
Alternative Phone No	OFFICE-98383702
Vehicle Particulars	
Manufacturer	MAZDA
Model	3-1.5 L 4-DOOR SEDAN SP.6EAT (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA250346/1
Cover Note Number	

Driver

Name of Driver	ANG KHENG OON
NRIC No	S7424262F
Date Of Birth	28/07/1974
Occupation	INDOOR
Date Of Driving Pass	26/06/1992
Driving Experience	26 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98383702
Fax Number	
Contact Number	OFFICE-98383702
Email Address	KHENGGOON@SINGNET.COM.SG

Address	12 FLORA DRIVE #02-11
Postcode	506943
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : HAN XU GENDER: : MALE
Passenger 2	NAME: : JULIA ANGGRAENI GENDER: : FEMALE
Passenger 3	NAME: : CYNTHIA THERESA GENDER: : FEMALE
Passenger 4	NAME: : ARIES YANG GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED ACCIDENT REPORT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB6918D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE

Name of Driver	KALYANASUNDARAM RAJKAMAL
NRIC/Passport Number	G6520384M
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

K: SKP2229E.

B: 68B6918D

SHOULDER



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was stuck in a jam above SLE towards city ~~at~~ at the 2nd lane. Traffic was almost at a standstill when suddenly I felt a bump at the back of my car. I stepped out and found out a lorry had hit the back of my car. There are no injuries sustained on me and my colleagues/passengers.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.

Individual Statement

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/PPN No:

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SKP 2229E

Vehicle Model : MAZDA 3

Chassis Number : JM6BM42A8F0138122

Estimated Repair Cost

S/N	Parts Description	Qty	List Price
1	BOOT LID	1	958.00 X SUC
2	BOOT LID "MAZDA" LOGO	1	75.00 X NN
3	BOOT LID "MAZDA 3" EMBLEM	1	54.00 X NN
4	BOOT LID "SKYACTIV" EMBLEM	1	64.00 X NN
5	BOOT LID WEATHERSTRIP	1	130.00 X NN
6	BOOT LID LOCK	1	178.00 X SUC
7	BOOT LID LAMP LH & RH	2	530.00 X SUC
8	TAIL LAMP LH & RH	2	1020.00 X SUC
9	REAR BUMPER 1074.80	1	1075.00 / CRK
10	REAR BUMPER CLIPS	10 PCS	50.00 / NEL
11	REAR BUMPER RETAINER LH & RH	2	74.00 ? / CRK
12	REAR BUMPER REINFORCEMENT 541.70	1	538.00 ? / BT
13	END PANEL 447.60	1	506.00 ? / BT
14	END PANEL UPPER GARNISH	1	86.00 X SUC
15	END PANEL UPPER GARNISH CLIPS	10 PCS	50.00 X SUC
16	SPARE TYRE BOARD	1	350.00 ? X SUC
17	REAR BUMPER REFLECTOR LH & RH	2	102.00 X SUC
18	TOW COVER X 2 \$18	2	\$ 5840.00
			36.00 ? / BT
	Discount Less 20%	\$	1168.00
	List Prices Total	\$	4,672.00

S/N	Special Nett Items:	Qty	
1	REAR NUMBER PLATE WITH HOLDER	1	\$ 60.00 X NN
2	REVERSE SENSOR	1 SET	\$ 350.00 X SUC
	Special Nett Total	\$	410.00
	Spare Part's Total Price	\$	5082.00

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SKP 2229E

Vehicle Model : MAZDA 3

Chassis Number : JM6BM42A8F0138122

S/N	Labour Descriptions	Charges	
1	LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD WHERE NECESSARY; TO STRAIGHTEN & REPAIR BOOT FLOOR PANELS, TO REPLACE DAMAGED PARTS AS LISTED ABOVE	\$ 1800.00	300
2	TO SPRAY PAINTING ON: BOOT LID (INNER & OUTER), REAR BUMPER, REAR END PANEL & BOOT LID FLOOR PANEL	\$ 1500.00	300
3	TO REMOVE & REPLACE REVERSE SENSORS & TEST FUNCTION	\$ 100.00	30
4	TO REMOVE & TRANSFER BOOT LID SERVICEABLE COMPONENTS & TRIMMINGS TO NEW BOOT LID & TEST FUNCTION	\$ 100.00	X NN
5	TO REMOVE & INSTALL BOOT COMPARTMENTS ATTACHMENTS, TRIMMINGS & FITTINGS TO ENABLE REPAIRS	\$ 120.00	X NN
6	TO RESET & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS	\$ 150.00	30
7	TO CHECK ELECTRICAL WIRINGS & REAR LIGHTS FUNCTIONS	\$ 50.00	X NN
Labour Total		\$ 3820.00	
Parts & Labour Total		\$ 8902.00	8930.80

NAZ LKK
24/10/18 1700

3 DAY

CHECK ITEMS PHOTOS

AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18019314/NVD3N2

Date: 26/11/2018

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.

Policy No: DMCVSN1404471804

Claimant Vehicle No: SKP2229E

Insured Vehicle No: GBB6918D

Date of Loss: 15/10/2018

Nature of Claim: TP

Claim No: SNM18D04950C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKP2229E

Make & Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)

Engine No: P520224170

Reg. Date: 25/08/2014 (Man. Year: 2014)

Chassis No: JM6BM42A8F0138122

Colour: Grey

Odometer: 89436 km

Engine Capacity: 1496 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16

Rear Tyre Size: 205/60R16

Front Left Side: Yokohama 4 mm

Rear Left Side: Yokohama 4 mm

Front Right Side: Yokohama 4 mm

Rear Right Side: Yokohama 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	5,110.80	1,776.32	3,334.48	65.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,820.00	660.00	3,160.00	82.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,930.80	2,436.32	6,494.48	72.72
Approved Total (Overridden) (S\$)		1,950.00		
(S\$)	8,930.80	1,950.00	6,980.80	78.17
+ GST 7.00/7.00% (S\$)	625.16	136.50	488.66	78.17
Nett Amount (S\$)	9,555.96	2,086.50	7,469.46	78.17

INSPECTION

Date of Assignment: 23/10/2018

Date Inspected: 24/10/2018 Inspected At:

Elite Automotive Pte Ltd (HQ)
280 Woodlands Industrial Park E5, #01-17, Harvest@Woodlands
Singapore 757322

Estimated Period of Repair: 3.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Nov 2018)
Parts:	143	MAZDA 3 1.5 L 4-DOOR SEDAN SP.6EAT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKP2229E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Serviceable	958.00 FL	*- FL
2	1		*BOOT LID MAZDA LOGO	Not Necessary	75.00 FL	*- FL
3	1		*BOOT LID MAZDA 3 EMBLEM	Not Necessary	54.00 FL	*- FL
4	1		*BOOT LID SKYACTIV EMBLEM	Not Necessary	64.00 FL	*- FL
5	1		*BOOT LID WEATHERSTRIP	Not Necessary	130.00 FL	*- FL
6	1		*BOOT LID LOCK	Serviceable	178.00 FL	*- FL
7	2		*BOOT LID LAMP LH & RH	Serviceable	530.00 FL	*- FL
8	2		*TAIL LAMP LH & RH	Serviceable	1,020.00 FL	*- FL
9	1		*REAR BUMPER	Cracked	1,075.00 FL	*1,074.80 FL
10	10		*REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
11	2		*REAR BUMPER RETAINER LH & RH	Cracked	74.00 FL	*74.00 FL
12	1		*REAR BUMPER REINFORCEMENT	Bent	538.00 FL	*538.00 FL
13	1		*END PANEL	Bent	506.00 FL	*447.60 FL
14	1		*END PANEL UPPER GARNISH	Serviceable	86.00 FL	*- FL
15	10		*END PANEL UPPER GARNISH CLIPS	Serviceable	50.00 FL	*- FL
16	1		*SPARE TYRE BOARD	Serviceable	350.00 FL	*- FL
17	2		*REAR BUMPER REFLECTOR LH & RH	Serviceable	102.00 FL	*- FL
18	2		*TOW COVER	Bent	36.00 FL	*36.00 FL
19	1		*REAR NUMBER PLATE WITH HOLDER	Not Necessary	60.00 FS	*- FS
20	1		*SET REVERSE SENSOR	Serviceable	350.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,286.00	2,220.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,175.20	444.08
Total Parts (\$\$)	5,110.80	1,776.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD WHERE NECESSARY; TO STRAIGHTEN & REPAIR BOOT FLOOR PANELS, TO REPLACE DAMAGED PARTS AS LISTED ABOVE	New	1,800.00	300.00
2	TO SPRAY PAINTING ON; BOOT LID (INNER & OUTER), REAR BUMPER, REAR END PANEL & BOOT LID FLOOR PANEL	New	1,500.00	300.00
3	TO REMOVE & REPLACE REVERSE SENSORS & TEST FUNCTION	New	100.00	30.00
4	TO REMOVE & TRANSFER BOOT LID SERVICEABLE COMPONENTS & TRIMMINGS TO NEW BOOT LID & TEST FUNCTION	New	100.00	-
5	TO REMOVE & INSTALL BOOT COMPARTMENTS ATTACHMENTS, TRIMMINGS & FITTINGS TO ENABLE REPAIRS	New	120.00	-
6	TO RESET & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS	New	150.00	30.00
7	TO CHECK ELECTRICAL WIRINGS & REAR LIGHTS FUNCTIONS	New	50.00	-
Gross Labour Cost (\$\$)			3,820.00	660.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >