

ASS. REC. BY:

REF:

CS3/SM018019318/Ucd3⁸²

Special Instruction:

Surveyor
Menmen

ASSIGNMENT (Office)

From (Person):

The/mu choo

of

SMG

Date/Time:

23/10/18 @ 5:07pm

Estimated Cost:

Bill to:

OD / (IP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE1498R

Insured:

GBE 6179D

at Workshop m/s

Kerentuh Motor

Tel:

92996636

of

14 Batu Lene ID # 01-406

Policy No:

DI8MTHCVE000138

Claim No:

CM1D1804614

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/10/2018

CA / REV / REP. / REV 24 HRS ^(up)

25/10/2018

H.O.D. Endorsement:

Date/Time:

9:59am @ 24/10/18

Person Contacted:

Ah chong

Vehicle IN

(OUT)

Date/Time

Action/Instruction (X) Estimate

GBE1498R - X

GBE 6179D - X

After repair: 24/10/2018

PRS
mercus

REF: SMD

ASSIGNMENT

From: Date: 25-10-2018

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBE 1498R
at Workshop m/s: Jementah Motor
of 14 Defu Lane 10 #01-406

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: 2 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

10/18

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBE/498R Yr Regn: Sep / 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan NV350 C.C. 2488

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 78360 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN1MC2E2620005065

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / (STD)A/Rim or

Tyre Size: F: 195R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSD / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 21/10/18 D.O.I. 25/10/18

Survey held at @ 1025

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

No setting.
2800-3800

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) S+RS SI

) Photos

) Others

TOTAL

Report Format : PRS

Lump Sum / I.B.I. (\$))

Add Fee: ☐ : Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Oct 2018		23 Oct 2018 17:07 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H		
Main Claimant:	WEI JIE ELECTRICAL MOTOR SERVICES, Co. Reg. No.: 52851018E		
Vehicle Reg. No.:	GBE1498R	Date of Loss:	21/10/2018 15:00 - :59
Claim Type:	TP / CMTD1804614	Policy/Cover Note No.:	D18MTHCVE000138 (Third Party Only)
Vehicle Reg. No. (Insured):	GBE6179D	Policy No. (Claimant):	
		Excess:	
Repairer:	Jementah Motor Works (HQ) 14 Defu Lane 10, #01-406, 539195 Defu Lane - Tel: 92996636		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 01/11/2018]		
Driver/Custodian (Insured):	LIM SIEW HOCK (), NRIC: S0121089J, Tel: +6597109583		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Bone?
No results.									

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 23 October 2018 5:06 PM
To: Lheny; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Choo, Thelma; Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD1804614/THE - SUV(LKK)/ GBE6179D & GBE1498R ON 21.10.2018

Our Reference: CMTD1804614/THE

Your Reference: CY. GBE1498R. 18.JM(HW).wp(Lh)

Date: 23rd October 2018

Without Prejudice

EMAIL ONLY

Attention:
M/S C YOGARAJAH LLC

Dear Lheny,

ACCIDENT INVOLVING GBE6179D & GBE1498R ON 21.10.2018

We refer to your email reply of today.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Lheny [mailto:lheny@yoga-legal.com]

Sent: Tuesday, October 23, 2018 4:50 PM

To: Teo, Grace

Cc: Choo, Thelma; Ye, Yong Kang Melvin; Henry, Irene James

Subject: RE: CMTD1804614/THE - PRI/ GBE6179D & GBE1498R ON 21.10.2018

WITHOUT PREJUDICE

Dear Grace Teo

We refer to your email on the even date.

Please be informed that we are not agreeable to your proposed motor surveyors. Instead we propose you choose a surveyor from our list of surveyors as appended below:-

1. Dennis Yap
2. Alan Chong
3. Winson Goh

Please be informed that if we do not hear from you **within 2 working days** from the date hereof, we will assume, as per the Protocol, that you have no objections to our list of motor surveyors you will be deemed to have agreed to the any of the above motor surveyors as a "single joint expert".

We will accordingly inform you who the "single joint expert" is to facilitate your conduct of a pre-repair survey.

Best regards,

Lheny

M/s C YOGARAJAH LLC
883 North Bridge Road
#19-05 Southbank
Singapore 198785

Tel: 6292 5838

Fax: 6292 5938

Email: lheny@yoga-legal.com

From: Teo, Grace [mailto:grace.teo@sompo.com.sg]
Sent: Tuesday, 23 October, 2018 4:48 PM
To: lheny@yoga-legal.com
Cc: Choo, Thelma; Ye, Yong Kang Melvin; Henry, Irene James
Subject: CMTD1804614/THE - PRI/ GBE6179D & GBE1498R ON 21.10.2018

Our Reference: CMTD1804614/THE

Your Reference: CY. GBE1498R. 18.JM(HW).wp(Lh)

Date: 23rd October 2018

Without Prejudice
EMAIL ONLY

Attention:
M/S C YOGARAJAH LLC

Dear Lheny,

ACCIDENT INVOLVING GBE6179D & GBE1498R ON 21.10.2018

We refer to your Notice of Accident dated 23/10/2018 via fax.

Kindly re-direct your future motor claims survey request to motorsurvey@sompo.com.sg

Please be informed that Ms. Thelma Choo is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	

4	JP Knights Adjusters & Surveyors	Jason Lek	
5	In House surveyor	Teo See Ling	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy



SINGAPORE POLICE FORCE



T/20181021/2054

1 of 3

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

Report No: T/20181021/2054

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/10/2018 16:39	Vide Report No.: J/20181021/0175	Station Diary No.: 64
--	-------------------------------------	--------------------------

Informant's Particulars

Informant's Particulars				
Name of Informant: HAN LEI			Address: C/O 2A Second Chin Bee Rd SINGAPORE 618781	
ID Type / ID No.: FIN NO / G2560797Q			Contact No.: Home/Office: Mobile: 94274264	
Nationality: CHINESE			Email:	
Sex: Male	Age: 27	Date of Birth: 01/01/1991	Type of Informant: Driver	
Race: Chinese			Language: Chinese	Institution / School Name:
Occupation: TECHNICIAN			Driving Licence Information: Class:	Date of Expiry:

General Information of the Accident

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 21/10/2018 15:15	Type of Location:
Location: Junction of Road 1 and Road 2 BOON LAY WAY BOON LAY AVENUE				
Weather:		Road Surface:	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision:			Anyone conveyed by ambulance: Yes	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBE1498R	Van	NISSAN		Black	Slightly Damaged	3
GBE6179D	Lorry	TOYOTA		White	Seriously Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE
POLICE FORCE**



T/20181021/2054

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

2 of 3

Report No. T/20181021/2054

CONTINUATION OF REPORT

Driver			
Name	HAN LEI	ID No.	G2560797Q
Related Vehicle	NIL	Contact No.	94274264
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the above mentioned date, time and location, I was driving my vehicle (GBE1498R) along Jln Boon Lay. I stopped at traffic light and waiting for the traffic light to turn into Boon Lay Avenue. Out of sudden, There was a vehicle(GBE6179D) from the opposite lane on Jln Boon Lay crashed on the road barrier. The road barrier then hit on my vehicle's right rear body panel. There was some scratches and dents on my vehicle's right rear body panel. Traffic police was at scene and advised me to lodge a police report. Vide report: J/20181021/0175. There was a pedestrian involved in this accident and conveyed by ambulance. My passengers and I do not need any medical attention. There was in car camera in my vehicle and SD card was already taken by Traffic Police.



**SINGAPORE
POLICE FORCE**



T/20181021/2054

3 of 3

Report No. T/20181021/2054

Police Station Of Origin:

Jurong West N.P.C

700 Corporation Road SINGAPORE 649818

Tel No: 1800-2689999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 1 LIM JUNJIE

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

SI THABAGESH JEYATHESH

Contact No.: 65476232

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

21/10/2018 16:39

Classification Of Case:

SN 126

[> Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details

Vehicle No. :	GBE1498R
Vehicle Type :	A50 - Goods (Closed) Van/Van Panel (Delivery)
Vehicle Attachment 1 :	No Attachment
Vehicle Scheme :	Normal
Vehicle Make :	NISSAN
Vehicle Model :	NV350 PANEL VAN 2.5 5MT 5DR EURO V
Chassis No. :	JN1MC2E26Z0005065
Propellant :	Diesel
Engine No. :	YD25380117A
Engine Capacity :	2488 cc
Maximum Power Output :	-
Maximum Laden Weight :	3300 kg
Unladen Weight :	1800 kg
Year Of Manufacture :	2015
Original Registration Date :	16 Sep 2015
Lifespan Expiry Date :	15 Sep 2035
COE Category :	C - Goods Vehicle & Bus
Quota Premium :	\$49,302.00
COE Expiry Date :	15 Sep 2025
Road Tax Expiry Date :	15 Sep 2019
Inspection Due Date :	15 Sep 2019
Intended Transfer Date :	26 Oct 2018
CO2 Emission :	232.00 (g/km)
CEV/VES Rebate Utilised Amount :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

Amount Payable

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	1018E
Vehicle Details	
Vehicle No.:	GBE1498R
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Oct 2018
Vehicle Make:	NISSAN
Vehicle Model:	NV350 PANEL VAN 2.5 5MT 5DR EURO V
Primary Colour:	Brown
Manufacturing Year:	2015
Engine No.:	YD25380117A
Chassis No.:	JN1MC2E26Z0005065
Maximum Power Output:	-
Open Market Value:	\$22,481.00
Original Registration Date:	16 Sep 2015
First Registration Date:	16 Sep 2015
Transfer Count:	0
Actual ARF Paid:	\$1,125.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Sep 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$49,302.00
COE Rebate Amount:	\$33,961.00
Total Rebate Amount:	\$33,961.00

The information contained herein is correct as at 26 Oct 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Oct 2018		23 Oct 2018 17:07 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H		
Main Claimant:	WEI JIE ELECTRICAL MOTOR SERVICES, Co. Reg. No.: 52851018E		
Vehicle Reg. No.:	GBE1498R	Date of Loss:	21/10/2018 15:00 - :59 [37 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1804614	Policy/Cover Note No.:	D18MTHCVE000138 (Third Party Only)
Vehicle Reg. No. (Insured):	GBE6179D	Policy No. (Claimant):	
		Excess:	
Repairer:	Jementah Motor Works (HQ) 14 Defu Lane 10, #01-406, 539195 Defu Lane - Tel: 92996636		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by Thelma Choo - 6322 4681]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 01/11/2018]		
Driver/Custodian (Insured):	LIM SIEW HOCK (), NRIC: S0121089J, Tel: +6597109583		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***GBE1498R (CMTD1804614)**
[GBE6179D]

TP

WEI JIE ELECTRICAL MOTOR SERVICES

Oct 21 2018 3:00PM

[ETHOZ GROUP LTD]


Jementah Motor Works

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼






























Assessment Reports















1 per page ▼ ☒

No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	23/10/18 17:07	Accident Statement From: SC - Reg. No: GBE6179D, Claimant: ETHOZ GROUP LTD	 Load HTM	<input type="checkbox"/>

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
22	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
23	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
24	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
25	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
26	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
27	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
28	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
29	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
30	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
31	28/10/18 12:59	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
32	28/10/18 12:59	General View	 Load JPG	✓
33	28/10/18 12:59	General View	 Load JPG	✓
34	30/10/18 15:57	Photo After Spray	 Load JPG	✓
35	30/10/18 15:57	Photo After Spray	 Load JPG	✓
36	30/10/18 15:57	Photo After Spray	 Load JPG	✓
37	30/10/18 15:57	Photo After Spray	 Load JPG	✓
38	30/10/18 15:57	Photo After Spray	 Load JPG	✓
39	30/10/18 15:57	Photo After Spray	 Load JPG	✓
40	30/10/18 15:57	Photo After Spray	 Load JPG	✓
41	30/10/18 15:57	Photo After Spray	 Load JPG	✓
42	30/10/18 15:57	Photo After Spray	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	23/10/18 14:28	FAX FR C YOGARAJAH LLC FOR SURVEY - GBE1498R From: SC - Reg. No: GBE6179D, Claimant: ETHOZ GROUP LTD	 Load PDF	
2	23/10/18 16:48	Third Party E-filed GIA report	 Load PDF	
3	23/10/18 17:06	Pre-Repair Survey ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO18019318/UCD3S2

Date: 02/11/2018

REFERENCE

Handling Insurer: Somp Insurance Singapore Pte. Ltd. Policy No: D18MTHCVE000138
 Claimant Vehicle No: GBE1498R Insured Vehicle No: GBE6179D
 Date of Loss: 21/10/2018 Nature of Claim: TP Claim No: CMTD1804614

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE1498R
 Make & Model: NISSAN NV350, 2.5 (A) Engine No: YD25380117A
 Reg. Date: 16/09/2015 (Man. Year: 2015) Chassis No: JN1MC2E26Z0005065
 Colour: Black Odometer: 78360 km
 Engine Capacity: 2488 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
 Front Left Side: OHTSU 6 mm Rear Left Side: OHTSU 6 mm
 Front Right Side: OHTSU 6 mm Rear Right Side: OHTSU 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 23/10/2018
 Date Inspected: 25/10/2018 Inspected At: Jementah Motor Works (HQ)
 14 Defu Lane 10, #01-406
 Singapore 539195
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,800.00 - \$3,800.00

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Nov 2018)	
Parts:	N/A	NISSAN NV350 2.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE1498R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >