

22/03/2002

SS. REC. BY:

REF:

CS3 / ALH18019320 / Gcbez

Special Instruction:

Survivor:

G02

ASSIGNMENT (Office)

From (Person):

Chin Lee Yng

of

ALH

Date/Time:

24/02/08 1037am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

Ym 8964 B

Insured:

SKX 7647G

at Workshop m/s

Kent Auto

Tel:

9754 7573

of

Blk 2 Kaki Bukit Ave 2 #01-21

Policy No:

0999994449

Claim No:

48600573303G

Sum Insured:

Excess:

Make of Veh:

D.O.A.

17/02/08

(Client's Record)

CA / REV / REP. / REV 24 HRS' WP

H.O.D. Endorsement:

Date/Time:

24/02/08

Person Contacted:

Kent

Vehicle IN / OUT

Date/Time

Action/Instruction (X) Estimate

Ym 8964 B - x

SKX 7647G - x

Dismantle: 25/10/2018

After repair: 29/10/2018

PKS
Karl.

REF:

Alb

B800C

(-2023)

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

Kent Anto

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est Repairs: 5 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

YM8964B

Yr Regn:

04 Sep 2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit Fuso

C.C

2977

Colour:

white

A/C:

Insured / Std / NI / NA

Sp.Reading

355402

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

FE 84B BA 102 45

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

7.00 R16 (Kajah Tunge)

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Delium (Kear)

Front

Rear

R/Bal.

5

mm

R/Bal.

5/5

mm

L/Bal.

5

mm

L/Bal.

5/5

mm

D.O.A.

D.O.I.

24-10-18

Survey held at

w/s

4:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

1/11

~~\$4000~~ ~~\$5000~~
Submit DAR report.

RECEIVED 01 NOV 2010

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format: DAR.

Lump Sum / I.B.I: (\$

180

20

200

-PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 24/10/2018 10:37:39 AM
Attachments:  tmp21EF.TIF

Hi KK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

Claims | AIG Asia Pacific Insurance Pte. Ltd.
Raffles Way #08-16 Singapore 079120
Tel: +(65) 6419 1947 | Fax +(65) 6835 7416
Email: Lee.Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not disseminate the information. If you have received this email in error, please immediately notify me by "Reply" and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

883 North Bridge Road
#11-03 Southbank
Singapore 198705
Tel: 6292 5938
Fax: 6292 5939
(Call Now No: 201353127N)

Our Ref : CY.YIM8964B.18.KA.wp(Lh)

Your Ref : Your insured vehicle SKX 7647G

23 October 2018

BLUE STAR CONCEIRGE PTE LTD
c/o The Motor Claims Department
AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way #07-16
Singapore 079120

By Fax No: 6835 7416

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES YM 8964B & SKX 7647G ON 17.10.2018 @ 15:20HRS ALONG PORTSDOWN ROAD

We are instructed by ONG FENCING CONTRACTOR CO to notify you of a road traffic accident on 17.10.2018 @ 15:20hrs along Portsdown Road involving our client's vehicle registration number YM 8964B and vehicle registration number SKX 7647G driven by you at the material time.

As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully,


C. Yogarajah) LLC
Enc

cc: M/s Kent Auto Services
2 Kaki Bukit Ave 2
#01 - 21 Kaki Bukit Auto Hub
Singapore 417921
Mr. Kent Tan (9754 7573 / 6741 2539)
By fax 6741 2539

Confidentiality & Privilege: This message is intended for the recipient to whom it is addressed. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not send copy or circulate this communication. Disclaimer: Mail/Fax/Internet communication is not secure. C. Yogarajah LLC cannot be responsible for alterations made to the contents of communication without its express consent. If you wish to receive a hard copy of this communication for comparison or should you require any other form of confirmation of the contents of this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the firm shall be understood as neither given nor endorsed by C. Yogarajah LLC Advocates & Solicitors. Thank you.

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	1800C
Vehicle Details	
Vehicle No.:	YM8964B
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Oct 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	FE84BE6SRDEA
Primary Colour:	White
Manufacturing Year:	2008
Engine No.:	4M42A61713
Chassis No.:	FE84BEA10245
Maximum Power Output:	-
Open Market Value:	\$27,670.00
Original Registration Date:	04 Sep 2008
First Registration Date:	04 Sep 2008
Transfer Count:	1
Actual ARF Paid:	\$1,384.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	03 Sep 2023
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$15,348.00
COE Rebate Amount:	\$14,911.00
Total Rebate Amount:	\$14,911.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 25 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/10/2018 15:49
Date Of Accident	17/10/2018 15:20
Exact Location Of Accident	PORTSDOWN ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YM8964B
-----------------------------	---------

Insured/Policyholder

Name Of Registered Owner	ONG FENCING CONTRACTOR CO
Co Reg No	NA
Email Address	ONGFENCE@SINGNET.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-64816663

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FE84

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	CN51001405
Cover Note Number	

Driver

Name of Driver	LIM GUEK SENG
NRIC No	S1578988C
Date Of Birth	09/08/1963
Occupation	OUTDOOR
Date Of Driving Pass	12/10/1983
Driving Experience	35 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81125123
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	BLK 144 SERANGOON NORTH AVENUE 1 #06-361
Postcode	550144
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - MAJOR/MINOR RD
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT RECORDED BY LILY - PROGRESSIVE CAR CARE PTE LTD 67415336

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKX7647G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	MARIMUTHU ULAGUSUNDARAM
NRIC/Passport Number	S7867992A
Contact Number	88332702
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any false or untrue information reported may result in the policyholder being liable to repudiate policy liability.
4. If the accident is a major one, it is a criminal offence to fail to report the accident to the police. It is also a criminal offence to provide false information to the police.
5. Any false reporting may be referred to the police for investigation.
6. The policyholder is responsible for the accuracy of the information provided. If the policyholder is not the Authorised Driver, the policyholder must ensure that the Authorised Driver is aware of the information provided and that the Authorised Driver is responsible for the accuracy of the information provided.
7. The policyholder is responsible for the accuracy of the information provided. If the policyholder is not the Authorised Driver, the policyholder must ensure that the Authorised Driver is aware of the information provided and that the Authorised Driver is responsible for the accuracy of the information provided.

Signature of the Policyholder or Authorised Driver:

Signature of the Witness (if applicable):

Signature of the Authorised Driver (if applicable):

Signature of the Police Officer (if applicable):

Signature of the Insurance Company Representative (if applicable):

Signature of the Other Party (if applicable):

Signature of the Other Party (if applicable):

Signature of the Other Party (if applicable):

Signature of the Other Party (if applicable):

Signature of the Other Party (if applicable):

Signature of the Other Party (if applicable):

Signature of the Other Party (if applicable):

Signature of the Other Party (if applicable):

Signature of the Other Party (if applicable):

Signature of the Other Party (if applicable):

Signature of the Other Party (if applicable):

Signature of the Other Party (if applicable):

Signature of the Other Party (if applicable):

19/10/18

Sketch Plan #2

SKETCH PLAN

		Vehicle A - B -
		Legend

DETAILED CIRCUMSTANCES OF THE ACCIDENT

I was travelling along Main Rd (Portsmouth Rd).

Car B Suddenly dash out from left side.

Without stopping hitting the front of my

car causing damage.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

I/We declare that I/We are not a member of the public and that I/We are not a member of the public and that I/We are not a member of the public.

Policyholder's Signature	Driver's Signature	Reporting Centre Personnel's Signature
Date & Time	(If driver is not the policyholder) Date & Time	Name NRIC/ID No

19/10/18.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1578988C



Name
LIM GUEK SENG
林月星

Race
CHINESE

Date of birth
09-08-1963

Sex
M

Country/Place of birth
SINGAPORE

51578988C



REPUBLIC OF SINGAPORE DRIVING LICENCE




6005411



NRIC No. S1578988C




Date of issue
21-08-2018

Address
APT BLK 144 SERANGOON NORTH AVENUE 1
#06-361
SINGAPORE 550144

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

Class	Description	Valid Until
Class 3	Motor Cars of unladen weight not exceeding 3000 kg with not more than 7 passengers, exclusive of the driver; and Motor Tractors and other Motor Vehicles of unladen weight not exceeding 2500 kg	12 Oct 1983
Class 4	Heavy Motor Cars and Motor Tractors the weight of which unladen exceeds 2500 kg	19 Sep 1986

License No: S1578988C



Accident Photo



Accident Photo





Accident Photo



VAN / HARRY (Frt)

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate	BT	✓	
1002	991887	Frt Number Plate Base			
1004	991300	Frt Bumper	DD	✓	
2001	991477	Frt Bumper Upper			
2002	991387	Frt Bumper Lower			
2003	991449	Frt Bumper Side Cover			
2004	991443	Frt Bumper Side			
1006	991325	Frt Bumper Bracket	BT	✓	
1008	991433	Frt Bumper Reinforcement			
2005	991466	Frt Bumper Signal Lamp			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	CRA	✓	
1022	991328	Frt Grille Emblem	NEC	✓	
2006	990247	Frt Grille Sticker			
1023	991799	Frt Grille Chrome Moulding			
2007	991891	Frt Panel	BUC	✓	
2008	991874	Frt Lower Panel			
2009	991328	Frt Panel Emblem	NEC	✓	
2010	990247	Frt Panel Sticker			
2011	991893	Frt Panel <i>Company Logo</i>	NEC	✓	
1024	991222	Frt Apron Panel			
2012	991527	Frt Corner Panel RH	DD	✓	
2013	991532	Frt Corner Panel Signal Lamp			
2014	995245	Frt Signal Lamp LH			
2015	995246	Frt Signal Lamp RH	CRA	✓	
1029	995153	Frt LH Headlamp Assy			
1030	991821	Frt RH Headlamp Assy	CRA	✓	
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp	CRA	✓	
2016	992149	Frt Wiper Panel			
2017	995043	Frt Wiper Nozzle			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
2018	992145	Frt Wiper Link			
2019	992148	Frt Wiper Motor			
1122	995045	Wiper Panel Garnish			
1114	992093	Frt Windscreen			
1115	992097	Frt Windscreen Rubber	NEC	✓	
1117	992098	Frt Windscreen Sealant			
2020	992114	Frt Windscreen Outer Pillar			
2021	992113	Frt Windscreen Inner Pillar			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
2022	991958	Frt Side Mirror (Big)	BT	✓	
2023	991959	Frt Side Mirror (Small)			
2024	991962	Frt Side Mirror (Round)			
2025	995015	Frt Wing Mirror Stay <i>Garnish</i>	CUT	✓	
1025	992013	Frt Support Panel	BUCR	✓	
1033	990248	Bonnet			
1035	990287	Bonnet Lock			
1037	990273	Bonnet Hinge			
1039	990305	Bonnet Rubber			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1056	992758	Radiator Hose Top			
1058	992741	Radiator Expansion Tank			
2026	992596	Oil Cooler			
1079	994431	Power Steering Cooler Pipe			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1067	990219	Battery			
1069	990213	Battery Bracket			

Vehicle No: YM 8964 B

NAC	INC	Item	CON	AC	Qty
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
2027	991500	Frt Cabin Assy			
2028	991501	Frt Cabin Mounting			
2029	991502	Frt Cabin Rear Panel			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
2030	990143	Air Con Evaporator Assy			
2031	990106	Air Con Blower			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
2032	990431	Brake Pedal			
2033	990021	Accelerator Pedal			
2034	990627	Clutch Pedal			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1131	990029	Airbag Control Unit			
1133	991922	Frt RH Seat Belt Assy			
1135	995182	Frt LH Seat Belt Assy			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
2035	994966	Frt LH Wheel Guard			
1102	995170	Frt LH Wheel Rim			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
2036	994966	Frt RH Wheel Guard			
1111	992087	Frt RH Wheel Rim			
1113	995065	Frt RH Tyre			
1255	995326	Frt LH Door			
1256	995140	Frt LH Door Protector			
1257	995104	Frt LH Door Hinge			
1258	995142	Frt LH Door Wing Mirror			
1262	995103	Frt LH Door Glass			
1263	991595	Frt LH Door Glass Regulator			
1264	991596	Frt LH Door Glass Regulator Motor			
1265	991662	Frt LH Door Rubber			
1266	991636	Frt LH Door Outer Handle			
1272	991617	Frt LH Door Inner Trim Board			
1316	995327	Frt RH Door			
1317	991654	Frt RH Door Protector			
1318	991601	Frt RH Door Hinge			
1319	991685	Frt RH Door Wing Mirror			
1323	991584	Frt RH Door Glass			
1324	991595	Frt RH Door Glass Regulator			
1325	991596	Frt RH Door Glass Regulator Motor			
1326	991662	Frt RH Door Rubber			
1327	991636	Frt RH Door Outer Handle			
1333	991617	Frt RH Door Inner Trim Board			
2037	991644	Frt Door Frt Pillar			
2038	991657	Frt Door Rear Pillar			
2039	992072	Frt Wheel Arch Panel			
2040	992069	Frt Wheel Arch Panel Garnish			
2041	991996	Frt Step Panel			
2042	994498	Frt Step Panel Top Garnish			
2043	994495	Frt Step Panel Inner Garnish			
1073	995053	Wiper Washer Tank			
1136	990247	Sticker			

No of Items:

Assessor:

31/10/2018

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Oct 2018 Edit Reg		24 Oct 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]			
Insured:	BLUE STAR CONCIERGE PTE LTD, Co. Reg. No.: 201506692D				
Main Claimant:	ONG FENCING CONTRACTOR CO				
Vehicle Reg. No.:	YM8964B	Date of Loss:	17/10/2018 15:00 - :59 [121 Months and 13 Days From LTA Reg Date (Man Yr)]		
Claim Type:	TP / 4860057330SG	Policy/Cover Note No.:	0999994449 (Comprehensive)		
Vehicle Reg. No. (Insured):	SKX7647G	Policy No. (Claimant):			
		Excess:			
Repairer:	Kent Auto Services - Kaki Bukit (HQ) BLOCK 2 KAKI BUKIT AVE 2, #01-21 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel:				
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah] Norsiah.MdNoor@aig.com				
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 05/11/2018]				
Claimant's Solicitor:	C YOGARAJAH LLC - Tel: 62925838				

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
AIG_SG (26/10/2018): Request to upload TP GIA Report		

ALL ASSOCIATED TASKS	View All	Search Tasks	Create New Task	Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***YM8964B (4860057330SG)**
[SKX7647G]
TP
ONG FENCING CONTRACTOR CO
Oct 17 2018 3:00PM
[BLUE STAR CONCIERGE PTE LTD]
Kent Auto Services - Kaki Bukit

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		v	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)														Thumbnail	Print	
1	27/10/18 14:26	General View														Load JPG	☒	
2	27/10/18 14:26	General View														Load JPG	☒	
3	27/10/18 14:26	General View														Load JPG	☒	
4	27/10/18 14:26	General View														Load JPG	☒	
5	27/10/18 14:26	General View														Load JPG	☒	
6	27/10/18 14:26	General View														Load JPG	☒	
7	27/10/18 14:26	General View														Load JPG	☒	
8	27/10/18 14:26	General View														Load JPG	☒	
9	27/10/18 14:26	General View														Load JPG	☒	
10	27/10/18 14:26	General View														Load JPG	☒	
11	27/10/18 14:26	General View														Load JPG	☒	
12	27/10/18 14:26	General View														Load JPG	☒	
13	27/10/18 14:26	General View														Load JPG	☒	
14	27/10/18 14:26	General View														Load JPG	☒	
15	27/10/18 14:26	General View														Load JPG	☒	
16	27/10/18 14:26	General View														Load JPG	☒	
17	27/10/18 14:26	General View														Load JPG	☒	
18	27/10/18 14:26	General View														Load JPG	☒	
19	27/10/18 14:26	General View														Load JPG	☒	
20	27/10/18 14:26	General View														Load JPG	☒	
21	27/10/18 14:26	Photographs of Damaged Parts														Load JPG	☒	
22	27/10/18 14:26	Photographs of Damaged Parts														Load JPG	☒	
23	27/10/18 14:26	Photographs of Damaged Parts														Load JPG	☒	
24	27/10/18 14:26	Photographs of Damaged Parts														Load JPG	☒	
25	27/10/18 14:26	Photographs of Damaged Parts														Load JPG	☒	
26	27/10/18 14:26	Photographs of Damaged Parts														Load JPG	☒	
27	27/10/18 14:26	Photographs of Damaged Parts														Load JPG	☒	
28	27/10/18 14:26	Photographs of Damaged Parts														Load JPG	☒	
29	27/10/18 14:26	Photographs of Damaged Parts														Load JPG	☒	
30	27/10/18 14:26	Photographs of Damaged Parts														Load JPG	☒	
31	27/10/18 14:26	Photographs of Damaged Parts														Load JPG	☒	
32	27/10/18 14:26	Photographs of Damaged Parts														Load JPG	☒	
33	27/10/18 14:26	Photographs of Damaged Parts														Load JPG	☒	
34	27/10/18 14:26	Photographs of Damaged Parts														Load JPG	☒	
35	27/10/18 14:26	Photographs of Damaged Parts														Load JPG	☒	
36	27/10/18 14:26	Photographs of Damaged Parts														Load JPG	☒	
37	27/10/18 14:26	Photographs of Damaged Parts														Load JPG	☒	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	27/10/18 14:26	Photographs of Damaged Parts	 Load JPG	☒
39	27/10/18 14:26	Photographs of Damaged Parts	 Load JPG	☒
40	27/10/18 14:26	Photographs of Damaged Parts	 Load JPG	☒
41	31/10/18 18:11	Photo After Spray	 Load JPG	☒
42	31/10/18 18:11	Photo After Spray	 Load JPG	☒
43	31/10/18 18:11	Photo After Spray	 Load JPG	☒
44	31/10/18 18:11	Photo After Spray	 Load JPG	☒
45	31/10/18 18:11	Photo After Spray	 Load JPG	☒
46	31/10/18 18:11	Photo After Spray	 Load JPG	☒
47	31/10/18 18:11	Photo After Spray	 Load JPG	☒
48	31/10/18 18:11	Photo After Spray	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	26/10/18 10:01	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18019320/GCBE2

Date: 14/11/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994449
 Claimant Vehicle No: YM8964B Insured Vehicle No: SKX7647G
 Date of Loss: 17/10/2018 Nature of Claim: TP Claim No: 4860057330SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YM8964B**
 Make & Model: MITSUBISHI FE84BE6SRDEA, 3.0 D B30 (A) Engine No: 4M42A61713
 Reg. Date: 04/09/2008 (Man. Year: 2008) Chassis No: FE84BEA10245
 Colour: White Odometer: 355402 km
 Engine Capacity: 2977 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 7.00 R16 Rear Tyre Size: 7.00 R16 (D)
 Front Left Side: Gajah Tunggal 5 mm Rear Left Side: Delium 5/5 mm
 Front Right Side: Gajah Tunggal 5 mm Rear Right Side: Delium 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 24/10/2018
 Date Inspected: 24/10/2018 Inspected At: Kent Auto Services - Kaki Bukit (HQ)
 BLOCK 2 KAKI BUKIT AVE 2, #01-21
 KAKI BUKIT AUTOHUB
 Singapore 417921
 Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRT BUMPER	Dented	0.00 F	*- F
3	1		*FRT BUMPER BRACKET	Bent	0.00 F	*- F
4	1		*FRT GRILLE	Cracked	0.00 F	*- F
5	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
6	1		*FRT PANEL	Buckled	0.00 F	*- F
7	1		*FRT PANEL EMBLEM	Necessary	0.00 F	*- F
8	1		*FRT PANEL COMPANY LOGO	Necessary	0.00 F	*- F
9	1		*FRT CORNER PANEL RH	Dented	0.00 F	*- F
10	1		*FRT SIGNAL LAMP RH	Cracked	0.00 F	*- F
11	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
12	1		*FRT RH SIDE LAMP	Cracked	0.00 F	*- F
13	1		*FRT WINDSCREEN RUBBER	Necessary	0.00 F	*- F
14	1		*FRT SIDE MIRROR (BIG)	Bent	0.00 F	*- F
15	1		*FRT WING MIRROR STAY GARNISH	Cut	0.00 F	*- F
16	1		*FRT SUPPORT PANEL	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >