

ASS. REC. BY:

REF:

CS/FCL18019340/Urban2

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Lurene jaw

of

FCI

Date/Time:

25/10/18 @ 9:40am

Estimated Cost:

Bill to:

OD / TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBH 5884S

Insured:

SHA 279M

at Workshop m/s

Erofia Motor

Tel:

67527740

of

1 Kaki Bkt Ave 6 #02-62

Policy No:

Claim No:

D18006796MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

11/01/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

10:09am @ 25/10/18

Person Contacted:

De Lee

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (✓) Estimate

FBH 5884S - X

SHA 279M - NG / INC 18014269 / Klubnz

DQA: 030818

Revert IA thru email.

Director (M/M)

REF:

701 /

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No. FBH5884S
 at Workshop m/s Enofu
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 4/2
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS LTAS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No. FBH5884S Yr Regn: 7.13
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: BAJAJ PULSAR C.C. 200
 Colour: Orange A/C. Insured / Std / NI / NA
 Sp. Reading: Setting flap T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MD2A36F200CC89354
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 110 / 70 - 17
 R: 140 / 70 - 17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front: _____ Rear: _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. 11/9/18 D.O.I. 24/10/18
 Survey held at: _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S, O/S only
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
4 yrs. 10th.

31/10/18 45 @ 2100 cont. and with MR 120
Red: 81548.20, 42%.

RECEIVED 01 NOV 2018

Date/Time, File Pass to? ☐ : Preli. Report
☒ : Final Report

1) typist
 Date/Time, File Return to?
 2) _____

Report Format: TP
 Lump Sum / ~~1st~~ (\$) 2100

Days Of Repair: 4
 Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp. (\$) ☐ : Interview (\$) ☐ : Tech. Invs (\$) ☐ : Weekend (\$)

Survey Fee: 130
 Transportation 50
) S + RS. \$ 50
) Photos 96
) Others _____

TOTAL

326

Your Ref: D18006796MFSHDate: 26 October 2018Our Ref: CS/FCI18019340/Urd3The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. FBH 5884S.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24/10/2018 at the premises of M/s EROFIA MOTOR PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,648.20</u>
Revised Estimate Amount	: S\$ <u>1,586.20</u>
"Check" Items Amount	: S\$ <u>1,178.20</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
at the n/s and o/s body.



Yours faithfully

MARCUS
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	13-09-2018	Our Ref No. D18006796MFSH
Accident Date	11-09-2018	Claim Type. Third Party
Insured Vehicle	SHA0279M	Third Party Vehicle. FBH5884S
Survey Location	1 KAKI BUKIT AVE 6 #02-62 AUTOBAY @ KAKI BUKIT	
Contact Person.	LEELEE TAN	
Contact No.	67527740/ 97761091	Fax No. 67528669
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	EROFIA MOTOR TRADING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Friday, October 26, 2018 2:55 PM
To: 'CWS Motor Claims'; assignments
Cc: 'Lurene Jaw'; SUR
Subject: RE: SURVEY ASSESSMENT - D18006796MFSH/1
Attachments: FBH 5884S.pdf

Dear Sir/ Madam,

Enclosed preliminary revised for FBH 5884S.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, October 25, 2018 10:10 AM
To: 'CWS Motor Claims' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: 'Lurene Jaw' <LureneJaw@msfirstcapital.com.sg>; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18006796MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: CWS Motor Claims [mailto:cwsmotorclaims@msfirstcapital.com.sg]
Sent: Thursday, 25 October 2018 9:40 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWS Motor Claims <cwsmotorclaims@msfirstcapital.com.sg>; Lurene Jaw <LureneJaw@msfirstcapital.com.sg>
Subject: PRI: SURVEY ASSESSMENT - D18006796MFSH/1

Dear Sir/Mdm,

We refer to the above reference.


Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Note: All the accident reports are uploaded into CWS for your perusal.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.



This email has been checked for viruses by AVG antivirus software.
www.avg.com



**SINGAPORE
POLICE FORCE**



T/20180912/2213

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

Report No. T/20180912/2213

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 12/09/2018 23:08		Vide Report No.: A/20180911/0092		Station Diary No.: 274	
Informant's Particulars					
Name of Informant: RAFLY RAMADHAN			Address: APT BLK 817 JURONG WEST STREET 81 #05-28 SINGAPORE 640817		
ID Type / ID No.: NRIC NO / S9350654E			Contact No.: Home/Office: Mobile: 87499820		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 25	Date of Birth: 14/03/1993	Type of Informant: Rider		
Race: Javanese			Language:		Institution / School Name:
Occupation: SPORT ADVISOR			Driving Licence Information: Class: 2B		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 11/09/2018 12:30	Type of Location: Straight Road
Location: Along Road 1 SYED ALWI ROAD				
Weather: Drizzling	Road Surface: Wet		Road Speed Limit:	
Traffic Flow: Two Way	Traffic Control: Not Controlled		Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No. of Pass.
FBH5884S	Motorcycle	BAJAJ CHETAK	Pulsar 200 NS	Yellow	Seriously Damaged	0
SHA279M	Taxi	HYUNDAI	i40	Yellow	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	Use of Pedestrian Crossing: NA
No. of Pedestrians Injured: NIL	



**SINGAPORE
POLICE FORCE**



T/20180912/2213

2 of 3

Report No. T/20180912/2213

Station Of Origin:
N.P.C
2 Jurong West Avenue 5 SINGAPORE
99882
Tel No: 1800-7929999

CONTINUATION OF REPORT

Rider Name	RAFLY RAMADHAN	ID No.	S9350654E
Related Vehicle	FBH5884S (Motorcycle)	Contact No.	87498820
Hospital/Clinic	RAFFLES HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	11/09/2018	Date Discharge	12/09/2018
No. of Days granted Medical Leave	07	Degree of Injury	Serious
Driver Name	Unknown Driver	ID No.	NIL
Related Vehicle	SHA279M (Taxi)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Treatment	NIL	Date Discharge	NIL
Days granted Medical Leave	NIL	Degree of Injury	NIL

Details.

On 11/09/2018 at about 1230hrs, I was riding my motorcycle registration number: FBH5884S along the left lane of the 04 lanes road of Syed Alwi road. I was travelling at about 60km/hrs. Out of the sudden there was a yellow taxi registration number: SHA279M came out of the left road and was travelling straight. I noticed the taxi driving into my lane, I tried to stop but I was no able to stop in time. My motorcycle then hit the driver's door. I was then knocked to the ground by the impact. Traffic police and ambulance were called to the scene. I suffered abrasion at both leg, bruise at the right wrist and broken left pinkie. I was conveyed to Raffles Hospital and discharged on the following day and I was given 07 days of outpatient leave.

Video incident: A/20180911/0092, TP IO-charge: Shikin, contact number: 6547 6439.



**SINGAPORE
POLICE FORCE**



T/20180212/2213

3 of 3

Report No. T/20180912/2213

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 3 CHEN JIANDA

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Staff Sgt LEE GUANG HUI

Contact No.: 65476138

Authentication Stamp

NP158

Singapore Police Force

Signature Of Informant:

Date/Time:

12/09/2018 23:08

Classification Of Case:



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623
Tel: 6461 6555 : Fax: 6221 3302 : Website: www.sompo.com.sg
Co. Reg. No.: 198905490E : GST Reg. No.: M200903196

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No. : D18MTMC01005673
Insured : RAFLY RAMADHAN
Motor Vehicle (Regn No.) : FBH5884S
Cover : Third Party
Policy Commencement Date : 12 SEPTEMBER 2018 15:28
Policy Expiry Date : 11 SEPTEMBER 2019 23:59
Maximum Liability (Section I) : Third Party
Excess* : NIL
Named Driver 1 : RAFLY RAMADHAN
HIRE PURCHASE OWNER : NIL

* Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*
RAFLY RAMADHAN

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purposes and
(a) by the Insured in person in connection with his business or profession or
(b) in connection with the Insured's business or profession

The Policy does not cover

- (i) Use for hire or reward
- (ii) Use for racing pacemaking, reliability trial or speed-testing
- (iii) Use for the carriage of goods (other than samples) in connection with any trade or business
- (iv) Use for any purpose in connection with the Motor Trade

Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Vehicle within 24 hours of the accident or by the next working day thereof.

For list of Accident Reporting Centres, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6461 6555.

We hereby certify that the Policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Transport Act, 1967 (Malaysia); and (2) the policy terms, conditions and exceptions of the Motorcycle Policy (Ref MCY-MTMC.02)

Sompo Insurance Singapore Pte. Ltd.

Stella

Authorised Signatory

Date/Time of Issue : 12 SEPTEMBER 2018 15:28

ENSURE PTE LTD
Co. Reg. No.: 201017457N
38 Toh Guan Road East
#01-57 Enterprise Hub
Singapore 608581
Tel: 6515 5988 Fax: 6896 6321

IMPORTANT NOTICE

- o Keep the Certificate in your Motor Vehicle;
- o Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act;
- o On the sale of the Motor Vehicle or if for any reason the insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company, if the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189);
- o This Policy will cease to be valid once the Motor Vehicle has been sold to another person. The Policy is not transferable to the new owner of the Motor Vehicle.

Intermediary Code & Name : 11E07901 & ENSURE PTE. LTD. (MOTORCYCLE) CI Code: MY3 JKDSLS4R4JLBMZAJ

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S9350654E**

Name: **RAFLY RAMADHAN**

Birth Date: **14 Mar 1993**

Issue Date: **17 Oct 2016**

002620282A



REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S9350654E



Name: **RAFLY RAMADHAN**

Race: **JAVANESE**

Date of birth: **14-03-1993**

Country/Place of birth: **INDONESIA**

Sex: **M**

S9350654E



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 2B Motorcycles =< 200 cc

EFFECTIVE DATE

18 Jan 2013

NP 428A



Licence No: S9350654E

5983093



NRIC No: **S9350654E**



Date of issue
20-07-2018

Address

**APT BLK B17 JURONG WEST STREET B1
#05-28
SINGAPORE 640817**

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0654E
Vehicle Details	
Vehicle No.:	FBH5884S
Vehicle to be Exported:	No
Intended Deregistration Date:	24 Oct 2018
Vehicle Make:	BAJAJ
Vehicle Model:	PULSAR 200 NS MANUAL
Primary Colour:	Yellow
Manufacturing Year:	2013
Engine No.:	JLZCDB85354
Chassis No.:	MD2A36FZ0DCC89354
Maximum Power Output:	-
Open Market Value:	\$1,739.00
Original Registration Date:	23 Jul 2013
First Registration Date:	23 Jul 2013
Transfer Count:	1
Actual ARF Paid:	\$261.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 Jul 2023
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$1,712.00
COE Rebate Amount:	\$811.00
Total Rebate Amount:	\$811.00
Message	
Transfer of ownership or deregistration is not allowed for this vehicle.	

The information contained herein is correct as at 24 Oct 2018

OK

Brand	Bajaj (/listing/usedbike/brand/bajaj/)
Model	Bajaj Pulsar RS200 (/listing/usedbike/model/bajaj-pulsar-rs200/)
Engine Capacity	200cc
Classification	2B
Registration Date	27/01/2016
COE Expiry Date	26/01/2026 (7 years 3 months left)
Mileage	20000km
No. of owners	1
Type of Vehicle	Sport Bikes (/listing/usedbikes/listing/?bike_type=8)

Price: SGD\$8800

DETAILS

Downpayment \$500 or \$0 Without insurance (Terms and conditions apply). Please call 67468582 De Xing Motor Pte Ltd Block 3006 Ubi Road 1 #01-356 S 408700.

SIMILAR BIKES

[VIEW ALL \(/LISTING/USEDBIKES/LISTING/\)](/listing/usedbikes/listing/)



Bajaj Pulsar RS200

[\(/listing/usedbike/bajaj-bajaj-pulsar-rs200/9469/\)](/listing/usedbike/bajaj-bajaj-pulsar-rs200/9469/)



Bajaj Pulsar RS200



Bajaj Pulsar RS200

[\(/listing/usedbike/bajaj-bajaj-pulsar-rs200/3045/\)](/listing/usedbike/bajaj-bajaj-pulsar-rs200/3045/)



Bajaj Pulsar RS200

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 / 97761091 Fax : 67528669

Co. Reg No. 201202259N

first

Owner : Rafly Ramadhan

Accident Date : 11-Sep-18

Vehicle No : FBH 5884 S

Vehicle Model : Bajaj Pulsar

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
1	Front fender <i>12</i>	\$ 75.00 <i>X</i>
2	Fork inner tubes <i>Self/turn</i>	\$ 290.00 <i>2</i>
1	Fork under bracket <i>Self</i>	\$ 185.00 <i>2</i>
2	Fork outer tubes <i>1/2 Damage</i>	\$ 250.00 <i>2</i>
1	Front brake disc <i>11</i>	\$ 135.00 <i>X</i>
1	Front rim shaft <i>Self</i>	\$ 45.00 <i>2</i>
1	Front rim bearing <i>Free</i>	\$ 38.00 <i>2</i>
1	Front wheel rim <i>DD</i>	\$ 280.00 <i>—</i>
1	Windshield <i>Self</i>	\$ 68.00 <i>—</i>
2	Front signals <i>cut</i>	\$ 160.00 <i>—</i>
1	Front side cowlings <i>cut</i>	\$ 180.00 <i>2</i>
2	Handle bars <i>Self</i>	\$ 190.00 <i>2</i>
1	Handle bar grip (1 set) <i>cut</i>	\$ 80.00 <i>—</i>
1	Brake lever <i>cut</i>	\$ 32.00 <i>—</i>
1	Clutch lever <i>11</i>	\$ 30.00 <i>X</i>
2	Side mirrors <i>0/5 cut</i>	\$ 110.00 <i>2</i>
1	Front footrest -R/H <i>cut</i>	\$ 35.00 <i>—</i>
1	Front footrest bracket <i>11</i>	\$ 50.00 <i>X</i>
1	Brake pedal <i>2</i>	\$ 42.00 <i>X</i>
1	Rear tailboard <i>cut</i>	\$ 245.00 <i>2</i>
2	Rear signals <i>11</i>	\$ 130.00 <i>X</i>
1	Crash bar (1 set) <i>DD</i>	\$ 250.00 <i>—</i>
1	Rear footrest -R/H <i>cut</i>	\$ 25.00 <i>—</i>
1	Rear footrest bracket <i>Self</i>	\$ 48.00 <i>—</i>
1	Main stand <i>R</i>	\$ 95.00 <i>X</i>
1	Rear number plate holder <i>Self</i>	\$ 90.00 <i>2</i>
		\$ 3,158.00
	Less 10%	\$ 315.80
		\$ 2,842.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883
Tel : 67527740 / 97761091 Fax : 67528669
Co. Reg No. 201202259N

Owner : Rafly Ramadhan

Accident Date : 11-Sep-18

Vehicle No : FBH 5884 S

Vehicle Model : Bajaj Pulsar

Estimated Repair Costs

c/f: \$ 2,842.20

<u>Special Neff Items</u>				
1	Number plate (1 set)	\$	34	28.00 20
1	Fork oil	\$	14	15.00 2
1	Fork oil seal	\$	14	28.00 2
1	Steering cone (1 set)	\$	14	75.00 3
1	Helmet	\$	2	150.00 X
		\$		296.00

<u>S/No.</u>	<u>Labour</u>			
1	To provide towing service.	\$	35	50.00
2	To check wiring and reset headlamp focusing.	\$	11	80.00 X
3	To provide labour.	\$	300	380.00
		\$		510.00
				2657.9

Grand Total

\$ 3,648.20

Dollars: Three Thousand Six Hundred Forty-Eight And Twenty Cents Only.


EROFIA MOTOR TRADING PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18019340/Urbn2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 05-11-2018



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 279M	Veh. Inspected	FBH 5884S
Policy No.		Coverage (\$)	0.00
Claim No.	D18006796MFSH	Excess (\$)	0.00
Assign From	LURENE	Assign Date	25/10/2018

2. Vehicle Particulars & Condition

Make & Model	BAJAJ PULSAR	c.c	200
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	MD2A36FZ0DCC89354	Colour	ORANGE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	110/70-17	PIRELLI	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70-17	PIRELLI	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S AND O/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	11/09/2018	Inspection Date	24/10/2018
Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBH 58845

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT FENDER	TO REPAIR SEE LABOUR	75.00	-
2	FORK INNER TUBES	BENT / TWISTED	290.00	290.00
1	FORK UNDER BRACKET	BENT	185.00	185.00
2	FORK OUTER TUBES	N/S DAMAGED	250.00	60.00
1	FRONT BRAKE DISC	NOT NECESSARY	135.00	-
1	FRONT RIM SHAFT	BENT	45.00	45.00
1	FRONT RIM BEARING	NECESSARY	38.00	38.00
1	FRONT WHEEL RIM	DENTED	280.00	280.00
1	WINDSHIELD	SCRATCHED	68.00	68.00
2	FRONT SIGNALS	CUT	160.00	160.00
1	FRONT SIDE COWLING	CUT	180.00	180.00
2	HANDLE BARS	BENT	190.00	190.00
1	SET HANDLE BAR GRIP	CUT	80.00	80.00
1	BRAKE LEVER	CUT	32.00	32.00
1	CLUTCH LEVER	NOT NECESSARY	30.00	-
2	SIDE MIRRORS	O/S CUT	110.00	55.00
1	FRONT FOOTREST-R/H	CUT	35.00	35.00
1	FRONT FOOTREST BRACKET	NOT NECESSARY	50.00	-
1	BRAKE PEDAL	TO REPAIR SEE LABOUR	42.00	-
1	REAR TAILBOARD	CRACKED	245.00	245.00
2	REAR SIGNALS	NOT NECESSARY	130.00	-
1	SET CRASH BAR	DENTED	250.00	250.00
1	REAR FOOTREST-R/H	CUT	25.00	25.00
1	REAR FOOTREST BRACKET	BENT	48.00	48.00
1	MAIN STAND	TO REPAIR SEE LABOUR	95.00	-
1	REAR NUMBER PLATE HOLDER	BENT	90.00	90.00
	LESS 10% DISCOUNT		-315.80	-235.60
			2,842.20	2,120.40

Report Ref No. CS/FCI18019340/Urbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	SET NUMBER PLATE (SN)	BENT	28.00	20.00
1	FORK OIL (SN)	NECESSARY	15.00	15.00
1	FORK OIL SEAL (SN)	NECESSARY	28.00	28.00
1	SET STEERING CONE (SN)	NECESSARY	75.00	75.00
1	HELMET (SN)	TO REPAIR SEE LABOUR	150.00	-
			296.00	138.00
	LABOUR			
	TO PROVIDE TOWING SERVICE.		50.00	35.00
	TO CHECK WIRING AND RESET HEADLAMP FOCUSING.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR, INCLUSIVE OF THE REPAIR OF FRONT FENDER, BRAKE PEDAL, MAIN STAND AND HELMET.		380.00	300.00
			510.00	335.00
	GRAND TOTAL		3,648.20	2,593.40
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,100.00

Report Ref No. CS/FC118019340/Urbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.