

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG NO : 53105453E

Vehicle Number : SJL 7687R
Vehicle Model : MIT.LANCER EX
Accident Date : 20.10.2018
Original Reg Date : 11.12.2008 (30.06.2023)

Date : 22.10.2018
Chassis : JMYSRCY2A9U002255
TP Ins. AXA

ESTIMATE

1	1 pc	Front Bumper / CRK	892.00	/
2	1 pc	Front Bumper Side Retainer RH / ncl	38.00	/
3	1 pc	Front Bumper Top Rubber / ncl	42.00	/
4	1 set	Front Bumper Clips / ncl	50.00	/
5	1 pc	Front Bumper Fog Lamp RH ?	450.00	/
6	1 pc	Front Bumper Fog Lamp Cover RH / ncl	48.00	/
7	1 pc	Wiper Tank / ncl	95.00	/
8	1 pc	Wiper Tank Motor X NN	128.00	/
9	1 pc	Headlamp RH / CRK	912.00	/
10	1 pc	Headlamps Lower Retainer RH ?	56.00	/
11	1 set	Headlamps Clips / ncl	20.00	/
12	1 pc	Front Fender RH / ncl	531.00	/
13	1 pc	Front Fender Side Bracket RH / BT	52.00	/
14	1 pc	Front Fender Signal Lamp RH X NN	47.00	/
15	1 pc	Front Fender Inner Shield RH / ncl	109.00	/
16	1 set	Front Fender Inner Shield Clips / ncl	30.00	/
17	1 pc	Front Shock Absorber RH X	461.00	/
18	1 pc	Front Lower Arm RH X	324.00	/
19	1 pc	Front Knuckle Arm RH X	384.00	/
20	1 pc	Front Wheel Bearing RH X	189.00	/

4,858.00 2819

Less 10% 485.80

4,372.20 2532.1

C/F

4,372.20

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG NO : 53105453E

B/F

4,372.20

Special Nett

1	1 pc	Front Sport Rim RH 16" X <i>NN</i>	450.00
2	1 pc	Front Sport Rim Tyre X <i>NN</i>	280.00

Labour charge

Panel Beating	1,000.00
Spray painting	1,000.00
Check Wiring	50.00
Anti rust	100.00
Remove and install front undercarriage.	450.00
To perform computerize wheel alignment.	90.00

7,792.20

1,558.44

Lump sum

6,233.76

5 Days.

Lump sum repair

After repair photos.

Gmo Qicf.

23/10/18

3777.1

20% 3000

*500
600
30
50
X NN
60.
1240*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: