

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG NO : 53105453E

Vehicle Number : SJL 7687R
Vehicle Model : MIT.LANCER EX
Accident Date : 20.10.2018
Original Reg Date : 11.12.2008 (30.06.2023)

Date : 22.10.2018
Chassis : JMYSRCY2A9U002255
TP Ins. AXA

ESTIMATE

1	1 pc	Front Bumper / CMA		892.00	/
2	1 pc	Front Bumper Side Retainer RH / MC		38.00	/
3	1 pc	Front Bumper Top Rubber / MC		42.00	/
4	1 set	Front Bumper Clips / MC		50.00	/
5	1 pc	Front Bumper Fog Lamp RH X NN		450.00	/
6	1 pc	Front Bumper Fog Lamp Cover RH / S.M.		48.00	/
7	1 pc	Wiper Tank / de		95.00	/
8	1 pc	Wiper Tank Motor X NN		128.00	/
9	1 pc	Headlamp RH / CMA		912.00	/
10	1 pc	Headlamps Lower Retainer RH X NN		56.00	/
11	1 set	Headlamps Clips / MC		20.00	/
12	1 pc	Front Fender RH / MC		531.00	/
13	1 pc	Front Fender Side Bracket RH / OT		52.00	/
14	1 pc	Front Fender Signal Lamp RH X NN		47.00	/
15	1 pc	Front Fender Inner Shield RH / de		109.00	/
16	1 set	Front Fender Inner Shield Clips / MC		30.00	/
17	1 pc	Front Shock Absorber RH X		461.00	/
18	1 pc	Front Lower Arm RH X		324.00	/
19	1 pc	Front Knuckle Arm RH X		384.00	/
20	1 pc	Front Wheel Bearing RH X		189.00	/

4,858.00 2819

Less 10% 485.80

4,372.20 2537.1

C/F 4,372.20

EM-1 AUTO TRADE

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY REG NO : 53105453E

B/F

4,372.20

Special Nett

1	1 pc	Front Sport Rim RH 16"	X		450.00
2	1 pc	Front Sport Rim Tyre	X		280.00

Labour charge

Panel Beating		1,000.00
Spray painting		1,000.00
Check Wiring		50.00
Anti rust		100.00
Remove and install front undercarriage.		450.00
To perform computerize wheel alignment.		90.00

7,792.20

1,558.44

Lump sum 6,233.76

5 Days.
Lump sum repair
After repair photos.
Gmo Qicp.
23/10/18

4187.1
~~3777.1~~
20% 755.4
3350

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____