

ASS. REC. BY:

REF:

CS3/AIG18019364/R1cd321

Special Instruction:

Surveyor

Rasul

ASSIGNMENT (Office)

From (Person):

Meimen

Chin Lee Ying

of

AIG

Date/Time:

24/10/18 @ 1:50pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLP 58897

Insured:

SLJ 8685B

at Workshop m/s

C.H. Motor Vehicle

Tel:

6841 8841

of

Blk 3019A Ubi Road | #01-30

Policy No:

2100496125

Claim No:

956127274086

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/10/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

2:55pm @ 24/10/18

Person Contacted:

Mdm. Wong

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (X) Estimate

SLP 58897-X

SLJ 8685B-X

Dismantle: 25/10/2018

After repair: 29/10/2018

GIA ✓






**- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...**

From: Chin, Lee-Ying

To: assignments, admin-a@lkkauto.com

Cc: Fong, Andy-SY

Sent: 24/10/2018 1:50:32 PM

Attachments:  [20181023175117.pdf](#)  [20181023170051.pdf](#)  
 [20181023144358.pdf](#)

---

Hi LKK,

Please assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.com.sg](http://www.aig.com.sg)

**IMPORTANT NOTICE:**

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

# VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths  
Agents for Trade Marks

(Incorporated with limited liability)

ERIC NG CHING BOON  
RAYNEY WONG KENG LEONG  
AUDREY WONG SU-HSIEN  
PAUL YAP TAI SAN  
ANJALLI D/O MUNIANDY  
SEGA PARAM  
DIANE ANG KIM NOI  
RAVENDRA KRISHNASAMY  
TAY HAO RAN  
JANICE HAN JIA LIN  
SELWYN TAN YINGXIAN

Unique Entity Number: 200721148H

## ✓ HEAD OFFICE

133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413

Branch: 490 Toa Payoh Lorong 6  
#03-11 HDB Hub  
Singapore 310490

## ✓ HEAD OFFICE

TEL : (65) 65342811 (Hunting)  
FAX : (65) 65356802 (General)  
✓: (65) 65355905 (Litigation)  
E-mail : yvonnellm@visionlawllc.com

## BRANCH

TEL : (65) 63580703  
FAX : (65) 63580448 (Conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE – PLEASE REPLY TO HEAD OFFICE FOR THIS MATTER

Our Ref: SLP 5889 T (PM)  
Your Ref: SLJ 8685 B

23 October 2018

BY EMAIL ONLY

**AIG ASIA PACIFIC INSURANCE PTE. LTD.**  
78 Shenton Way  
#07-16 AIG Building  
Singapore 079120  
[Attention : Motor Claim Department]

Dear Sirs,

**ACCIDENT INVOLVING MOTOR VEHICLE SLP 5889 T AND SLJ 8685 B ON 20 OCTOBER 2018  
ALONG PAN ISLAND EXPRESSWAY AT ABOUT 1840 HOURS  
(NOTICE TO INSURER TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS  
PURSUANT TO PARAGRAPH 6.2 OF PRE-ACTION PROTOCOL FOR NIMA CASES)**

We refer to your email of even date whereby parties are not agreeable to each other's list of motor surveyors.

Under the circumstances, no Single Joint Expert has been agreed for this matter.

Please be informed that the said vehicle can be inspected at:

Venue : **C.H. MOTOR VEHICLE REPAIR TRAINING**  
**Block 3019A Ubi Road 1**  
**#01-30**  
**Singapore 408713**

Contact Person : **Mr. Joe @ 6841-8841 / 6748-8888 (Please call before going)**

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully

DIANE ANG  
(HEAD OFFICE)

cc: SLP 5889 T – By fax: 67436878 only

## FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :  
(Name & Signature)

Date & Time of Inspection :

## CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

> Back to OneMotoring

## Enquire Transfer Fee

Vehicle Details			
Vehicle No.:	SLP5889T		
Vehicle Type:	P10 - Passenger Motor Car		
Vehicle Attachment 1:	With Sun Roof		
Vehicle Scheme:	Normal		
Vehicle Make:	MAZDA		
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT		
Chassis No.:	JM6BN22A8H0148530		
Propellant:	Petrol		
Engine No.:	P520438410		
Engine Capacity:	1496 cc		
Maximum Power Output:	88.0 kW ( 118 bhp)		
Maximum Laden Weight:	1835 kg		
Unladen Weight:	1331 kg		
Year Of Manufacture:	2017		
Original Registration Date:	22 May 2017		
Lifespan Expiry Date:	-		
COE Category:	A - Car up to 1600cc & 97kW (130bhp)		
Quota Premium:	\$51,106.00		
COE Expiry Date:	21 May 2027		
Road Tax Expiry Date:	21 Nov 2018		
PARF Eligibility Expiry Date:	21 May 2027		
Inspection Due Date:	21 May 2020		
Intended Transfer Date:	05 Nov 2018		
CO2 Emission:	135.00 (g/km)		
CEV/VES Rebate Utilised Amount:	\$5,000.00		
CO Emission:	-		
HC Emission:	-		
NOx Emission:	-		
PM Emission:	-		
The current road tax expiry is 21 Nov 2018. You may renew the road tax from 22 Aug 2018 with all pre-requisite(s) fulfilled. If the road tax is renewed after 21 Nov 2018, late renewal fee(s) will be imposed. Please use Enquire Road Tax Payable to check on the late fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable (From 22 Nov 2018 to 21 May 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	341.00	-	341.00
Total Amount Payable:			366.00
Amount Payable (From 22 Nov 2018 to 21 Nov 2019)			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee:	25.00	-	25.00
Sub Total:			25.00
Nett Road Tax Amount (After Offsetting Over Payment):	682.00	-	682.00
Total Amount Payable:			707.00

You may print this page for reference.

OK

Print

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	2976H
<b>Vehicle Details</b>	
Vehicle No.:	SLP5889T
Vehicle to be Exported:	No
Intended Deregistration Date:	05 Nov 2018
Vehicle Make:	MAZDA
Vehicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	P520438410
Chassis No.:	JM6BN22A8H0148530
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$19,359.00
Original Registration Date:	22 May 2017
First Registration Date:	22 May 2017
Transfer Count:	0
Actual ARF Paid:	\$14,359.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 May 2027
PARF Rebate Amount:	\$10,769.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	21 May 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,106.00
COE Rebate Amount:	\$43,659.00
<b>Total Rebate Amount:</b>	<b>\$54,428.00</b>

The information contained herein is correct as at 05 Nov 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/10/2018 15:41
Date Of Accident	20/10/2018 18:40
Exact Location Of Accident	PAN ISLAND EXPRESSWAY
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP5889T
-----------------------------	----------

#### Insured/Policyholder

Name Of Registered Owner	KWEK SENG WEE, JOHN
NRIC No	S8422976H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-86129693
Alternative Phone No	OTHERS-86129693

#### Vehicle Particulars

Manufacturer	MAZDA
Model	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

#### Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	8VPCP1800210
Cover Note Number	

#### Driver

Name of Driver	KWEK SENG WEE, JOHN
NRIC No	S8422976H
Date Of Birth	01/08/1984
Occupation	INDOOR
Date Of Driving Pass	15/09/2005
Driving Experience	13 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-86129693
Fax Number	
Contact Number	OTHERS-86129693
Email Address	NOEMAIL

Address	BLK 112A EDGEDALE PLAINS #11-175
Postcode	821122
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PUNGGOL N.P.C
Police Station Address	ROAD: 21A TEBING LANE , POSTCODE: 828837 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

AS PER POLICE REPORT NO.T/20181021/2010

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	WITH DRIVER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLJ8685B
Vehicle Make/Model/Colour	AUDI A1 SB 1.0 TFSI (PI)
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JANSEN ONG JUN SEN
NRIC/Passport Number	S9308026B
Contact Number	82882868
Address	
Postcode	
Insurance Company Name	



Nature Of Damage

No. Of Passenger (Including Driver)

2

Passenger 1

NAME: : -

GENDER: : FEMALE

#### DETAILS OF INJURED PERSON 1

Name

KWEK SENG WEE, JOHN

Approximate Age

34

Injuries Sustain

3 DAYS MC

Injured person in which vehicle?

SLP5889T

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

Address

BLK 112A EDGEDALE PLAINS #11-175

Postcode

821122

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 21 OCT 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

**IDAC KAKI BUKIT (VAC)**


Reporting Centre Roadside Sign

Name: Singapore 415933

NRIC/TEL: 67416697 Fax: 67492305

Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AS PER POLICE REPORT

The description area consists of several horizontal lines. A large, stylized signature or scribble is drawn across the middle of the section, starting from the left and extending towards the right.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature:

Date & Time: 21 OCT 2018 15:50H

Driver's Signature: \_\_\_\_\_  
(If driver is not the policyholder)  
Date & Time: \_\_\_\_\_

**IDAC KAKI BUKIT (VAC)**  
23 Kaki Bukit Ave 4  
Reporting Centre Personnel's Signature: \_\_\_\_\_  
Name: \_\_\_\_\_  
Tel: 67416697 Fax: 67492305  
Email: [vackb@singnet.com.sg](mailto:vackb@singnet.com.sg)

# Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20181021/2010

Police Station Of Origin:  
Punggol N.P.C  
21A Tebing Lane SINGAPORE 828837  
Tel No: 1800-6049999

1 of 4

Report No. T/20181021/2010

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 21/10/2018 02:10	Vide Report No.:	Station Diary No.: 18
--	------------------	--------------------------

Informant's Particulars			
Name of Informant: KWEK SENG WEE, JOHN		Address: APT BLK 122A EDGEDALE PLAINS #11-175 SINGAPORE 821122	
ID Type / ID No.: NRIC NO / S8422976H		Contact No.: Home/Office: Mobile: 86129693	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 34	Date of Birth: 01/08/1984	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: SAF REGULAR		Driving Licence Information: Class: 3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 20/10/2018 18:40	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY  Along PIE towards Changi between exit 15 and 16A				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SLJ8685B	Car					1
SLP5889T	Car	MAZDA	MAZDA3 4-DOOR SEDAN 1.5L SP 6EAT	Blue		0

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date

# Accident Sketch Plan Pg. 1



**SINGAPORE  
POLICE FORCE**



T/20181021/2010

Police Station Of Origin:  
Punggol N.P.C  
21A Tebing Lane SINGAPORE 828837  
Tel No: 1800-6049999

2 of 4

Report No. T/20181021/2010

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLP5889T	MSIG INSURANCE (SINGAPORE) PTE. LTD.	8VPCP1800210	22/05/2018	21/05/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	Jansen Ong Jun Sen		ID No.	S9308026B
Related Vehicle	SLJ8685B (Car)		Contact No.	82882868
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		NIL	Degree of Injury	NIL
Driver				
Name	KWEK SENG WEE, JOHN		ID No.	S8422976H
Related Vehicle	SLP5889T (Car)		Contact No.	86129693
Hospital/Clinic	MOUNT ELIZABETH HOSPITAL		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave		03	Degree of Injury	NIL

## **Brief Details.**

On 20/10/2018 at about 1839hrs, I was driving my car bearing registration plate number SLP5889T along PIE towards Changi on lane 1. After I past exit 16A of PIE, I noticed that there was three vehicles in front which stopped on lane 1 with their brake light on. As such I slowed down and came to a stop. However when I managed to come to a stop, there was a car SLJ8685B who could not stop in time and collided to the rear of my vehicle. Thereafter I got to know that in front of the 3 cars which was stopped on lane 1, there was an accident which occurred between 2 other vehicles.

I had exchanged particulars with the driver of SLJ8685B, he was with a female passenger who showed me her LTA pass. The driver of SLJ8685B did not ask if I am alright, he said that "Heng did not hit until". I told him that our car collided and his front plate already dented in, how can it be that our vehicle did not collided. He then asked why did I brake my vehicle, I told him that there was vehicles in front that brake, how can I not brake. Subsequently, I went left the scene as I was in a rush. Shortly after I felt pain on my back area, my right knee and feel stiffness on my neck.



**SINGAPORE  
POLICE FORCE**



T/20181021/2010

Police Station Of Origin:  
Punggol N.P.C  
21A Tebing Lane SINGAPORE 828837  
Tel No: 1800-6049999

3 of 4

Report No. T/20181021/2010

CONTINUATION OF REPORT



**SINGAPORE  
POLICE FORCE**



T/20181021/2010

Police Station Of Origin:  
Punggol N.P.C  
21A Tebing Lane SINGAPORE 828837  
Tel No: 1800-6049999

4 of 4

Report No. T/20181021/2010

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

F /

Sgt 3 LIM JIN YEOW, BENNY

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

21/10/2018 02:10

Officer In Charge Of Case:

TP / AEIT /

SSI 2 YEO GEAK ENG CECILIA

Contact No.: 65476404

Classification Of Case:

SN 085

Authentication Stamp  
NP168



Signature:

Singapore Police Force



Mount Elizabeth™  
ORCHARD

24HR WALK-IN CLINIC AND ACCIDENT & EMERGENCY  
3 Mount Elizabeth #01-00 Singapore 228510  
Tel: 67312218 Fax: 67374040 Co Reg No: 19-9509118-D

### MEDICAL CERTIFICATE

This is to certify that:  
Name: KWEK SENG WEE JOHN  
NRIC:

MC No: MEH2018105783001

Medical leave for 3 day/s from 21.10.2018 to 23.10.2018 inclusive

Date: 21.10.2018

DR KWOK WEI LIANG (GUO  
WEILIANG)

THIS CERTIFICATE IS NOT VALID FOR ABSENCE FROM COURT OR OTHER  
JUDICIAL PROCEEDINGS UNLESS SPECIFICALLY STATED OTHERWISE



Address	601 JURONG WEST STREET 62 11-163 SINGAPORE
Postcode	640601
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Collision - Head to Rear (I hit a third party vehicle), #straightroad, Moving straight & Moving straight. Blue Car SLJ8685B, White Car SLP5889T. The front vehicle went on to ebrake due to an accident in front. There were no damages done to the vehicle in front as it was a slight kiss. The damage done was only to my car. There was ample road space but the driver ebrake without considering the safety of the people behind. Such unluckiness. No damage as shown.


#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO


#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP5889T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	86129693
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


## Sketch Plan



Insd's Nric (Front)



Insd's Nric (Back)



Insd's Driving License (Front)



Insd's Driving License (Back)



# MOTORCAR (Rear)

(1) Replace (✓) (2) Repair (✓) (3) Check (✓)  
 (4) Not Consistent (N/C)

Vehicle No: **SLP 58897**

## Rear Portion

NAC	INC	Item	CON	ACQ	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	DD	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover	MIS	✓	
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	DIS	✓	
1149	993045	Rear Bumper Reinforcement	DD	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	DM	✓	
1159	993327	Rear End Panel			
1160	993339	Rear End Panel Top Garnish			
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	SCR	✓	
1171	991328	Bootlid Emblem	NEC	✓	
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH			
1176	992899	Bootlid Lamp RH			
1177	995243	Bootlid Lock			
1178	990377	Bootlid Rubber			
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	ACQ	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Oct 2018 <a href="#">Edit Reg</a>		24 Oct 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by adjuster]

Insured:	<b>JANSEN ONG JUN SEN</b> , ID: S9308026B		
Main Claimant:	-		
Vehicle Reg. No.:	<b>SLP5889T</b>	Date of Loss:	20/10/2018 00:00 - :59 [16 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	<b>TP / 9561272740SG</b>	Policy/Cover Note No.:	2100496125 (Comprehensive)
Vehicle Reg. No. (Insured):	<b>SLJ8685B</b>	Policy No. (Claimant):	
		Excess:	
Repairer:	<b>Ch Motor Vehicle Repair (HQ)</b> BLK 3019A, #01-30 UBI ROAD 1, 408713 Ubi - Tel: 6748 8888		
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Wui, Shawn-KJ</b> ] Shawnkaijye.Wui@aig.com		
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 02/11/2018]		
Claimant's Solicitor:	<b>VISION LAW LLC</b> - Tel: 65342811		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

- AIG\_SG (25/10/2018): Request to upload TP GIA Report

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*SLP5889T (9561272740SG)

[SLJ8685B]





































TP





-

Oct 20 2018 12:00AM

[JANSEN ONG JUN SEN]

Ch Motor Vehicle Repair

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Photos/Images												3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	27/10/18 14:05	General View											Load JPG	<input checked="" type="checkbox"/>
2	27/10/18 14:05	General View											Load JPG	<input checked="" type="checkbox"/>
3	27/10/18 14:05	General View											Load JPG	<input checked="" type="checkbox"/>
4	27/10/18 14:05	General View											Load JPG	<input checked="" type="checkbox"/>
5	27/10/18 14:05	General View											Load JPG	<input checked="" type="checkbox"/>
6	27/10/18 14:05	General View											Load JPG	<input checked="" type="checkbox"/>
7	27/10/18 14:05	General View											Load JPG	<input checked="" type="checkbox"/>
8	27/10/18 14:05	General View											Load JPG	<input checked="" type="checkbox"/>
9	27/10/18 14:05	General View											Load JPG	<input checked="" type="checkbox"/>
10	27/10/18 14:05	General View											Load JPG	<input checked="" type="checkbox"/>
11	27/10/18 14:05	General View											Load JPG	<input checked="" type="checkbox"/>
12	27/10/18 14:05	General View											Load JPG	<input checked="" type="checkbox"/>
13	27/10/18 14:05	General View											Load JPG	<input checked="" type="checkbox"/>
14	27/10/18 14:05	General View											Load JPG	<input checked="" type="checkbox"/>
15	27/10/18 14:05	General View											Load JPG	<input checked="" type="checkbox"/>
16	27/10/18 14:05	General View											Load JPG	<input checked="" type="checkbox"/>
17	27/10/18 14:05	General View											Load JPG	<input checked="" type="checkbox"/>
18	27/10/18 14:05	General View											Load JPG	<input checked="" type="checkbox"/>
19	27/10/18 14:05	General View											Load JPG	<input checked="" type="checkbox"/>
20	27/10/18 14:05	General View											Load JPG	<input checked="" type="checkbox"/>
21	27/10/18 14:05	General View											Load JPG	<input checked="" type="checkbox"/>
22	27/10/18 14:38	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
23	27/10/18 14:38	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
24	27/10/18 14:38	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
25	27/10/18 14:38	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
26	27/10/18 14:38	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
27	27/10/18 14:38	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
28	27/10/18 14:38	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
29	27/10/18 14:38	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
30	27/10/18 14:38	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
31	27/10/18 14:38	Photographs of Damaged Parts											Load JPG	<input checked="" type="checkbox"/>
32	31/10/18 18:35	Photo After Spray											Load JPG	<input checked="" type="checkbox"/>
33	31/10/18 18:35	Photo After Spray											Load JPG	<input checked="" type="checkbox"/>
34	31/10/18 18:35	Photo After Spray											Load JPG	<input checked="" type="checkbox"/>
35	31/10/18 18:35	Photo After Spray											Load JPG	<input checked="" type="checkbox"/>
36	31/10/18 18:35	Photo After Spray											Load JPG	<input checked="" type="checkbox"/>
37	31/10/18 18:35	Photo After Spray											Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	31/10/18 18:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	31/10/18 18:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	31/10/18 18:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	31/10/18 18:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	31/10/18 18:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	31/10/18 18:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
44	31/10/18 18:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
45	31/10/18 18:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
46	31/10/18 18:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
47	31/10/18 18:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
48	31/10/18 18:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
49	31/10/18 18:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	25/10/18 11:33	OI GIA REPORT	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18019364/R1CD3E2

Date: 08/11/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100496125  
**Claimant Vehicle No :** SLP5889T **Insured Vehicle No :** SLJ8685B  
 Date of Loss: 20/10/2018 Nature of Claim: TP Claim No: 9561272740SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLP5889T**  
 Make & Model: MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A) Engine No: P520438410  
 Reg. Date: 22/05/2017 (Man. Year: 2017) Chassis No: JM6BN22A8H0148530  
 Colour: Blue Odometer: 50246 km  
 Engine Capacity: 1496 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16  
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm  
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment: 24/10/2018  
 Date Inspected: 24/10/2018 Inspected At: Ch Motor Vehicle Repair (HQ)  
 BLK 3019A, #01-30 UBI ROAD 1  
 Singapore 408713  
 Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	0.00 F	*- F
2	1		*REAR BUMPER TOW COVER	Missing	0.00 F	*- F
3	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
4	1		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*- F
6	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
7	1		*BOOTLID	Repair	0.00 F	*- F
8	1		*BOOTLID EMBLEM	Necessary	0.00 F	*- F

F=Franchise part.

<b>Total Parts (S\$)</b>	<b>0.00</b>	<b>0.00</b>
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.
---

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >