

NATIONAL Assessment Centre Services

(Unit 1) (1/1/2008)

MANA/18/38569

Date In: 25/10/2018 11:33	Job description	Date & Time Completed	Done by
Ref No: NBA/180601938917	SAS e-illing		
Veh No: 892 2206 R	E-mail (within 3hrs, AIO 3hrs)		
D.O.A: 25/10/2018 08:30	I-Motor Claim Form	mt1017147-001	25/10/2018 14:58
OD / TP / Reporting Only	I-Motor W/O (within 3hrs, AIO 3hrs)		
	I-Photo Uploaded		
TP Insurer:	Assessment/Survey Report		
	Ass't Report by Fax / Hand to Owner/Wksp		

Preferred Wksp / INC Assign Wksp / OW: (

Tel:

Fax:

TP Particulars:	Veh No: SLZ4304T	INC () / Non-INC ()
Owner / Driver: (		Tel: ()
Policy No: (	Period: (	Cover Type: (
Confirmed by: (	Date: (	Time: (
Insured/Driver Liability: (	% (Note: Est. Status (WO): N: 0-20%; P: 21-79%; P: 80-100%)	
Year of Registration: (	Warranty: YES () / NO ()	
Excess: (\$	Loading: \$1,000 () / \$2,000 ()	

General Remarks:	
() Walk-In Customer: Customer's information strictly Confidential & Strictly NO refer of repeller.	
() Total Loss Case: to e-mail Insurer URGENTLY.	
Drive-In () / Towed-In () : Invoice: YES () / NO () : Towing Co: (	

Remarks:	Date & Time Completed:	Done by:
1) Apply for Transport Allowance () / Courtesy Car ()		
2) QC Check / Post Repair Inspection ()		
3) Upload Resurvey Photo (Repair Cost > \$3000) ()		

Injury:

Date/Time	Action

NA1806914

Human's Particulars:	Invoice Preparation Checklist:
river/Owner:	1) AR: Accident Reporting (330):
Contact No:	2) DA: Damage Assessment (3100): INC (330)
amaged Portion:	3) TP: Towing Fee \$40/\$45
	4) FT: Follow-Through Survey \$120
	5) PT: Follow-Through Survey (Resurvey) \$20
	For claimant against INC Only (over 10 Jan 2010)
	6) TR: Re-inspection \$15
	7) NI: Delay DA + SMRT Survey \$160
	8) NTUC Additional Services:
	9) NI: Delay DA + SMRT Survey \$15
	10) NI: Repair Coordination \$10
	11) NI: Post Repair Inspection \$20
	12) NI: DY / Collect Unseen Coordination \$5
	13) TP (NI) / TP (Rn INC) against INC \$20
	14) NI: Delay DA + SMRT Survey \$10
	Invoice dated
	Invoice dated
	Not Charged
	Not Charged

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/10/2018 11:33
Date Of Accident	25/10/2018 08:30
Exact Location Of Accident	PIE (CHANGI AIRPORT) NEAR CHANGI CITY EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGZ2206R
Insured/Policyholder	
Name Of Registered Owner	LIONG KWOK YEAN (LIANG GUOXIAN)
NRIC No	S7702322D
Email Address	KULIONG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-92251750
Alternative Phone No	OTHERS-92251750

Vehicle Particulars

Manufacturer	HONDA
Model	STREAM-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	GOING TO OFFICE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096687398
Cover Note Number	

Driver

Name of Driver	LIONG KWOK YEAN (LIANG GUOXIAN)
NRIC No	S7702322D
Date Of Birth	23/01/1977
Occupation	INDOOR
Date Of Driving Pass	31/07/2007
Driving Experience	11 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92251750
Fax Number	
Contact Number	OTHERS-92251750
Email Address	KULIONG@GMAIL.COM

Address	BLK 259 TAMPINES STREET 21 #04-330
Postcode	520259
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : WIFE GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLZ4304T
Vehicle Make/Model/Colour	HONDA VEZEL
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	LIM YU JIE JOSEPH
NRIC/Passport Number	S8635344Z
Contact Number	86851212
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 25/10/18
138.com

Driver's Signature


(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 25th Oct 2018 at around 830am, I was driving along PIE (Changi Airport) near the Changi city exit, going towards the ECP. There was a major 4-car accident that happened earlier on further up front at the Changi Flyover, causing a jam leading to PIE (Changi) near exit 1.

I was travelling on lane 1 and noticed the Red Honda Vezel (SLZ 4304T) in front of me stopped due to the jam ahead. I immediately step hard on my brakes to stop my car (SLZ 2206R). However, my car continued to move due to the momentum and hit the Honda Vezel (SLZ 4304T) in front. The back and bumper of the Honda Vezel was damaged, while the front bumper and bonnet of my car was damaged.

The Honda Vezel's driver was a private hire driver, sending a passenger in his car to his destination. I was driving to work in my car with my wife as the driver. No one was injured in the accident.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 28/10/18 1130am

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No:

25/10/2018

Rishi Kumar

Claim Handling

Accident MT/1817147

Policy No.	5096687398	Vehicle No.	SG22206R	GST Registration No.	
Certificate No.					
Policyholder Name	LIONG KWOK YEAN (LIANG GUOKIAN)	Cover Type	DRIVE CLASSIC	Policyholder NRIC	S77023220
Product Code	PRIVATE CAR INSURANCE	Contact No.(Office)		Loading	0
Contact No.(Mobile)	92251750	Special Remark		Contact No.(Home)	
Email Address		TCA	Yes No	eCode	No *
KFK	Yes No	NCD Entitlement(%)	0	eCode Reason	
NCD Protection	No			Private Hire	No
Accident Details					
Report Date	25/10/2018 14:21	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Head to Rear
Date of Accident	25/10/2018	Time of Accident (hh:mm)	08:30	Country of Accident	Singapore
Reporting Centre		Orange Force		ICM No.	
Accident Location	PTE (CHANGI AIRPORT) NEAR CHANGI CITY EXIT				
Excess					
Own damage Excess	500.00	Additional Excess	0	Windscreen Excess	100.00
Uninsured Driver Excess	0.00	Outside Singapore OD Excess	500.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		
Benefits					
GST Registered Information					
GST Registered	No	GST Registration Date		GST Status Verified	Yes
GST Registration No.					
Modification history					
Policyholder Mailing Address					
Address 1	BLK 259 #04-330	Address 2	TAMPINES STREET 21	Address 3	SINGAPORE S20259
Address 4		Address Type	Singapore address	Post Code	S20259
Unit No.		Related Policy Number	5096687398		
OL Driver Info					
Driver Name	LIONG KWOK YEAN	Driver Type	Main Driver	Driver DOB	23/01/1977
Unnamed driver Name		Driver NRIC	S77023220	Driving Experience	21
Register Date of Driver License	01/01/1997	Driver Age	41	Contact No.(Home)	
Contact No.(Mobile)	92251750	Contact No.(Office)		Address 3	SINGAPORE S20259
Address 1	BLK 259 #04-330	Address 2	TAMPINES STREET 21	Post Code	S20259
Address 4		Address Type	Singapore address		
Unit No.				Driver Insurer Company	MTUC
Does he own a Singapore Registered car?	Yes No	Driver Vehicle No.	SG22206R		
Declaration					
Breathalyzer or Blood Test Reading?	0 mg	Any injury?	Yes No		

Modification History

Claim 001 **Next**

Claim Type *	OD-MD	Insured Name	LIONG KWOK YEAN (LIANG GUOKIAN)	Insured NRIC	S77023220
Contact No.(Mobile)	92251750	Contact No.(Home)		Contact No.(Office)	
Email Address	KYLIONG@GMAIL.COM.SG	OL Vehicle Number	SG22206R	TP Vehicle Number	SL24304T
Claim Description	SG22206R / SL24304T ON 25 Oct 2018				
Preferred Workshop		Insured Liability	Fully at Fault	GIA report	Received
Workshop Finalisation	Yes	Repair Option	Income to assign workshop		
Date Registered	25/10/2018 14:54	Claim Close Date		Date Received	25/10/2018
Report Taken By	NOSLI WAHAB				
Print AK letter					
OD Excess Collected by Workshop					
Save Submit					

Attachment

Accident No.	MT/1817147	Claim No.	001
Last Doc. Received	Yes No	Upload Date	25/10/2018 14:58
Path *			
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Choose File	No file chosen	Clear	Please Select
Message Read			
Attachment List			
Attachment	Uploaded By/Date	Category	Urgency
NAC_BUKIT_MERAH_900676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 25 Oct 2018 14:58		Photos	Normal
Description Photos 2018-10-28			

	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 25 Oct 2018 14:54	Photos	Normal	Photos 2018-10-25
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 25 Oct 2018 14:54	Photos	Normal	Photos 2018-10-25
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 25 Oct 2018 14:54	NRIC/ Driving License	Normal	NRIC/ Driving License 2018-10-25
	NAC_BUKIT_MERAH_800676(NATIONAL ASSESSMENT CENTRE SERVICE S (BUKIT MERAH)) on 25 Oct 2018 14:54	SAS	Normal	SAS 2018-10-25
 Video List				
Uploaded By/Date	Folder Date	File Name		Source
		Display in New Window	Scan and uploading	

MOTOR CAR (Fr)

Vehicle No:

SG2 2206 R

Front Portion

NAC	INC	Item	CON	AC	QTY
1001	991886	Fr Number Plate			
1002	991887	Fr Number Plate Base			
1003	991889	Fr Number Plate Garnish			
1004	991300	Fr Bumper	SR		
1005	992341	Fr Bumper Clips	NAC		
1006	991325	Fr Bumper Bracket	BR		
1007	991402	Fr Bumper Side Retainer	NAC		
1008	991433	Fr Bumper Reinforcement			
1009	991318	Fr Bumper Beam			
1010	991468	Fr Bumper Sponge			
1011	991427	Fr Bumper Protector			
1012	991420	Fr Bumper Pad			
1013	991363	Fr Bumper Grille			
1014	991301	Fr Bumper Moulding			
1015	991407	Fr Bumper Lower Spoiler			
1016	991438	Fr Bumper Sensor			
1017	995100	Fr LH Bumper Fog Lamp Cover			
1018	991355	Fr RH Bumper Fog Lamp Cover			
1019	995079	Fr LH Bumper Fog Lamp			
1020	995080	Fr RH Bumper Fog Lamp			
1021	991793	Fr Grille			
1022	991328	Fr Grille Emblem	SR		
1023	991799	Fr Grille Chrome Moulding			
1024	991222	Fr Apron Panel			
1025	992013	Fr Support Panel	BT		
1026	992025	Fr Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Fr Brace Panel			
1029	995153	Fr LH Headlamp Assy			
1030	991821	Fr RH Headlamp Assy	SR		
1031	995088	Fr LH Side Lamp			
1032	995089	Fr RH Side Lamp			
1033	990248	Bonnet	BT		
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock	DS		
1036	990285	Bonnet Insulator	DS		
1037	990273	Bonnet Hinge	BT		
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber	NAC		
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992736	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Fr Exhaust Manifold			
1064	991713	Fr Exhaust Manifold Cover			
1065	991054	Fr Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	QTY
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounning			
1087	990949	Engine Mounning Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Fr LH Chassis Member			
1093	991520	Fr RH Chassis Member			
1094	990728	Fr Vertical Cross Member			
1095	991863	Fr Lower Cross Member			
1096	995070	Fr LH Fender			
1097	995072	Fr LH Fender Inner Panel			
1098	995147	Fr LH Fender Lamp			
1099	995148	Fr LH Fender Protector			
1100	991740	Fr LH Fender Inner Shield			
1101	995179	Fr LH Mudflap			
1102	995170	Fr LH Wheel Rim			
1103	994025	Fr LH Rim Cover			
1104	995065	Fr LH Tyre			
1105	995071	Fr RH Fender			
1106	991739	Fr RH Fender Inner Panel			
1107	991744	Fr RH Fender Lamp			
1108	991752	Fr RH Fender Protector			
1109	991740	Fr RH Fender Inner Shield			
1110	991884	Fr RH Mudflap			
1111	992087	Fr RH Wheel Rim			
1112	994025	Fr RH Rim Cover			
1113	995065	Fr RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Fr Wiper Arm			
1121	992142	Fr Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	990749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Fr Driver Seat			
1133	991922	Fr RH Seat Belt Assy			
1134	991899	Fr Passenger Seat			
1135	995182	Fr LH Seat Belt Assy			
1136	990247	Sticker			

No of Items:

Accessories:

original copy

By Assessor- 1) Vehicle Information

- 1) Vehicle hit Vehicle: ☐ 2) Vehicle hit ? ☐
- a) Motorcycle ☐ b) Pedestrian ☐
- c) Bicycle ☐ d) Animal ☐
- 3) Vehicle hit Road Side Objects: ☐
- a) Govn. Property ☐ b) Road Work Object ☐
- (Eg. signpost, barrier, tree etc) c) Private Property ☐
- 4) Vehicle drop into drain ☐
- 5) Damage due to Act of God: ☐
- a) Fallen Object ☐ b) Flood ☐
- c) Other: ☐
- 6) Parked & Found Damaged: ☐
- a) Vandalism ☐ b) Hit by Moving Object ☐
- 7) Theft Case ☐
- a) Stolen ☐ b) Damage found ☐
- when recovered.
- 8) Fire ☐
- a) Whilst driving ☐ b) Parked ☐
- 9) Accident date more than 24hrs ☐

Remarks for internal information

Remarks to appear in Works Order & Assessment report

- 1) Potential Total Loss ☐
- 2) SRS Light on ☐
- 3) ABS Light on ☐

By Assessor- 2) Comments

Vehicle: SGZ 2206 R Year: 007 2017

Type: M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make & Model: Honda Stream 1.8A 1999

Colour: Blue Transmission Type: Auto / Manual

EngNo: R/BA1745656 Sp. Reading: 123286

C/Nr: RUB1040460

Gen. Cond: Good / Fair / Poor / Burnt or

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15
R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm

Parallel Import: Yes / No ☒ No

Repair Type: LS / LB.I

No of Repair Days: 6

D.O.I. 24/01/2018

Towed-In: Yes / ☒ No

Towing Required: Yes / ☒ No

Vehicle in Idac: Yes / ☒ No

Time: 11:30

By Assessor- 2) Comments

- 1) Damages not due to recent accident.
- 2) Damages do not seem hit onto:
- a. Vehicle ☐ b. Motorcycle ☐ c. Bicycle ☐ d. Pedestrian ☐
- e. Animal ☐ f. Govn Object ☐ g. Road Work Object ☐
- h. Private Property ☐ i. Drain ☐ j. Road Kerb/Grass Verge ☐
- 3) Vehicle does not seem damaged as a result of:
- a. Fallen Object ☐ b. Flood ☐ c. Vandalism ☐ d. Fire ☐
- e. Moving Object ☐ f. Stolen ☐ g. Stolen & Recovered ☐

Time Started

Time completed

1) CSO

2) ABS

3) Entire Operation Completed Time:

Claim Handling

Accident MT/1017147

Policy No.	509687398	Vehicle No.	SGZ2206R	GST Registration No.	
Certificate No.					
Policyholder Name	LIONG KWOK YEAN (LIANG GUOXIAN)			Policyholder NRIC	S7702322D
Product Code	PRIVATE CAR INSURANCE	Cover Type	drive CLASSIC	Loading	0
Contact No.(Mobile)	92251750	Contact No.(Office)		Contact No.(Home)	
Email Address		Special Remark		eCode	No
KFK	+ No Yes	TCA	+ No Yes	eCode Reason	
NCD Protection	No	NCD Entitlement(%)	0	Private Hire	No

Accident Details

Report Date	25/10/2018 14:21	Accident Report Within 24 hrs	Yes	Accident Type	Collision - Head to Rear
Date of Accident	25/10/2018	Time of Accident (hh:mm)	08:30	Country of Accident	Singapore
Reporting Centre	NATIONAL ASSESSMENT CENTR	Orange Force	No	ICM No.	
Accident Location	PIE (CHANGI AIRPORT) NEAR CHANGI CITY EXIT				

Excess

Own damage Excess	600.00	Additional Excess	0	Windscreen Excess	100.00
Unnamed Driver Excess	0.00	Outside Singapore OD Excess	600.00		
Third Party Excess	0.00	Outside Singapore TP Excess	0.00		

Benefits

GST Registered Information

GST Registered	No	GST Registration Date	
GST Registration No.		GST Status Verified	Yes
Modification History			

Policyholder Mailing Address

Address 1	BLK 259 #04-330	Address 2	TAMPINES STREET 21	Address 3	SINGAPORE 520259
Address 4		Address Type	Singapore address	Post Code	520259
Unit No.		Related Policy Number	509687398		

O1 Driver Info

Driver Name	LIONG KWOK YEAN	Driver Type	Main Driver	Driver DOB	23/01/1977
Unnamed driver Name		Driver NRIC	S7702322D	Driving Experience	21
Register Date of Driver License	01/01/1997	Driver Age	41	Contact No.(Home)	
Contact No.(Mobile)	92251750	Contact No.(Office)		Address 3	SINGAPORE 520259
Address 1	BLK 259 #04-330	Address 2	TAMPINES STREET 21	Post Code	520259
Address 4		Address Type	Singapore address		
Unit No.					
Does he own a Singapore Registered car?	Yes + No	Driver Vehicle No.	SGZ2206R	Driver Insurer Company	NTUC

Declaration

Breathalyzer or Blood Test Reading?	0 mg	Any injury?	Yes + No
-------------------------------------	------	-------------	----------

Modification History

Investigation

Claim 001 OD-MD

Claim: Case Officer Zursimae Bin Mantau

Claim Type	OD-MD	Insured Name	LIONG KWOK YEAN (LIANG GUC	Insured NRIC	S7702322D
Contact No.(Mobile)	92251750	Contact No. (Home)		Contact No. (Office)	
Email Address	KYLIONG@GMAIL.COM.SG	CI Vehicle Number	SGZ2206R	TP Vehicle Number	SLZ4304T
Claim Description	SGZ2206R / SLZ4304T ON 25 Oct 2018			Name of Preferred Workshop	
Preferred Workshop Contact Registration	Yes	Preferred income to assign workshop		Insured liability report	Fully at Repaired
Date Registered	25/10/2018 14:59	Claim Close Date		Date Received	25/10/2018 00:00
Report Taken By	ROSLI WAHAB	Workshop Repairer		Total Loss Int. Repaired	
				OD Excess Collected by Workshop	

Print AK letter

Modification History

Special Claim Creation Approval

Approval	Reason
Remarks	

damage assessment Attachment

Vehicle Info

Vehicle Make	HONDA	Vehicle Model	STREAM	Engine Capacity	
Date of Registration	23/10/2007	Class No.	RNS1040440		
Towing Required *	☐ Yes ☒ No	Vehicle in IDAC *	☐ Yes ☒ No	Parallel Import *	☐ Yes ☒ No
Type of Tender	Own Damage	Assessor Name *	ROSLI WAHAB	Survey Current Status	

IDAC/Workshop Name NATIONAL ASSESSMENT CENTR

IDAC/Workshop Location 51 UB1 AVENUE 1 #01-25 PAYA

Windscreen
Parts & Labour
CostTotal Loss * ☐ Yes * ☒ No

Market Value(\$)

Scrap Value(\$)

Economical Repair Value(\$)

Remark

Remark for
Supplementary

Damage Listing

Find a Part	No.	Part No.	Description	Qty *	Repair Code *	
root						
Not Applicable	1	16000101	BUMPER (FRONT)	1	Replace	☒
ABS	2	16001201	BUMPER BRACKET (FRONT LEFT)	1	Replace	☒
ABSORBER	3	16001302	BUMPER BRACKET (FRONT RIGHT)	1	Replace	☒
ACCELERATOR	4	16002401	BUMPER CLIPS (FRONT)	1	Replace	☒
ACTUATOR	5	16002701	BUMPER FOG LAMP (FRONT LEFT)	1	Replace	☒
ADVERTISEMENT STICKER	6	16002702	BUMPER FOG LAMP (FRONT RIGHT)	1	Unconfirm	☒
AIR BAG	7	16002901	BUMPER FOG LAMP COVER (FRONT LEFT)	1	Unconfirm	☒
AIR BLOWER	8	16002902	BUMPER FOG LAMP COVER (FRONT RIGHT)	1	Unconfirm	☒
AIR BOX	9	16005001	BUMPER REINFORCEMENT (FRONT)	1	Unconfirm	☒
AIR CHAMBER BOX	10	16005101	BUMPER RETAINER (FRONT LEFT)	1	Replace	☒
AIR CLEANER	11	16005102	BUMPER RETAINER (FRONT RIGHT)	1	Replace	☒
AIR COMPRESSOR	12	16005601	BUMPER SPONGE (FRONT)	1	Unconfirm	☒
AIR CON	13	41300101	SUPPORT PANEL (FRONT)	1	Repair	☒
AIR CON (VAN)	14	41300801	SUPPORT PANEL TOP GARNISH (FRONT)	1	Unconfirm	☒
AIR COOLER	15	27100601	GRILLE EMBLEM (FRONT)	1	Replace	☒
AIR DISTRIBUTOR	16	27100101	GRILLE (FRONT)	1	Unconfirm	☒
AIR FILTER	17	27700101	HEAD LAMP (LEFT)	1	Unconfirm	☒
AIR FLOW	18	27700102	HEAD LAMP (RIGHT)	1	Replace	☒
AIR GRILLE	19	149001	BONNET	1	Replace	☒
AIR HORN	20	149029	BONNET INSULATOR	1	Replace	☒
AIR INTAKE	21	14903401	BONNET LOCK (LOWER)	1	Replace	☒
AIR RESONATOR BOX	22	14903402	BONNET LOCK (UPPER)	1	Replace	☒
AIR THROTTLE BODY AND SENSOR	23	14902201	BONNET HINGE (LEFT)	1	Replace	☒
ALARM	24	14902202	BONNET HINGE (RIGHT)	1	Replace	☒
ALTERNATOR	25	149041	BONNET RUBBER (CENTRE)	1	Replace	☒
ALUMINIUM PANEL - SIDE	26	112023	AIR CON CONDENSER	1	Unconfirm	☒
AMPLIFIER	27	344001	RADIATOR	1	Unconfirm	☒
ANTENNA						
ANTI ROLL						
APRON						
ARCH						
ARM REST						
ASH TRAY						
AUTO CLUTCH						
AUTO COOLER PIPE						
AUTO CRUISE MOTOR						

Save Submit

rsbm

From: Zuraimee Bin Mantau <zuraimee.mantau@income.com.sg>
Sent: Friday, 26 October, 2018 11:39 AM
To: Modern Automotive (admin@modernautomotive.com.sg)
Cc: LKK Bukit Merah (rsbm@lkkauto.com); LKK Paya Ubi
Subject: Vehicle SGZ2206R, OD Claim No: MT/1017147-001, DOA: 25/10/2018

Dear Modern Automotive

Excess \$600 applies.

Vehicle is currently with the owner. Please arrange with Mr Liang Kwok Yean at 92251750 for the repair.

Strictly no further supplementary is allowed.

**Please forward the invoice and DV within 7 working days to us once repairs has been done.
Update the 'Repair Status' when repairs are done.**

XX

Our Ref: MT/CA/OD/051/1017147-001/ZBM

26 Oct 2018

MODERN AUTOMOTIVE PTE LTD

BLK 3023A #01-61 UBI ROAD 1

SINGAPORE 408717

Dear Sir

CLAIM NUMBER: MT/1017147-001

REPAIR OF VEHICLE NUMBER: SGZ2206R

We are pleased to inform you that you are successful in your tender to repair the vehicle. The details are as follows:

Award Date: 26 Oct 2018

Make: HONDA

Model: STREAM

Estimated Repair Days: 4

Location: NATIONAL ASSESSMENT CENTRE SERVICES (BUKIT MERAH)

Address: 51 UBI AVENUE 1 #01-25 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Benefits Applicable: N/A

Excess Applicable: 600.00

Please note that supplementary items will not be allowed.

If you have any queries, please contact Zuraimee Bin Mantau at 64307891 or email us at

motor@income.com.sg.

Yours sincerely

Jenny Pe

Deputy Vice President

Motor Insurance

Thank you

Zuraimee Bin Mantau

Senior Executive

Motor Insurance

T +65 6430 7891



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

ACCIDENT STATEMENT

ACCIDENT DATE: 25/10/2018 (DD/MM/YYYY) TIME: 08:30 (HH:MM)

LOCATION: PIE (Changi Airport) near Changi city exit (towards ECP)

1. DETAILS OF VEHICLE

- a) VEHICLE NUMBER: SGZ 2206 R
 b) INSURANCE COMPANY: HTUC
 c) POLICY NUMBER: 5096687398
 d) POLICY TYPE: COMPREHENSIVE / THIRD PARTY / THIRD PARTY FIRE & THEFT
 e) MAKE & MODEL: HONDA STREAM 1.8
 f) TYPE: (SALOON / COUPE / MPV / VAN / LORRY / MOTORCYCLE / OTHERS)
 g) VEHICLE CATEGORY: (PRIVATE / COMMERCIAL / MOTORCYCLE)
 h) PURPOSE OF USING AT ACCIDENT TIME: GOING TO OFFICE
 i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO)
 IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY)

2. INSURED / POLICY HOLDER

- A) NAME: LIONG KWOK YEAN (MALE / FEMALE)
 b) NRIC/FIN/PASSPORT: S7702322 CONTACT: 92251752
 c) ADDRESS: BLK 559, TAMPINES ST 21
#04-330, S(520259)

* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

DRIVER

- a) NAME: LIONG KWOK YEAN (MALE / FEMALE)
 b) NRIC/FIN/PASSPORT: S7702322 CONTACT: 92251752
 c) ADDRESS: BLK 559, TAMPINES ST 21
#04-330, S(520259)

* d) DATE OF BIRTH: 23/01/1977 (DD/MM/YYYY)

e) OCCUPATION: (INDOOR / OUTDOOR)

f) DATE OF DRIVING PASS 31/7/2007

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES/NO)

IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED:

5. a) WEATHER CONDITION: (CLEAR / RAINING / OTHERS)

b) ROAD SURFACE: (DRY / WET / OTHERS)

6. WAS ANYBODY INJURED (YES/NO)

7. a) REPORTED TO POLICE (YES/NO)

IF YES, PLEASE STATE WHICH POLICE STATION:

8. THIRD PARTY VEHICLE

- a) VEHICLE NUMBER: SLZ 4304 T MODEL: HONDA VEEZEL
 b) DRIVER'S NAME: LIM YU JIE JOSEPH
 c) NRIC/FIN/PASSPORT: S86353442 CONTACT: 86851212

9. THIRD PARTY VEHICLE

- d) VEHICLE NUMBER: _____ MODEL: _____
 e) DRIVER'S NAME: _____
 f) NRIC/FIN/PASSPORT: _____ CONTACT: _____

email = Kyliang@gmail.com

fax =

VIDEO

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7702322D



Name

LIONG KWOK YEAP
(LIANG GUOXIAN)

梁国贤

Race

CHINESE

Date of birth

23-01-1977

Sex

M

S7702322D

Country of birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S7702322D

Name

LIONG KWOK YEAP
(LIANG GUOXIAN)

Birth Date: 23 Jan 1977

Issue Date: 31 Jul 2007



3995160

NRIC No. S7702322D



Date of issue

05-02-2007

APT BLK 259 TAMPINES STREET 21 #04-330
SINGAPORE 520259
S7702322D

20/07/2013

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3

Motor Cars < 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles < 2500kg

PASS DATE

31 Jul 2007

NP 428A



Policy Query

Policy No.		Date of Accident	25/10/2018 15:10
Vehicle No.(For Motor)	SGZ2206R	Certificate Number	
Search			

Select	Policy No.	Certificate Number	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	5096687398		LIONG KWOK YEAN (LIANG GUOXIAN)	S7702322D	GPC	drive CLASSIC	SGZ2206R	SGZ2206R	15/12/2017	14/12/2018