

22/03/2002

ASS. RFC. BY:

REF: CS3/MSG18019403/R1cd3e1 Special Instruction:

Surveyor: Rasul  
Monir

ASSIGNMENT (Office)

From (Person): Jasmine Tok

of

MSG

Date/Time:

24/10/18 @ 4pm

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJO 9361R

Insured:

SIF 66802

at Workshop m/s

AMA Autocare

Tel:

8778 3636

of

36 Joh Guan Rd East #01-36

Policy No:

80456695 QMX

Claim No:

573963

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 20/10/2018

CA / REV / REP. / REV 24 HRS

'up'

H.O.D. Endorsement:

Date/Time:

11:27am @ 25/10/18

Person Contacted:

MelvinVehicle ☒ IN / OUT

Date/Time	Action/Instruction (x) Estimate
	<u>SJO 9361R - X</u>
	<u>SIF 66802 - X</u>
	<u>Dismantle: 25/10/2018</u>

108-111  
Surrey *Panu*

REF:


ASSIGNMENT

95764  
COG EXPIRY: 2019/11/14

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
To Inspect Vehicle No: SJQ 9361R  
at Workshop m/s AMA Automotive  
of 26, 70th Avenue Road East # 01-36  
Insured: MSIG  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: 11K  
IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 6 days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJQ 9361R Yr Regn: 2009 / 11/14  
Type: C M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or

Make: Hyundai Avante 1.6A c.c (591  
Colour: WHITE A/C: Insured / Std / NI / NA  
Sp. Reading: 185204 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_  
C/No: KM HCU 41BRQU 757904

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or

Brake: Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15  
R: -

C BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front Rear  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. 20/10/18 D.O.I. 28/10/18  
Survey held at AMA Automotive

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

- Estimate repair range \$5,000 - \$6,000.

*[Signature]*  
29/10/2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Survey Fee:

Transportation:

\_\_\_\_ \$ + RS \_\_\_\_ SI

Photos

Others

TOTAL

Report Format: PRQ

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

120

10

130

## ...CLAIM SUBFOLDER...(New Assignment)

**CLAIM SUBFOLDER TRACKING**

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Oct 2018		24 Oct 2018 16:00 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main

Reference

Claim Details

Documents

[Show All](#)
**CLAIM SUBFOLDER DETAILS**

[Created by insurer]

Insured:	SUZANA BINTE SARIKON, ID: S7033762B		
Main Claimant:	TAN KIAN LI JASON, ID: S8729976G		
Vehicle Reg. No.:	SJQ9361R	Date of Loss:	20/10/2018 00:00 - :59 [112 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 573963	Policy/Cover Note No.:	80456695QMX Coverage: 29/04/2018 - 28/04/2019
Vehicle Reg. No. (Insured):	SLF6680Z	Policy No. (Claimant):	
		Excess:	
Repairer:	Ama Autocare Pte Ltd (HQ) 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 25/10/2018]		
Adj Asg. Remarks:	Non Reporting. Liability unclear. Contact Person: Mr Melvin / 8778 3636. TP disagree with our SJE list. Proceed to appoint LKK Auto Consultants.		

**ASSOCIATED MAIL RECEIVED**
[View All](#)[Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS**
[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



Aviva Ltd., 4 Shenton Way, #01-01 SGX Centre 2, Singapore 068807 Tel: (65) 6627 9966 www.aviva.com.sg

## CERTIFICATE OF INSURANCE

ROAD TRANSPORT ACT 1987 (MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP 189 OF THE REVISED EDITION)  
(REPUBLIC OF SINGAPORE)  
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION  
(REPUBLIC OF SINGAPORE) OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

CERTIFICATE NUMBER, 10834823

- 1) VEHICLE REGISTRATION NO. SJQ9361R
- 2) NAME OF INSURED  
FAMILY NAME TAN  
GIVEN NAME KIAN LI JASON
- 3) EFFECTIVE DATE OF COMMENCEMENT OF INSURANCE FOR THE PURPOSE OF THE ACT 30-May-2018 00:00hours
- 4) DATE OF EXPIRY OF INSURANCE 29-May-2019 23:59hours
- 5) PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE  
You and any driver aged 30 or over  
  
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by any reason of any enactment or regulation in that behalf from driving the Motor Vehicle.  
  
And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been canceled at the time of accident or loss.  
  
Please refer to the policy document for full terms and conditions.
- 6) LIMITATIONS AS TO USE\*  
Use only for social, domestic and pleasure purposes and for the Insured's business. The Policy does not cover use for hire or reward, tuition or driving tests, racing, pace-making, reliability trials, speed-testing or the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with the Motor Trade.  
  
\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.
- NAMED DRIVER
- 7) FINANCE COMPANY

I / We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia), or any amendment, act or acts passed in substitution thereof.

Issued in Singapore: 14-May-2018 at 23:42hours

Aviva Ltd.

### IMPORTANT NOTE:

- If you want to cancel your policy at any time, you will need to return the certificate to us.
- You must report all accidents to us within 24 hours of the occurrence or by the next working day at our accident reporting centre regardless of whether you intend to claim on your own policy or not, or whether your car is damaged or not. Should you fail to do so, Your NCD could be affected and your claim may be prejudiced.

For the list of our accident reporting centres, please visit <https://www.aviva.com.sg/Car/Repairs>. Alternatively, you may call us at 6333 2222 for assistance (including assistance on windscreen damage).

Nishit Majmudar  
Chief Executive Officer

In case of vehicle breakdown, accident or windscreen damage, please call 6333 2222 (24 hours) immediately.

ORIGINAL

**REPUBLIC OF SINGAPORE DRIVING LICENCE**

**S8729976G**

**TAN KIAN LI, JASON**  
**CHEN JIANLI**

Birth Date: 23 Sep 1987  
Valid Date: 16 Oct 2015

002483918K

SG 50

**REPUBLIC OF SINGAPORE**  
**IDENTITY CARD NO. S8729976G**



Name

**TAN KIAN LI, JASON**  
**(CHEN JIANLI)**

**陳 建 利**

Race

**CHINESE**

Date of birth

**23-09-1987**

Sex

**M**

Country/Place of birth

**SINGAPORE**

S8729976G

**YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)**

**Class 3** Motor Cars =< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg

**EFFECTIVE DATE**

**06 Mar 2008**

NP 428A



Licence No: S8729976G

5914536



NRIC No **S8729976G**



Date of issue

**13-04-2018**

Address

**APT BLK 205 BUKIT BATOK STREET 21**  
**#09-60**  
**SINGAPORE 650205**

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9976G
Vehicle Details	
Vehicle No.:	SJQ9361R
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Oct 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	HD AVANTE 1.6 A
Primary Colour:	White
Manufacturing Year:	2009
Engine No.:	G4FC9U653002
Chassis No.:	KMH DU41BR9U757904
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,362.00
Original Registration Date:	30 May 2009
First Registration Date:	30 May 2009
Transfer Count:	2
Actual ARF Paid:	\$11,362.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 May 2019
PARF Rebate Amount:	\$5,681.00
Intended COE Rebate Details	
COE Expiry Date:	29 May 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$9,889.00
COE Rebate Amount:	\$576.00
<b>Total Rebate Amount:</b>	<b>\$6,257.00</b>

The information contained herein is correct as at 29 Oct 2018

OK

11,000  
6,257  
4743  
//

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/10/2018 22:06
Date Of Accident	20/10/2018 13:50
Exact Location Of Accident	PIE TOWARDS CHANGI AT CTE ENTRANCE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJQ9361R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN KIAN LI JASON
NRIC No	S8729976G
Email Address	TKL.JASON@GMAIL.COM
Mobile Phone No	(LOCAL) +65-91523880
Alternative Phone No	OFFICE-91523880

### Vehicle Particulars

Manufacturer	HYUNDAI
Model	HD AVANTE 1.6 A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10834823
Cover Note Number	

### Driver

Name of Driver	TAN KIAN LI JASON
NRIC No	S8729976G
Date Of Birth	23/09/1987
Occupation	INDOOR
Date Of Driving Pass	06/03/2008
Driving Experience	10 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91523880
Fax Number	
Contact Number	OFFICE-91523880
Email Address	TKL.JASON@GMAIL.COM

Address APT BLK 205 BUKIT BATOK STREET 21 #09-60 SINGAPORE 650205

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

I WAS DRIVING ALONG PIE TOWARDS CHANGI. WHEN THE TRAFFIC IN FRONT SLOWED DOWN, I SLOWED DOWN MY VEHICLE AS WELL. SUDDENLY VEHICLE B COLLIDED ONTO THE REAR OF MY VEHICLE. NO INJURIES INVOLVED.

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: WILL UPLOAD VIDEO INTO MERIMEN ONCE INSURED SEND

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLF6680Z

Vehicle Make/Model/Colour MITSUBISHI/ASX 2.0 6-CVT (M) ABS D/AIRBAG SR 2WD

Details Of Properties

Vehicle Category PRIVATE CAR

Name of Driver SULAIMI THAQIF BIN TAJUDDIN

NRIC/Passport Number S9616431I

Contact Number 98002415

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)



# Sketch Plan

1. Please read carefully the details of the accident to assist in the claims process.
2. This form must be completed by the policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any false representation or withholding of material facts may affect insurance cover and/or result in repudiation of policy benefits.
4. The loss and attendance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers to the CJA Accident Management Centre established by the General Insurance Association of Singapore (GIAS) for advising and the copies of this report will be made available upon request by interested parties.
7. By the submission of this report to the insurers, you hereby consent to the forwarding of this report to the centre and to update of the report being made available.

## Consent under the Personal Data Protection Act (PDPA)

I, the undersigned, hereby agree and consent that:

- (a) the insurer, my workshop and the General Insurance Association of Singapore (GIAS) may be permitted to collect, use, disclose and/or process my personal information (including but not limited to my name, my vehicle registration number and any other personal information provided by me or possessed by my insurer) (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurers who have issued and/or are involved in this accident (all insurers who have issued and/or are involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the Police) for the purposes of:
  - (i) facilitating the handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims including the making of correspondence, assessments, invoices, reports or notices to me, which could involve processing of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages; and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurers (and their insurers' lawyers/law firms) involved in this accident and the insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for two or more of the above Purposes; and
- (c) my Personal Information may also be disclosed by any of the Insurers and/or GIAS to their third party service providers or agents (including their lawyers/law firms), which may be third parties of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS  
REPORTING OFFICER  
Jun Keat

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

## Sketch Plan



Common Statement

ACCIDENT STATEMENT (2000 characters)

I WAS DRIVING ALONG PIE TOWARDS CHANGI. WHEN THE TRAFFIC IN FRONT SLOWED DOWN, I SLOWED DOWN MY VEHICLE AS WELL. SUDDENLY VEHICLE B COLLIDED ONTO THE REAR OF MY VEHICLE. NO INJURIES INVOLVED.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
WONG JUN KEAT

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

20 October 2018 at 5:01 PM

Date/Time:

20 October 2018 at 5:01 PM

### ...CLAIM SUBFOLDER...(Pending for Survey Report)


























CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Oct 2018		24 Oct 2018 16:00 <a href="#">Edit Adj Rpt</a>	<b>S\$0.00</b> <a href="#">Edit Estimates</a>	<b>S\$0.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: <b>SUZANA BINTE SARIKON</b> , ID: S7033762B									
Main Claimant: <b>TAN KIAN LI JASON</b> , ID: S8729976G									
Vehicle Reg. No.:	<b>SJQ9361R</b>	Date of Loss:	20/10/2018 00:00 - :59 [112 Months and 20 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 573963</b>	Policy/Cover Note No.:	80456695QMX Coverage: 29/04/2018 - 28/04/2019						
Vehicle Reg. No. (Insured):	<b>SLF6680Z</b>	Policy No. (Claimant):							
		Excess:							
Repairer: <b>Ama Autocare Pte Ltd (HQ)</b> 36 Toh Guan Road East, #01-36, 608580 Jurong East - Tel:									
Handling Insurer: <b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Pauline Tham</b> - 6594 2545]									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Imm.Advice due 25/10/2018]									
Adj Asg. Remarks: Non Reporting. Liability unclear. Contact Person: Mr Melvin / 8778 3636. TP disagree with our SJE list. Proceed to appoint LKK Auto Consultants.									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJQ9361R (573963)  
[SLF6680Z]  
TP  
TAN KIAN LI JASON  
Oct 20 2018 12:00AM  
[SUZANA BINTE SARIKON]  
Ama Autocare Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
2	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
3	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
4	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
5	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
6	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
7	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
8	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
9	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
10	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
11	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
12	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
13	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
14	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
15	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
16	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
17	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
18	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
19	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
20	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
21	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
22	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
23	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
24	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
25	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
26	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
27	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
28	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
29	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
30	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
31	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
32	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
33	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
34	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
35	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
36	29/10/18 15:42	General View						Load JPG	<input checked="" type="checkbox"/>	
37	29/10/18 15:43	Photographs of Damaged Parts						Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	29/10/18 15:43	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	24/10/18 10:47	Email - PRI	 Load PDF	
2	24/10/18 10:47	Notice of PRI	 Load PDF	
3	24/10/18 10:47	TP disagree with our SJE list. Proceed to appoint LKK	 Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>				
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>				

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18019403/R1CD3E2

Date: 02/11/2018

## REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 80456695QMX

Claimant Vehicle No : SJQ9361R

Insured Vehicle No : SLF6680Z

Date of Loss: 20/10/2018

Nature of Claim: TP

Claim No: 573963

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SJQ9361R

Make &amp; Model: HYUNDAI HD AVANTE 1.6 A (BI-FUEL), 1.6 (A)

Engine No: G4FC9U653002

Reg. Date: 30/05/2009 (Man. Year: 2009)

Chassis No: KMH DU41BR9U757904

Colour: White

Odometer: 185204 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 185/65 R15

Rear Tyre Size: 185/65 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

## INSPECTION

Date of Assignment: 24/10/2018

Date Inspected: 25/10/2018 Inspected At:

Ama Autocare Pte Ltd (HQ)  
36 Toh Guan Road East, #01-36  
Singapore 608580

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.

B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.

THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000.00 -\$6,000.00



## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 02 Nov 2018)
<b>Parts:</b>	143	HYUNDAI HD AVANTE 1.6 A (BI-FUEL) 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJQ9361R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.



## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >