

**MOVA AUTOMOTIVE PTE  
LTD**

**MOVA BUILDING  
22 JALAN KILANG  
SINGAPORE 159419**

**Claim Reference: TP  
Assessment Number: CK132960  
Version: MOVAAUTO/1  
Date Calculated: 24/10/2018 05:54**

**Full Report - V1  
Registration: SDL5141H  
Printed: 24/10/2018 13:15**

**Summary Information**

**Claim**

Location:	Singapore (SG)	Currency:	SGD
Printed by:	Jacelyn Ooi	Date of Incident:	21/10/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	AXA Insurance S'pore Pte Ltd	Repairs Authorised:	TBA
Claim Reference:	TP	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:		Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

**Vehicle Details**

**Vehicle**

Manufacturer:	MERCEDES
Model:	E Class
Sub Model:	200 KOMPRESSOR
Model Sheet Number:	341 43
Registration:	SDL5141H
Registration Month:	
Registration Year:	
VIN Number:	WDB2110412B325979
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%

**Model Specs**

EQUIPMENT AVANTGARDE	HEAVY DUTY COOLING
FROM VIN B296713	FOLDING DOOR MIRRORS
AUDIO SYSTEM 20 CC	CD AUTO CHANGER
BI-XENON HEADLAMPS	HEADLAMP WASHERS
LEATHER UPHOLSTERY	MEMORY PACKAGE
ILLUM SUN VISORS	DIPPING MIRROR
L/F MEMORY SEAT ADJ	LEATHER STRG WHEEL
KEYLESS GO	EQUIP CURLED MAPLE
EMISSION STD EURO 4	H/DUTY ALTERNATOR
AUTO GEARBOX 5 SPEED	PARAMETER STEERING
TYRES 245/45 WR 17	SPARE WHEEL
EXTENDED FUEL TANK	ALU WHEEL 8 J X 17
MODEL 2008	TWO COAT METALLIC
PREPARE OFF VEHICLE	CLEAR COAT HARD

**Vehicle Condition**

**Vehicle Status**

Pre-Accident Condition: **Advisors Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Brakes Pedal Travel: **TP**

Place of Inspection: **TP**

Pre-Accident Damage: **TP**

Tyres Condition: **TP**

Tread Depth LHF: **TP**

Tread Depth LHR: **TP**

Damage Areas: **TP**

Signature: **TP**

Date: **TP**

Severity of Impact:  
Vehicle Status on  
Inspection:  
Date of Inspection:

24/10/2018

Tread Depth RHF:  
Tread Depth RHR:  
Direction of Impact:

Tan Jiah 97495749  
WP  
7/11/18 11:50pm  
Resurvey before paint  
sue@144auto.com  
03 days

**MOVA AUTOMOTIVE PTE LTD**

Claim Reference: TP

Assessment Number: CK132960



Version: MOVAAUTO/1

Date Calculated: 24/10/2018 05:54

Full Report - V1

Registration: SDL5141H

Printed: 24/10/2018 13:15

**Addresses****Cost Summary**

Total Labour	\$526.50
Total Paint/Material	\$67.30
Total Parts	\$2,185.00
Excess:	TBA
Grand Total Exc GST:	\$2,778.80
7 % GST:	\$194.52
Grand Total Inc GST:	\$2,973.32

**Repair Information****LABOUR**

Time Basis 10 WU = 1 HR. Price/CL 1 = \$45.00/HR

Price/Dent = \$45.00/HR

**Repair /****Guide Number Repair Details**

		WU	Cost Price (\$)
40-6500 01	ALIGNMENT CPL BEFORE REPAIR	7.0	31.50
40-6500 01	ALIGN VEHICLE CPL	7.0	31.50
40-4064 01	ADJUST FRONT AXLE TOE	2.0	9.00
40-6717 01	ADDITIONAL TO OPTICAL ALIGNMENT	6.0	27.00
	ADJUST R/FRONT AXLE HALF CAMBER/CASTER		
88-3956 01	RENEW R/F WING	15.0	67.50
	INCLUDES: R + R PARTITION CPL		
40-1580 01	R + R LEFT AND RIGHT FRONT WHEEL	3.0	13.50
40-2710 01	FIT R/F WHEEL	3.0	13.50
40-2125 ZAX	BALANCE WHEEL ASS WORK	2.0	9.00
33-2280 02	R + R RIGHT FRONT WHEEL HUB, RENEW RING SEAL (WHEEL REMOVED)	13.0	58.50
	INCLUDES: R + R BRAKE CALIPER WITH ATTACHED BRAKE HOSE		
1156	REPAIR R/UPP W-HOUSE S-MEMB	10.0*	45.00
0840	CHECK R/F W-HOUSE CVR FRT		
0842	CHECK R/F W-HOUSE CVR REAR		
7050	CHECK R/F UPP CONTROL ARM		
7072	CHECK R/F TENSION ROD		
7082	CHECK R/F STEERING KNUCKLE		
7088	CHECK R/F SHOCK ABSORBER		
7312	CHECK R/OUTER TIE ROD BALL		

**LABOUR COST****Total Work Units**

68.0

**Panel / Mechanical Labour**

4.6HRS

\$207.00

**Visual Alignment Labour**

2.2HRS

\$99.00

**Corrosion Protection External Labour**

0.0HRS

0.00

**Corrosion Protection Internal Labour**

0.0HRS

0.00

**Sub Total**

6.8HRS

\$306.00

# MOVA AUTOMOTIVE PTE LTD

Claim Reference: TP  
 Assessment Number: CK132960  
 Version: MOVAAUTO/1  
 Date Calculated: 24/10/2018 05:54

Full Report - V1  
 Registration: SDL5141H  
 Printed: 24/10/2018 13:15

Paint Labour	4.9HRS	\$220.50
Total Labour	11.7HRS	\$526.50

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$45.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- TWO COAT METALLIC		
	- PREPARE OFF VEHICLE		
742	R/F WING NEW PART PAINTING	11.0	
782	R/F WING MOULDING NEW PART PAINT K1R	3.0	
1156	R/UPP W-HOUSE S-MEMBSURFACE PAINT	5.0	
<b>LABOUR COST - PAINT</b>			
	TIME(PAINT)	19.0	
	Preparation Main Work Plastic	5.0	
	Preparation Main Work Metal	25.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	49.0	
	Total Paintwork Labour	4.9HRS	\$220.50
<b>MATERIAL COST - PAINT</b>			Cost Price
	New Part Painting		\$23.74
	New Part Painting - Plastic K1R		\$0.98
	Material-Constant Main Work Metal		\$28.60
	Surface-/Blend Paint		\$4.98
	Material-Const Main Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$67.30
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$67.30

## PARTS

Guide No. Qty		Description	Part Number	Supplier	Bet.	Price (\$)
7202	1	R/F WHEEL ALLOY	211 401 3602		0%	530.00*
7132	1	R/F WHEEL HUB	230 330 0325		0%	850.00*
742	1	R/F WING	211 880 1418		0%	440.00*
786	1	R/F WING BADGE	211 817 4820		0%	35.00*
782	1	R/F WING MOULDING	211 690 2862 9999		0%	45.00*
f: OEM Parts			Sub Total			\$1,900.00
g: Original			Mark Up From Cost	(15 %)		\$285.00
h: Secondhand			Sundry Parts	(Fixed)		\$0.00
p: Parallel			<b>Total Parts</b>			<b>\$2,185.00</b>
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

**Total Extras** \$0.00

## Final Calculation

<b>Total Parts</b>	\$2,185.00
<b>Labour</b>	
Total Panel/Mechanical	\$207.00
Total Paintwork	\$220.50
Total Visual Alignment work	\$99.00
<b>Total Labour</b>	<b>\$526.50</b>
<b>Total Paint/Material Costs</b>	<b>\$67.30</b>
<b>Grand Total Excludes GST</b>	<b>\$2,778.80</b>

**MOVA AUTOMOTIVE PTE LTD**

**Claim Reference: TP**  
**Assessment Number: CK132960**  
**Version: MOVAAUTO/1**  
**Date Calculated: 24/10/2018 05:54**

**Full Report - V1**  
**Registration: SDL5141H**  
**Printed: 24/10/2018 13:15**

GST @ 7 %  
**Grand Total Includes GST**

**\$194.52**  
**\$2,973.32**

**Assessment Notes**