

15/02/11

INS. CASE OWNER:

Richard

CC4 / AXA1801

AGM: 4422, K ph352

LKK: IDAC:

Surveyor:

BSC

ASSIGNMENT
DOI: 25/10/06

Date / Time:

25/10/06

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLX 6687K

Claim No.:

98m0109V / 33471

Name of Insured:

PEK TELK HONG

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

27/10/06

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

If NO, Driver Name / Age:

(VA) YES / NO

Insured Liability: % Final? Yes / No

Driver Tel No.:

SLN 1976L



INSRS:
WSP:
Tel:
Liability:
RMKS:

Cheng Hoo



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time	STAGE	DATE / PIC
20/10/06	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	25/10/06
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	Towing Invoice:	<input type="checkbox"/> <input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input type="checkbox"/> <input type="checkbox"/>
	PIR:	<input type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LOD:	<input type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: Sent By: Confirm with: Confirm by:

FINALIZATION Date/Time: Confirm with: days) Reduction: % Email Call

Repair Cost: S\$

FINAL SETTLEMENT Date/Time: 27/11/06 Confirm with: June Email Call

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 200700.01D 6th

Repair Cost: S\$ 19260.00

Loss of Rental (LOR): S\$

Loss of Use (LOU): S\$ 780.00 (S\$ 60 x 13 days)

Loss of Income (LOI): S\$

LOR only LOU only LOR + LOU LOR + LO [Tick only one]

GIA/LTA Search: S\$ 8.00

Medical: S\$

Disbursement: S\$ (e.g. Tow/Independent)

Legal Cost: S\$

Total: S\$ 5078.00 Global Sum S\$: 20000.00 (as per AXA mandate)

FINAL PAYMENT Date/Time: Confirm with: Email Call

Payee 1: S\$ 20000.00 Name 1: Cheng Hoe Motor Pte Ltd

Payee 2: (Strike if N.A.) S\$ Name 2:

Payee 3: (Strike if N.A.) S\$ Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18019422/Kpb3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 25-10-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLX 6687K	Veh. Inspected	SLN 1976L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	25/10/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	23/10/2018	Inspection Date	25/10/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811
TEL: 63387288 **FAX:** 68804739
ATTN: Motor Claim Department
WS Ref: TP/AXA/YS
Claim Type: Third Party
Accident Date: 23/10/2018
TP Veh Reg No: SLX6687K

Estimate No: ES1891222/YISHUN
Date: 24 Oct 2018
Policy No: MT101628
Veh Reg No: SLN1976L
Make/Model: KIA FORTE K3 1.6A
Chassis No: KNAFJ411MH57144264
Engine No: G4FGGH647529
Reg. Date: 26/04/2017

Estimate Repair Cost to Vehicle No :SLN1976L

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
35 FRONT WINDSCREEN GLASS MOULDING	60.00	1 PC	60.00	✓
36 FRONT WIPER ARMS	108.00	2 PCS	216.00	✓
37 FRONT WIPER BLADES	75.00	2 PCS	150.00	✓
38 FRONT WIPER GARNISH (CENTRE)	80.00	1 PC	80.00	✓
39 FRONT WIPER GARNISHS (SIDES)	25.00	2 PCS	50.00	✓
40 FRONT WIPER NOZZLES	22.00	2 PCS	44.00	✓
41 TOP ROOF RUBBERS	48.00	2 PCS	96.00	✓
42 AIR-CON CONDENSER	687.00	1 PC	687.00	✓
43 RADIATOR	493.00	1 PC	493.00	✓
44 RADIATOR FAN ASSY	567.00	1 PC	567.00	✓
45 AIR-CON GAS DISCHARGE HOSE	617.00	1 PC	617.00	✓
46 AIR-FILTER DUCTING	94.00	1 PC	94.00	✓
47 AIR FILTER HOUSING	140.00	1 PC	140.00	✓
48 RADIATOR EXT PIPE	48.00	1 PC	48.00	✓
49 VACCUM PUMP	149.00	1 PC	149.00	✓
50 INLET MANIFOLD	906.00	1 PC	906.00	✓
51 FRT SUPPORT PANEL	662.00	1 PC	662.00	✓
52 AIRCON CONDENSER SIDE GARNISHS	28.00	2 PCS	56.00	✓
			16,579.00	
		Less 10%	1,657.90	14,921.10
Special Net				
53 FRONT NUMBER PLATE	35.00	1 PC	35.00	✓
54 REVERSE SENSOR	200.00	1 PC	200.00	✓
55 FRONT WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
56 ERP BRACKET	20.00	1 PC	20.00	✓
57 COOLANT (2 LTRS)	40.00	1 UNIT	40.00	✓
			335.00	335.00
Labour				
58 TOWING	50.00	1 LA	50.00	✓
59 REMOVE AND REFIX FRONT WINDSCREEN GLASS	100.00	1 LA	100.00	✓
60 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AXA INSURANCE (S) PTE LTD
 8 SHENTON WAY
 #27-02 AXA TOWER
 SINGAPORE 068811
TEL: 63387288 **FAX:** 68804739
ATTN: Motor Claim Department
WS Ref: TP/AXA/YS
Claim Type: Third Party
Accident Date: 23/10/2018
TP Veh Reg No: SLX6687K

Estimate No: ES1891222/YISHUN
Date: 24 Oct 2018
Policy No: MT101628
Veh Reg No: SLN1976L
Make/Model: KIA FORTE K3 1.6A
Chassis No: KNAFJ411MH57144264
Engine No: G4FGGH647529
Reg. Date: 26/04/2017

Estimate Repair Cost to Vehicle No :SLN1976L

Description	U/Price	Quantity	List Price	Amount
			SS	SS
61 REMOVE & REFIX FRT BUMPER ASSY,HEADLAMPS,GRILLE,BONNET & ATTACHMENT,RADIATOR,FRT FENDERS,MOTOR,TO CUT,WELD & RENEW FRT SUPPORT PANEL,KNOCK & REPAIR FRT LH FENDER, TOP ROOF PANEL,FRT FENDER INNER PANEL,PILLARS & REALIGN THE SAME	1,200.00	1 LA	1,200.00	1000
62 REMOVE & REFIX VACCUM PUMP,INLET MANIFOLD & CHECK ENGINE	100.00	1 LA	100.00	✓
63 PUTTY & RESPRAY ON TOP ROOF PANEL,FRT RH DOOR,FRT FENDERS,FRT BUMPER,SUPPORT PANEL,FRT FENDER INNER PANELS,BONNET & ALL AFFECTED AREAS	1,300.00	1 LA	1,300.00	1200
64 REMOVE & REFIX DASHBOARD,METER ASSY & CHECK WIRING	250.00	1 LA	250.00	✓
65 REMOVE & REFIX TOP ROOF LINING,SEAT,CARPET & WASH CUSHION	120.00	1 LA	120.00	✓
66 REMOVE & REFIX REAR BUMPER ASSY,TAILLAMPS,REAR BOOT & ATTACHMENT,CUT,WELD & RENEW REAR PANEL,REAR SPARE TYE COMPARTMENT,KNOCK & REPAIR REAR FENDERS,REAR CHASSISS & REALIGN THE SAME	1,500.00	1 LA	1,500.00	1400
67 PUTTY & RESPRAY REAR PANEL,REAR SPARE TYRE COMPARTMENT,REAR CHASSISS,REAR PANEL,BUMPER,BOOT	1,300.00	1 LA	1,300.00	1200
68 REMOVE & REFIX REAR UNDER CARRIAGE,REAR EXHAUST	250.00	1 LA	250.00	220
69 TO MOUNT ON CAR-O-LINER & REALIGN REAR CHASSIS	250.00	1 LA	250.00	✓
70 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
71 RUSTPROOFING	120.00	1 LA	120.00	✓
			6,700.00	6,700.00

Total SS 21,956.10

Add GST @ 7% 1,536.93

Total Amount Payable SS 23,493.03

24589.104

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

For Cheng Hoe Motor Pte Ltd



 AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

SLN 1976 L

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

Supp 1

M/S : TOKIO MARINE INSURANCE (S) LTD
 20 MCCALLUM STREET
 #09-01 TOKIO MARINE CENTRE
 SINGAPORE 069046

TEL: 62216111 FAX: 62212101
 ATTN: Motor Claim Department
 WS Ref: TP/AXA/YS
 Claim Type: Third Party
 Accident Date: 23/10/2018

Estimate No: ES1891222/YISHUN
 Date: 05 Nov 2018
 Policy No: MT101628
 Veh Reg No: SLN1976L
 Make/Model: KIA FORTE K3 1.6A
 Chassis No: KNAFJ411MH57144264
 Engine No: G4FGGH647529
 Reg. Date: 26/04/2017

Estimate Repair Cost to Vehicle No :SLN1976L

Description	U/Price	Quantity	List Price	Amount
			SS	SS
Supplementary 1				
Net Price				
1 DASHBOARD	<i>Net/Ln</i> 1,903.00	1 PC	1,903.00	
2 LH TAILLAMP	354.00	1 PC	<i>CM</i> 354.00	
3 ENGINE OIL STICK	30.00	1 PC	<i>CM</i> 30.00	
4 ENGINE OIL HOUSING	70.00	1 PC	<i>Net</i> 70.00	
5 REAR BUMPER REINFORCEMENT RETAINERS	7.00	5 PCS	<i>Net</i> 35.00	
6 FRONT BUMPER FOG LAMP GARNISHS	49.00	2 PCS	<i>Net</i> 98.00	
7 RADIATOR TOP HOSE	29.00	1 PC	<i>Net</i> 29.00	
8 EXHAUST HEAT SEAL	109.00	1 PC	<i>Net</i> 109.00	
9 REAR BUMPER RH LOWER COVER	42.00	1 PC	<i>Net</i> 42.00	
			2,670.00	
		Less 10%	267.00	2,403.00
Special Net				
10 FRONT CHASSIS PLATE	80.00	1 PC	<i>Net</i> 80.00	
11 REAR SPARE TYRE PANEL TOP COAT	150.00	1 PC	<i>Net</i> 150.00	
			230.00	230.00
		Total	SS 2,633.00	
		GST Amount	SS 184.31	
		Total Amount Payable	SS 2,817.31	

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

24589.10

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6671R
Vehicle Details	
Vehicle No.:	SLN1976L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	23 Oct 2018
Vehicle Make:	KIA
Vehicle Model:	FORTE K3 1.6A
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	G4FGGH647529
Chassis No.:	KNAFJ411MH5714264
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$11,958.00
Original Registration Date:	26 Apr 2017
First Registration Date:	26 Apr 2017
Transfer Count:	0
Actual ARF Paid:	\$11,958.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Apr 2027
PARF Rebate Amount:	\$8,968.00
Intended COE Rebate Details	
COE Expiry Date:	25 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,000.00
COE Rebate Amount:	\$41,600.00
Total Rebate Amount:	\$50,568.00

The information contained herein is correct as at 23 Oct 2018

OK

CHEAPEST CAR INSURANCE RENEWAL  Compare 10+ Insurers **GET A CHEAPER QUOTE NOW!**


kia k3 Price Range Depreciation 2017 Vehicle Type Submit Advanced Search

Home > Used Cars > Steven Mobile > Kia Forte K3 1.6A

Resources

- Car Buying
- Car Selling
- Car Ownership
- Car Aftermarket
- On The Move
- Lifestyle

Tyres



YOKOHAMA
Dramatic Silence. ADVAN

TRADING CURRENCY DATA MONEY TRANSFERS

Currency goes by **OANDA**

Kia Forte K3 1.6A

Overview Financial Accessories Similar Research Photos Map

Add to Shortlist Add to Compare Add a Note Report Error More Actions Share

Car Details

Price	\$67,800	1
Depreciation	\$7,270 /yr <small>View models with similar depreciation</small>	2
Reg Date	17-Apr-2017 <small>(Byrs 5mths 24days COE left)</small>	2
Manufactured	2017	2
Mileage	25,800 km (17k /yr)	2
Transmission	Auto	2
Engine Cap	1,591 cc	2
Road Tax	\$738 /yr	2
Power	95.3 kW (127 bhp) <small>View specs of the Kia Cerato K3 (2013-2018)</small>	2
Curb Weight	1,295 kg	2
Features	1.6L 4 Cylinders 16 Valves, DOHC Dual CVT Engine, 127BHP, 6 Speed Auto Transmission, SRS Airbags, ABS, Disc Brakes, Knockdown Rear Seats.	2
Accessories	Sports Rims, Leather Seats, Solar Film, Factory Audio System Aux/USB Port, Cruise Control, Multi Steering Wheel.	2
Description	1 Owner, KIA K 3, Low Dowpayment Only 12 K, Monthly \$792 x 84. Very Well Maintained, Low Depreciation, Bank Loan Or In House Loan. High Trade In All Welcome, Come Viewing/Test Drive Now.	2
COE	\$50,101	2
OMV	\$12,181	2
ARF	\$12,181	2
Dereg Value	\$51,646 as of today (change)	2
No. of Owners	1	2
Type of Veh	Mid-Sized Sedan	2
Category	PARF Car	2
Availability	Available	2

Add to Shortlist Add to Compare Add a Note

Posted on: 22-Oct-2018 | Last Updated on: 23-Oct-2018
Tags: Kia Forte, kia forte, 2017 Kia Forte, 2017 kia forte, Kia, Forte, forte, Used Kia

Upfront Payment > more Financial info

Transfer Fee	\$25	2
Down Payment	\$20,340 (change)	Maximum 70% Loan 2
1st Instalment	\$683	2
Total Upfront Payment	\$21,048 (excluding insurance)	2

Estimates based on 70% loan at 2.98% interest rate. Check with seller for exact figure.



Location Map Price Analysis

Seller Information

Company	Steven Mobile <small>> dealer's pricelist > 38 vehs sold 13 vehs available</small>
Address	8 Kaki Bukit Avenue 4 #07-16 <small>Search cars nearby this location</small>
Location	Premier @ Kaki Bukit
Office No	63489909
Contact Person(s)	Steven 96788282

Useful Services

STA VEHICLE INSPECTION

Afraid of lemons? Request to have this car evaluated professionally.
Vehicle Evaluation

Find out the market value for your car. Get a free Car Valuation.
Free Valuation

1 CRV \$17K



24 Hours Towing Services

Efficient Towing Services

403 Sin Ming Avenue #13-307, Sin Ming Garden, Singapore 570403

Ah Di Mobile: 8588 8877

Email : efficienttowing.sg@gmail.com

Business Reg. No: 53349344K

NO. 20132

CASH SALE / JOB ORDER

Date : 23/10/18

Messrs: CASH
 车牌 SLN1976L 车型 KIA K3
 Vehicle No. SLN1976L Model No: KIA K3
 时间 (日/夜) 1035 联络号码 97535453
 Time (day/night): 1035 Contact No: 97535453
 由 5050 ANG MO KEO IND.
 Location: 5050 ANG MO KEO IND.
 到 1019 YISHUN IND #01-374.
 To: 1019 YISHUN IND #01-374.
 银额 50h 其他 _____
 Cash S 50h Others: _____
 经手人 _____
 Authorised By: DEWISE Tow Truck Driver Name: TEO

- Jump Start/Changing of battery
- Tyre Replacement
- Accident/Breakdown
- Multi/Basement
- With Load/Cargo Box
- King Dolly
- Transport Charge
- Low Body Kit
- Door Opening Service
- Crane Up/Winch Out
- Collect Doc/Key
- Repo
- Woodlands and Tuas Checkpoint

注意: 本公司对所拖之车辆, 在迫行中如有任何损失或破坏, 一概由车主自行负责。

Note: Vehicle is towed at owner's risk. The company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

E. & O. E.

Enquire Vehicle & Owner Information (Vehicle No. SLX6687K As At 23 Oct 2018 / 08:20:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: CHM-SLN1976

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S7937320F

Owner Name: PEH TECK CHONG (BAI DECHONG)

Registered Address Type: HDB / HUDC

Registered Block/House No.:238

Registered Street Name: COMPASSVALE WALK

Registered Unit No.: # 09 - 552

Registered Building Name: -

Registered Postal Code: 540238

Current Vehicle Details

Vehicle No.: SLX6687K

Make Description/Model: HYUNDAI / ELANTRA AD 1.6 GLS AT (AMS)

Insurance Company Name: AXA INSURANCE PTE LTD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/10/2018 11:45
Date Of Accident	23/10/2018 08:20
Exact Location Of Accident	TPE TOWARDS SLE AFTER PUNGGOL RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN1976L
Insured/Policyholder	
Name Of Registered Owner	ADVANET PTE LTD
Co Reg No	200416671R
Email Address	BENEDETTE@ADVANET.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-63319122

Vehicle Particulars

Manufacturer	KIA
Model	FORTE K3-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	TOKIO MARINE INSURANCE SINGAPORE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MT101628
Cover Note Number	26/4/18-25/4/19

Driver

Name of Driver	GOH QI EN
NRIC No	S8733375B
Date Of Birth	27/10/1987
Occupation	INDOOR
Date Of Driving Pass	29/11/2007
Driving Experience	10 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97535453
Fax Number	
Contact Number	
EMail Address	NOEMAIL

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJU3727M
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	JUN LIANG
NRIC/Passport Number	
Contact Number	90676503
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SKU6773Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	IVY
NRIC/Passport Number	
Contact Number	90263096
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	


DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number	SHD6641U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	STEVEN
NRIC/Passport Number	
Contact Number	98369851
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number	SJK5171E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	POLLY
NRIC/Passport Number	
Contact Number	97505416
Address	
Postcode	

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along TPE towards SLE after Punggol Rd. I slowed down as m(car CB) ahead of me braked. I then continue to drive when the said vehicle e-braked. I immediately brake to stop and the next moment I felt an impact and realize I am involve in a chain accident. I got down and noted total 7 vehicles involved however no one was injured.

Police attended to the scene. After which EMAS came and tow my vehicle to the nearest o/park.

Note : Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

23/10/18

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.: (YS)

GIARMC SketchPlanForm_V3 Claim Own Policy Claim Third Party Reporting Only Claim OD/TP at other workshop ()

◀ Service Request Details

Claim

S8M0109V

Reference

None ✎

Loss Date

October 23, 2018

Request Date

October 24, 2018

Due Date

October 31, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

*25.10.2018 @ 11:07 am
Ifeoluwa Veh in
Kenneth*

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SLN1976L

Make

TPVD

Model

TBC

Service Address

...

Primary Contact/Insured

PEH TECK CHONK
BLK 238 COMPASSVALE WALK, #09-552, 540238, Singapore
91060994

Claim Handler

ANG Richard

richard.angbs@axa.com.sg

Additional Instructions
NON REPORTED

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message



26 October, 2018

PEH TECK CHONK
BLK 238 COMPASSVALE WALK, #09-552,
Singapore 540238

Dear Sir,

OUR REF : CC4/ASM18019422/Kpb3
YOUR REF : SLX 6687K
ACCIDENT INVOLVING SLX 6687K & SLN 1976L ON 23/10/2018 ALONG/AT TPE
TOWARDS SLE AFTER PUNGGOL ROAD

We write to inform you that we are the appointed loss adjuster by your motor insurer, AXA insurance Pte Ltd to deal with the third party claim against your motor policy.

We refer to the above subject matter. We have received third party claim(s) against your motor insurance policy.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We highlight that this accident has not been reported to your insurer. Under the Motor Claims Framework (MCF), you are required to report any accident with the accident vehicle (whether damaged or not) within 24 hours or by the next working day after the accident. The primary purpose of this reporting is to provide your version of the accident to AXA. Omission to report the accident will result in a loss of your No Claim Discount (NCD) upon renewal of your policy, and will prejudice any claim(s) by or against you. We would appreciate it if you could urgently file a report at our approved reporting centre.

The report has to be lodged at any of AXA Premium Workshops or reporting centres (subject to your policy). For the list of AXA Premium Workshops conveniently located throughout Singapore, please refer to the back of your Certificate of Insurance or the accompanying folder, or visit <https://www.axa.com.sg/customer-care/personal/motor/owndamageaccidentreporting>.

Your full co-operation is required. Kindly submit the following when lodging the report which list is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)

- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without our prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to us immediately. You may email it to chewht@lkkauto.com or deliver it by hand to 51 Ubi Avenue 1, #01-25 Paya Ubi Ind. Park S(408933).

You should also IMMEDIATELY forward us by hand any letters or Courts Summons received from the other party involved in the accident. You should not negotiate, admit liability or offer payment to them.

We would like to bring to your attention that under Policy Condition, your insurer shall have full discretion in the process and settlement of the said third party claim subject to the merits of the case and according to the rights afforded under the policy.

Your NCD (No Claim Discount) will be reduced by 30% (20% for motorcycle/commercial vehicles) if a claim is made under your policy.

To enable us to look into the matter immediately, please let us hear from you within seven (7) days from date of this letter. In accordance with the policy conditions, your insurer reserve the right to repudiate the said claim to you should you not give proper notice to us of any occurrence which may give rise to it.

Kindly contact us at 6742 3197 if you have any further enquiries.

Yours sincerely,
Claim Department

This is a computer generated letter and no signature is required.

CC : AXA INSURANCE PTE LTD
Motor Claim Department

Hsiao Tong (LKKAuto)

From: Peh Teck Chong <teckchong@gmail.com>
Sent: Saturday, 24 November 2018 11:22 PM
To: Hsiao Tong (LKKAuto)
Subject: Document submission for traffic accident

Hi Hsiao Tong,

Resending as the previous email gor rejected.

I am writing to submit the attached document for my case on traffic accident involving my vehicle SLX6687K.

see link:

<https://1drv.ms/u/s!Aup34nen71mzvviy5Obz62hKcWzP->

<https://1drv.ms/u/s!Aup34nen71mzvgsr4VXFG38a6pF2>

<https://1drv.ms/u/s!Aup34nen71mzvg2GloS0yDQ-CBTF>

https://1drv.ms/u/s!Aup34nen71mzvg_9yRjNC2a0zpca

https://1drv.ms/u/s!Aup34nen71mzvhmUwY_pfthbBWZ1

<https://1drv.ms/u/s!Aup34nen71mzvg2GloS0yDQ-CBTF>







<MANDATE IA> - S8M0109V [ACCIDENT INVOLVING SLX 6687K(OI) / SLN 1976L (TP) / OTHERS ON 23/10/2018]

Type

🔔 Question

Message

Liability: 100%. 7 vehicles chain collision, insured was the 6th car. Inform OI about third party claim. Agreed to settle at best and aware NCD issue. We seek your mandate at \$ \$19,987.49(if claim LOU) - \$20,551.49(if claim LOR). Mandate IA had been uploaded in Smartclaims. Kindly let us have your approval/instruction.
Hsiao Tong - 14 Dec 2018

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 14/12/2018

Survey Details:

Date of loss	23-Oct-18
Date of appointment	25-Oct-18
Date of survey	25-Oct-18
Location of survey	CHENG HOE MOTOR PL

Vehicle Details:

Claim Type:	Third party
Vehicle number	SLN 1976L
Make and Model	KIA FORTE K3 1.6A
Date of registration	26/4/2017
Excess	
Market Value	\$69,000
Part Rebate	\$50,568
Nett Loss	\$18,432

Repair details:

Initial Estimate	\$	21,956.10
------------------	----	-----------

Proposed/Revised repair cost:

Parts	\$	15,157.10
Check items (estimate)	-	
Labour	\$	6,170.00
Total	\$	21,327.10
Lump Sum(if applicable)	\$	18,000.00

Number of days for repair		10
---------------------------	--	----



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

We have not authorized repairs.

Mandate:

Liability(TP)		100%
Proposed repair cost (w/GST)	\$	19,260.00 \$ 19,260.00
Loss of use (12days x \$60.00)	\$	720.00 NIL
Loss of rental (12days x \$100.00)(w/GST)	NIL	\$ 1,284.00
Loss of income	NIL	NIL
LTA search fees	\$	7.49 \$ 7.49
Others	NIL	NIL
Proposed Total	\$	19,987.49 \$ 20,551.49