



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD	Ref : CC4/ASM18019422/Kpb3s2
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811	Date : 09-12-2019
ATTN: JAS TAN	Code : ASM



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLX 6687K	Veh. Inspected	SLN 1976L
Policy No.	VPA/P2120779	Coverage (\$)	0.00
Claim No.	S8M0109V	Excess (\$)	0.00
Assign From	JAS TAN	Assign Date	25/10/2018

2. Vehicle Particulars & Condition

Make & Model	KIA FORTE K3 (A)	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KNAFJ411MH5714264	Colour	METALLIC DARK BLUE
Odometer	55031	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	NEXEN	7 mm
L/H Front Tyre	195/65 R15	NEXEN	7 mm
R/H Rear Tyre	195/65 R15	NEXEN	7 mm
L/H Rear Tyre	195/65 R15	NEXEN	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/10/2018	Inspection Date	25/10/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **21 Working Days**