

ASS. REC. BY:

REF

es/FCI/8019127/Kqd3n2

Special Instruction:

Surveyor  
CWS

Kenneth

ASSIGNMENT (Office)

From (Person):

Lurene jaw

of

FCI

Date/Time:

9:43am@25/10/18

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHC 5932S

Insured:

SHB 4906E

at Workshop m/s

Thurs Coib

Tel:

6287 6666

of

No. 2 AMK St-63

Policy No:

Claim No:

018007705 MFS4

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/10/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

10:01am@25/10/18

Person Contacted:

zhe wei

Vehicle:

IN/OUT

| Date/Time        | Action/Instruction (✓) Estimate                   |
|------------------|---------------------------------------------------|
|                  | SHC 5932S-CC3/AIG/6003648/K/pa3q2 JDA: 23/02/2016 |
| 26/10/18@11:18pm | SHB 4906E-CC3/AIG/6001718/H/hg3q2 JDA: 25/01/2016 |
|                  | 18pm revised to Lurene by email.                  |
|                  |                                                   |
|                  |                                                   |
|                  |                                                   |

REF: FCF

## ASSIGNMENT

From: Date: 25/10/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHC 5932S

at Workshop m/s

Trans. cab

of

No. 2 AMK st-63

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'wp'

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SHC 5932S Yr Regn: 03 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercury Latitude C.C. 1995

Colour: M. White / Red A/C: Insured / Std / NI / NA

Sp. Reading: 409413 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: VI-1ABL-15AUG 281452

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Giti

Front

Rear

R/Bal. 8 mm

R/Bal. 8 mm

L/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 23/10/18

D.O.I. 25/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR N/S door

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

26/10 Rk pass to Customer  
 1/1 Sur @ 1500 CRed \$8910.71, 86%

RECEIVED 26 OCT 2018

Date/Time, File Pass to?

1) 26/10 Trans

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final Report

Days Of Repair: 2

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: 7P

Lump Sum / I.B.I. (\$) 1500

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

170

50

10

230



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18007705MFSH

Date: 26 October 2018

Our Ref: CS/FCI18019427/Kqd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SHC 5932S .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 25/10/2018 at the premises of M/s TRANS-CAB, and have the following to report:-

|                          |                                    |
|--------------------------|------------------------------------|
| Workshop Estimate Amount | : <u>S\$ 10,410.71</u> .           |
| Revised Estimate Amount  | : <u>S\$ 1,500.00 (Lump Sum)</u> . |
| "Check" Items Amount     | : <u>S\$ -</u> .                   |
| Market Value             | : <u>S\$ -</u> .                   |
| LTA Reimbursement Value  | : <u>S\$ -</u> .                   |
| Nett Value               | : <u>S\$ -</u> .                   |

**Description of Damage:**

The vehicle sustained damages  
at the front n/s door.



Yours faithfully

KONG SENG CHEONG  
Licensed Appraiser

**MOTOR SURVEY ASSIGNMENT**

|                    |                              |                               |
|--------------------|------------------------------|-------------------------------|
| Date               | 24-10-2018                   | Our Ref No. D18007705MFSH     |
| Accident Date      | 23-10-2018                   | Claim Type. Third Party       |
| Insured Vehicle    | SHB4906E                     | Third Party Vehicle. SHC5932S |
| Survey Location    | NO. 2 ANG MO KIO STREET 63   |                               |
| Contact Person.    | KEK ZHEWEI                   |                               |
| Contact No.        | 62876666/ 0                  | Fax No. 62571330              |
| Survey Type        | WITHOUT PREJUDICE:           |                               |
| Appointed Surveyor | LKK AUTO CONSULTANTS PTE LTD |                               |
| Contact Person     | NA                           | Fax No. 68416315              |
| Contact Number.    | NA                           |                               |

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

|                   |                                 |                         |
|-------------------|---------------------------------|-------------------------|
| Cc : Workshop     | TRANS-CAB AUTO SERVICES PTE LTD | Attention. NIL          |
| Cc : TP Solicitor | NA                              | TP Solicitor Fax No. NA |
| Officer Incharge  | LURENE                          |                         |

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

**Shiau Chan (LKKAUTO)**

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 26 October 2018 1:18 PM  
**To:** 'CWS Motor Claims'; assignments  
**Cc:** 'Lurene Jaw'; SUR  
**Subject:** RE: SURVEY ASSESSMENT - D18007705MFSH/1  
**Attachments:** CSFC18019427Kqd3.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SHC 5932S.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Thursday, 25 October 2018 10:03 AM  
**To:** 'CWS Motor Claims' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Cc:** 'Lurene Jaw' <[LureneJaw@msfirstcapital.com.sg](mailto:LureneJaw@msfirstcapital.com.sg)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D18007705MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** CWS Motor Claims [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Thursday, 25 October 2018 9:43 AM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** CWS Motor Claims <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; Lurene Jaw <[LureneJaw@msfirstcapital.com.sg](mailto:LureneJaw@msfirstcapital.com.sg)>  
**Subject:** PRI: SURVEY ASSESSMENT - D18007705MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

**Note:** All the accident reports are uploaded into CWS for your perusal.

Best Regards,  
Admin Team  
Claim Workflow System

### Enquire PARF/COE Rebate for Registered Vehicle

| Owner ID Type: | Company |
|----------------|---------|
| 1              | 1       |
| 2              | 2       |
| 3              | 3       |
| 4              | 4       |
| 5              | 5       |
| 6              | 6       |
| 7              | 7       |
| 8              | 8       |
| 9              | 9       |
| 10             | 10      |
| 11             | 11      |
| 12             | 12      |
| 13             | 13      |
| 14             | 14      |
| 15             | 15      |
| 16             | 16      |
| 17             | 17      |
| 18             | 18      |
| 19             | 19      |
| 20             | 20      |
| 21             | 21      |
| 22             | 22      |
| 23             | 23      |
| 24             | 24      |
| 25             | 25      |
| 26             | 26      |
| 27             | 27      |
| 28             | 28      |
| 29             | 29      |
| 30             | 30      |
| 31             | 31      |
| 32             | 32      |
| 33             | 33      |
| 34             | 34      |
| 35             | 35      |
| 36             | 36      |
| 37             | 37      |
| 38             | 38      |
| 39             | 39      |
| 40             | 40      |
| 41             | 41      |
| 42             | 42      |
| 43             | 43      |
| 44             | 44      |
| 45             | 45      |
| 46             | 46      |
| 47             | 47      |
| 48             | 48      |
| 49             | 49      |
| 50             | 50      |
| 51             | 51      |
| 52             | 52      |
| 53             | 53      |
| 54             | 54      |
| 55             | 55      |
| 56             | 56      |
| 57             | 57      |
| 58             | 58      |
| 59             | 59      |
| 60             | 60      |
| 61             | 61      |
| 62             | 62      |
| 63             | 63      |
| 64             | 64      |
| 65             | 65      |
| 66             | 66      |
| 67             | 67      |
| 68             | 68      |
| 69             | 69      |
| 70             | 70      |
| 71             | 71      |
| 72             | 72      |
| 73             | 73      |
| 74             | 74      |
| 75             | 75      |
| 76             | 76      |
| 77             | 77      |
| 78             | 78      |
| 79             | 79      |
| 80             | 80      |
| 81             | 81      |
| 82             | 82      |
| 83             | 83      |
| 84             | 84      |
| 85             | 85      |
| 86             | 86      |
| 87             | 87      |
| 88             | 88      |
| 89             | 89      |
| 90             | 90      |
| 91             | 91      |
| 92             | 92      |
| 93             | 93      |
| 94             | 94      |
| 95             | 95      |
| 96             | 96      |
| 97             | 97      |
| 98             | 98      |
| 99             | 99      |
| 100            | 100     |

Owner ID: 3878K

### Vehicle Details

Vehicle No.: SHC5932S

Vehicle to be Exported: Yes

Intended Deregistration Date: 23 Oct 2018

Vehicle Make: RENAULT

Vehicle Model: LATITUDE 2.0L DCI AUTO D/AB 4DR

|                 |     |
|-----------------|-----|
| Primary Colour: | Red |
|-----------------|-----|

Manufacturing Year: 2015

Engine No.: M9R8839C002549

Chassis No.: VF1ABL15AUC281452

Maximum Power Output: 127.0 kW (170 bhp)

|                    |             |
|--------------------|-------------|
| Open Market Value: | \$19,998.00 |
|--------------------|-------------|

Original Registration Date: 23 Mar 2015

First Registration Date: 23 Mar 2015

|                 |   |
|-----------------|---|
| Transfer Count: | 0 |
|-----------------|---|

|                  |             |
|------------------|-------------|
| Actual ARF Paid: | \$12,498.00 |
|------------------|-------------|

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 22 Mar 2023

|                     |            |
|---------------------|------------|
| PARF Rebate Amount: | \$9,373.00 |
|---------------------|------------|

### Intended COE Rebate Details

COE Expiry Date: 22 Mar 2023

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

|           |             |
|-----------|-------------|
| POP Paid: | \$51,092.00 |
|-----------|-------------|

|                    |             |
|--------------------|-------------|
| COE Rebate Amount: | \$28,147.00 |
|--------------------|-------------|

|                      |             |
|----------------------|-------------|
| Total Rebate Amount: | \$37,520.00 |
|----------------------|-------------|

## Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 23 Oct 2018

OK

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5932S****AAD1810-245***Not Notified  
L1 Syg & 1500*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

**SHC 5932S**

VF1ABL15AUC281452

RENAULT

LATITUDE

23.10.18

**FCIL****PART****LIST**

|   |                     |    |                             |
|---|---------------------|----|-----------------------------|
| 1 | FENDER PANEL FRT LH | \$ | <i>n</i> 783.83 <i>x</i>    |
| 1 | DOOR PANEL FRT LH   | \$ | <i>n</i> 2,844.66 <i>x</i>  |
| 1 | DOOR MIRROR ASSY LH | \$ | <i>cm</i> 1,483.40 <i>✓</i> |

|              |           |                 |
|--------------|-----------|-----------------|
| <b>TOTAL</b> | <b>\$</b> | <b>5,111.90</b> |
| <b>10%</b>   | <b>\$</b> | <b>511.19</b>   |
|              | <b>\$</b> | <b>4,600.71</b> |

**Special Nett**

|              |                                |           |           |               |             |
|--------------|--------------------------------|-----------|-----------|---------------|-------------|
| 1            | FRONT DOOR STICKER 'Trans-cab' | \$        | <i>nn</i> | 80.00         | <i>60sn</i> |
| 1            | FRONT DOOR STICKER 'Classic'   | \$        | <i>nn</i> | 50.00         | <i>15sn</i> |
| <b>TOTAL</b> |                                | <b>\$</b> |           | <b>130.00</b> |             |

|                    |           |                 |
|--------------------|-----------|-----------------|
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>4,730.71</b> |
|--------------------|-----------|-----------------|

**LABOUR**

|                                                                                                                           |    |                           |
|---------------------------------------------------------------------------------------------------------------------------|----|---------------------------|
| Putty and spray painting of the affected portion.                                                                         | \$ | <i>300l</i> 2,100.00      |
| To rust-proofing of the affected areas.                                                                                   | \$ | <i>nn</i> 170.00 <i>x</i> |
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | <i>150l</i> 2,100.00      |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$ | <i>nn</i> 380.00 <i>x</i> |

## Trans-cab Auto Services Pte Ltd

AAD1810-245

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5932S

|                                                                                  |           |                  |         |
|----------------------------------------------------------------------------------|-----------|------------------|---------|
| To Check Electrical Lighting Concerned.                                          | \$        | 170.00           | 201     |
| To transfer of front fender fittings, attachment and perform water seepage test. | \$        | 380.00           | ~ 201 X |
| To transfer of front door fittings, attachment and perform water seepage test.   | \$        | 380.00           | ~ 201 X |
| <b>TOTAL</b>                                                                     | <b>\$</b> | <b>5,680.00</b>  |         |
| <b>Over All Total</b>                                                            | <b>\$</b> | <b>10,410.71</b> |         |

LUMP SUM (REPAIR DAY)

7 DAYS

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                                                                      |                                                                              |                 |                             |                                                                                     |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------|-----------------|-----------------------------|-------------------------------------------------------------------------------------|
| FIRST CAPITAL INSURANCE LTD                                                                                                                                                            |                                                                              |                 | Ref : CS/FCI18019427/Kqd3n2 |                                                                                     |
| 36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877                                                                                                                                  |                                                                              |                 | Date : 29-10-2018           |  |
|                                                                                                                                                                                        |                                                                              |                 | Code : FCI2                 |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                                                                      |                                                                              |                 |                             |                                                                                     |
| Insured Veh.                                                                                                                                                                           | SHB 4906E                                                                    | Veh. Inspected  | SHC 5932S                   |                                                                                     |
| Policy No.                                                                                                                                                                             |                                                                              | Coverage (\$)   | 0.00                        |                                                                                     |
| Claim No.                                                                                                                                                                              | D18007705MFSH                                                                | Excess (\$)     | 0.00                        |                                                                                     |
| Assign From                                                                                                                                                                            | LURENE                                                                       | Assign Date     | 25/10/2018                  |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                                                                          |                                                                              |                 |                             |                                                                                     |
| Make & Model                                                                                                                                                                           | RENAULT LATITUDE (A)                                                         | c.c             | 1995                        |                                                                                     |
| Engine No.                                                                                                                                                                             | HIDDEN                                                                       | Year of Reg.    | 2015                        |                                                                                     |
| Chassis No.                                                                                                                                                                            | VF1ABL15AUC281452                                                            | Colour          | METALLIC WHITE / RED        |                                                                                     |
| Odometer                                                                                                                                                                               | 409413                                                                       | Steering        | IN ORDER                    |                                                                                     |
| Brakes                                                                                                                                                                                 | IN ORDER                                                                     | Modification    | NIL                         |                                                                                     |
| General                                                                                                                                                                                | GOOD                                                                         |                 |                             |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                                                                          |                                                                              |                 |                             |                                                                                     |
|                                                                                                                                                                                        | Size                                                                         | Make            | Balance                     |                                                                                     |
| R/H Front Tyre                                                                                                                                                                         | 215/60 R16                                                                   | GITI            | 8 mm                        |                                                                                     |
| L/H Front Tyre                                                                                                                                                                         | 215/60 R16                                                                   | GITI            | 8 mm                        |                                                                                     |
| R/H Rear Tyre                                                                                                                                                                          | 215/60 R16                                                                   | GITI            | 8 mm                        |                                                                                     |
| L/H Rear Tyre                                                                                                                                                                          | 215/60 R16                                                                   | GITI            | 8 mm                        |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                                                                       |                                                                              |                 |                             |                                                                                     |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S DOOR.<br>DAMAGES SEE DETAILS.                                                                                                           |                                                                              |                 |                             |                                                                                     |
| <b>5. General Information</b>                                                                                                                                                          |                                                                              |                 |                             |                                                                                     |
| Accident Date                                                                                                                                                                          | 23/10/2018                                                                   | Inspection Date | 25/10/2018                  |                                                                                     |
| Survey held at                                                                                                                                                                         | TRANS-CAB AUTO SERVICES PTE LTD<br>NO.2 ANG MO KIO ST 63<br>SINGAPORE 569111 |                 |                             |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                                                                     |                                                                              |                 |                             |                                                                                     |
| A) DAMAGES CONSISTENT TO ACCIDENT REPORT.<br>B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                              |                 |                             |                                                                                     |
| <b>5b. Estimate Days of Repair</b>                                                                                                                                                     |                                                                              |                 |                             |                                                                                     |
| ESTIMATED NORMAL PERIOD FOR REPAIR:                                                                                                                                                    |                                                                              | 2 Working Days  |                             |                                                                                     |



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 5932S

| Qty | Description of Parts                                                                                                                                                                         | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------------|-------------------|
|     | <b>REPLACEMENT OF PARTS</b>                                                                                                                                                                  |                      |                           |                   |
| 1   | FENDER PANEL FRT LH                                                                                                                                                                          | TO REPAIR SEE LABOUR | 783.83                    | -                 |
| 1   | DOOR PANEL FRT LH                                                                                                                                                                            | TO REPAIR SEE LABOUR | 2,844.66                  | -                 |
| 1   | DOOR MIRROR ASSY LH                                                                                                                                                                          | CRACKED              | 1,483.40                  | 1,483.40          |
|     | LESS 10% DISCOUNT                                                                                                                                                                            |                      | -511.19                   | -148.34           |
|     |                                                                                                                                                                                              |                      | 4,600.70                  | 1,335.06          |
|     | <b>SPECIAL NETT ITEMS</b>                                                                                                                                                                    |                      |                           |                   |
| 1   | FRONT DOOR STICKER "TRANS-CAB" (SN)                                                                                                                                                          | NECESSARY            | 80.00                     | 60.00             |
| 1   | FRONT DOOR STICKER "CLASSIC" (SN)                                                                                                                                                            | NECESSARY            | 50.00                     | 15.00             |
|     |                                                                                                                                                                                              |                      | 130.00                    | 75.00             |
|     | <b>LABOUR</b>                                                                                                                                                                                |                      |                           |                   |
|     | PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.                                                                                                                                            |                      | 2,100.00                  | 300.00            |
|     | TO RUST-PROOFING OF THE AFFECTED AREAS.                                                                                                                                                      | NOT NECESSARY        | 170.00                    | -                 |
|     | PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FENDER PANEL FRT LH AND DOOR PANEL FRT LH. |                      | 2,100.00                  | 150.00            |
|     | TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR.                                                                                                 | NOT NECESSARY        | 380.00                    | -                 |
|     | TO CHECK ELECTRICAL LIGHTING CONCERNED.                                                                                                                                                      |                      | 170.00                    | 20.00             |
|     | TO TRANSFER OF FRONT FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.                                                                                                              | NOT NECESSARY        | 380.00                    | -                 |
|     | TO TRANSFER OF FRONT DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST.                                                                                                                | NOT NECESSARY        | 380.00                    | -                 |
|     |                                                                                                                                                                                              |                      | 5,680.00                  | 470.00            |
|     | <b>GRAND TOTAL</b>                                                                                                                                                                           |                      | <b>10,410.70</b>          | <b>1,880.06</b>   |
|     | <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>                                                                                                                  |                      |                           | <b>1,500.00</b>   |

Report Ref No. CS/FCI18019427/Kqd3n2



Report Ref No. CS/FCI18019427/Kqd3n2

A handwritten signature in black ink, appearing to read 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.