

15/5/2010

INS. CASE OWNER:

CC 3/QBE1801

LKK:
IDAC:

Surveyor:

Enlwin

DOI:

ASSIGNMENT

27/10/18

Date / Time:

m/10/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SUE 9779A

Claim No.:

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :S\$

D.O.A.:

27/10/18

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

PIC 16000

SUE 9779A

SUE 9779A

SMD 48300



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

WGE
45
TP

Date/Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	☐ ☐
	After call ltr to OI:	☐ ☐
	Authorisation To Act:	☐ ☐
	Release Voucher:	☐ ☐
	Final Repair Bill:	☐ ☐
	Car Rental Invoice:	☐ ☐
	Towing Invoice:	☐ ☐
	LTA / GIA:	☐ ☐
	Medical Bill:	☐ ☐
	PIR:	☐ ☐
	Mandate/Reject Instruction:	☐ ☐
	LOD	☐ ☐
	Payment Breakdown Form:	☐ ☐
	Post-Repair Photos:	☐ ☐
	Others:	☐ ☐

PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	S\$	(days) Reduction: %
		Email ☐ Call ☐
FINAL SETTLEMENT	Date/Time:	Confirm with:
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:
Repair Cost:	S\$	
Loss of Rental (LOR):	S\$	(days)
Loss of Use (LOU):	S\$	(\$ x days)
Loss of Income (LOI):	S\$	(\$ x days)
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LO ☐		[Tick only one]
GIA/LTA Search	S\$	
Medical:	S\$	
Disbursement:	S\$	(e.g. Tow/ Independent)
Legal Cost	S\$	
Total:	S\$	Global Sum S\$:
FINAL PAYMENT	Date/Time:	Confirm with:
		Email ☐ Call ☐
Payee 1:	S\$	Name 1:
Payee 2: (Strike if N.A.)	S\$	Name 2:
Payee 3: (Strike if N.A.)	S\$	Name 3:

Workshops

59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717
45 Pandan Road Singapore 609286
320 Ubi Road 3 Singapore 408669

24 Senoko Loop Singapore 758156
7 Sungei Kadut Way Singapore 726791
501 Yehun Industrial Park A Singapore 768732

A member of COMFORTDELGRO

Date/Time: 22.10.2018 15:25 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO.: 305229024

STOMER

MS

STOMER NO.

DRESS

(R)

(P)

COUNT CARD NO.

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

(O)

REGN NO.:

SHD4830D

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

I-40

DATE/TIME IN

22.10.2018 11:30

YR OF MANU

06.03.2014

TARGET DATE

CHASSIS CODE

KMHLB41UMEU048415

COMPLETION DATE/TIME:

JOB DESCRIPTION

Accident Date: 22.10.2018


NATURE: 3P 22.10.2018

S/NO

LABOR CODE

DESCRIPTION

FRONT



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Knowledge Slip

to:

to:

to No.:

SHD4830D

CHIANG

Exit Pass

Vehicle No.:

SHD4830D

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard