

22/03/2002

ASS. REC. BY:

REF:

CS3/CTI18019446/ACD302

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

Mentmen

From (Person):

Elaine Cheong

of

CTI

Date/Time:

25/10/18 @ 3:31pm

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA 3367A

Insured:

SLD1338G

at Workshop m/s

Team Auto pro

Tel:

90927279

of

8 kaki Bkt Ave 4 # 06-21 premier

Policy No:

DMPCSN3044541802

Claim No:

8NM18D0306C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/10/2018

CA / REV / REP. / REV 24 HRS

(up)

26/10/2018

H.O.D. Endorsement:

Date/Time:

A:40pm @ 25/10/18

Person Contacted:

Alan

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (x) Estimate

SLA 3367A - CCG/ALG16016239/Ayb3q2

DOA: 26/8/16

SLD1338G - CS/CTI18019313/Urd3

DOA: 22/10/18

Dismantle: 21/10/2018

REF: CFI

ASSIGNMENT

From: Date: 26/10/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLA 3367A

at Workshop m/s Team Autopro

of 8kaki Blk Ave 4 # 06-21 premier

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLA 3367A- Yr Regn: 2016 Feb.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota uellfire C.C 2493

Colour: Black A/C: Insured / Std / NI / NA

Sp.Reading: 55064 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: AGH 300046376

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil S/Rim STD A/Rim or

Tyre Size: F: 235/50R18

R: 235/50R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Landsail

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 26/10/18

Survey held at Team Autopro

Des. of Damages: F / R / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Claim PRS.

- Estimated repair range \$9,000 - \$11,000

29/10/2018

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 10

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. \$.

Photos

Others

TOTAL

Report Format: PRS.

Lump Sum / I.B.I. (\$))

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

150

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Oct 2018		25 Oct 2018 15:31 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	YAP YEE FARN (YE YIFAN), ID: S7716182A		
Main Claimant:	ZIMMIZ TECH, Co. Reg. No.: 53313171E		
Vehicle Reg. No.:	SLA3367A	Date of Loss:	22/10/2018 08:00 - :59
Claim Type:	TP / SNM18D05006C02	Policy/Cover Note No.:	DMPCSN3044541802 (Comprehensive)
Vehicle Reg. No. (Insured):	SLD1338G	Policy No. (Claimant):	5098268435
		Excess:	S\$0.00
Repairer:	Team Autopro Pte Ltd (KAKI BUKIT) No.8 Kaki Bukit Avenue 4, #06-21 Premier@ Kaki Bukit (Gate 2), 415875 Kaki Bukit - Tel: 90927279		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/11/2018]		
Driver/Custodian (Insured):	LIU WEITING (34 / Female), NRIC: S8416413E, Tel: +6591881589		
Adj Asg. Remarks:	NO EST, CASE W/O SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	3171E
Vehicle Details	
Vehicle No.:	SLA3367A
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VELLFIRE 2.5Z A-EDITION A
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	2ARH653689
Chassis No.:	AGH300046376
Maximum Power Output:	134.0 kW (179 bhp)
Open Market Value:	\$41,152.00
Original Registration Date:	26 Feb 2016
First Registration Date:	26 Feb 2016
Transfer Count:	0
Actual ARF Paid:	\$49,613.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	25 Feb 2026
PARF Rebate Amount:	\$37,209.00
Intended COE Rebate Details	
COE Expiry Date:	25 Feb 2026
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$51,000.00
COE Rebate Amount:	\$36,714.00
Total Rebate Amount:	\$73,923.00

The information contained herein is correct as at 29 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/10/2018 15:22
Date Of Accident	22/10/2018 08:55
Exact Location Of Accident	CTE(CITY)/PIE CHANGI SLIP RD BEFORE UPP SERANGOON
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA3367A
Insured/Policyholder	
Name Of Registered Owner	ZIMMIZ TECH
Co Reg No	53313171E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-88222218
Alternative Phone No	OFFICE-88222218

Vehicle Particulars

Manufacturer	TOYOTA
Model	VELLFIRE
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5098268435
Cover Note Number	

Driver

Name of Driver	TOH CHIN TAT (ZHUO ZHENDA)
NRIC No	S7642012B
Date Of Birth	22/12/1976
Occupation	INDOOR
Date Of Driving Pass	02/07/1997
Driving Experience	21 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-88222218
Fax Number	
Contact Number	OFFICE-88222218
EMail Address	NOEMAIL

Address	APT BLK 550 WOODLANDS DRIVE 44 #08-82 SINGAPORE
Postcode	730550
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD1338G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHB4138E
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLR2827G
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name TOH CHIN TAT (ZHOU ZHENDA)
Approximate Age 41
Injuries Sustain REFER POLICE REPORT (NECK & BACK PAIN)
Injured person in which vehicle? SLA3367A
Were seat belts worn?
Was this injured conveyed to hospital by ambulance? NO
Address APT BLK 550 WOODLANDS DRIVE 44
#08-82 SINGAPORE
Postcode 730550

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) Investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on the stated date and time, i vehicle 'A' was travelling
 on my designated lane. The car in front of me slowed
 down and i followed suit. I slowed down and came to a
 stop, about 2 seconds later suddenly a huge impact came
 and hit me from the rear, causing me to propel forward and
 hit vehicle 'c' in front. I came down from my car
 and realized that i was involved in a four car chain
 collision. That is all.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Common Statement Pg. 1



**SINGAPORE
POLICE FORCE**



T/20181023/7002

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20181023/7002

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 23/10/2018 10:14		Vide Report No.:		Station Diary No.:	
Informant's Particulars					
Name of Informant: TOH CHIN TAT			Address: APT BLK 550 WOODLANDS DRIVE 44 #08-82 SINGAPORE 730550		
ID Type / ID No.: NRIC NO / S7642012B			Contact No.: Home/Office: Mobile: 88222218		
Nationality: SINGAPORE CITIZEN			Email: jimmy72tct@gmail.com		
Sex: Male	Age: 41	Date of Birth: 22/12/1976	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name:
Occupation: Director			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 22/10/2018 08:55	Type of Location: Straight Road
Location: CENTRAL EXPRESSWAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
SHB4138E	Car					0
SLA3367A	Car	TOYOTA	VELLFIRE	Black	Seriously Damaged	1
SLD1338G	Car					0
SLR2827G	Car					0



**SINGAPORE
POLICE FORCE**



T/20181023/7002

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3
Report No. T/20181023/7002

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLA3367A	NTUC Income Insurance Co-Operative Limited			

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	TOH CHIN TAT		ID No.	S7642012B
Related Vehicle	SLA3367A (Car)		Contact No.	88222218
Hospital/Clinic	24 HOUR WALK-IN CLINIC		Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	23/10/2018		Date Discharge	23/10/2018
No. of Days granted Medical Leave	05		Degree of Injury	Serious

Brief Details.

ON THE STATED DATE AND TIME, I VEHICLE 'A' WAS TRAVELLING ON MY DESIGNATED LANE ALONG CTE CITY/ PIE CHANGI SLIP ROAD BEFORE UPP SERANGOON EXIT. THE VEHICLE IN FRONT OF ME SLOWED DOWN TO A STOP AND I FOLLOWED SUIT. I SLOWED DOWN FOR ABOUT 2 SECONDS AND SUDDENLY A HUGE IMPACT CAME AND HIT ME FROM BEHIND CAUSING ME TO PROPEL FOWARD HITTING THE VEHICLE IN FRONT OF ME. I ALIGHTED AND FOUND OUT THAT I WAS INVOLVED IN A 3 CAR CHAIN COLLISION. THAT IS ALL.

Common Statement Pg. 1



**SINGAPORE
POLICE FORCE**



T/20181023/7002

Police Station Of Origin:
Traffic Police Division HQ
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

3 of 3

Report No. T/20181023/7002

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
JUREMAH BINTE AHMAD
Contact No.: 65472076

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
23/10/2018 10:14

Classification Of Case:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Oct 2018		25 Oct 2018 15:31 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case





















Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: YAP YEE FARN (YE YIFAN) , ID: S7716182A									
Main Claimant: ZIMMIZ TECH , Co. Reg. No.: 53313171E									
Vehicle Reg. No.: SLA3367A		Date of Loss: 22/10/2018 08:00 - :59 [31 Months and 26 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D05006C02		Policy/Cover Note No.: DMPCSN3044541802 (Comprehensive)							
Vehicle Reg. No. (Insured): SLD1338G		Policy No. (Claimant): 5098268435							
		Excess: S\$0.00							
Repairer: Team Autopro Pte Ltd (KAKI BUKIT) No.8 Kaki Bukit Avenue 4, #06-21 Premier@ Kaki Bukit (Gate 2), 415875 Kaki Bukit - Tel: 90927279									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]									
Claimant's Insurer: NTUC Income Insurance Co-operative Ltd (HQ) - Tel:									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 05/11/2018]									
Driver/Custodian (Insured): LIU WEITING (34 / Female), NRIC: S8416413E, Tel: +6591881589									
Adj Asg. Remarks: NO EST, CASE W/O SJE.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLA3367A (SNM18D05006C02)
[SLD1338G]
TP
ZIMMIZ TECH
Oct 22 2018 8:00AM
[YAP YEE FARN (YE YIFAN)]
Team Autopro Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser	
Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	23/10/18 15:49	Accident Statement		Load HTML	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	23/10/18 15:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	23/10/18 15:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	23/10/18 15:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	23/10/18 15:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	23/10/18 15:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	23/10/18 15:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	23/10/18 15:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
8	23/10/18 15:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
9	23/10/18 15:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
10	23/10/18 15:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
11	23/10/18 15:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
12	23/10/18 15:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
13	23/10/18 15:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
14	23/10/18 15:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/10/18 10:06	General View		Load PDF	
2	30/10/18 10:06	Photographs of Damaged Parts		Load PDF	
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	25/10/18 15:30	PRS WITH TP GIA		Load PDF	
2	25/10/18 15:30	OI GIA		Load PDF	
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)		Thumbnail	Print
1	23/10/18 15:47	Sketch Plan [Linked Accident Report Documents]		Load TIF	
2	23/10/18 15:47	Sketch Plan #2 [Linked Accident Report Documents]		Load TIF	
3	23/10/18 15:47	Common Statement [Linked Accident Report Documents]		Load TIF	
4	23/10/18 15:47	Common Statement [Linked Accident Report Documents]		Load TIF	
5	23/10/18 15:47	Common Statement [Linked Accident Report Documents]		Load TIF	

Linked Accident Report Documents

			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	23/10/18 15:49	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	23/10/18 15:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	23/10/18 15:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	23/10/18 15:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	23/10/18 15:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	23/10/18 15:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	23/10/18 15:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	23/10/18 15:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	23/10/18 15:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	23/10/18 15:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	23/10/18 15:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	23/10/18 15:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
12	23/10/18 15:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	23/10/18 15:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
14	23/10/18 15:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	STA INSPECTION PTE LTD (Sin Ming)	Thumbnail	Print
1	23/10/18 15:47	Sketch Plan	 Load TIF	
2	23/10/18 15:47	Sketch Plan #2	 Load TIF	
3	23/10/18 15:47	Common Statement	 Load TIF	
4	23/10/18 15:47	Common Statement	 Load TIF	
5	23/10/18 15:47	Common Statement	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<div style="border: 1px solid black; height: 100px; margin-bottom: 10px;"></div> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18019446/ACD3E2

Date: 01/11/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3044541802

Claimant Vehicle
No : SLA3367AInsured Vehicle
No : SLD1338G

Date of Loss: 22/10/2018

Nature of Claim: TP

Claim
No: SNM18D05006C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLA3367A

Make & Model: TOYOTA VELLFIRE, 2.5 (A)

Reg. Date: 26/02/2016 (Man. Year: 2015)

Colour: Black

Engine Capacity: 2493 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

Engine No: 2ARH653689

Chassis No: AGH300046376

Odometer: 55064 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/50 R18

Front Left Side: Landsail 6 mm

Front Right Side: Landsail 6 mm

Rear Tyre Size: 235/50 R18

Rear Left Side: Landsail 6 mm

Rear Right Side: Landsail 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 25/10/2018

Date Inspected: 26/10/2018 Inspected At:

Team Autopro Pte Ltd (KAKI BUKIT)
No.8 Kaki Bukit Avenue 4, #06-21
Premier@ Kaki Bukit (Gate 2)
Singapore 415875

Estimated Period of Repair: 10.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$9,000.00 -\$11,000.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Nov 2018)

Parts: M1-MPV TOYOTA VELLFIRE 2.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLA3367A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >