Date In and In the	Jeb description	Date & Time Completed	Done by		
Date In: 35/12/17 - 16:11					
Res No: NA ALL 18019456124	SAS e-filing				
Veli No: 1MD 8057 P	E-mail (within Shrs, AIC 2)	irs)			
D.O.A: M/10/18-17:75	i-Motor Claim Form				
OD TP ! Reporting Only	i-Motor W/O (Within: O	i-Motor W/O (Within: OD 2hrs, TP 4hrs)			
ob . O . Authoriting only	i-Photo Uploaded				
TP Insurer:	Assessment/Survey Rep	ort			
IP insurer:	Ass't Report by Fax / H	and to Owner/Wksp			
Preferred Wksp / INC Assign Wksp / QW:	(Tel: F	ax:		
TP Particulars: Veh No: F	DD6877C IN	IC()/Non-INC()	V Company		
Owner / Driver: (Tel:)		
Policy No: ()	Period: () Cover Type: ()		
Confirmed by : (Date:	Time:)		
Insured/Driver Liability: (%	6) [Note-Est. Status (WO): N	: 0-20%; P: 21-79%. P: 80-1	00%]		
Year of Registration: () Warranty: YES () / NO	()			
Excess: (\$) Loading:	\$1,000()/\$2,000()				
General Remarks:			1. A. C.		
() Walk-In Customer: Customer's	the state of the s	The state of the s			
() Total Loss Case : to e-mail In					
		Tourism Co. (
Drive-In ()/ Towed-In (); Inv	voice: YES () / NO (; Towing Co: (,		
Remarks: (INC hotline: 6788 661	6)	Date&Time Completed	Done by		
1) Apply for Transport Allowance () / Courtesy Car ()	Mary Mary and Mary Mary and Mary Mary and Mary Mary and M			
Apply for Transport Allowance (OC Check / Post Repair Inspection)/ Courtesy Car ()	-			
2) QC Check / Post Repair Inspection	()				
2) QC Check / Post Repair Inspection	()				
2) QC Check / Post Repair Inspection	()				
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost Injury:	()				
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost Injury:	()		Para de la companya d		
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost Injury:	()				
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost Injury:	()				
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost Injury:	()				
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost Injury:	()				
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost Injury : Date/Time Actions	() > \$3000] ()	Preparation Checklist	Ant (S) Amt		
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost Injury : Date/Time Actions	() > \$3000] ()	Preparation Checklist	Ant (S) Ami		
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost Injury : Date/Time Actions	() > \$3000] () Invoice 1) AR: Ac 2) DA: Da	cident Reporting (\$30); image Assessment (\$100); INC (\$500)	fitBill Add I		
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost Injury : Pate/Time Actions NA 1806895 atimant's Particulars :-	() > \$3000] () Invoice 1) AR: As 2) DA: Ds 3) TF: To 4) FT: Fol	cident Reporting (\$30); Image Assessment (\$100); INC (\$40) Ing Fee . \$40 Iow-Through Survey	7ft Bill Add I 50) 0/545 5120		
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost Injury : Date/Fime Actions NA [Co689] aumant's Particulars :- iver/Owner:	Invoice	cident Reporting (\$30); Image Assessment (\$100); INC (\$20); ING (\$40); INC (\$	7ft.Bill Add 1 50) 0/\$45 \$120 \$30		
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost Injury : Date/Time Actions NA [Co689] aimant's Particulars :- iver/Owner:	Invoice	cident Reporting (\$30); Image Assessment (\$100); INC (\$500); INC (\$60) 0/\$45 \$120 \$30 \$75		
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost Injury : Date/Time Actions NA [Co684] alimant's Particulars :- iver/Owner:	Invoice	cident Reporting (\$30); Image Assessment (\$100); INC (\$500); ING (\$500); INC (10.Bill Add 1 30) 0/545 5120 530		
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost Injury : Date/Time Actions NA [0689 The Particulars :- river/Owner: Intact No: Imaged Portion:	Invoice	cident Reporting (\$30); Image Assessment (\$100); INC (\$500); INC (\$60) 0/\$45 \$120 \$30 \$) \$75		
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost Injury : Date/Time Actions NA [Co684] Laimant's Particulars :- iver/Owner: Intact No: Imaged Portion:	Invoice	cident Reporting (\$30); Image Assessment (\$100); INC (\$100); wing Fee \$40 low-Through Survey (Resurvey) ming against INC Only (wef 10 Jan 200) -inspection to DA + SMRT Survey Additional Services:-	\$60) 0/\$45 \$120 \$30 6) 575 \$160		
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost Injury : Date/Time 'Actions NA Co6895 Inimant's Particulars :- river/Owner: Ontact No: Inmaged Portion: C Checked by (Engr-In-Charge):	Invoice	cident Reporting (\$30); Image Assessment (\$100); INC (\$30); Inc IN	\$60) 0/\$45 \$120 \$30 \$) \$75		
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost Injury : Date/Time 'Actions NA Co6895 Inimant's Particulars :- river/Owner: Ontact No: Inmaged Portion: C Checked by (Engr-In-Charge):	Invoice	cident Reporting (\$30); Image Assessment (\$100); INC (\$30); Image Assessment (\$100); Image Assessment (\$100); INC (\$30); INC	\$60) 0/\$45 \$120 \$30 \$) \$75 \$160 \$5 \$10 \$25 \$35		
2) QC Check / Post Repair Inspection 3) Upload Resurvey Photo [Repair Cost Injury: Date/Time Actions	Invoice	cident Reporting (\$30); Image Assessment (\$100); INC (\$30); Incomplete Assessment (\$30); Incomplete Asse	\$60) 00/\$45 \$120 \$30 \$10) \$75 \$160 \$51 \$510 \$525		

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Service of the servic	
Service Livering Control	ACCIDENT STATEMENT
Date Of Report	25/10/2018 16:11
Date Of Accident	24/10/2018 12:35
Exact Location Of Accident	JUNC LOR 7 TOA PAYOH & TOA PAYOH EAST
Country/State of Loss	SINGAPORE
建的 UNIX HARDWALL DANGER	DETAILS OF OWN VEHICLE
Vehicle Registration Number	SMD8055P
Insured/Policyholder	
A MARINE AND AND ADDRESS OF THE PARTY OF THE	

Name Of Registered Owner CHUA LI FUNG (CAI YIFANG)
NRIC No S8031942H

Email Address NOEMAIL

Mobile Phone No (LOCAL) +65-9

 Mobile Phone No
 (LOCAL) +65-94316633

 Alternative Phone No
 OFFICE-94316633

Vehicle Particulars

Manufacturer MITSUBISHI
Model ATTRAGE 1.2 CVT

Exact Purpose for which vehicle was being used at time of accident PRIVATE USE

Are you claiming under your own insurance policy NO

for repair to your vehicle?

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company AIG ASIA PACIFIC INSURANCE PTE. LTD.

Type Of Coverage COMPREHENSIVE

Fleet Policy NO

Policy Number 1800104002

Cover Note Number

Driver

 Name of Driver
 HO KAI MUN

 NRIC No
 \$7315299B

 Date Of Birth
 04/05/1973

 Occupation
 INDOOR

 Date Of Driving Pass
 05/11/2014

Driving Experience 3 YEARS AND 11 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-94316633

Fax Number

Contact Number OFFICE-94316633

EMail Address NOEMAIL

BLK 523D TAMPINES CENTRAL 7 Address

#16-109

524523

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured SPOUSE

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - CROSS JUNCTION

Weather Conditions CLEAR Road Surface DRY

Other Information

Postcode

Was any foreign vehicle involved in this accident? NO Number of vehicles involved in the accident 2 Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

Passenger 2

Was any other material or property damaged? YES I have been approached by unknown person(s) NO soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

3 Passenger 1

NAME: .

GENDER: : MALE

NAME: . GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES

If Yes, Please state which Police Station

Police Station Name TOA PAYOH NEIGHBOURHOOD POLICE CENTRE

NO

ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING, Police Station Address

POSTCODE: 319194, COUNTRY: SINGAPORE

Police Station Contact TEL NO: 1800-2519999 - FAX NO: 63548749

Was notice of intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT - T/20181025/2030.

Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? YES

Remarks/ Reasons: VIDEO FOOTAGE WITH DRIVER

Was there any audio recorded?

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number FBD6877C

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category MOTORCYCLE Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

1

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material
 facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance
 Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by
 interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of
 the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to coffect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time

Driver's Signature

(if driver is not the policyholder)

Date & Time:

Reporting Centre Pa

el's Signature

NRIC/FIN No.:

VENICUE A + SMO 8055P

VANICUE A - PAD 6899C

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

s per fouch effort.	TOA PASON NPC
	7/2018 1027/2030
-12+11 CUZ A - SMD 8055P	
VAMI CUR B - FBD 6177 C	
/	

DECLARATION

I/We declare the foregoing part/culars are true in every respect.

Policyholder's algne wes Date & T. He: Oriver a Signature (if driver is not the policyholder)

Reporting Contra Personnel's Signature Name:

MOTO PERMIT

Vehicle No.	SMD 808519 Model / Make MITSHEISHI ATTRACE				
Date of Accident	24/10/2018				
Time of Accident	12 35 HRS				
Location of Accident	JUNETION OF LOR I TOP PASON / TOP PASON EAST				
Exact purpose use during acci					
Name of Owner	CHUA LI FUNG				
Telephone No.	H/P: Home: Office:				
NRIC	S 8031942 H				
Address	BUK 523 O TOMPINES CENTRAL 7 \$16-109 5(524723				
Claim type	OD THIRD PARTY REPORTING ONLY				
Insurance Company	AIG.				
Type of Coverage	Comprehensive Third Party Third Party / Fire / Theft				
Policy No.	1800104002				
Name of Driver	As Above If No, 40 KAI MUN				
NRIC NRIC	6.0				
Date of birth	57315299B Any Passengers: 2 (BOTH MACE)				
Occupation	Outdoor / Indoor				
Driving License Pass Date	05 NOV 2014				
Gender	Male / Female				
Contact No.	H/P: 94316633 Home: Office:				
Address	SUR 523) TAMPINES CENTRAL 7 # 16-109 5(124523)				
Driver have any own vehicle	No? If yes, Reg No.				
Relationship	Employee, If no, state				
Weather condition	Clear Raining Other				
Road Surface	Ory Wet Other				
Any Injuries	Nō> If Yes, Who?				
Name And Contact No.					
Name And Contact No.					
Police Report	No, If Yes, Where? TOA PASON NPC				
Vehicle B No.	F-80 G877 C Any Passengers: N'L				
Name of Driver	Contact No. :				
Vehicle C No.	Any Passengers :				
Vehicle D No.	Any Passengers :				
Vehicle E no.	Any Passengers :				
Vehicle F No.	Any Passengers :				
Vehicle G No.	Any Passengers :				
Witness Name	Witness Contact :				
Accident Portion	RIGHT SIPE OF VEHICUE				
Camera Recorder	Yes / No				
Email Address					
	BY UNKNOWN PERSON SOLICITING /				
OFFERING ACCIDENT CLAIMS	ASSISTANCE? Yes / No				
PARTICULAR WORKSHOP	TWINCAR AMOMOTIVE PIE LTD				
CONTACT NO.	6842 0051 / 6744 0510				
CONTACT PERSON	IAN				
FAX NO	6741 0510				
WORKSHOP EMAIL APDRESS	sales @ n51. com. sg				





20101023/2030

1 of 3

Report No. T/20181025/2030

Police Station Of Origin: Toa Payoh N.P.C 93 Toa Payoh Central #01-02 Toa Payoh Community Building SINGAPORE 319194 Tel No: 1800-2519999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 25/10/2018 10:37		/lade:	Vide Report No.:	Station Diary No.: 55	
Informa	nt's Partic	ulars			
Name of Informant: HO KAI MUN			Address: APT BLK 523D TAMPINES CENTRAL 7 #16-109 SINGAPORE 524523		
ID Type / ID No.: NRIC NO / S7315299B			Contact No.: Home/Office: Mobile: 94316633		
National SINGAP	ity: ORE CITIZ	EN.	Email:		
Sex: Age: Date of Birth: Male 45 04/05/1973			Type of Informant: Driver		
Race: Chinese			Language:	Institution / School Name:	
Occupation: Real estate agent			Driving Licence Information: Class: 3	Date of Expiry:	

General Infor	mation of the Accident			
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 24/10/2018 12:38	Type of Location
Location: Junction of R LORONG 7 T TOA PAYOH Weather: Clear		Road Surface:		Road Speed Limit:
Traffic Flow: Traff		Traffic Control: Traffic Light - Wo	orking	Traffic Volume:
Type of Collision: Between Moving Vehicles - Side Swipe - Sam				Anyone conveyed by ambulance: Yes

Details of Vehicle Involved						
Vehicle No.	Туре	Make	Model	Color	Condition	No of Passenger
FBD6877C	Motorcycle					0
SMD8055P	Car				Slightly Damaged	2

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA





2 of 3

Report No. T/20181025/2030

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

CONTINUATION OF REPORT

Rider		100-100-				
Name	LIM ENG MING		ID No		S7385953J	
Related Vehicle	FBD6877C (Motorcycle)		Conta	ct No.	81330937	
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date		Class: NIL Date of Expiry: NIL	
Date Treatment	NIL	4	Date Disc	charge	NIL	
THE PERSON NAMED IN COLUMN TO THE PE			Degree o	f Injury	NIL	
Driver						
Name	HO KAI MUN		ID No		S7315299B	
Related Vehicle	SMD8055P (Car)		Conta	ct No.	94316633	
Hospital/Clinic	NIL			Class Drivin Licene Expiry	g	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Disc	charge	NIL		
No. of Days gran	ted Medical Leave NIL		Degree o	Degree of Injury NIL		

Brief Details.

On 24/10/2018 at about 1235hrs, I was driving my vehicle bearing registration number SMD8055P along Lorong 7 Toa Payoh. I was at the junction of Lorong 7 Toa Payoh and Toa Payoh East, checking for oncoming vehicles before making a right turn to Lorong 6 Toa Payoh. While I was making the right turn, a motorcycle(FBD6877C) suddenly collided against the right side of my vehicle. I wish to state that the rider was riding on the 'only right-turn' lane however he was going straight hence, the collision. I wish to also state that my right signal was on at that point of time.

I then alighted my vehicle to assist the rider as he had fallen off his bike due to the collision. I also made a check to my vehicle and it was dented on the front right side with scratches. TP and ambulance subsequently came to scene and the rider was conveyed to the hospital. I was advised by TP to lodge a Police report. There is an in-car camera in my vehicle.

The first report that I lodged is T/20181025/2027.





Police Station Of Origin: Toa Payoh N.P.C 93 Toa Payoh Central #01-02 Toa Payoh Community Building SINGAPORE 319194 CONTINUATION OF REPORT Tel No: 1800-2519999

3 of 3 Report No. T/20181025/2030


Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: E / Sgt 2 LIM JIAN HONG	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 25/10/2018 10:37
Officer In Charge Of Case: TP / GIT /	Classification Of Case:
Sr Staff Sgt SHAHRUL NIZAM BIN SAMARRI Contact No.: 654769049 SINGAPO	SN 168
Authentication Stamp NP168	
SIGNATURE	





KEPUBLIC OF SINGAPORE IDENTITY CARD NO. \$73152998





HO KAI MUN

CHINESE Date of Barr 54 04-05-1973 M

SINGAPORE



DRIVING LICENCE



Licence Number S7315299B

HO KAI MUN







YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars=< 3000 kg with =<7 passengers, exclusive 05 Nov 2014 of the driver; and other motor vehicles =< 2500 kg

NP 428A

Licence No: S73152998



CERTIFICATE OF INSURANCE

CYCLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder

: Chua Li Fung (Cai Yifang)

Period of Insurance

: 05 Sep 2018 To 04 Sep 2019

Engine No.

: 3A92UHG5051

: MMBSTA13AJH003131 Chassis No.

Vehicle No.

: SMD8055P

Policy No.

: 1800104002

Endorsement No.

Issued Date

: 14 Sep 2018

ABOUT THE COVER

Make/Model

: MITSUBISHI ATTRAGE 1.2 CVT

Engine Capacity/Tonnage : 1,193.00 CC

Sum Insured : Market Value

First Year of Registration : 2018

Driver Restriction

: NA

Off Peak Car : No

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

b) Any other person who is driving on the Policyholder's order or with his/her permission. This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than

Age Condition

: All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trace or business or use for any purpose in connection with Motor Trade

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Matayala), are not to be included under these headings

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

Chua Li Fung (Cai Yifang) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre: Add: 20 Leng Kee Rd Singapore 159094 64708688

2. Cycle & Carriage Authorised Service Centre (For windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000 3. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

For other Approved Reporting Contriss/AIG Authorised Repairers, please contact our 24-hour accident emergency holline at +65 8338 6200, Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from ITunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Standard Chartered Bank (Singapore) Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of State Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0500722050

C&C FULCO-CORPORATE 22 UBI ROAD 4 FULCO BUILDING SINGAPORE 408617 ANSP-MOTOR

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

SECSAN