

Surveyor

REF: C93 / NSM180D3412 / BSB<sup>S2</sup>-1

Special Instruction:

From (Person): Heng Xinyi of Seah Ong Date/Time: 25-10-2018  
Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

US: 16100.00

Third Parties:

Claimant:

Surveyor: PAR Automotive

Workshop: N-51 Automotive

OD/TP Re-inspection / (Evaluation)

To Inspect Vehicle No: PC 1145D Insured: GBF 7963U  
at Workshop m/s N-51 Automotive Tel: 6842 0051  
of 2 Kaki Bukit Ave 3 # 01-17

Policy No: \_\_\_\_\_ Claim No: 18-25395 PD-0

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 20-02-2018  
(Client's Record)

H.O.D. Endorsement/Date: \_\_\_\_\_

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT

Date/Time: \_\_\_\_\_ Confirmed with \_\_\_\_\_ Final Fig \_\_\_\_\_, \_\_\_\_\_ days (Red \$ \_\_\_\_\_ / \_\_\_\_\_ %; Original 19 days)

Date/Time: 08/11/18 Submit Final Fig \$10,500/-, 13 days (Red \$ 5,600/- / 135 %; Original 19 days)

Date/Time	Action/Instruction
	PC 1145D - C93 / NSM180D3412 / Wd362
	GBF 7963U - X
	Repair days 13
	RECEIVED 08 NOV 2018
	<i>[Signature]</i>
	7/11/2018
	TERIM
	7/11/18

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value : \_\_\_\_\_  
Salvage Value : \_\_\_\_\_  
Nett Value : \_\_\_\_\_

Inspected/  
Evaluated by:

Fee Charged:

Basic & Add  
Transport  
Photos  
Others  
Total

Date:


- |                                       |   |
|---------------------------------------|---|
| 1) Date/Time _____ File Pass to _____ | 2) Date/Time _____ File Return to _____ |
| 3) Date/Time _____ File Pass to _____ | 4) Date/Time _____ File Return to _____ |
| 5) Date/Time _____ File Pass to _____ | 6) Date/Time _____ File Return to _____ |

REF: CS3/ASM18003412/Wd3<sup>2</sup>  
 ASSIGNMENT (Office)  
 From: Ernest toy - ASM Date: 22/2/18  
 Estimated Cost: \_\_\_\_\_  
 OD  IP  WS  IP RES  OD RES  EVA  INV  MV  CS  
 To Inspect Vehicle No: PC1145D Insured: GBE79634  
 at Workshop no: N-SI Automotive Tel: 6842 0051  
 of: 2 kaki Bkt Ave 2 #01-17  
 Policy No: \_\_\_\_\_ Claim No: S8M009BW  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 Make of Veh: \_\_\_\_\_ DOA: 20/2/18  
 (Client's Record)  
 CA / REV / REP. / REV 24 HRS <sup>up</sup> HOI: Estimation: \_\_\_\_\_  
 Date/Time: 1:41pm @ 22/2/18 Person Contacted: Melody VEH:  IN  OUT

Date/Time	Action/Instruction (X) Estimate
	PC1145D - NA / IN 20/2/18 337 DOA 20/2/18
	GBE79634 - X
	Dismantle: 27/2/2018
	After repair: 9/3/2018 (Guo Ming)

**ASSIGNMENT**

From \_\_\_\_\_ Date \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

**OD/TP/WS/TP RES/OD RES/EVA/INV/MV**

To inspect Vehicle No: R 1145 D

at Workshop No: 221

Insured \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured \_\_\_\_\_ Excess \_\_\_\_\_

Client's Report \_\_\_\_\_

Make of Car \_\_\_\_\_

(Policy Condition) \_\_\_\_\_

Remark: The veh had commenced its repair at the time of inspection.

Est. of Market Value \_\_\_\_\_

JDAC Accident Report Consistent? Yes or No \_\_\_\_\_


GIA PR Seen Consistent? Yes or No \_\_\_\_\_

Est. Repairs days Res. Yes or No \_\_\_\_\_

Lump Sum \$ Val Yes or No \_\_\_\_\_

CA / REV / REP. / 24 HRS \_\_\_\_\_

Date \_\_\_\_\_ Person Contacted \_\_\_\_\_ Vehicle: IN / OUT \_\_\_\_\_



Van No: R 1145 D Reg: 09 2011

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toyota Hilux CC: 2982

Colour: White Insured / Std / Nil / NA \_\_\_\_\_

Sp. Reading: 3910.5 T. Fac: Insured / Std / Nil / NA \_\_\_\_\_

Eng. No: \_\_\_\_\_

Ch. No: JTFST 22A 00011472

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175 R15  
R: 175 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or \_\_\_\_\_

Front \_\_\_\_\_ Rear \_\_\_\_\_

R. Bal: 14 mm R. Bal: 3 mm

L. Bal: 4 mm L. Bal: 3 mm

D.O.A: 21/2/2011 D.C: 21/2/2011

Survey held at: 16/11/11

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date Time Action Instruction -

11/11/11 Submit PRS report

One Time Fee Pass:  Prel. Report

Final Report

Date Time Fee Return: \_\_\_\_\_

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  Site Insp \$ \_\_\_\_\_

Interview \$ \_\_\_\_\_

Tech Insp \$ \_\_\_\_\_

Weekend \$ \_\_\_\_\_

Survey Fee \_\_\_\_\_

Transported \_\_\_\_\_

Other Fee \$ \_\_\_\_\_


Report Format: PRS

Lump Sum / I.B. \$: \_\_\_\_\_

## Catherine Chong (LKK Auto)

---

**From:** Xin Yi <xinyi@seahong.com.sg>  
**Sent:** Thursday, 25 October, 2018 4:22 PM  
**To:** 'Catherine Chong (LKK Auto)'  
**Cc:** 'Chee Kiong'; samson@seahong.com.sg; amanda@seahong.com.sg  
**Subject:** PC 1145D [Our file ref: 18.25395 PD-O]  
**Attachments:** TPPD LITIGATION LOD 3H TRANSPORTATION & TRADING.pdf

Dear Catherine

**CLAIMANT :** 3H TRANSPORTATION & TRADING  
**VEHICLE NUMBER :** PC 1145D  
**ALLEGED ACCIDENT DATE :** 20.02.2018  
**AXA VEHICLE NUMBER :** GBF 7963U

We act for AXA Insurance Pte Ltd for the above matter.

We understand that you were engaged to survey the claimant's vehicle.

The claimant has issued their LOD and their surveyor's report is attached. A copy is enclosed.

Please let us hear from you on the following: -

- a. If you have conducted post-repair inspection already, please let us have your survey report urgently.
- b. If you have not conducted post-repair inspection, please arrange for inspection with the claimant's solicitor and let us have your survey report in due course.

May we hear from you on the above soonest.

Thanks & Best Regards

**Heng Xinyi**

(Secretary to Mr Tan Chee Kiong)

Seah Ong & Partners LLP

36 Robinson Road

#12-03 City House

Singapore 068877

Tel: 6536 5369

Fax: 6536 5811

This message is intended for the recipient named above. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not read, copy, use or circulate this communication. Thank you.

Disclaimer: Internet communications are not secure. While every reasonable effort has been made to ensure that this communication has not been tampered with, Seah Ong & Partners LLP cannot be responsible for alterations made to the contents of this message without its express consent. If you wish to receive a hard copy of this message for comparison or should you require any other form of confirmation of the contents of this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the company shall be understood as neither given nor endorsed by Seah Ong & Partners LLP.

# VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths  
Agents for Trade Marks  
(Incorporated with Limited Liability)

3 0 1 9 5 3 9 1 3 7 - - -

ERIC NG CHING BOON  
WONG KENG LEONG RAYNEY  
AUDREY WONG SU-HSIEN  
PAUL YAP TAI SAN  
ANJALI D/O MUNIANDY  
SEGA PARAM  
DIANE ANG KIM NOI  
RAVENDRA KRISHNASAMY  
TAY HAO RAN  
JANICE HAN JIA LIN  
TAN YINGXIAN SELWYN  
CHEONG YUNHUI, CLARISSA  
EDISON TAM CHYI EU

Company Registration No. 200721148H

Head Office: 133 New Bridge Road  
#18-01/02 Chinatown Point  
Singapore 059413

Branch: 490 Toa Payoh Lorong 6  
#03-11 HDB Hub  
Singapore 310490



## HEAD OFFICE

TEL: 6534 2811  
FAX: 6535 6802  
E-Mail: margarettan@visionlawllc.com

## BRANCH (TOA PAYOH)

TEL: 6358 0703  
FAX: 6358 0448

60115574

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to HEAD OFFICE for this matter

Our Ref : PY.mtv.Ins.T140.108271.18(jo)

Your Ref : GBF 7963U

Date : 18<sup>th</sup> October 2018

**AXA INSURANCE SINGAPORE PTE LTD**  
8 Shenton Way  
#27 - 01 AXA Tower  
Singapore 068811  
Attention : Motor-Claims Department

**Tan Hoe Guan**  
22 Defu Lane 10  
#01 - 256  
Singapore 539203

**Dane Tan Jing Hann**  
22 Defu Lane 10  
#01 - 256  
Singapore 539203

**WITHOUT PREJUDICE  
BY HAND**

**CERTIFICATE OF POSTING  
[For your information only]**

**CERTIFICATE OF POSTING  
[For your information only]**

Dear Sir,

**CLAIMANT : 3H TRANSPORTATION & TRADING  
ACCIDENT ON 20<sup>TH</sup> FEBRUARY 2018 INVOLVING VEHICLES NO. PC 1145D AND GBF  
7963U ALONG KRANJI EXPRESSWAY (KJE) NEAR TO EXIT OF JALAN BAHAR AT  
ABOUT 1430 HOURS**

We are instructed by the above named to claim damages against you/ your insured in connection with a road traffic accident on **20<sup>TH</sup> FEBRUARY 2018 ALONG KRANJI EXPRESSWAY (KJE) NEAR TO EXIT OF JALAN BAHAR AT ABOUT 1430 HOURS** involving our client's vehicle registration number **PC 1145D** and vehicle registration number **GBF 7963U** driven by you/ your insured at the material time.

### CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

# VISION LAW LLC

Advocates & Solicitors

Our Ref : PY.mtv.Ins.T140.108271.18(jo)

Your Ref : GBF 7963U

Date : 18<sup>th</sup> October 2018

---

We are instructed that the accident was caused by you/ your insured's negligent driving and/ or management of you/ your insured vehicle. As a result of the accident, our client's vehicle was damaged and our client has been put to loss and expense, particulars of which are as follows:-

1.	Cost of Repair	\$ 17,227.00
2.	Rental fees for 18 days at \$260.00 per day	\$ 4,680.00
3.	Survey report fees	\$ 1,065.00
4.	Towing fees	\$ 80.00
5.	GIA & LTA search / report fees	\$ 49.00
6.	Cost Contribution (at this stage)	\$ 1,605.00
7.	Disbursements (at this stage)	\$ 50.00
	<b>TOTAL</b>	<b>\$25,176.00</b>

We enclose a copy of each of the following documents for your consideration:-

- (a) GIA report lodged by driver of vehicle no. PC 1145D;
- (b) Photographs taken at scene of accident;
- (c) Insurance Search and LTANet Search of vehicle no. GBF 7963U;
- (d) GIA report lodged by driver of GBF 7963U;
- (e) Certificate of Insurance;
- (f) PARF/ COE Certificate;
- (g) Towing receipt;
- (h) Rental Invoice and Rental Agreement;
- (i) Final Repair Bill;
- (j) Surveyor's report & invoice; and
- (k) **116 coloured photographs** depicting the damages to motor vehicle no. PC 1145D.  
- (P.S:- Original photographs will be sent to insurance co. only)

The demand herein is in respect of our client's claim for damages pertaining to his motor vehicle and any settlement following or subsequent to this demand shall not prejudice our client's claim in respect of damages and consequential loss in relation to his personal injuries.

Please note that if you are insured and you wish to claim under your insurance policy, you should immediately pass this letter and all the enclosed documents to your insurer.

Please note that you or your insurer should send to us an acknowledgement of receipt of this letter within 14 days of your receipt of this letter, failing which our client will have no alternative but to commence proceedings against you without further notice to you or your insurer. Our client's claim herein is quantified based on supporting documents in our file. Until a settlement is reached, all negotiations are conducted on the basis that the damages quantified herein are subject to revision if so instructed by our client.

#### CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

## **VISION LAW LLC**

Advocates & Solicitors

Our Ref : PY.mtv.Ins.T140.108271.18(jo)

Your Ref : GBF 7963U

Date : 18<sup>th</sup> October 2018

---

Please also note that if you have a counterclaim against our client arising out of the accident, you are also required to send to us a letter giving full particulars of the counterclaim together with all relevant supporting documents within 8 weeks of your receipt of this letter.

Yours faithfully



**Paul Yap**  
(HEAD OFFICE)

cc: client: 3H Transportation & Trading

*As per your instruction we have submitted your claim as set out above to the third party insurance company. Please do notify us if there is any discrepancy, if any, particularly, the number of days claimed for rental charges and/or loss of use as soon as possible. Thank you.*

### **CONFIDENTIALITY**

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/02/2018 18:05
Date Of Accident	20/02/2018 14:30
Exact Location Of Accident	KJE NEAR TO EXIT OF JALAN BAHAR
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	PC1145D
<b>Insured/Policyholder</b>	
Name Of Registered Owner	3H TRANSPORTATION & TRADING
Co Reg No	53203678J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94890712
Alternative Phone No	OFFICE-94890712
<b>Vehicle Particulars</b>	
Manufacturer	TOYOTA
Model	TOYOTA HIACE HIROOF AUTO 14 SEATER
Exact Purpose for which vehicle was being used at time of accident	WORKING HOURS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	BUS
<b>Insurance Company</b>	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5093864366
Cover Note Number	
<b>Driver</b>	
Name of Driver	ZULKANAIN BIN MOHD NOR
NRIC No	S1702839A
Date Of Birth	11/10/1965
Occupation	OUDDOUR
Date Of Driving Pass	30/12/1995
Driving Experience	22 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-94890712
Fax Number	
Contact Number	OTHERS-94890712
Email Address	NOEMAIL

Address BLK 622A PUNGGOL CENTRAL  
 #11-258  
 Postcode 821622  
 Was driver an employee of the Insured's Company YES  
 If No, Relationship of the Driver with the Insured  
 Vehicle Registration Number of Driver's Own Vehicle  
 Insurance Company of Driver's Own Vehicle

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 2

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name BUKIT PANJANG NORTH NEIGHBOURHOOD POLICE POST  
 Police Station Address ROAD: BLK 27 MARSILING DRIVE , POSTCODE: 730027 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: 1800-3689999 - FAX NO: 63682383  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

PLS REFER TO THE POLICE REPORT : T/20180220/2159

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY**

Vehicle Registration Number GBF7963U  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category COMMERCIAL VEHICLE  
 Name of Driver DANE TAN  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name	ZULKANAIN BIN MOHD NOR
Approximate Age	
Injuries Sustain	SLIGHT
Injured person in which vehicle?	PC1145D
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Image As per Original  
---CSU---

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available if needed.

d) Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my work and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this (Form) and any other personal information provided by me or possessed by my employer collectively the "Personal Information" and disclose and/or transfer such Personal Information to all insurers (who have insured vehicles) involved in this accident (all insurers) who have insured vehicles involved in this accident, that they collectively, are referred to as the "Insurers", the Insurers, and its subsidiaries, statutory authority, of Singapore and its constituent government, its agent, author or both as the "Data Controller" in relation to:

- (i) processing, handling and dealing with my claims including the settlement of these claims and any related investigations relating to the claim;
  - (ii) investigating the accident and circumstances;
  - (iii) carrying out and/or dealing with my instructions in responding to any enquiries to me;
  - (iv) administering my claims including the making of correspondence, statements, notices, reports and other documents which could involve disclosure of certain personal data about me to bring about delivery of the same (as well as copying external cover of envelopes, mail packages) and/or
  - (v) complying with applicable law, administrative orders, & enforcing the law & will (as well as for the "Purposes")
- (b) I allow those who are involved in the accident and the insurers, sub-insurers, reinsurers, agents, brokers, to collect, use, disclose and/or process my Personal Information for use in any of the above Purposes and
- (c) my Personal Information may, and be, collected by any of the insurers and/or GIA to help in to carry out any of the above Purposes including their insurers, law firms, which may be based out of Singapore, for the primary of the above Purposes.
- (d) My Personal Information may be collected, stored, processed, managed, transferred, disclosed, used, disseminated, reproduction and management in electronic and any other form.
- (e) The information collected under (d) above may be shared / disclosed
- (i) to all insurers and/or any other third parties that assist in resolving, investigating, settling or handling my claim;
  - (ii) to regulatory, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (iii) for complying with requirements under any regulations, laws or court orders.



## Sketch Plan #3



SINGAPORE  
POLICE FORCE



T/20180220/2159

Police Station Of Origin  
Bukit Panjang North NPP  
27 Marsiling Drive #01-237 SINGAPORE  
730027  
Tel No 1800-3689999

2 of 2

Report No T/20180220/2159


## CONTINUATION OF REPORT

Name	DANE TAN	ID No	NIL
Related Vehicle	GBF7963U (Lorry)	Contact No	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver:			
Name	ZULKANAIN BIN MOHD NOR	ID No.	S1702839A
Related Vehicle	PC1145D (Bus/Coach/Minibus)	Contact No	94890712
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B, 2A 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 20/02/2018 at about 1440hrs, I was driving an excursion bus along KJE with bus attendant in the bus namely Sarah Binta Tangkie NRIC: S161440CB. I was on the left most lane as I wanted to exit to Jalan Bahar. As there was only one lane to exit to Jalan Bahar the traffic was slow. While moving slowly out of a sudden I felt an impact from the rear right of my vehicle. I then saw the lorry moving forward and stopped. I then drive forward and went in front of the lorry. I then alighted from my bus and discovered the driver could not exit his vehicle as his leg stuck. SCDF and ambulance arrived. SCDF then help to release the driver's leg. I then exchange particulars with the driver of the lorry. Damage to my vehicle are broken rear right mirror and dented rear right side of the bus. No one was conveyed to the hospital. Both vehicle still movable hence after exchanging particulars, I drove off while the lorry had called for a tow. No government property damaged.

Accident Photo



Accident Photo




Accident Photo




Accident Photo



Accident Photo




Accident Photo



Accident Photo




Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo





**SINGAPORE  
POLICE FORCE**



T/20180220/2159

Police Station Of Origin:  
Bukit Panjang North NPP  
27 Marsiling Drive #01-237 SINGAPORE  
730027  
Tel No: 1800-3689999

1 of 3

Report No. T/20180220/2159

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 20/02/2018 19:03	Vide Report No.:	Station Diary No.: 43
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: ZULKANAIN BIN MOHD NOR		Address: APT BLK 622A PUNGGOL CENTRAL #11-258 SINGAPORE 821622	
ID Type / ID No.: NRIC NO / S1702839A		Contact No.: Home/Office: Mobile: 94890712	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 52	Date of Birth: 11/10/1965	Type of Informant: Driver
Race: Malay		Language:	Institution / School Name:
Occupation: Bus driver		Driving Licence Information: Class: 2B,2A,3 Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Non-Injury Others	Drink Drive: No	Date/Time of Accident: 20/02/2018 14:30	Type of Location: Straight Road
Location: Along Road 1 KRANJI EXPRESSWAY Near to Exit of Jalan Bahar				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control: Not Controlled		Traffic Volume: Light
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF7963U	Lorry				Seriously Damaged	0
PC1145D	Bus/Coach/Minibus				Seriously Damaged	1

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20180220/2159

2 of 3

Police Station Of Origin:  
Bukit Panjang North NPP  
27 Marsiling Drive #01-237 SINGAPORE  
730027  
Tel No: 1800-3689999

Report No. T/20180220/2159

**CONTINUATION OF REPORT**

Name	DANE TAN		ID No.	NIL
Related Vehicle	GBF7963U (Lorry)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
<b>Driver</b>				
Name	ZULKANAIN BIN MOHD NOR		ID No.	S1702839A
Related Vehicle	PC1145D (Bus/Coach/Minibus)		Contact No.	94890712
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

**Brief Details.**

On 20/02/2018 at about 1440hrs, I was driving an excursion bus along KJE with bus attendant in the bus namely Sarah Binte Tangkie NRIC: S1614400B. I was on the left most lane as I wanted to exit to Jalan Bahar. As there was only one lane to exit to Jalan Bahar the traffic was slow. While moving slowly, out of a sudden I felt an impact from the rear right of my vehicle. I then saw the lorry moving forward and stopped. I then drive forward and went in front of the lorry. I then alighted from my bus and discovered the driver could not exit his vehicle as his leg stuck. SCDF and ambulance arrived. SCDF then help to release the driver's leg. I then exchange particulars with the driver of the lorry. Damage to my vehicle are broken rear right mirror and dented rear right side of the bus. No one was conveyed to the hospital. Both vehicle still moveable hence after exchanging particulars, I drove off while the lorry had called for a tow. No government property damaged.

Police Report



**SINGAPORE  
POLICE FORCE**



1/20180220/2159

Police Station Of Origin  
Bukit Panjang North NPP  
27 Marsiling Drive #01-237 SINGAPORE  
730027  
Tel No: 1800-3689999

2 of 3

Report No T/20180220/2159

CONTINUATION OF REPORT

Name	DANE TAN		ID No.	NIL
Related Vehicle	GBF7963U (Lorry)		Contact No.	NIL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL
<b>Driver</b>				
Name	ZULKANAIN BIN MOHD NOR		ID No.	S1702839A
Related Vehicle	PC1145D (Bus/Coach/Minibus)		Contact No.	94890712
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B,2A 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

**Brief Details.**

On 20/02/2018 at about 1440hrs, I was driving an excursion bus along KJE with bus attendant in the bus namely Sarah Binte Tangkie NRIC S1614400B. I was on the left most lane as I wanted to exit to Jalan Bahar. As there was only one lane to exit to Jalan Bahar the traffic was slow. While moving slowly, out of a sudden I felt an impact from the rear right of my vehicle. I then saw the lorry moving forward and stopped. I then drive forward and went in front of the lorry. I then alighted from my bus and discovered the driver could not exit his vehicle as his leg stuck. SCDF and ambulance arrived. SCDF then help to release the driver's leg. I then exchange particulars with the driver of the lorry. Damage to my vehicle are broken rear right mirror and dented rear right side of the bus. No one was conveyed to the hospital. Both vehicle still moveable hence after exchanging particulars, I drove off while the lorry had called for a tow. No government property damaged.

## Police Report



SINGAPORE  
POLICE FORCE



T/20180220/2159

2 of 3

Police Station Of Origin:  
Bukit Panjang North NPP  
27 Marsiling Drive #01-237 SINGAPORE  
730027  
Tel No 1800-3589999

Report No T/20180220/2159

## CONTINUATION OF REPORT

Name	DANE TAN	ID No	NIL
Related Vehicle	GBF7963U (Lorry)	Contact No	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	ZULKANAIN BIN MOHD NOR	ID No.	S1702839A
Related Vehicle	PC1145D (Bus/Coach/Minibus)	Contact No.	94890712
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B, 2A 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 20/02/2018 at about 1440hrs, I was driving an excursion bus along KJE with bus attendant in the bus namely Sarah Binte Tangkie NRIC: S1614400B. I was on the left most lane as I wanted to exit to Jalan Bahar. As there was only one lane to exit to Jalan Bahar the traffic was slow. While moving slowly, out of a sudden I felt an impact from the rear right of my vehicle. I then saw the lorry moving forward and stopped. I then drive forward and went in front of the lorry. I then alighted from my bus and discovered the driver could not exit his vehicle as his leg stuck. SCDF and ambulance arrived. SCDF then help to release the driver's leg. I then exchange particulars with the driver of the lorry. Damage to my vehicle are broken rear right mirror and dented rear right side of the bus. No one was conveyed to the hospital. Both vehicle still moveable hence after exchanging particulars, I drove off while the lorry had called for a tow. No government property damaged.

Police Report



SINGAPORE  
POLICE FORCE



T/20180220/2159

Police Station Of Origin  
Bukit Panjang North NPP  
27 Marsiling Drive #01-237 SINGAPORE  
730027  
Tel No 1800-3689999

3 of 3

Report No T/20180220/2159

CONTINUATION OF REPORT

**Sketch Plan**

Informant is not able to provide sketch plan

**IMPORTANT** Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference

Signature Of Officer Recording The Report J/ Sgt 2 MUHAMMAD FAIDHI BIN ROZZID	Signature Of Informant 
Signature Of Interpreter Not applicable	Date/Time: 20/02/2018 19:03
Officer In Charge Of Case TP / GIA / Staff Sgt TANG SIEW PING Contact No 65476430	Classification Of Case
Authentication Stamp NP153	







