



Land Transport Authority
 10 Sin Ming Drive
 Singapore 575701
 GST Registration No. : M4-0006529-2

Print Date/Time : 21 Feb 2018 / 17:26:34

Receipt Date/Time : 21 Feb 2018 / 17:26:34

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180221-001725

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - GBF7963U As at 20 Feb 2018/14:40:00 Insurance Co: AXA INSURANCE PTE LTD			
1	Insurance Enquiry - GBF7963U Enquiry Fee 20180221172456189673	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	xxxxxxxxxxxx8062		Credit Card: Visa/MasterCard	7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Vision

Enquire Vehicle & Owner Information (Vehicle No. GBF7963U As At 20 Feb 2018 / 14:40:00)**Law Firm Search Details**

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: T140-108271-18-MT

Current Owner Details

Owner ID Type: Business

Owner ID: 08669000X

Owner Name: TAN HOE GUAN

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.: 22

Registered Street Name: DEFU LANE 10

Registered Unit No.: # 01 - 256

Registered Building Name: -

Registered Postal Code: 539203

Current Vehicle Details

Vehicle No.: GBF7963U

Make Description/Model: KIA / K2500 6M/T

Insurance Company Name: AXA INSURANCE PTE LTD

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/02/2018 17:56
Date Of Accident	20/02/2018 14:45
Exact Location Of Accident	JALAN BAHAR EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBF7963U
Insured/Policyholder	
Name Of Registered Owner	TAN HOE GUAN
Vehicle Particulars	
Manufacturer	KIA
Model	K2500-2.5 D 6M/T (M)
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VCA/P1923126
Cover Note Number	09/03/2017 - 08/03/2018

Driver

Name of Driver	DANE TAN JING HANN
NRIC No	S9149170B
Address	BLK 22 DEFU LANE 10 #01-256

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
Number of Passengers (Including Driver)	1

Circumstances of Accident

STATEMENT RECORDED BY PEI WEN - PROGRESSIVE AUTOMOTIVE PTE LTD (6741 5336)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

PC1145D

Vehicle Make/Model/Colour

Name of Driver

ZULKANAIN BIN MOHD NOR

Insurance Company Name

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name: STW
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DOA 20/2/18
A. GBF 7963U
B. PC 1145D

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle B
veh B, e-brake, I failed to brake in
time hit onto the veh rear portion of veh B

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time

Driver's Signature
(if driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name: *SR*
NRIC/FIN No

Common Statement

ACCIDENT STATEMENT (Part I) Reporting Centre Progressive Automotive Pte Ltd

This is NOT an admission of blame / liability, but a summary of details
 and facts which will assist in the settlement of claims

(1) Date of accident: 20/2/18 Time: 2:45pm Exact location of accident: Jln Behar Exit

To be signed by BOTH drivers
 Injured even if slight
 No Yes

(5) Material damage
 To vehicle other than vehicle A and B: No Yes
 To object other than vehicle: No Yes

(6) Witness' name, address and tel no. (to be underlined if helpful in passenger in vehicle A or vehicle B):
 Vehicle Type: Caravan Motorbike
 No Yes

Registration No. (VEHICLE A) GSF 7963U

(7) Insured / policyholder (see insurance card)
 Name: Tan Hui Guan
 Address: B1K 22 Jln Behar
 (W # 01-256)

MRIC / Passport no. 90121483

(8) Vehicle
 Make, type: Kia

(9) Insurance company: AXA TPFT IPO

Does the policy cover damage to vehicle A?
 No Yes

Policy No. VCA / PA23126

(10) Driver: Name as Owner
 Name: Dore Tan Jey Hee
 MRIC / Passport no. SA149170B

Gender: Male Female

(12) CIRCUMSTANCES
 Put a check (✓) in each of the relevant boxes applicable to your accident

parked / stopped (at the roadside)
 leaving a parking space / opening the door (at the roadside)
 creating a parking space (at the roadside)
 emerging from a car park, private grounds, from a minor road
 entering a car park, private grounds, a minor road
 creating a roundabout or similar traffic system
 circulating in a roundabout or similar traffic system
 driving the rear of the other vehicle while going in the same direction and in the same lane
 going in the same direction but different lane
 changing lanes
 overtaking
 lining up to the right, making a left-turn (actual U-turn)
 turning to the left
 reversing
 encroaching in the opposite traffic lane
 coming from the right (at road junctions)
 not observing a right-of-way sign (e.g. red traffic light, stop sign, etc.)

State TOTAL number of boxes marked with a cross: _____

Registration No. (VEHICLE B) PC 1145D

(7) Insured / policyholder (see insurance card)
 Name: Zulkefalin Bin Mohd Nur
 Address: _____
 MRIC / Passport no. 970283AA
 Tel no. (from Penang): _____
 HP: _____

(8) Vehicle
 Make, type: _____



(9) Insurance company: TPFT IPO

Does the policy cover damage to vehicle B?
 No Yes

Policy No. (if available): _____

(10) Driver (See driving licence, if different from insured if above)
 Name: _____
 MRIC / Passport no. _____

Does of licence: _____
 HP: _____
 Gender: Male Female



(15) Visible damage to vehicle A
 F4 0 14 parts

(16) Visible damage to vehicle B

(17) Remarks

(18) Signatures of drivers

(19) Remarks



In the event of accident or in the event of damage to object other than to vehicles A and B, give immediate report.
 Do not alter entries in this statement after signing. Subsequently, each driver should take own costs.
 For insurance's individual statement (Part II) see appendix 10

Individual Statement

john.tauto@gmail.com

INDIVIDUAL STATEMENT (Part II) One written word / 1 is 01 and 10

To be completed and submitted within 24 hours to your insurer or IAC or an appointed workshop (fill a separate sheet of paper where necessary)

Insured Of which vehicle is/are you the holder? <input type="checkbox"/> A <input checked="" type="checkbox"/> B	1. Convulsion (if more than one, state all) _____ Street: _____	
	2. Vehicle registration no. <u>CC</u>	3. If commercial vehicle, state permitted carrying capacity _____
	3. Is driver the owner? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes If no, state name of Driver with address _____ Date the vehicle bought and name of Dealer of truck and vehicle (where applicable) _____	
	4. Exact purpose for which vehicle was being used at time of accident: <input type="checkbox"/> Private use <input checked="" type="checkbox"/> Commercial use <input type="checkbox"/> Hire & reward <input type="checkbox"/> Others (please specify) _____	
	5. Is the vehicle still in use? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> If no, state where it is at present _____ Tel no. _____	
	6. Are you claiming under your own insurance policy for repair to your vehicle? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> If no, state action to be taken: <input type="checkbox"/> Third Party <input type="checkbox"/> Reporting Only <input type="checkbox"/> Third Party (Own Workshop)	
Driver or person in charge of vehicle at the time of accident (including insured)	7. Date of birth: <u>20/7/1991</u> Occupation: <u>Indoor</u> Date of license issue: <u>8/7/2003</u> Was vehicle driven with the insured's permission? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
	8. Give details of any pre-existing impairment of sight or hearing and of any other disability _____	
	9. Full details of all driving convictions including pending prosecutions in the last 36 months	
Injured persons	10. Name(s), address(es) and approximate age(s) _____	
	Injury substance _____	
	If vehicle involved, state in which office _____	
	Were you taken to hospital? <input type="checkbox"/> Yes <input type="checkbox"/> No	
	Was injured conveyed to hospital by ambulance? <input type="checkbox"/> Yes <input type="checkbox"/> No	
Damage to property & vehicles (other than vehicles A and B)	11. Name(s) and address(es) of owner(s) _____	
	Vehicle registration no. or details of property _____ Nature of damage _____ Insurer's name and address (if known) _____	
Police action	12. Was the accident reported to the Police? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
	If yes, please state which Police station _____	
	13. Was notice of intended prosecution given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
ACCIDENT DETAILS	14. Weather conditions: <input checked="" type="checkbox"/> Clear <input type="checkbox"/> Rainy <input type="checkbox"/> Others _____	
	15. Road surface: <input checked="" type="checkbox"/> Wet <input type="checkbox"/> Dry <input type="checkbox"/> Others _____	
	16. Speed of vehicle: A: <u>CC</u> km/hr B: _____ km/hr	
	17. What warnings were given by driver or other party? _____	
	18. Were street lights illuminated? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
	19. What lights were displayed on your vehicle (or other vehicles)? _____	
	20. If your vehicle is a truck, state weight of load carried at time of accident _____	
21. State how accident happened, width of roads, speed limits, etc (prefer to attach a sketch) _____		
22. State number of Passengers including Driver: _____		
Declaration	I/We declare the foregoing particulars are true to the best of my/our knowledge	
	Policyholder's signature: _____ Date: <u>21/02/13</u> Driver's signature (if driver is not the policyholder): _____ Date: <u>21/02/13</u>	

AXA INSURANCE PTE LTD
 8 Shenton Way, #24-01
 AXA Tower, Singapore 068811
 Customer Service Centre #B1-01
 Tel:(65)63387286 Fax:(65)63382522
 Website:www.axa.com.sg
 GST Registration Number: 199903512M
 customer.service@axa.com.sg



CERTIFICATE OF INSURANCE

*Motor Vehicles (Third-Party Risks and Compensation) Act. (Chapter 189) *Motor Vehicles (Third-Party Risks and Compensation) Rules. 1960 *Road Transport Act. 1987 (Malaysia) *Motor Vehicles (Third-Party Risks) Rules. 1959 (Malaysia)

CERTIFICATE NO. : VCA/P1923126 Account No. : 04437
 Coverage : Comprehensive
 Sum Insured : Market Value At The Time Of Loss
 Name of Policy Holder : TAN HOE GUAN
 Vehicle Registration No. : GBF7963U
 Period of Insurance : From 09/03/2017 To 08/03/2018 (Both Dates Inclusive)

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*

Any person who is driving on the Policyholder's order or with their permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE*

- (a) Use in connection with the Policyholder's business
 - (b) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business
 - (c) Use for social, domestic and pleasure purposes
- This Policy does not cover
- (a) Use for hire or reward or for racing, pace-making, reliability trial or speed-testing
 - (b) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle.

(05)

EXCESS :

Sect I - Any Authorised Driver : SGD 700.00
 Windscreen Excess : SGD 100.00

(Please refer to your policy for Additional Excess)

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

Authorized Signature

Issued by - SGOSP on 19/04/2017

IMPORTANT :

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189)).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

ALLINK INSURANCE AGENCY

Blk 153 Bukit Batok Street 11
 #02-290 Singapore 651112
 Tel: 6567 3116

Accident Photo



Accident Photo




Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo



THE SCHEDULE

Private Bus Insurance Policy

This Policy sets out the terms of a contract between NTUC Income Insurance Co-operative Limited (INCOME) and you (the Insured named in the schedule to this Policy).

The statements, information and declaration provided by you at the time of proposal shall form the basis of this contract. We (INCOME) will provide the insurance set out in this Policy in respect of events occurring during the Period of Insurance shown in the Schedule and any further period for which we may accept a renewal premium.

The provision of this insurance is subject to:

1. any Endorsement specified as operative in the Schedule
2. the Conditions and General Exclusions of this Policy, and
3. the payment of the premium specified in the Schedule.

This Policy, the Schedule and the Certificate of Insurance are to be read together as one document.

GST Reg No. M4-0003030-8

Policy Number	:	5093864366
The Policyholder	:	3H TRANSPORTATION & TRADING 10 ANSON ROAD #16-12 INTERNATIONAL PLAZA SINGAPORE 079903
Period of Insurance	:	31 Aug 2017 To 30 Aug 2018
Sum Insured	:	Market Value of Insured Vehicle at Time of Loss
Premium (inclusive GST)	:	S\$1,951.07

Interest Insured

Cover Type	:	Comprehensive			
Make/Model	:	TOYOTA/HIACE			
Capacity	:	2982 ton(s)	Number of Seater	:	13
Registration Number	:	PC1145D	Registration Date	:	15 Sep 2011
Chassis Number	:	JTFST22PX00011472	Insure with COE	:	Yes
Excess (Section I)	:	S\$2,000	NCD Entitlement	:	0%
Excess (Section II)	:	S\$3,000			
Windscreen Excess	:	S\$500			
Geographical Limit	:	WITHIN THE REPUBLIC OF SINGAPORE ONLY			
Hire Purchase Company	:	ABWIN PTE LTD			

Memo A : N/A

Endorsement Operative : N/A

Agency	:	ABWIN PTE LTD (00000614234)
Date of Issue	:	30 Aug 2017 14:49 hrs

DUTY OF DISCLOSURE

We would remind you that you must disclose to us, fully and faithfully, the facts you know or ought to know, otherwise you may not receive any benefit from your Policy.

Signed in Singapore by order of the Board of Directors



Chief Executive

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business

Owner ID: 3678J

Vehicle Details

Vehicle No.: PC1145D

Vehicle to be Exported: No

Intended De-registration Date: 21 Feb 2018

Vehicle Make: TOYOTA

Vehicle Model: TOYOTA HIACE HIROOF AUTO 14 SEATER

Primary Colour: Silver

Manufacturing Year: 2011

Engine No.: 1KD2115947

Chassis No.: JTFST22PX00011472

Maximum Power Output: -

Open Market Value: \$37,122.00

Original Registration Date: 15 Sep 2011

First Registration Date: 15 Sep 2011

Transfer Count: 2

Actual ARF Paid: \$1,857.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 14 Sep 2021

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid:	\$34,009.00
COE Rebate Amount:	\$12,629.00
Total Rebate Amount:	\$12,629.00

The information contained herein is correct as at 21 Feb 2018

OK

ACCIDENT
CLAIM

CASH SALE / WORK ORDER
SPEEDO TOWING SERVICE

Nº 9132

Bus. Reg. No: 53217861X
H/P: 9767 6774

Date: 22/02/18

Name / Company CASH

Vehicle No. PC 1145 D TOYOTA (H/R) 007

Contact No. -

From JIN BATHON c/p

To N51 wls.

Amount \$ 80/2 Remarks

- 1) Jump Start
- 2) Tyre Replacement
- 3) Accident / Breakdown
- 4) Multi / Basement
- 5) With Load / Cargo Box
- 6) King Dolly
- 7) Transport Charge
- 8) Low Body Kit
- 9) Door Opening Service
- 10) Crane Up / Winch Out
- 11) Collect Doc / Key
- 12) Petrol Charge

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

Tow Truck Driver

**24 HRS
TOWING SERVICE**

Received By [Signature]

H H Coach Bus
Blk 175 Woodlands St.13 #10-321
Singapore 730175
HP : 96881679 Fax : 62691997

10th March 2018

INVOICE NO : HHCB/N510002/03/18

To : Mr Zulkanain Bin Mohd Nor
(3H Transportation Pte Ltd)
Blk 622A Punggol Central #11-258
Singapore 821622

I/C : S1702839A


1. Being rental of bus PC3350P S\$ 4680.00
from 20th Febuary 2018 to 10th March 2018.
(18days X S\$ 260/-)

Amount Payable : S\$ 4680.00

TERMS : CASH

Singapore Dollars : Four thousand six hundred eighty only.

H H Coach Bus


Authorised Signature

HIRING AGREEMENT

Vehicle No.

PC 3350P

Owner

HH COACH BUS

Hirer

ZULKANAIN BIN MOHD NOR

Address

BLK 622A PUNGGOL CENTRAL

#11-258 S(821622)

Contact No.

94890712

Hiring Period

20/2/18 5pm

10/3/18 3pm

Hiring Rate

18 DAYS X \$260/- = \$4680/-

Hiring Rules

Full tank of diesel at the point of vehicle-hand-over before and after used.

DOB

11/10/1965

All damages, summons and accident's excess during the hiring period are to be borne by the hirer.

The standard terms and conditions of hiring services apply over the hiring period.

Pickup point

Please pickup the vehicle at FIRST CENTRE

Attn : Mr Lim 93227087

: Ms Lilian 96881679

: Ms Sandy 97306185

SH TRANSPORTATION & TRADING

Signature of Owner

I/C no.

Name : Lim Yan CHANG

Date : 20/2/18

(Please attach copies of I/C, Driving Licence & Vocational Licence of the hirer.)

Signature of hirer

I/C no.

Name : ZULKANAIN BIN MOHD NOR

Date : 20/2/18

Lim Yan
Certified True Copy

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

3H TRANSPORTATION & TRADING
10 ANSON ROAD #16-12 INTERNATIONAL PLAZA
SINGAPORE 079903

Contact : 91902787 94890712

TAX INVOICE

Date : 27/09/2018

Date in : 20/02/2018

Vehicle Num. : PC1145D

Make/Model : TOYOTA HIACE HIROOF AUTO 14 SEATER-2011

Chassis/Eng# : JTFST22PX00011472/1KD2115947

Accident Date : 20/02/2018

Claim No : CLM14011

Reference : FEB-06/2018

Policy No. : 5093864366 (30/08/2018)

LUMPSUM REPAIR BILL
AS PER SURVEYOR REPORT
REF : 0581-18-TCA DATED 24/09/2018
BY PAR AUTOMOTIVE CONSULTANCY

Amount S\$

16,100.00

E. & O.E. Sub S\$: 16,100.00

Add GST (7 %) S\$: 1,127.00

Total Amount S\$: 17,227.00



for TWINCAR AUTOMOTIVE PTE LTD

PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0581-18-TCA

24 September 2018

3H Transportation & Trading
c/o Twincar Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-17
Kaki Bukit Auto Hub
Singapore 417921

INVOICE No. **0581-18-TCA**


Vehicle No. **PC1145D**

<u>S/NO.</u>	<u>SERVICES RENDERED</u>	<u>Amount due</u>
1	Being accident vehicle appraisal services, transport, photographs and re-inspection (work in progress and post repair inspection).	\$1,065.00
	Total amount payable	<u>\$1,065.00</u>

Kindly cross your cheque in favour of "PAR Automotive Consultancy"

We thank you in anticipation for your prompt payment.

PAR Automotive Consultancy



PAR Automotive Consultancy

Regn. No: S2986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 645 31173, Fax : 645 36131.

Report No: 0581-18-TCA

24 September 2018

ACCIDENT VEHICLE SURVEY REPORT

3H Transportation & Trading
c/o Twincar Automotive Pte Ltd
2 Kaki Bukit Ave 2 #01-17
Kaki Bukit Auto Hub
Singapore 417921

VEHICLE INFORMATION:

<i>Vehicle Reg No.:</i>	PC1145D	<i>Odometer:</i>	391015km
<i>Make & Model:</i>	Toyota Hiace Hiroof Auto	<i>Colour:</i>	Silver
<i>Chassis number:</i>	JTFST22PX00011472	<i>Date of accident:</i>	20/02/2018
<i>Year of Regn.:</i>	15/09/2011	<i>Date inspected:</i>	22/02/2018
<i>Repairer at:</i>	Twincar Automotive Pte Ltd 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Auto Hub Singapore 417921	<i>Date inspected (After Repair):</i>	10/03/2018

STATIC CHECKS, where applicable:

<i>Steering :</i>	serviceable
<i>Footbrake :</i>	serviceable
<i>Handbrake :</i>	serviceable
<i>Paintwork :</i>	Good
<i>General condition :</i>	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
<i>Front:</i>	6mm/Bridgestone	6mm/Bridgestone	195R15
<i>Rear:</i>	6mm/Bridgestone	6mm/Bridgestone	195R15

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear RH portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

PARTS

Description of part	Qty	Condition	Repairer's estimate	Our adjustment	
CENTER EXHAUST GASKET	1	necessary	20.50	20.50	NECV
CENTER EXHAUST RUBBER MOUNTING	3	distorted	197.40	197.40	BTV
CENTER EXHAUST SILENCER BOX	1	bent	1,985.30	20.10	1,985.30 BTXNN
REAR BUMPER	1	squashed	471.20	471.20	DDV
REAR BUMPER SIDE RETAINER L/R	RH 1	necessary	332.40	166.20	332.40 NEC
REAR END PANEL 'INNER'	1	repair	403.10	0.00	
REAR END PANEL 'OUTER'	1	buckled	410.10	410.10	DDV
REAR END PANEL INNER TOP MOULDING	1	bent	95.00	95.00	BTV
REAR END PANEL RUBBER GUIDE STOPPER L/R	2	deformed	90.40	-90.40	NNX
REAR EXHAUST SILENCER GASKET	1	necessary	63.90	63.90	NECV
REAR EXHAUST SILENCER PIPE	1	bent	1,092.00	770.00	1,092.00 BTV
REAR RH FENDER	1	buckled	1,062.70	1,062.70	DDV
REAR RH FENDER AIR VENT	1	warped	211.40	211.40	DIS
REAR RH FENDER INNER CARDBOARD	1	fractured	781.90	781.90	BRV
REAR RH FENDER INNER PANEL	1	buckled	1,114.70	1,114.70	BTV
REAR RH FENDER INNER WHEEL HOUSE	1	repair	985.30	0.00	
REAR RH SAFETY BELT	1	jammed	495.30	495.30	JMV
REAR TAILGATE	1	buckled	1,049.10	1,049.10	DDV
REAR TAILGATE 'LOGO' EMBLEM	1	necessary	34.10	34.10	NECV
REAR TAILGATE 3RD BRAKE LAMP	1	fractured	183.20	183.20	CRAV
REAR TAILGATE CENTRE LOCK MECHANISM	1	bent	484.60	380.00	484.60 BV
REAR TAILGATE DAMPER L/R	2	bent	418.20	418.20	NNX
REAR TAILGATE HINGES L/R	2	bent	132.20	132.20	BTXNN
REAR TAILGATE INNER CARDBOARD	1	fractured	235.00	235.00	CRAV
REAR TAILGATE INNER OPENER MECHANISM	1	distorted	289.10	289.10	BTV
REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH	1	fractured	435.10	435.10	CRAV
REAR TAILGATE MECHANISM LOCK	1	bent	203.10	203.10	BTV
REAR TAILGATE OUTER GARNISH	1	fractured	75.10	75.10	CRAV
REAR TAILGATE OUTER HANDLE	1	distorted	282.25	282.25	CUTV
REAR TAILGATE RUBBER GUIDE STOPPER L/R	R 1	deformed	87.80	43.50	87.80 CUTV
REAR TAILGATE WEATHERSTRIP	1	deformed	299.10	299.10	CUTV
REAR TAILGATE WINDSCREEN GLASS	1	shattered	1,257.10	1096.13	1,257.10 BRV
REAR TAILGATE WIPER ARM	1	reuse	70.40	0.00	
REAR TAILGATE WIPER ARM COVER	1	reuse	12.80	0.00	
REAR TAILGATE WIPER BLADE	1	abraded	45.70	45.70	NNX
REAR TAILGATE WIPER MOTOR	1	shorted	572.10	572.10	NNX
REAR TAILLAMP BACK RUBBER GASKET L/R	1	necessary	38.20	19.10	38.20-NECV
REAR TAILLAMP L/R	2	fractured	606.20	606.20	BRV
REAR TAILLAMP RH INNER PANEL	1	buckled	435.00	435.00	DDV
REAR TAILLAMP RH LOWER GARNISH	1	deformed	78.95	78.95	CUTV
REAR TAILLAMP RH LOWER GARNISH BRACKET L/R	2	bent	82.90	82.90	BTV
REAR TAILLAMP RH OUTER PANEL	1	buckled	485.30	485.30	DDV

ROOF LINING

	1	reuse	1,435.10	0.00
	Subtotal before discount		S\$ 19,140.30	S\$ 16,233.60
	Percentage discount 25% and 25%		S\$ 4,785.08	S\$ 4,058.40
	Sub-total 1		S\$ 14,355.23	S\$ 12,175.20
REAR BUMPER CLIPS - SET	1	necessary	50.00	40 50.00 NECV
REAR BUMPER REVERSE SENSOR - SET	1	shorted	600.00	200.00 600.00 CUT
REAR CHILDREN TRIANGLE SIGN	1	shorted	100.00	60 100.00 CUT
REAR END PANEL INNER TOP MOULDING CLIPS - SET	1	necessary	30.00	30.00
REAR RH FENDER GLASS SEALANT	1	necessary	100.00	60.00 100.00 } NECV
REAR RH FENDER INNER CARDBOARD CLIPS - SET	1	necessary	80.00	30.00 80.00 NECV
REAR RH SEAT ASSY	1	repair	800.00	0.00
REAR TAILGATE '70KM/H' STICKER	1	necessary	15.00	15.00
REAR TAILGATE '80/90KM' STICKER	1	necessary	30.00	30.00
REAR TAILGATE INNER CARDBOARD CLIPS - SET	1	necessary	50.00	30 50.00
REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH CLIPS - SET	1	necessary	50.00	30.00 50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET	1	necessary	30.00	30.00
REAR TAILGATE PRIVATE HIRE BUS STICKER	2	necessary	160.00	100.00 -160.00 } NECV
REAR TAILGATE WINDSCREEN SEALANT	1	necessary	100.00	60.00 100.00
REAR TAILLAMP CLIPS L/R - SET	2	necessary	60.00	40.00 60.00
REAR TAILLAMP RH LOWER GARNISH CLIPS - SET	1	necessary	30.00	30.00
ROOF LINING CLIPS - SET	1	necessary	100.00	80.00 100.00
	Subtotal before discount		S\$ 2,385.00	S\$ 1,585.00
	Sub-total 2		S\$ 2,385.00	S\$ 1,585.00
	Parts-total		S\$ 16,740.23	S\$ 13,760.20

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.	100.00	60.00	40
To remove, reinstall tailgate windscreen	300.00	80.00	150.00 120
To remove, reinstall fender glass	200.00	80.00	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	300.00	80.00	150.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	2,300.00	1,500.00	800.00 + 400
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	250.00	80.00	160.00
To provide labour, workmanship to change the above damaged bodyparts, repair, reconstruct and re-align body structure, body alignments and damaged consistent to the accident.	4,500.00	2,500.00	1600.00
To mount vehicle on to Car 'O' Liner.	400.00	400.00	NNX
To apply anti-rust chemical on repaired and replaced panel.	150.00	60.00	90.00
	Labour Total	S\$ 8,500.00	S\$ 5,160.00
	Parts & Labour Total	S\$ 25,240.23	S\$ 18,920.20

Repair days 13

TGlim Jim

7/11/18

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

**Hence, the recommended cost of repairs based on Lump Sum repairs is : S\$ 16,100.00
and the recommended number of working days for the repairs is within 19 day(s).**



B J Loi (1 Eng., MIMI, AIRTE)
Automotive Appraiser



Your Ref: 18.25395 PD-O

Date: 15th November 2018

Our Ref: CS3/ASM18003412/Bsbs2-1

M/s AXA Insurance Pte Ltd

C/o: Seah Ong & Partners LLP
36 Robinson Road
#12-03 City House
Singapore 068877

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: PC 1145D
INSURED VEHICLE: GBF 7963U
ACCIDENT DATE: 20/02/2018**

We thank you for your instruction on 25/10/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of PC 1145D from M/s PAR Automotive Consultancy.
- b) Final Repair Bill of PC 1145D from M/s TwinCar Automotive Pte Ltd.
- c) Singapore Accident Statement of Vehicles PC 1145D and GBF 7963U.
- d) Colour damaged vehicle photographs of PC 1145D.

Pre-Repair Inspection Date : 22/02/2018 at M/s N-51 Automotive Pte Ltd, 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Autohub Singapore 417921.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: PC 1145D
Make & Model	: Toyota Hiace
Year of Registration	: 2011
Chassis Number	: JTFST22PX00011472
Engine Capacity	: 2982 cc

2. We recommend that the repairs of the entire damage require about 13 (Thirteen) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 1145D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	CENTER EXHAUST GASKET	NECESSARY	20.50	20.50
3	CENTER EXHAUST RUBBER MOUNTING	BENT	197.40	197.40
1	CENTER EXHAUST SILENCER BOX	NOT NECESSARY	1,985.30	-
1	REAR BUMPER	DENTED	471.20	471.20
2	REAR BUMPER SIDE RETAINER L/R	O/S NECESSARY	332.40	166.20
1	REAR END PANEL 'INNER'	TO REPAIR SEE LABOUR	403.10	-
1	REAR END PANEL 'OUTER'	DENTED	410.10	410.10
1	REAR END PANEL INNER TOP MOULDING	BENT	95.00	95.00
2	REAR END PANEL RUBBER GUIDE STOPPER L/R	NOT NECESSARY	90.40	-
1	REAR EXHAUST SILENCER GASKET	NECESSARY	63.90	63.90
1	REAR EXHAUST SILENCER PIPE	BENT	1,092.00	770.00
1	REAR RH FENDER	DENTED	1,062.70	1,062.70
1	REAR RH FENDER AIR VENT	DISTORTED	211.40	211.40
1	REAR RH FENDER INNER CARDBOARD	BROKEN	781.90	781.90
1	REAR RH FENDER INNER PANEL	BENT	1,114.70	1,114.70
1	REAR RH FENDER INNER WHEEL HOUSE	TO REPAIR SEE LABOUR	985.30	-
1	REAR RH SAFETY BELT	JAMMED	495.30	495.30
1	REAR TAILGATE	DENTED	1,049.10	1,049.10
1	REAR TAILGATE 'LOGO' EMBLEM	NECESSARY	34.10	34.10
1	REAR TAILGATE 3RD BRAKE LAMP (CRACKED)	NOT CONSISTENT WITH THE IMPACT	183.20	-
1	REAR TAILGATE CENTRE LOCK MECHANISM	BENT	484.60	380.00
2	REAR TAILGATE DAMPER L/R	NOT NECESSARY	418.20	-
2	REAR TAILGATE HINGES L/R	NOT NECESSARY	132.20	-
1	REAR TAILGATE INNER CARDBOARD	CRACKED	235.00	235.00
1	REAR TAILGATE INNER OPENER MECHANISM	BENT	289.10	289.10
1	REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH	CRACKED	435.10	435.10
1	REAR TAILGATE MECHANISM LOCK	BENT	203.10	203.10
1	REAR TAILGATE OUTER GARNISH	CRACKED	75.10	75.10
1	REAR TAILGATE OUTER HANDLE	CUT	282.25	282.25
2	REAR TAILGATE RUBBER GUIDE STOPPER L/R	O/S CUT	87.80	43.50
1	REAR TAILGATE WEATHERSTRIP	CUT	299.10	299.10
1	REAR TAILGATE WINDSCREEN GLASS	BROKEN	1,257.10	1,096.13



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILGATE WIPER ARM	REUSE	70.40	-
1	REAR TAILGATE WIPER ARM COVER	REUSE	12.80	-
1	REAR TAILGATE WIPER BLADE	NOT NECESSARY	45.70	-
1	REAR TAILGATE WIPER MOTOR	NOT NECESSARY	572.10	-
2	REAR TAILLAMP BACK RUBBER GASKET L/R	NECESSARY 1PC ONLY	38.20	19.10
2	REAR TAILLAMP L/R	BROKEN	606.20	606.20
1	REAR TAILLAMP RH INNER PANEL	DENTED	435.00	435.00
1	REAR TAILLAMP RH LOWER GARNISH	CUT	78.95	78.95
1	REAR TAILLAMP RH LOWER GARNISH BRACKET L/R	BENT	82.90	82.90
1	REAR TAILLAMP RH OUTER PANEL	DENTED	485.30	485.30
1	ROOF LINING	REUSE	1,435.10	-
	LESS 25% DISCOUNT		-4,785.07	-2,997.34
			14,355.23	8,991.99
	SPECIAL NETT ITEMS			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	40.00
2	REAR BUMPER REVERSE SENSOR (SN)	CUT	600.00	200.00
1	REAR CHILDREN TRIANGLE SIGN (SN)	CUT	100.00	60.00
1	SET REAR END PANEL INNER TOP MOULDING CLIPS (SN)	NECESSARY	30.00	30.00
1	REAR RH FENDER GLASS SEALANT (SN)	NECESSARY	100.00	60.00
1	SET REAR RH FENDER INNER CARBOARD CLIPS (SN)	NECESSARY	80.00	30.00
1	REAR RH SEAT ASSY (SN)	TO REPAIR SEE LABOUR	800.00	-
1	REAR TAILGATE '70KM/H' STICKER (SN)	NECESSARY	15.00	15.00
1	REAR TAILGATE '80/90KM' STICKER (SN)	NECESSARY	30.00	30.00
1	SET REAR TAILGATE INNER CARBOARD CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR TAILGATE INNER UPHOLSTERY TRIM GARNISH CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR TAILGATE OUTER GARNISH CLIPS (SN)	NECESSARY	30.00	30.00
2	REAR TAILGATE PRIVATE HIRE BUS STICKER (SN)	NECESSARY	160.00	100.00
1	REAR TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	100.00	60.00
2	SET REAR TAILLAMP CLIPS L/R (SN)	NECESSARY	60.00	40.00
1	SET REAR TAILLAMP RH LOWER GARNISH CLIPS (SN)	NECESSARY	30.00	30.00
1	SET ROOF LINING CLIPS (SN)	NECESSARY	100.00	80.00
			2,385.00	865.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING AND REWIRE FOR PARKING SENSOR.		100.00	40.00
	TO REMOVE, REINSTALL TAILGATE WINDSCREEN.		300.00	120.00
	TO REMOVE, REINSTALL FENDER GLASS.		200.00	80.00
	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)		300.00	80.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		2,300.00	1,200.00
	TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE. RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT.		250.00	80.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF REAR END PANEL 'INNER', REAR RH FENDER INNER WHEEL HOUSE AND REAR RH SEAT ASSY.		4,500.00	1,600.00
	TO MOUNT VEHICLE ON TO CAR 'O' LINER.	NOT NECESSARY	400.00	-
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.		150.00	60.00
			8,500.00	3,260.00
	GRAND TOTAL		25,240.23	13,116.99
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,500.00

Report Ref No. CS3/ASM18003412/Bsbs2-1

LIM TEOW GUAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.