

ASS. REC. BY:

REF:

CS/CT#18019484/Uvd3

Special Instruction:

Surveyor:

Mennen

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time:

25/10/18 @ 4:32pm

Estimated Cost:

Bill to:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GY 9109Y

Insured:

GBA 40304

at Workshop m/s

Mah Hian Motor

Tel:

6282 3336

of

No. 38 Defu Lane 9

Policy No:

DMCVSN1810721800

Claim No:

SNM18DOS057C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/10/2018

CA / REV / REP. / REV 24 HRS

(up)

29/10/18 @ after lunch.

H.O.D. Endorsement

Date/Time:

9am @ 26/10/18

Person Contacted:

Wan Roe

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

GY 9109Y - NA/CTI 18019324 / K4

D.O.A: 23/10/2018

GBA 40304 - NA/CTI 18019324 / K4

D.O.A: 23/10/2018

REF: C11

ASSIGNMENT

From:

Date: 29/10/2018

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

G49109Y

at Workshop m/s

Mah Lian Motor

of

No. 38 Defu Lane 9

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

After Lunch

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

14

IDAC Accident Report

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4

days

Res.: Yes or No

Lump Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

No. 4617

Veh No:

G49109Y

Yr Regn:

9:05

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

M)

Make:

Nissan cabster

C.C.

3153

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

334869

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JN15F4F2320854684

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-R15

R:

155-R12

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

hankook

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

23/10/18

D.O.I.

29/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

31/10/18 4/5 2700 confirmed with Silver, (Red 7407.56, 735)

coe 20/9/2020 170 9383 1 yes 1/1. 701/10/1399.70N

RECEIVED 01 NOV 2018

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

Date/Time, File Return to?

1) 1/11 - typist

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

TOTAL

220

Report Format:

menmen

Lump Sum / I.B.I. (\$)

2700/2

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Oct 2018		25 Oct 2018 16:32 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	ISW ENGINEERING PTE LTD		
Vehicle Reg. No.:	GY9109Y	Date of Loss:	23/10/2018 00:00 - :59
Claim Type:	TP / SNM18D05057C02	Policy/Cover Note No.:	DMCVSN1810721800
Vehicle Reg. No. (Insured):	GBA4030H	Policy No. (Claimant):	
		Excess:	\$0.00
Repairer:	Mah Lian Motor Vehicle Repairer (HQ) NO. 38 DEFU LANE 9, 539278 Defu Lane - Tel:		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 05/11/2018]		
Adj Asg. Remarks:	NO EST, ASSIGN MARCUS CHUA AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)


Nissan Cabstar

Price Range ▾

Depreciation ▾

> 10 year(s) ▾

Vehicle Type ▾


 Advanced
Search

[Home](#) » [Used Cars](#) » [Direct Owners](#) » Nissan Cabstar (COE till 01/2021)

Resources

[Car Buying](#)
[Car Selling](#)
[Car Ownership](#)
[Car Aftermarket](#)
[On The Move](#)
[Lifestyle](#)

Car Tyres



75,000
MEMBERSHIP
REWARDS* POINTS
WELCOME BONUS



THE
PLATINUM
CARD*

[App](#)

T&Cs apply.

Nissan Cabstar (COE till 01/2021)

[Overview](#) [Financial](#) [Accessories](#) [Similar](#) [Research](#) [Photos](#) [Map](#)

DIRECT OWNER

[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)
[Report Error](#)
[More Actions](#)
[Share](#)

Car Details

Price	\$18,000	
Depreciation	\$7,960 /yr	?
Reg Date	17-Feb-2001 (2yrs 3mths 2days COE left)	
Lifespan	16-Feb-2021	
Manufactured	2001	?
Mileage	-	
Transmission	Manual	
Engine Cap	3,153 cc	
Curb Weight	1,500 kg	?
Fuel type	Diesel	
Features	Well Maintained. Serviced Regularly. New Tyres.	
Accessories	High Box. Able To Lock The Back Of The Lorry. Box With Back Door And Side Door For Easy Loading And Unloading. Racks In The Box For Small Item Storage	
Description	Direct Owner. Keen Buyers Only Please.	
COE	\$22,583	?
OMV	\$20,792	?
ARF	\$1,040	?
Dereg Value	\$10,209 as of today (change)	?
No. of Owners	2	?
Type of Veh	Truck	
Category	COE Car, Direct Owner Sale	
Availability	Available	DIRECT OWNER

[Add to Shortlist](#)
[Add to Compare](#)
[Add a Note](#)

Posted on: 13-Oct-2018 | Last Updated on: 20-Oct-2018

Tags: Nissan Cabstar, nissan cabstar, 2001 Nissan Cabstar, 2001 nissan cabstar, Nissan, Cabstar, cabstar, Used Nissan

Upfront Payment

[more Financial info](#)

Transfer Fee	\$25	?
Down Payment	\$1,800 (change)	Maximum 90% Loan ?
1st Instalment	\$661	?
Total Upfront Payment	\$2,486 (excluding insurance)	?

Estimates based on 90% loan at 4.5% interest rate. Check with seller for exact figure.



100% FREE
PAPERWORK
SUPPORT FOR
BOTH BUYER
& SELLER



Seller Information

Contact Person(s) Sebastian Quek

Contact No. 92203003

Enquiry ☒ Contact Seller

USEFUL FORMS

» Indemnity form » Sales agreement

» Receipt » Hand-over form

» M01

Instructions on how to complete a seller to end-consumer deal

Regardless of buying or selling, we'll handle your paperwork, loans & insurance for FREE.



Useful Services



Afraid of lemons? Request to have this car evaluated professionally.

[Vehicle Evaluation](#)


Find out the market value for your car. Get a free Car Valuation.

[Free Valuation](#)

Enquire PARF/COE Rebate for Registered Vehicle

The information contained herein is correct as at 29 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/10/2018 13:28
Date Of Accident	23/10/2018 22:00
Exact Location Of Accident	TUAS SOUTH STREET 15
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GY9109Y
Insured/Policyholder	
Name Of Registered Owner	ISW ENGINEERING PTE LTD
Co Reg No	-
Email Address	SIHUI.G@GMAIL.COM
Mobile Phone No	(LOCAL) +65-94505947
Alternative Phone No	OFFICE-94505947

Vehicle Particulars

Manufacturer	NISSAN
Model	-
Exact Purpose for which vehicle was being used at time of accident	WORK
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	DMCVSN3010771801
Cover Note Number	

Driver

Name of Driver	AMMASI PANDIYAN
Passport No/FIN	G2638499R
Date Of Birth	10/03/1993
Occupation	OUTDOOR
Date Of Driving Pass	15/09/2017
Driving Experience	1 YEAR AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-94505947
Fax Number	
Contact Number	OTHERS-94505947
Email Address	SIHUI.G@GMAIL.COM

Address

MAHA ARUL SITHI CONSTRUCTION & ENGINEERING PTE LTD

Postcode

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident CHAIN COLLISION

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance NO

Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLS REFER TO THE ATTACHED STATEMENT.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBA4030H

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category COMMERCIAL VEHICLE

Name of Driver MURUGESAN DHANASEKARAN

NRIC/Passport Number G2536281R

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number XD5080E

Vehicle Make/Model/Colour

Details Of Properties:

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

RAMU THEVAR CHINNAMANI

NRIC/Passport Number

G7249688X

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the Claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers at the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA):**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposes:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud; regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/FIN No.

Sketch Plan #2

SKETCH PLAN

7-22 South Street E

Vehicle A, B, C

A - GYA109Y
B - GBA4030H
C - XDS000E

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle A was parked on the South Street on
road side and vehicle B also was parked
Vehicle C hit on vehicle B and vehicle B
hit on vehicle A near portion.
Vehicle A damage was at the rear
bumper portion.

DECLARATION

I/We hereby declare the following particulars are true in every respect

Policyholder's Signature
Date & Time

Driver's Signature
If driver is not the policyholder:
Date & Time

Reporting Centre Personnel's Signature
Name
NRIC/FIN No.

Sketch Plan #3



Accident Photo



Accident Photo



MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278

TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg

GST:M90362564P RCB NO:201327339E

M/S : China Taiping Insurance (Singapore) Pte Ltd

TEL: - FAX: -
 ATTN: Motor Claim Department \ 9366 3603
 Your Ref No: ISW ENGINEERING PL
 Claim Type: Third Party
 Accident Date: 23/10/2018

Estimate No: ES1700348
 Date: 23 Oct 2018
 Policy No: DMCVSN3010771801
 Veh Reg No: GY9109Y
 Make/Model: NISSAN CABSTAR
 Chassis No: JN1SF4F23Z0854684
 Engine No: QD32210761
 Reg. Date: 21/09/2005

Estimate Repair Cost to Vehicle No :GY9109Y

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 Rear Mudguard LH/RH	129.80	2 PC	259.60	X
2 Rear Tipper Door	1,688.40	1 PC	1,688.40	—
3 Rear Tipper Side Panel LH/RH	2,915.10	2 PC	5,830.20	X
4 Rear Tipper Lower Member	628.30	1 PC	628.30	—
5 Rear Crossmember	453.10	1 PC	453.10	X
			8,859.60	23167.69
	Less 30%		2,657.88	1621.69
Net Price				
6 Tail Lamp LH/RH	129.40	2 PC	258.80	—
7 Rear Tipper Lock LH/RH	33.40	2 PC	66.80	X
8 Rear Tipper Side Frame LH/RH	450.00	2 SET	900.00	1 PC
9 Rear Tipper Hinges	53.60	3 PC	160.80	X
10 Side Tipper Hinges LH/RH	53.60	2 PC	107.20	9
11 Rear Spring Assy LH/RH	543.90	2 SET	1,087.80	X
12 Rear Spring Bush LH/RH	28.80	2 PC	57.60	X
13 Rear Mudguard Bracket LH/RH	46.30	2 PC	92.60	X
			2,731.60	708.80
	Less 20%		546.32	2,185.28
Special Net				
14 Rear Mudguard Rubber Seal LH/RH	43.70	2 PC	87.40	X
15 Rear Number Plate	30.00	1 PC	30.00	14
			117.40	117.40

Labour

- 16 Labour to renew & refix all parts
 17 To spray & painting all accident dented area .

680.00 1 JOB 680.00

650.00 1 JOB 650.00

the Repairer of the following: 1,330.00

• To resurvey before/after spray painting

• To display damaged part(s) during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not allowed
 2/5 \$2700/-
 4 day.
 29/10/18
 to be paid. Attached

1,330.00 1,330.00

3458.61

MAH LIAN MOTOR VEHICLE REPAIRER

No.38 Defu Lane 9 Singapore 539278

TEL: 62823336 FAX: 62893336 Email: mahlian@singnet.com.sg

GST:M90362564P RCB NO:201327339E

M/S : China Taiping Insurance (Singapore) Pte Ltd

TEL: - FAX: -
 ATTN: Motor Claim Department \ 9366 3603
 Your Ref No: ISW ENGINEERING PL
 Claim Type: Third Party
 Accident Date: 23/10/2018

Estimate No: ES1700348
Date: 23 Oct 2018
Policy No: DMCVSN3010771801
Veh Reg No: GY9109Y
Make/Model: NISSAN CABSTAR
Chassis No: JN1SF4F23Z0854684
Engine No: QD32210761
Reg. Date: 21/09/2005

Estimate Repair Cost to Vehicle No :GY9109Y

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
		10,107.56	Total	S\$ 9,834.40
			Add GST @ 7%	688.41
			Total Amount Payable	S\$ 10,522.81

TOTAL: SINGAPORE DOLLAR TEN THOUSAND FIVE HUNDRED TWENTY TWO AND CENTS EIGHTY ONE ONLY

**For MAH LIAN MOTOR VEHICLE
REPAIRER**

 AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18019484/UVD3N2
Date: 05/11/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN1810721800
Claimant Vehicle No :	GY9109Y	Insured Vehicle No :	GBA4030H
Date of Loss:	23/10/2018	Nature of Claim:	TP
		Claim No:	SNM18D05057C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GY9109Y	Engine No:	QD32210761
Make & Model:	NISSAN CABSTAR, 3.2 D (M)	Chassis No:	JN1SF4F23Z0854684
Reg. Date:	21/09/2005 (Man. Year: 2005)	Odometer:	334869 km
Colour:	Silver		
Engine Capacity:	3153 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	155 R12 (D)
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6/6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,777.56	2,273.61	6,503.95	74.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,330.00	1,180.00	150.00	11.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,107.56	3,453.61	6,653.95	65.83
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	10,107.56	2,700.00	7,407.56	73.29
+ GST 7.00/7.00% (S\$)	707.53	189.00	518.53	73.29
Nett Amount (S\$)	10,815.09	2,889.00	7,926.09	73.29

INSPECTION

Date of Assignment:	25/10/2018	
Date Inspected:	29/10/2018	Inspected At:
		Mah Lian Motor Vehicle Repairer (HQ) NO. 38 DEFU LANE 9 Singapore 539278
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 05 Nov 2018)	
Parts:	N/A	NISSAN CABSTAR 3.2 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GY9109Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR MUDGUARD LH/RH	Repair	259.60 FL	*- FL
2	1		*REAR TIPPER DOOR	Badly Dented	1,688.40 FL	*1,688.40 FL
3	2		*REAR TIPPER SIDE PANEL LH/RH	Repair	5,830.20 FL	*- FL
4	1		*REAR TIPPER LOWER MEMBER	Badly Dented/Bent	628.30 FL	*628.30 FL
5	1		*REAR CROSSMEMBER	Repair	453.10 FL	*- FL
6	2		*TAIL LAMP LH/RH	Broken	258.80 FN	*258.80 FN
7	2		*REAR TIPPER LOCK LH/RH	Not Necessary	66.80 FN	*- FN
8	1		*SET REAR TIPPER SIDE FRAME LH/RH	N/s Bent	900.00 FN	*450.00 FN
9	3		*REAR TIPPER HINGES	Not Necessary	160.80 FN	*- FN
10	2		*SIDE TIPPER HINGES LH/RH	Not Necessary	107.20 FN	*- FN
11	2		*SET REAR SPRING ASSY LH/RH	Not Necessary	1,087.80 FN	*- FN
12	2		*REAR SPRING BUSH LH/RH	Not Necessary	57.60 FN	*- FN
13	2		*REAR MUDGUARD BRACKET LH/RH	Not Necessary	92.60 FN	*- FN
14	2		*REAR MUDGUARD RUBBER SEAL LH/RH	Not Necessary	87.40 FS	*- FS
15	1		*REAR NUMBER PLATE	Bent	30.00 FS	*14.00 FS
					Sub Total (\$\$)	11,708.60 3,039.50
					- List Item Discount on L Items 30.00/30.00% (\$\$)	2,657.88 695.01
					- Nett Item Discount on N Items 10.00/10.00% (\$\$)	273.16 70.88
					Total Parts (\$\$)	8,777.56 2,273.61

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO RENEW & REFIX ALL PARTS	New	680.00	680.00
2	TO SPRAY & PAINTING ALL ACCIDENT DENTED AREA	New	650.00	500.00
Gross Labour Cost (\$\$)			1,330.00	1,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >