

22/03/2002

ASS. REC. BY:

REF: CS3/MSG18019486/Gcd3/ Special Instruction:

Surveyor:
Mehmen

ASSIGNMENT (Office)

From (Person): Chhia Nyuk Pui

of

MSG

Date/Time: 25/10/18 @ 4:26pm

Estimated Cost:

Bill to:

OD TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKZ 5385P

Insured:

SKK 5350T

at Workshop m/s

Hiap Lek Automobile

Tel:

9660 1347

of

160 Sin Ming Drive #05-17

Policy No:

B28923285QMX

Claim No:

573907

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/10/2018

CA / REV / REP. / REV 24 HRS

1wp

25.10.2018

H.O.D. Endorsement:

Date/Time:

9:03am @ 26/10/18

Person Contacted:

Hanwei

Vehicle IN /

OUT

Date/Time	Action/Instruction (X) Estimate
	SKZ 5385P - X
	SKK 5350T - CC3/AXA/4018427/Kha3q2-1 DOA: 25/9/14
	Dismantle: 31/10/2018
	After repair: 2/11/2018

PRs
Xhl
MCSH

REF: MCSH

22978

ASSIGNMENT

(-248)

From: Date: 29.10.2018

Estimated Cost:

OD / TR / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKZ 5385P

at Workshop m/s

of

Hiap Lek
160 Sin Ming Drive #05-17

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

\$12K.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

14

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SKZ 5385P

Yr Regn:

11 Dec 2008

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Jazz

C.C

1497

Colour

silver

A/C: Insured / Std / NI / NA

Sp.Reading

174800

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JH MGE 885095 200415

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55 R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

28-10-18

Survey held at

w/s

4:50pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$2000 - \$2000

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

: S + RS, SI

Photos

Others

TOTAL

Report Format :

PRE

Lump Sum / I.B.I: (\$

120

10

130

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Oct 2018		25 Oct 2018 16:26 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SOH CHEOW ON, ID: S7412423B, Tel: +6593822065, Email: SOH_KENNETH@YAHOO.COM.SG		
Main Claimant:	PANG SHOONG KON, ID: S1262297Z		
Vehicle Reg. No.:	SKZ5385P	Date of Loss:	19/10/2018 19:00 - :59 [118 Months and 8 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 573907	Policy/Cover Note No.:	B28923285QMX (Comprehensive) Coverage: 31/03/2018 - 30/03/2019
Vehicle Reg. No. (Insured):	SKK5350T	Policy No. (Claimant):	
		Excess:	S\$500.00
Repairer:	Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64531743		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/10/2018]		
Driver/Custodian (Insured):	SOH CHEOW ON (44 / Male), NRIC: S7412423B, Tel: +6593822065		
Adj Asg. Remarks:	Liability 100%. TP disagree with our SJE list, proceed to appoint LKK Auto Consultant. Contact Person: Hanwei / 9660 1347.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2297Z
Vehicle Details	
Vehicle No.:	SKZ5385P
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Oct 2018
Vehicle Make:	HONDA
Vehicle Model:	JAZZ 1.5L AT ABS D/AB HID 2WD 5DR
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	L15A71000517
Chassis No.:	JHMGE88509S200415
Maximum Power Output:	88.0 kW (118 bhp)
Open Market Value:	\$21,214.00
Original Registration Date:	11 Dec 2008
First Registration Date:	11 Dec 2008
Transfer Count:	2
Actual ARF Paid:	\$21,214.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Dec 2018
PARF Rebate Amount:	\$10,607.00
Intended COE Rebate Details	
COE Expiry Date:	10 Dec 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$7,721.00
COE Rebate Amount:	\$85.00
Total Rebate Amount:	\$10,692.00

The information contained herein is correct as at 30 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	20/10/2018 11:45
Date Of Accident	19/10/2018 19:00
Exact Location Of Accident	BKE (BEFORE TURF CLUB AVE EXIT)
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SKZ5385P
Insured/Policyholder	
Name Of Registered Owner	PANG SHOONG KON
NRIC No	S1262297Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98154915
Alternative Phone No	OFFICE-98154915
Vehicle Particulars	
Manufacturer	HONDA
Model	JAZZ
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5095502403
Cover Note Number	
Driver	
Name of Driver	KATRINA PANG PING PING
NRIC No	S8926942C
Date Of Birth	11/08/1989
Occupation	INDOOR
Date Of Driving Pass	09/02/2013
Driving Experience	5 YEARS AND 8 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-94569465
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 468D #15-215 ADMIRALTY DRIVE
Postcode	754468
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER STATEMENT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKK5350T
Vehicle Make/Model/Colour	TOYOTA WISH
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	SOH CHEOW ON
NRIC/Passport Number	S7412423B
Contact Number	93822065
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

20 OCT 2018


Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: **NG WING KIN JAMES**
NRIC/FIN No.: **S7927881E**



Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

on 19/10/18 @ about 1900 hrs, I am travelling along BKE towards SUE direction. The traffic at that time is slow moving. The cars ahead of me stop, I too stopped. moments later, I felt an impact on my rear portion.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

20 OCT 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

NG WING KIN JAMES

S7927881E





































...CLAIM SUBFOLDER...(Pending for Survey Report)













































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Oct 2018		25 Oct 2018 16:26 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SOH CHEOW ON , ID: S7412423B, Tel: +6593822065, Email: SOH_KENNETH@YAHOO.COM.SG									
Main Claimant: PANG SHOONG KON , ID: S1262297Z									
Vehicle Reg. No.: SKZ5385P		Date of Loss: 19/10/2018 19:00 - :59 [118 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 573907		Policy/Cover Note No.: B28923285QMX (Comprehensive) Coverage: 31/03/2018 - 30/03/2019							
Vehicle Reg. No. (Insured): SKK5350T		Policy No. (Claimant):							
		Excess: S\$500.00							
Repairer: Hiap Lek Automobile Trading (HQ) 160 Sin Ming Drive, #05-17 Sin Ming Autocity, 575722 Sin Ming - Tel: 64531743									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Imm.Advice due 26/10/2018]									
Driver/Custodian (Insured): SOH CHEOW ON (44 / Male), NRIC: S7412423B, Tel: +6593822065									
Adj Asg. Remarks: Liability 100%. TP disagree with our SJE list, proceed to appoint LKK Auto Consultant. Contact Person: Hanwei / 9660 1347.									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="checkbox"/> View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKZ5385P (573907)**
[SKK5350T]
TP
PANG SHOONG KON
Oct 19 2018 7:00PM
[SOH CHEOW ON]
Hiap Lek Automobile Trading

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/10/18 11:29	Accident Statement From:OD - Reg. No: SKK5350T, Claimant: SOH CHEOW ON	 Load HTML	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/10/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
2	31/10/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
3	31/10/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
4	31/10/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
5	31/10/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
6	31/10/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
7	31/10/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
8	31/10/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
9	31/10/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
10	31/10/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
11	31/10/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
12	31/10/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
13	31/10/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
14	31/10/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
15	31/10/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
16	31/10/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
17	31/10/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
18	31/10/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
19	31/10/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
20	31/10/18 09:19	General View	 Load JPG	<input checked="" type="checkbox"/>
21	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
22	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
23	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
24	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
25	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
26	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
27	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
28	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
29	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
30	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
31	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
32	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
33	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
35	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
36	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
37	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
38	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
39	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
40	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
41	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
42	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
43	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
44	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
45	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
46	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
47	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
48	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
49	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
50	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
51	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
52	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
53	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
54	05/11/18 09:57	Dismantled Parts	 Load JPG	<input checked="" type="checkbox"/>
55	05/11/18 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
56	05/11/18 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
57	05/11/18 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
58	05/11/18 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
59	05/11/18 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
60	05/11/18 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
61	05/11/18 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
62	05/11/18 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	05/11/18 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	05/11/18 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	05/11/18 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	05/11/18 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	05/11/18 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	05/11/18 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	05/11/18 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	05/11/18 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	05/11/18 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	05/11/18 09:57	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	25/10/18 09:32	PRI - C Paglar	 Load PDF	
2	25/10/18 09:32	Email to TP our SJE list	 Load PDF	
3	25/10/18 09:32	TP disagree with our SJE list, proceed to appoint LKK Auto Consultants as the surveyor	 Load PDF	
4	25/10/18 10:29	TP Workshop and details	 Load PDF	
5	25/10/18 11:29	TP GIA Report - SKZ5385P From:OD - Reg. No: SKK5350T, Claimant: SOH CHEOW ON	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/MSG18019486/GCD3E2

Date: 08/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B28923285QMX

Claimant Vehicle No : SKZ5385P

Insured Vehicle No : SKK5350T

Date of Loss: 19/10/2018

Nature of Claim: TP

Claim No: 573907

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKZ5385P

Make & Model: HONDA JAZZ, 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A)

Engine No: L15A71000517

Reg. Date: 11/12/2008 (Man. Year: 2008)

Chassis No: JHMGE88509S200415

Colour: Silver

Odometer: 174800 km

Engine Capacity: 1497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R15

Rear Tyre Size: 195/55 R15

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 25/10/2018

Date Inspected: 29/10/2018 Inspected At:

Hiap Lek Automobile Trading (HQ)
160 Sin Ming Drive, #05-17 Sin Ming
Autocity
Singapore 575722

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000.00 - \$3,000.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2018)
Parts:	144	HONDA JAZZ 1.5 1.5L MT ABS D/AB HID 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKZ5385P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >