

ASS. REC. BY:

REF:

S/MSG18019489/Upd3ⁿ²

Special Instruction:

Surveyor:

Meinmen

ASSIGNMENT (Office) ✓

From (Person):

Jasmine Lok

of

MSG

Date/Time:

25/10/18 @ 4:21 pm

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMD 7812C

Insured:

GBF 7484K

at Workshop m/s

Ace Autolution

Tel:

68441184

of

13 kaki Bkt Rd 4 #03-29

Policy No:

A29072909 MKC

Claim No:

574043

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23/10/2018

CA / REV / REP. / REV 24 HRS (up)

30/10/2018 @ Mmg

H.O.D. Endorsement:

Date/Time:

9:17am @ 26/10/18

Person Contacted:

Anna

Vehicle-

IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SMD 7812C-X

GBF 7484K - NAF/AIG 18016816 / h4

DOA: 12/09/2018

29/10/18-

VNI will be In on 30/10/18 - (Cancelled)

01/11/18 @ 3:20pm

Informed Jasmine Lok, we are pending estimate from reporter.

02/11/18 @ 1:50pm

revised to Jasmine Lok via Meinmen.

Surveyor

REF:

MSIN/

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMD7812C
at Workshop m/s: Ace Automot
of: 03-49

Insured:

Policy No.:

Claims No.:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS L1A46948

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SMD7812C Yr Regn: 9 18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Toyota C-HR Hybrid G.C.C 1797

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading: 6180 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: 24X102091656

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R17
R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front R/Bal. 2 mm Rear R/Bal. 2 mm

L/Bal. 2 mm L/Bal. 2 mm

D.O.A. 23/10/18 D.O.I. 30/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Lt. The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

8/11/18 2/3 ^{QAAA quality estimate} confirmed with Anne. (Red 86820.33, 68%)

RECEIVED 09 NOV 2018

[Signature]
9/11/2018

Date/Time, File Pass to? : Preli. Report

1) *ayla transit* : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation

S - RS, SI

Photos:

Others:

TOTAL

200
10
210

Add Fee: Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Report Format: MER-TP

Lump Sum / L.B.I: (\$ 3200)

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 09 Nov 2018

Preliminary Advice

Insured Vehicle No	: GBF7484K	Accident Date	: 23/10/2018
TP Vehicle No	: SMD7812C	Assignment Date	: 25/10/2018
Make	: TOYOTA C-HR HYBRID	Est. Duration of Repair	: 3
Date of Inspection	: 30/10/2018		
Inspection At	: ACE AUTOLUTION		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,020.33
Revised Amount	:S\$	4,030.83
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,030.83
Lump Sum Repair	:S\$	3,200.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Oct 2018		25 Oct 2018 16:21 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	HUP KEE TRADING COMPANY, Co. Reg. No.: -		
Main Claimant:	RASIDAH BTE MOHAMAD SHAH, ID: S1592573F		
Vehicle Reg. No.:	SMD7812C	Date of Loss:	23/10/2018 12:00 - :59 [1 Months and 19 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 574043	Policy/Cover Note No.:	A29072909MKC (Comprehensive) Coverage: 27/02/2018 - 26/02/2019
Vehicle Reg. No. (Insured):	GBF7484K	Policy No. (Claimant):	
		Excess:	
Repairer:	Ace Autolution (HQ) 13 KAKI BUKIT ROAD 4, #03-29 Bartley Biz Centre, 417807 Kaki Bukit - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 26/10/2018]		
Driver/Custodian (Insured):	TAN HWA LAM @ LAU SANG (), NRIC: S2551929I, Tel: +6594899318		
Adj Asg. Remarks:	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK (MARCUS CHUA). LIABILITY:UNCLEAR. CONTACT:MS ANNA 6844 1184		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Thursday, 1 November 2018 3:20 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE SMD 7812C (YOUR REF: 574043)

This mail is associated with :

***SMD7812C (574043)**
[GBF7484K]

TP

RASIDAH BTE MOHAMAD SHAH

Oct 23 2018 12:00PM

[HUP KEE TRADING COMPANY]

Ace Autolution

Dear Jasmine,

Please be informed that we have inspected the vehicle SMD 7812C on 30/10/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	2573F

Vehicle Details

Vehicle No.:	SMD7812C
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.8S CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2ZR8284022
Chassis No.:	ZYX102091656
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$27,166.00
Original Registration Date:	04 Sep 2018
First Registration Date:	04 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$20,033.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Sep 2028
PARF Rebate Amount:	\$15,024.00

Intended COE Rebate Details

COE Expiry Date:	03 Sep 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,429.00
COE Rebate Amount:	\$31,924.00
Total Rebate Amount:	\$46,948.00

The information contained herein is correct as at 30 Oct 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	24/10/2018 10:28
Date Of Accident	23/10/2018 11:55
Exact Location Of Accident	TAMPINES MALL CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMD7812C
Insured/Policyholder	
Name Of Registered Owner	RASIDAH BTE MOHAMAD SHAH
NRIC No	S1592573F
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-82337457
Alternative Phone No	OTHERS-82337457

Vehicle Particulars

Manufacturer	TOYOTA
Model	C-HR HYBRID 1.8S CVT
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V09559 (COMP)
Cover Note Number	

Driver

Name of Driver	RASIDAH BTE MOHAMAD SHAH
NRIC No	S1592573F
Date Of Birth	05/08/1963
Occupation	INDOOR
Date Of Driving Pass	31/08/2006
Driving Experience	12 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-82337457
Fax Number	
Contact Number	OTHERS-82337457
Email Address	NOEMAIL

Address	BLK 450A TAMPINES STREET 42 #02-352
Postcode	521450
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	SHELTERED CARPARK
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF7484K
Vehicle Make/Model/Colour	NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	TAN HWA LAM @LAU SANG
NRIC/Passport Number	S2551929I
Contact Number	94899318
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




 Policyholder's Signature
 Date & Time:
 24 OCT 2018



 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

IDAC KAKI BUKIT (VAC,
 23 Kaki Bukit Ave 4
 Singapore 415933
 Tel: 67416697 Fax: 67492305
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23 Oct 2018 at around 11:55 am, I was stationary at Tampines mall carpark. Suddenly, vehicle B (GBF7784K) reverse and bang into my front RH side.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Rel
 Policyholder's Signature
 Date & Time: 24 OCT 2018

Rel
 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

LDAC KAKI BUKIT (VAC)
 23 Kaki Bukit Ave 4
 Singapore 415933
 Tel: 67416697 Fax: 67492305
 Email: valet@sinara.com.sg
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:



ACE AUTOLUTION
 13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
 Singapore 417807
 Tel:6702 4282 Fax:6702 4202

Vehicle No. SMD7812C TOYOTA CHR

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR ADJUSTMENT	
PARTS (LIST ITEMS)					
1	FRONT BUMPER <i>DD/ae</i>	<i>ground</i>	1018.00	/	
1	FRONT BUMPER LOWER COVER <i>cut/n/c</i>		390.00	X	
1	FRONT FENDER SIDE RETAINER RH <i>best</i>		<i>81.10</i> 190.00	/	
1	FRONT FENDER WHEEL ARCH GARNISH RH		210.00	/	
1	FRONT FENDER INNER SHIELD RH <i>11</i>		310.00	X	
1	FRONT FENDER " HYBRID " EMBLEM <i>new</i>		<i>95.00</i> 150.00	/	
1	FRONT FENDER RH <i>DD/ae</i>		<i>826</i> 880.00	/	
1	HEADLAMP RH <i>new</i>		<i>1707</i> 1810.00	/	
1	LOWER ARM RH <i>11</i>		480.00	X	
1	BEARING RH <i>11</i>		650.70	X	
1	ABSORBER RH <i>11</i>		450.00	X	
1	KNUCKLE ARM RH <i>11</i>		688.40	X	
			7227.10		
less 25%			1806.78	25%	
			5420.33		
SPECIAL NETT ITEMS					
1	RIM RH <i>cut n/c</i>		980.00	X	
1	TYRE RH <i>11</i>		450.00	X	
1 SET	FRONT BUMPER CLIPS <i>new</i>		80.00	50	
Total Parts			6930.33		

*Not Authorized
 new
 1/5 # 3200/2
 3 day
 take photo after repair
 30/10/18*

*2-3961.10
 25%
 2970.82
 S.N + 50
 1 down + 1010
 4030.82
 less 20%
 3224.65*



ACE AUTOLUTION
13 Kaki Bukit Road 4 Bartley Biz Centre #03-29
Singapore 417807
Tel:6702 4282 Fax:6702 4202

Vehicle No. SMD7812C TOYOTA CHR

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	OUR ASSESSMENT (S\$)
1	LABOUR To remove the affected parts & fittings to commence repairs and replace damaged parts	1400.00	480
2	To supply paint materials, expandable items & putty, respray paint on parts replaced	1200.00	480
3	To remove and refix wiring at damaged areas	250.00	20
4	To perform anti rust treatment on affected areas	240.00	30
	Labour Total :	3090.00	
	TOTAL (PARTS & LABOUR):	10020.33	

1010

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18019489/UQD3N2

Date: 13/11/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A29072909MKC
Claimant Vehicle No :	SMD7812C	Insured Vehicle No :	GBF7484K
Date of Loss:	23/10/2018	Nature of Claim:	TP
		Claim No:	574043

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMD7812C	Engine No:	2ZR8284022
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Chassis No:	ZYX102091656
Reg. Date:	04/09/2018 (Man. Year: 2017)	Odometer:	6180 km
Colour:	Silver		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R17	Rear Tyre Size:	215/60R17
Front Left Side:	Dunlop 8 mm	Rear Left Side:	Dunlop 8 mm
Front Right Side:	Dunlop 8 mm	Rear Right Side:	Dunlop 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,930.32	3,020.82	3,909.50	56.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,090.00	1,010.00	2,080.00	67.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,020.32	4,030.82	5,989.50	59.77
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	10,020.32	3,200.00	6,820.32	68.06

INSPECTION

Date of Assignment:	25/10/2018	
Date Inspected:	30/10/2018	Inspected At:
		Ace Autolution (HQ) 13 KAKI BUKIT ROAD 4, #03-29 Bartley Biz Centre Singapore 417807
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 13 Nov 2018)
Parts: M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMD7812C)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Dented/Deformed	1,018.00 FL	*1,018.00 FL
2	1		*FRONT BUMPER LOWER COVER (CUT)	Not Consistent With The Impact	390.00 FL	*- FL
3	1		*FRONT FENDER SIDE RETAINER RH	Bent	190.00 FL	*85.10 FL
4	1		*FRONT FENDER WHEEL ATCH GARNISH RH	Grazed	210.00 FL	*210.00 FL
5	1		*FRONT FENDER INNER SHIELD RH	Not Necessary	310.00 FL	*- FL
6	1		*FRONT FENDER HYBRID EMBLEM	Necessary	150.00 FL	*95.00 FL
7	1		*FRONT FENDER RH	Dented/Buckled	880.00 FL	*826.00 FL
8	1		*HEADLAMP RH	Cracked	1,810.00 FL	*1,727.00 FL
9	1		*LOWER ARM RH	Not Necessary	480.00 FL	*- FL
10	1		*BEARING RH	Not Necessary	650.70 FL	*- FL
11	1		*ABSORBER RH	Not Necessary	450.00 FL	*- FL
12	1		*KNUCKLE ARM RH	Not Necessary	688.40 FL	*- FL
13	1		*RIM RH (CUT)	Not Consistent With The Impact	980.00 FS	*- FS
14	1		*TYRE RH	Not Necessary	450.00 FS	*- FS
15	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,737.10	4,011.10
- List Item Discount on L Items 25.00/25.00% (\$)	1,806.78	990.28
Total Parts (\$)	6,930.32	3,020.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS AND REPLACE DAMAGED PARTS	New	1,400.00	480.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED	New	1,200.00	480.00
3	TO REMOVE AND REFIX WIRING AT DAMAGED AREAS	New	250.00	20.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	240.00	30.00
Gross Labour Cost (\$\$)			3,090.00	1,010.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >