

ASS. REC. BY:

REF: CS/MSG18019490/Kqd3er

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Jasmine Lok

of MSIG

Date/Time: 26/10/18 @ 10:17am

Estimated Cost:

Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJB 3582M

Insured:

YP 3734R

at Workshop m/s

T & T Auto

Tel:

6266 8876

of

160 Sin Ming Drive #08-14

Policy No:

B2906753 MKF

Claim No:

574137

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 22/10/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

10:22am @ 26/10/18

Person Contacted:

Vincent

Vehicle IN ☒ OUT

Date/Time

Action/Instruction (✓) Estimate

SJB 3582M-X

YP 3734R-X

29/10/18-

called Vincent vni will arrange.

01/11/18 @ 3:20pm

Informed Jasmine Lok, we are pending estimate from repairer.

19/11/18 @ 3:27pm

revised to Jasmine Lok via Weimean.

LS \$1550, 3 days (red \$1404.40, 48%)

ASS. REC. BY:

REF:

ASSIGNMENT

Kenneth

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

31/10

File pass to Catherine

RECEIVED 19 NOV 2018

Date/Time, File Pass to?

☐

: Prell. Report

1) 19/11/18

☐

: Final Report

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) 1530

MER-TP

1530

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + R.S. \$1

Photos

Others

TOTAL

190

10

160

Veh No:

STB 3582m

Yr Regn:

01, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Honda Civic

c.c.

1595

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp. Reading

95149

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

J11MFD96 208S2005P7

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Venus

Front

R/Bal.

9

mm

Rear

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

22/10/18

D.O.I.

30/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Oct 2018		26 Oct 2018 10:17 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	BEN FOODS PTE LTD, Co. Reg. No.: 19690017H		
Main Claimant:	CAI HANMIN, ID: S8723232H		
Vehicle Reg. No.:	SJB3582M	Date of Loss:	22/10/2018 15:00 - :59 [129 Months and 12 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 574137	Policy/Cover Note No.:	B2906753MKF (Comprehensive) Coverage: 01/01/2018 - 31/12/2018
Vehicle Reg. No. (Insured):	YP3734R	Policy No. (Claimant):	
		Excess:	S\$1,500.00
Repairer:	T & T Auto Services Pte Ltd (160 Sin Ming) (HQ) BLK 160 SIN MING DRIVE, #08-14 SIN MING AUTOCITY, 575722 Sin Ming - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/10/2018]		
Driver/Custodian (Insured):	SOH PINK KIAT JOEY (), NRIC: S8515408G, Tel: +6588088459		
Adj Asg. Remarks:	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK. LIABILITY:100%. CONTACT: VINCENT TAN 6266 6876/ 9145 9776		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 19 Nov 2018

Preliminary Advice

Insured Vehicle No	: YP3734R	Accident Date	: 22/10/2018
TP Vehicle No	: SJB3582M	Assignment Date	: 26/10/2018
Make	: HONDA CIVIC	Est. Duration of Repair	: 3.00
Date of Inspection	: 30/10/2018		
Inspection At	: T & T AUTO SERVICES PTE LTD (160 SIN MING) (HQ) BLK 160 SIN MING DRIVE, #08-14 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,954.40
Revised Amount	:S\$	1,951.20
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,951.20
 Lump Sum Repair	 :S\$	 1,550.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Thursday, 1 November 2018 3:20 PM
To: do-not-reply@merimen.com
Cc: SUR
Subject: VEHICLE SJB 3582M (YOUR REF: 574137)

This mail is associated with :

***SJB3582M (574137)**

[YP3734R]

TP

CAI HANMIN

Oct 22 2018 3:00PM

[BEN FOODS PTE LTD]

T & T Auto Services Pte Ltd (160 Sin Ming)

Dear Jasmine,

Please be informed that we have inspected the vehicle SJB 3582M on 30/10/2018.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)



This email has been checked for viruses by AVG antivirus software.
www.avg.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/10/2018 16:43
Date Of Accident	22/10/2018 15:15
Exact Location Of Accident	BLK 463 SEMBAWANG DRIVE MULTI-STOREY CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJB3582M
Insured/Policyholder	
Name Of Registered Owner	CAI HANMIN
NRIC No	S8723232H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96561184
Alternative Phone No	OTHERS-96561184

Vehicle Particulars

Manufacturer	HONDA
Model	CIVIC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096548065
Cover Note Number	

Driver

Name of Driver	CAI HANMIN
NRIC No	S8723232H
Date Of Birth	01/08/1987
Occupation	INDOOR
Date Of Driving Pass	10/05/2006
Driving Experience	12 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96561184
Fax Number	
Contact Number	OTHERS-96561184
Email Address	NOEMAIL

Address	BLK 752 CHOA CHU KANG NORTH 5 #06-197
Postcode	680752
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YP3734R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

see attached

On 22/10/18 at about 1517 hrs, I stopped my vehicle beside Blk 463 Sembawang Drive Multi-storey carpark. Vehicle 7P 3734K was reversing out from the loading bay. While reversing the front right side hit onto the rear left portion of my car. I had video recording of the said incident.

I/We declare the foregoing particulars are true in every respect.

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #3 Pg. 1



Kg

T & T Auto Services Pte Ltd

160 Sin Ming Drive
#08-14 Sin Ming AutoCity
Singapore 575722
Tel: 6266 6876 Fax: 6266 6861

CAI HANMIN
BLK 752 CHOA CHU KANG NORTH 5
#06-197
SINGAPORE 680752

ESTIMATE

DATE : 31/10/2018
VEHICLE NO : SJB 3582 M
MAKE/MODEL : Honda Civic
ACC DATE : 22/10/2018

PARTICULAR

LIST ITEMS:

- 1 REAR BUMPER
- 1 REAR BUMPER LOWER LIP
- 1 REAR BUMPER SIDE RETAINER
- 1 REAR TAIL LAMP - LH
- 1 REAR TAIL LAMP BRACKET - LH

AMOUNT S\$

Bu 658.90 —
CPS 386.70 —
D.T 18.50 —
CM 237.40 ✓
R 16.50 X

1,318.00
Less Discount: 20%

263.60

1,054.40

SPECIAL NETT ITEMS:

- 10 REAR BUMPER CLIP
- 1 REAR REVERSE SENSOR

RM 50.00 —
RM 350.00 X

400.00

LABOUR CHARGES:

- TO CHECK WIRING
- TO REMOVE/REFIX REVERSE SENSOR
- TO REMOVE/REFIX UPHOLSTERY, CUSHION SEAT & ROOF LINING
- TO PANEL BEATING, REMOVING & REPLACING OF NEW PARTS
- TO SPRAY PAINTING ON AFFECTED AREA

50.00 2cl
100.00 5cl
RM 150.00 X
600.00 35cl
600.00 44cl

1,500.00

GRAND TOTAL: 2,954.40

Singapore Dollars: Two Thousand Nine Hundred And Fifty Four And Cents Forty Only.

T & T Auto Services Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

T & T Auto Services Pte Ltd

160 Sin Ming Drive
#08-14 Sin Ming AutoCity
Singapore 575722
Tel: 6266 6876 Fax: 6266 6861
GST Registration No: 200910712E

TAX INVOICE

MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807


DATE : 07/11/2018
VEHICLE NO : SJB 3582 M
MAKE/MODEL : Honda Civic
ACC DATE : 22/10/2018
CLAIM NO : 1018-1390
POLICY NO :

AMOUNT S\$

Lump sum repair inclusive of supplying parts, labour,
panel beating and spray painting

Repair Amount	1,550.00
Add 7% GST	108.50
Total	<u>1,658.50</u>

Singapore Dollars: One Thousand Six Hundred And Fifty Eight And Cents Fifty Only.


T & T Auto Services Pte Ltd

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Oct 2018		26 Oct 2018 10:17 Edit Adj Rpt	S\$1,550.00 Edit Estimates	S\$1,550.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: BEN FOODS PTE LTD , Co. Reg. No.: 19690017H									
Main Claimant: CAI HANMIN , ID: S8723232H									
Vehicle Reg. No.: SJB3582M		Date of Loss: 22/10/2018 15:00 - :59 [129 Months and 12 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 574137		Policy/Cover Note No.: B2906753MKF (Comprehensive) Coverage: 01/01/2018 - 31/12/2018							
Vehicle Reg. No. (Insured): YP3734R		Policy No. (Claimant):							
		Excess: S\$1,500.00							
Repairer: T & T Auto Services Pte Ltd (160 Sin Ming) (HQ) BLK 160 SIN MING DRIVE, #08-14 SIN MING AUTOCITY, 575722 Sin Ming - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 25/11/2018]									
Driver/Custodian (Insured): SOH PINK KIAT JOEY (), NRIC: S8515408G, Tel: +6588088459									
Adj Asg. Remarks: SURVEY AGREE ON SJE - REQ TO ASSIGN LKK. LIABILITY:100%. CONTACT: VINCENT TAN 6266 6876/ 9145 9776									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJB3582M (574137)**
[YP3734R]
TP
CAI HANMIN
Oct 22 2018 3:00PM
[BEN FOODS PTE LTD]
T & T Auto Services Pte Ltd (160 Sin Ming)

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	25/10/18 15:33	Accident Statement From: SC - Reg. No: YP3734R, Claimant: BEN FOODS PTE LTD		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/11/18 15:27	Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/11/18 15:16	General View		Load JPG	<input checked="" type="checkbox"/>
2	19/11/18 15:16	General View		Load JPG	<input checked="" type="checkbox"/>
3	19/11/18 15:16	General View		Load JPG	<input checked="" type="checkbox"/>
4	19/11/18 15:16	General View		Load JPG	<input checked="" type="checkbox"/>
5	19/11/18 15:16	General View		Load JPG	<input checked="" type="checkbox"/>
6	19/11/18 15:16	General View		Load JPG	<input checked="" type="checkbox"/>
7	19/11/18 15:16	General View		Load JPG	<input checked="" type="checkbox"/>
8	19/11/18 15:16	General View		Load JPG	<input checked="" type="checkbox"/>
9	19/11/18 15:16	General View		Load JPG	<input checked="" type="checkbox"/>
10	19/11/18 15:16	General View		Load JPG	<input checked="" type="checkbox"/>
11	19/11/18 15:16	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
12	19/11/18 15:16	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
13	19/11/18 15:17	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
14	19/11/18 15:17	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
15	19/11/18 15:17	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
16	19/11/18 15:17	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
17	19/11/18 15:17	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	25/10/18 15:33	SJB3582M TP E-FILE REPORT From: SC - Reg. No: YP3734R, Claimant: BEN FOODS PTE LTD		Load PDF	
2	25/10/18 15:34	EMAIL FROM TP TO ASSIGN SURVEY		Load PDF	
3	25/10/18 16:02	SURVEY AGREE ON SJE - REQ TO ASSIGN LKK		Load PDF	
4	27/10/18 12:22	E-FILE REPORT (SJB3582M) From: SC - Reg. No: YP3734R, Claimant: BEN FOODS PTE LTD		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18019490/KQD3E2

Date: 20/11/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: B2906753MKF

Claimant Vehicle No: SJB3582M

Insured Vehicle No: YP3734R

Date of Loss: 22/10/2018

Nature of Claim: TP

Claim No: 574137

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJB3582M

Make & Model: HONDA CIVIC, 1.6 L VTI (A)

Engine No: R16A13001964

Reg. Date: 10/01/2008 (Man. Year: 2007)

Chassis No: JHMF46208S200597

Colour: Multi-colour

Odometer: 95149 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R17

Rear Tyre Size: 215/45 R17

Front Left Side: Yokohama 9 mm

Rear Left Side: Yokohama 9 mm

Front Right Side: Yokohama 9 mm

Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,454.40	1,091.20	363.20	24.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	860.00	640.00	42.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,954.40	1,951.20	1,003.20	33.96
Approved Total (Overridden) (S\$)		1,550.00		
(S\$)	2,954.40	1,550.00	1,404.40	47.54
+ GST 7.00/7.00% (S\$)	206.81	108.50	98.31	47.54
Nett Amount (S\$)	3,161.21	1,658.50	1,502.71	47.54

INSPECTION

Date of Assignment: 26/10/2018

Date Inspected: 30/10/2018 Inspected At:

T & T Auto Services Pte Ltd (160 Sin Ming)
(HQ)
BLK 160 SIN MING DRIVE, #08-14 SIN
MING AUTOCITY
Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 20 Nov 2018)
Parts: 143	HONDA CIVIC 1.6 L VTI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJB3582M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	658.90 FL	*658.90 FL
2	1		*REAR BUMPER LOWER LIP	Cracked	386.70 FL	*386.70 FL
3	1		*REAR BUMPER SIDE RETAINER	Distorted	18.50 FL	*18.50 FL
4	1		*REAR TAIL LAMP-LH	Cracked	237.40 FL	*237.40 FL
5	1		*REAR TAIL LAMP BRACKET-LH	Repair	16.50 FL	*- FL
6	10		*REAR BUMPER CLIP	No	50.00 FS	*50.00 FS
7	1		*REAR REVERSE SENSOR	Serviceable	350.00 FS	*- FS
					Sub Total (S\$)	1,718.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	263.60
					Total Parts (S\$)	1,454.40

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	20.00
2	TO REMOVE/REFIX REVERSE SENSOR	New	100.00	50.00
3	TO REMOVE/REFIX UPHOLSTERY,CUSHION SEAT & ROOF LINING	New	150.00	-
4	TO PANEL BEATING,REMOVING & REPLACING OF NEW PARTS	New	600.00	350.00
5	TO SPRAY PAINTING ON AFFECTED AREA	New	600.00	440.00
Gross Labour Cost (\$\$)			1,500.00	860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >