



Case Details

Case Reference Number : BUS/10/18/7009
 Type of Repair : Accident Repair
 Vehicle Registration Number : SMB268E

Company Type : SMRT Buses Ltd
 Estimation ID : EST-4074-ID
 Assigned By : Claiming Case Owner Team

Insurance Company Name : EQ Insurance Company Ltd
 Accident Date and Time : 09/10/2018 01:53 AM
 Vehicle Age(In Months) : 77

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approv		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Re
Standard	Main	BODY RH	6009984	PANEL,SIDE:R3,FOR MAN A22 BUS	1	266.00	266.00	10.00	239.40	Replace	1	0	XR
Standard	Main	CONSUMABLE	4006314	ADHESIVE:DIRECT GLAZING	4	37.00	148.00	0.00	148.00	Replace	0	0	XNN
Standard	Main	CONSUMABLE	4006313	PRIMER (SIKA 206 G+P)	1	80.00	80.00	0.00	80.00	Replace	0	0	XNN
Standard	Main	Body	6010152	COVER,HEADLAMP:FRT,RH,FOR MAN A22 BUS	1	974.70	974.70	100.00	0.00	Repair	1	0.00	XR
Total Spare Part Cost									467.40		Surveyor Total	0.00	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)	20	
Final Spare Part Cost									373.92		Final Sur Total	0.00	

Labour's Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,060.00	795	
Total:		1,060.00	795.00	


Spray Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	528.00	446	
Total:		528.00	446.00	

Other Cost Detail

S.No.	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:		0.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	373.92	0.00
Total Labour Cost	1,060.00	795.00
Total Spray Painting	528.00	446.00
Other	0.00	0.00
Overall Total	1,961.92	1,241.00
Lump Sum Repair Option	☒	☒
Lump Sum Total	1,950.00	1,250.00
Surveyor Approved Amount		1,250.00
No of Repair Days*	3	2
Remarks	-	LUMP SUM REPAIR. 2 DAYS. AFTER REPAIR PHOTOS.
Surveyor Name		Naz
Signature		 Save Clear
Survey Date	24/10/2018	

NAZ LKK

24/10/18

LIS

2 DAYS

AFTER REPAIR PHOTOS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: