

ASS. REC. BY:

REF:

CS/ICS18019510/K9d3

n2

Special Instruction:

Surveyor:

Meinman

ASSIGNMENT (Office)

From (Person):

Janice Goh

of

ICS

Date/Time:

26/10/2018 @ 12:10pm

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

81H 186M

Insured:

81K 3193G

at Workshop m/s:

City Auto

Tel:

6453 1235

of

Blk 8 Sin Ming Ind. Est #01-60/62

Policy No:

Claim No:

DMPC1800407H

Sum Insured:

Excess:

Make of Veh:

D.O.A.

23/10/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

12:31pm @ 26/10/18

Person Contacted:

Vronica

Vehicle:

IN (OUT)

Date/Time

Action/Instruction (✓) Estimate

81H 186M-X

81K 3193G-X

01/11/18 @ 3.56pm revised to Janice Goh via Meinman.

02/11/18 @ 11.56am confirmed with Vronica final Ag \$2534.48, 2 days.

(Red \$1199.97, 32%)

ASS. REC. BY:

REF: 1051

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.:

Yes or No

Lum Sum:

1-B1

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLH186m

Yr Regn:

02, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Tug Prius

c.c

1.797

Colour:

M.P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

28006

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ZVW 50

6084652

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

23/10/18

D.O.I.

29/10/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

30/10

File pass to Catherine

RECEIVED 07 NOV 2018

Data/Time, File Pass to?

☐

Prell. Report

1) 01/11/18

☐

Final Report

Data/Time, File Return to?

2)

Days Of Repair:

2

Resurvey No. of Trip:

1

Survey Fee:

Transportation:

S + RS. SI

250

Factors

10

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

MEK-TP

Lump Sum / I.B.I. (\$

2534.48

TOTAL

260

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 01 Nov 2018

Preliminary AdviceInsured Vehicle No : SLK3193G
TP Vehicle No : SLH186M
Make : TOYOTA PRIUS
Date of Inspection : 29/10/2018
Inspection At : CITY AUTOAccident Date : 23/10/2018
Assignment Date : 26/10/2018
Est. Duration of Repair : 2**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,312.42
Revised Amount	:S\$	1,811.11
Check Items (Estimated)	:S\$	824.03
Total	:S\$	2,635.14

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Nivitha (LKK Auto)

From: ECICS Claims <claims@ecics.com.sg>
Sent: Friday, 26 October 2018 12:10 PM
To: City Auto; 'assignments'
Cc: ECICS Claims
Subject: RE: [Spam-pop3] RE: Arrange survey on SLH186M ; Our ref DMPC1800407H
Attachments: Estimate.pdf; GIA report.pdf

Without Prejudice

Dear Vronica

Thank you for your email.
We will appoint LKK for the survey.

Aside to LKK

Please assist on the TP survey.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: City Auto [mailto:cityauto@singnet.com.sg]
Sent: Friday, 26 October, 2018 11:47 AM
To: ECICS Claims
Subject: RE: [Spam-pop3] RE: Arrange survey on SLH186M ; Our ref DMPC1800407H

Dear Sir,

Kindly arrange **LKK Auto** to survey.

Thank you.

Best Regards,

Vronica Law
City Auto Pte Ltd
Blk 8 Sin Ming Industrial Estate,
#01-60/62 Sin Ming Road,
Singapore 575643

Tel : 6453 1235
Fax : 6453 7944

From: ECICS Claims [mailto:claims@ecics.com.sg]
Sent: Friday, 26 October, 2018 11:29 AM
To: City Auto
Cc: ECICS Claims
Subject: [Spam-pop3] RE: Arrange survey on SLH186M ; Our ref DMPC1800407H

Without prejudice

Dear Vronica

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Thank you.

Regards,
Janice Goh
Claims Division
DID: +65 6303 0182
FAX: +65 6338 9267

ECICS Limited
10 Eunos Road 8, Singapore Post Center #09-04A, Singapore 408600

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.

From: City Auto [mailto:cityauto@singnet.com.sg]
Sent: Friday, 26 October, 2018 10:15 AM
To: ECICS Claims
Subject: Arrange survey on SLH186M

Hi Arrangement survey dept,

Kindly arrange survey on following vehicle :

TP Survey

Your vehicle : SLK3193G

Our vehicle : SLH186M

D.O.A : 23/10/2018

LOCATION : Blk 160, Sin Ming Drive, Sin Ming Auto City #05-01 Singapore 575722

Thank you.

Best Regards,

Vronica Law

City Auto Pte Ltd

Blk 8 Sin Ming Industrial Estate,

#01-60/62 Sin Ming Road,

Singapore 575643

Tel : 6453 1235

Fax : 6453 7944



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

ECICS LIMITED

Contact : 98439539

Fax No. : 63389267

Estimate : QUOT201810-000461(00)

Date : 25/10/2018

Vehicle No. : SLH186M

Make/Model : TOYOTA PRIUS HYBRID 1.8S CVT

Mileage (km) : 0

Chassis No. : ZVW506064652

Accident Date : 23/10/2018 00:00:00

Claim No. : SLK3193G

Reference : SLH186M

Policy No. : 5087843575-01

Not Notified
Resurvey B& paint
2 days

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Rear bumper - Top	1.0	585.90	<i>Bar</i> 585.90 ✓
2	Rear bumper - Bottom	1.0	592.60	<i>not cut</i> 592.60 ✓
3	Rear end panel	1.0	696.90	<i>R</i> 696.90 ✗
4	Rear bumper reinforcement	1.0	401.80	<i>BT</i> 401.80 ✓
5	Rear boot emblem	1.0	69.70	<i>nn</i> 69.70 ✗
6	Rad reflector	2.0	38.80	<i>sun</i> 77.60 ✓
7	Tow hook cover	1.0	36.80	<i>hit</i> 36.80 ✓
List Total :				2,461.30
25% Discount S\$				615.31
				1,845.99
SPECIAL NET :				
1	Reverse sensor	1.0	376.43	<i>sun</i> 376.43 ✓
SPECIAL NET Total S\$:				376.43
LABOUR :				
	*To check and re-wiring	1.0	40.00	40.00 <i>15L</i>
	-To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	450.00	450.00 <i>20H</i>
	- Spray painting on affected & replace parts	1.0	600.00	600.00 <i>25H</i>
				1,090.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

E. & O.E.

Acknowledged by Repairer	Total S\$:	3,312.42
Signature:	GST 7% S\$:	231.87
Date:	Amount Due S\$:	3,544.29

for CITY AUTO PTE LTD

Kg



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-80/82, SIN MING ROAD, SINGAPORE 575643
TEL: 6453 1235, 6452 0850 FAX: 6453 7944
24hrs Towing Services Tel: 9823 9898
Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

ECICS LIMITED

Estimate : QUOT201810-000461(00)

Date : 25/10/2018

Vehicle No. : SLH186M

Make/Model : TOYOTA PRIUS HYBRID 1.8S CVT

Mileage (km) : 0

Chassis No. : ZVW506064652

Accident Date : 23/10/2018 00:00:00

Claim No. : SLK3193G

Reference : SLH186M

Policy No. : 5087843575-01

Contact : 98439539

Fax No. : 63389267

Not Attached

Reserve B & paint

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Rear bumper - Top	1.0	585.90	585.90 <i>Per</i>
2	Rear bumper - Bottom	1.0	592.60	592.60 <i>Per</i>
3	Rear-end-panel	1.0	696.90	696.90 <i>Per</i>
4	Rear bumper reinforcement	1.0	401.80	401.80 <i>Per</i>
5	Rear boot emblem	1.0	69.70	69.70 <i>Per</i>
6	Rad reflector	2.0	38.80	77.60 <i>Per</i>
7	Tow hook cover	1.0	36.80	36.80 <i>Per</i>
List Total :				2,461.30
25% Discount S\$				615.31
				1,845.99
SPECIAL NET :				
1	Reverse sensor	1.0	376.43	376.43 <i>Per</i>
SPECIAL NET Total S\$:				376.43
LABOUR :				
	*To check and re-wiring	1.0	40.00	40.00 <i>15%</i>
	-To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	450.00	450.00 <i>20%</i>
	- Spray painting on affected & replace parts	1.0	600.00	600.00 <i>25%</i>
				1,090.00

E. & O.E.

Total S\$: 3,312.42
GST 7% S\$: 231.87
Amount Due S\$: 3,544.29

for CITY AUTO PTE LTD

3734.43



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Supplementary Estimate : QUOT201810-000461(00)

ECICS LIMITED

Date : 25/10/2018

Vehicle No. : SLH186M

Make/Model : TOYOTA PRIUS HYBRID 1.8S CVT

Mileage (km) : 28208

Chassis No. : ZVW506064652

Accident Date : 23/10/2018 00:00:00

Claim No. : SLK3193G

Reference : TP ECICS

Policy No. : 5087843575-01

Contact : 98439539

Fax No. : 63389267

S/No	Particular	Quantity	Unit Price	Amount S\$
LIST ITEMS :				
1	Rear end lower splash guard	1.0	562.70	562.70
List Total :				562.70
25% Discount S\$				140.67
				422.03

P- \$ 1,694.70

- 25%

\$ 1,271.03

SN - \$ 376.43

L - \$ 465.00

supplementary - \$ 422.03

\$ 2,534.49

P/P - \$ 2,534.49 ✓/ok

3 Days

E. & O.E.

Total S\$: 422.03

GST 7% S\$: 29.54

Amount Due S\$: 451.57

for CITY AUTO PTE LTD

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS18019510/KQD3N2

Date: 08/11/2018

REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SLH186M	Insured Vehicle No :	SLK3193G
Date of Loss:	23/10/2018	Nature of Claim:	TP
		Claim No:	DMPC1800407H

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH186M	Engine No:	2ZRR972236
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	ZVW506064652
Reg. Date:	15/02/2017 (Man. Year: 2016)	Odometer:	28206 km
Colour:	Metallic Pearl White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,644.43	2,069.48	574.95	21.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,090.00	465.00	625.00	57.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,734.43	2,534.48	1,199.95	32.13
+ GST 7.00/7.00% (S\$)	261.41	177.41	84.00	32.13
Nett Amount (S\$)	3,995.84	2,711.89	1,283.95	32.13

INSPECTION

Date of Assignment:	26/10/2018	
Date Inspected:	29/10/2018 Inspected At:	City Auto Pte Ltd Blk 13, Sin Ming Industrial Estate Sector B, #01-47/49 Singapore 575657
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Nov 2018)
Parts: 144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLH186M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER-TOP	Buckled	585.90 FL	*585.90 FL
2	1		*REAR BUMPER-BOTTOM	Dented/Cut	592.60 FL	*592.60 FL
3	1		*REAR END PANEL	Repair	696.90 FL	*- FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	401.80 FL	*401.80 FL
5	1		*REAR BOOT EMBLEM	Not Necessary	69.70 FL	*- FL
6	2		*RAD REFLECTOR	Scratched	77.60 FL	*77.60 FL
7	1		*TOW HOOK COVER	Missing	36.80 FL	*36.80 FL
8	1		*REVERSE SENSOR	Scratched	376.43 FS	*376.43 FS
9	1		*REAR END LOWER SPLASH GUARD	Cracked	562.70 FL	*562.70 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,400.43	2,633.83
- List Item Discount on L Items 25.00/25.00% (\$\$)	756.00	564.35
Total Parts (\$\$)	2,644.43	2,069.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK AND RE-WIRING	New	40.00	15.00
2	TO KNOCK,JACKOUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS	New	450.00	200.00
3	SPRAY PAINTING ON AFFECTED & REPLACE PARTS	New	600.00	250.00
Gross Labour Cost (S\$)			1,090.00	465.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >