

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AUTO	MOTIVE ENGIN	EERING & MGT DIVISION	Ref : CS/SPF18019519/T1vd3e2		
ACCIDENT CLAIM SECTION(SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333 ATTN: FRANKIE THAY		Date: 07-11-2018  Code: SPF			
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	QX 910X	Veh. Inspected	SDV 7948G	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	AEMD/105/009/2018/150	Excess (\$)	0.00	
	Assign From	FRANKIE THAY	Assign Date	26/10/2018	
2. Vehicle Particulars & Condition					
	Make & Model	LEXUS LS460	c.c	4608	
	Engine No.	HIDDEN	Year of Reg.	2012	
	Chassis No.	JTHGL46F105047449	Colour	WHITE	
	Odometer	46872	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	245/45 R19	CONTINENTAL	6 mm	
	L/H Front Tyre	245/45 R19	CONTINENTAL	6 mm	
	R/H Rear Tyre	245/45 R19	CONTINENTAL	6 mm	
	L/H Rear Tyre	245/45 R19	CONTINENTAL	6 mm	
4. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	10/10/2018	Inspection Date	26/10/2018	
	Survey held at	BORNEO MOTORS (S) PTE LTD			
		2 PANDAN CRESCENT SINGAPORE 128462			
5a.	5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days				