

INS. CASE OWNER: Yvonne | CC 4 ASM | AXA1801 | 95N, KJ | 10/10/18 | LKK: 10/10/18 | IDAC: 10/10/18

Surveyor: ESC | DOI: 10/10/18 | Date / Time: 10/10/18 | Registered in Merimen: 20/10/18

Pre-assign / CCU / FTE: SLC 8742C  
 Insured Vehicle No.: SLC 8742C | Claim No.: 88M0LOPO (7843)  
 Name of Insured: 800 911 801 | Policy No.: P21300.92  
 Insured Tel No.: 800 911 801 | HP: 8777 8888 | Make / Model: BMW  
 Excess Sec II :SS: 19/10/18 | D.O.A.: 19/10/18 | Place of Accident: PVE TURNS TO EXIT Singapore  
 Is driver the owner? (YES / NO) | Nature of Accident:   
 If NO, Driver Name / Age:  | OI GIA REPORT: YES / NO:  | TP GIA REPORT: YES / NO:   
 Driver Tel No.:  | (V/L: YES / NO):  | Insured Liability: % | Final ? Yes / No:

SJP 261K → → → →  
 INSR: Accord | INSR:  | INSR:  | INSR:   
 WSP:  | WSP:  | WSP:  | WSP:   
 Tel:  | Tel:  | Tel:  | Tel:   
 Liability:  | Liability:  | Liability:  | Liability:   
 RMKS:  | RMKS:  | RMKS:  | RMKS:

Date / Time	STAGE	DATE / PIC
<u>7/10/18</u>	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	<u>18-4-19 JUY</u>
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	<input checked="" type="checkbox"/> <input type="checkbox"/>
	After call ltr to OI:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Authorisation To Act:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Release Voucher:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Final Repair Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Car Rental Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Towing Invoice:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LTA / GIA:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Medical Bill:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	PIR:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Mandate/Reject Instruction:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	LOD:	<input checked="" type="checkbox"/> <input type="checkbox"/>
	Payment Breakdown Form:	<input type="checkbox"/> <input type="checkbox"/>
	Post-Repair Photos:	<input type="checkbox"/> <input type="checkbox"/>
	Others:	<input type="checkbox"/> <input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 18-4-19 Sent By: 240 PW

FINALIZATION Date/Time: 28-11-18 Confirm with: CELIA Email:  Call:

Repair Cost: \$5 (days) Reduction:  % Email:  Call:

FINAL SETTLEMENT Date/Time: 28-11-18 Confirm with: CELIA Email:  Call:

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 27 If NO or B 28, Ass. Lin:

Repair Cost: GST \$5 / 214

Loss of Rental (LOR): \$5 (days)

Loss of Use (LOU): \$5 (60 (560 x 1 days))

Loss of Income (LOI): \$5 (5 x days)

LOR only  LOU only  LOR + LOU  LOR + LOI  [Tick only one]

GIA/LTA Search: \$5 / 2

Medical: \$5 | Disbursement: \$5 (e.g. Tow/Independent) | Legal Cost: \$5

Total: \$5 276.72 Global Sum \$5:

FINAL PAYMENT Date/Time: 27-11-18 Confirm with: ACCORD AUTO SERVICES PTE LTD Email:  Call:

Payee 1: \$5 276.22 Name 1: ACCORD AUTO SERVICES PTE LTD

Payee 2: (Strike if N.A.) \$5 Name 2: X

Payee 3: (Strike if N.A.) \$5 Name 3: X

18-4-19 @ 240 PW OI DISPUTED, BUT UNDERSTOOD WE WILL HAVE TO SETTLE, BASED ON PHOTO & SCENARIO.

REF: ASM (AXA)

ASSIGNMENT

From: Date: 29/10/2018

Veh No: SJP261K Yr Regn: 03 09

Estimated Cost:

Type:  Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or

OD  WS / TP RES / OD RES / EVA / INV / MV

Make: Picco Bravo cc 1368

To Inspect Vehicle No: SJP261K

Colour: White A/C: Insured / Std / NI / NA

at Workshop m/s: Accord Auto

Sp. Reading: 70151 T/Radio: Insured / Std / NI / NA

of 10 AMK Ind. Park 2A AMK #03-11

Eng/No:

Insured:

C/No: ZFA798-0000-4204064

Policy No:

Gen. Cond:  Good / Fair / Poor / Burnt

Claims No:

Steering:  In order / Jammed / Leaked / Burnt or

Sum Insured:

Excess:

Brake:  In order / Jammed / Leaked / Burnt or

(Client's Record)


Mod: Nil / S/Rim / STD A/Rim or

Make of Veh:

10am@owner waiting

Tyre Size: F: 225/45 R17

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Nexen

Bal. or Market Value: 812k

Front: R/Bal. 7 mm L/Bal. 7 mm D.O.A. 19/10/18

IDAC Accident Rport: Consistent? : Yes or No

Rear: R/Bal. 8 mm L/Bal. 8 mm D.O.I. 29/10/18

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 01 days Res.: Yes or No

Lum Sum: 1-B.1 % 3 Val.: Yes or No

Survey held at

CA / REV / REP. / 24 HRS (cup)

Des. of Damages: Frt /  Rear / O/S / N/S / U/C / Rooftop or

Date Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
30/10 R2 pass to Catherine @ 2006

R ( \$ 450 / 699. )

Date/Time. File Pass to?  : Preli. Report

Days Of Repair:

1)  : Final Report

Resurvey No. of Trip:

Date/Time. File Return to?

Survey Fee:

2)

Add Fee:  Site Insp (\$)

Transportation:

Report Format :

Interview (\$)

3 - RS. \$

Lump Sum / I.B.I: (\$)

Tech. Invs (\$)

Photos

Weekend (\$)

Others

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18019521/Kub3

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811

Date : 26-10-2018



Code : ASM

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLC 8342C	Veh. Inspected	SJP 261K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	26/10/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	19/10/2018	Inspection Date	29/10/2018
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



> [Back to OneMotoring](#)

### Enquire Transfer Fee

Vehicle No. :	SJP261K
Vehicle Type :	P10 - Passenger Motor Car
Vehicle Attachment 1 :	With Sun Roof
Vehicle Scheme :	Revised Off-Peak Car
Vehicle Make :	FIAT
Vehicle Model :	BRAVO 1.4A 120 BHP SMT TURBO D/AB SR
Chassis No. :	ZFA19800004204064
Propellant :	Petrol
Engine No. :	198A40001348701
Engine Capacity :	1368 cc
Maximum Power Output :	88.0 kW (118 bhp)
Maximum Laden Weight :	1770 kg
Unladen Weight :	1335 kg
Year Of Manufacture :	2008
Original Registration Date :	09 Mar 2009
Lifespan Expiry Date :	-
COE Category :	E - Open Category
Quota Premium :	\$6,509.00
COE Expiry Date :	08 Mar 2019
Road Tax Expiry Date :	08 Mar 2019
PARF Eligibility Expiry Date :	08 Mar 2019
Inspection Due Date :	08 Mar 2020
Intended Transfer Date :	25 Oct 2018
CO2 Emission :	-
CO Emission :	-
HC Emission :	-
NOx Emission :	-
PM Emission :	-

Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.

Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.

	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
<b>Total Amount Payable :</b>			<b>25.00</b>

You may print this page for reference.

OK

Print

**Catherine Chong (LKK Auto)**

---

**From:** KUMAR Shailendra <shailendra.kumar@axa.com.sg>  
**Sent:** Friday, 26 October, 2018 10:48 AM  
**To:** admin-d@lkkauto.com  
**Subject:** SERVICE APPOINTMENT IN VENDOR PORTAL: S8M010PD FOR SJP261K  
**Attachments:** Accident Involving SJP261K & SLC8342C on 19/10/2018 (1.20 MB)

Hi,

PFA

Best Regards  
Shailendra

-----Disclaimer-----

This message may contain confidential information intended solely for the use of the named addressee. If you are not the intended recipient, you should not read, use, disclose or reproduce the content of this message. If you have received this message by mistake, please notify the sender immediately. Any views or opinions presented in this message are solely those of the author and do not necessarily represent those of AXA Singapore - Externals or any other entity of the AXA Group, unless otherwise stated by the sender and duly authorized by the said companies.

26.10.2018 @ 11:12am  
Jessy wh not in.

**Catherine Chong (LKK Auto)**

---

**From:** Accord Auto(Claims) <claims@mycarworkshop.com.sg>  
**Sent:** Thursday, 25 October, 2018 5:06 PM  
**To:** SG AXA Insurance SM AXA SGP - Motor Survey  
**Cc:** Gilbert Ng  
**Subject:** Accident Involving SJP261K & SLC8342C on 19/10/2018  
**Attachments:** 261 - ADD HL.pdf

**Follow Up Flag:** Follow up  
**Flag Status:** Flagged

Dear Sir,

Please assist arrange Pre-Repair Survey for SJP261K and provide us 10 surveyor name list.

\*Vehicle not in workshop.

Thank you.

Kind regards,  
Jessy Soe

Accord Auto Services Pte Ltd  
10 Ang Mo Kio Ind Park 2A  
#03-11 Ang Mo Kio Auto Point  
Singapore 568047

Mobile : (65) 9740 0999  
Tel : (65) 6481 9517  
Fax : (65) 6481 9516

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.

## ◀ Service Request Details

### Claim

S8M010PD

### Reference

None 

### Loss Date

October 19, 2018

### Request Date

October 26, 2018

### Due Date

November 2, 2018

### Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

### Type of Loss

Third Party Vehicle Damage

### Services

Pending verification - Direct Settlement

### Actions

---

#### Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

---

#### Incident Vehicle Registration #

SJP261K

#### Make

TPVD FIAT

Model  
BRAVO-1.4 (A)

### Service Address

---

...

### Primary Contact/Insured

---

KOO GIN BOOI  
BLK 26D JALAN MEMBINA, #13-158, 167026, Singapore

maykoo2003@yahoo.com

### Claim Handler

---

ANG Yvonne  
6568804461  
yvonne.ang@axa.com.sg

Additional Instructions  
NON-REPORTED

---

[Messages](#)   [Invoices](#)   [History](#)   [Documents](#)   [Assessment](#)   [Metrics](#)   [Notes](#)

---

[New Message](#)

# ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3  
#01-80 SINGAPORE 159723  
TEL: 6271 5133/6271 7433 FAX: 6274 5715  
GST Regn No: 201113141K

17 November 2018

**AXA Insurance Singapore Pte Ltd**  
8 Shenton Way  
#27-01 AXA Tower  
Singapore 068811

**Attn: Motor Claims Department**

Dear Sirs,

**ACCIDENT INVOLVING VEHICLE: SJP261K and SLC8342C on 19.10.2018 Along Tuas Checkpoint Viaduct Toll Road.**

We are the authorized repair workshop for the owner of motor vehicle no: **SJP261K**, which was involved in the captioned accident with your insured vehicle: **SLC8342C**. The vehicle owner has requested and authorized us to assist him in presenting his/her claim against the party responsible for the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving, we are submitting these claims for your consideration on behalf of the owner/claimant.

01) Cost Of Repair	S	200.00
02) 7% GST	S	14.00
03) Loss Of Use 1 Days @ \$80	S	80.00
04) GIA/LTA Enquiry Fee	S	2.00
	<b>S</b>	<b>296.00</b>

We enclosed herewith the following documents to support the claims:-

- |                            |                                   |
|----------------------------|-----------------------------------|
| a) GIA report              | d) Insured NRIC & Driving License |
| b) Repair Statement AMK469 | e) GIA/LTA Enquiry Fee            |
| c) Letter Of Authority     |                                   |

Kindly look into the matter and let us hear from you on the settlement of our customer's claims as soon as possible.

**Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the owner/claimant.**

Thank you  
Yours faithfully

**ACCORD**  
Celtia Lai  
Accord Auto Services Pte Ltd  
Tel: 6271 7433 / 9274 0999  
Email: avclaims@mycarworkshop.com.sg

## Joy Irene (LKKAuto)

---

**From:** May Koo <maykoo2003@yahoo.com>  
**Sent:** Wednesday, 24 April 2019 6:44 PM  
**To:** Joy Irene (LKKAuto)  
**Cc:** Admin A  
**Subject:** Re: ACCIDENT INVOLVING SLC 8342C AND SJP 261K ALONG TUAS CHECKPOINT ON 19.10.2018

Hi Joy,

Shall leave it to my insurance AXA and the inspection report to determine. The inspection process should also consider checking the position of the scratch against the position of my vehicle and whether it is possible for the scratch to be caused by my vehicle. If the report determines as positive, my insurance AXA shall settle this accordingly.

On Thursday, April 18, 2019, 2:13:39 PM GMT+8, May Koo <maykoo2003@yahoo.com> wrote:

Hi,

Thank you for the below email. I have already made police report the next day, as well as report to my insurance and sent my car to Performance Motor for inspection. Performance Motor is one of the workshops assigned by my car insurance agent. They took a lot of photos of my car, as well as obtained the video clips on my in-car camera.

You may ask the driver's insurance company to contact my insurance company. I have already informed your client the same over messages in October.

Many thanks.

Best regards,  
Koo

On Thursday, April 18, 2019, 1:30:37 PM GMT+8, Joy Irene (LKKAuto) <JoyIrene@lkkauto.com> wrote:



**KOO GIN BOOI**

Policy Holder

Dear Sir/Madam,

**OUR REF : CC4/ASM18019521/Kjb3**

**YOUR REF : SLC 8342C**

**ACCIDENT INVOLVING SLC 8342C AND SJP 261K ALONG TUAS CHECKPOINT ON 19.10.2018**

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Singapore Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s ACCORD AUTO SERVICES PTE LTD, acting on behalf of the owner of SJP 261K against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had hit Third Party vehicle from the rear. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact the undersigned.

Please quote the claim reference when you contact us that we can assist you more effectively.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: [joyirene@lkkauto.com](mailto:joyirene@lkkauto.com) | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.

## LETTER OF AUTHORITY

To Whom It May Concern,

Accident Involving Vehicle: SJP261K and SLR 8342C on 19.10.2018 Along Tuas Checkpoint  
Viaduct Toll Rd

I/We, Zhang Hongqi @ Setlens Henry NRIC no. S81044582  
of \_\_\_\_\_

owner of motor vehicle no. SJP261K do hereby appoint **Accord Auto Services Pte Ltd**  
as my/ours authorised representation and \_\_\_\_\_

as my/ours solicitors to write, to negotiate and settle my/our claims against the other party/parties  
involved in the above mentioned accident. I/We, Zhang Hongqi @ Setlens Henry  
shall have absolute discretion to settle the matter at the best term.

I/We also confirm and instruct that any agreed settlement sum in respect my/our claims be paid  
**Accord Auto Services Pte Ltd** and such payment will be constitute a full and final discharge of my  
claims.

  
\_\_\_\_\_

Signature of Owner



# Without Prejudice on Injury Claims

## AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	SLC 8342C	(Insd veh)	Model: FIAT BRAVO 1.4 (A)
	SJP 261K	(TP veh)	
Date of Accident/ Time:	19/10/18		

Repair Estimate	✓	\$ 695.50	
Final Repair Cost	GST	\$ 214.00	
Loss of Use		\$ 80.00	1 days at \$ 80.00 per day
Rental (if any)		\$	days at \$ per day
LTA / GIA Search Fee		\$ 2.00	
Others		\$	
Final Settlement Sum		\$ 276.00	
Payee Name: ACCORD AUTO SERVICES PTE LTD			
Is Third Party Workshop GIA Registered?     YES  X  NO (Kindly indicate below)			
A)	For Non GIA Registered Workshop:	Agreed Liability	100 (%)
B)	For GIA Registered Workshop:	BOLA Applicable	Yes/ No BOLA Scenario No: _____
	BOLA Liability: _____ (%)	Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply			
Remarks			

**NOTE:**

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are **not received within 7 days** of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates

We/I confirmed that this is a **full and final settlement** that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

**ACCORD**  
AUTO SERVICES PTE LTD

**ACCORD**  
AUTO SERVICES PTE LTD

Signature of workshop representative / Workshop stamp

Name of Representative *Celia Lai*

Date: **28 MAY 2019**

Signature of Witness / Workshop stamp (if applicable)

Name of Witness *Gilbert Ng*

Date: **28 MAY 2019**

Signature of AXA's surveyor/representative

Name of AXA's surveyor /Representative

Date:

(AXA) j  
Lack

# ACCORD AUTO SERVICES PTE LTD

BLOCK 1009 BUKIT MERAH LANE 3  
#01-80 SINGAPORE 159723  
TEL: 6271 5133/6271 7433 FAX: 6274 5715  
GST Regn No: 201113141K

T

Date : 17 Nov 2018

AXA Insurance Singapore Pte Ltd  
8 Shenton Way  
#27-01 AXA Tower  
Singapore 068811

Our Ref No : AMK469  
Insured : Zhang HengMi@ Setiano Henry  
Insured NRIC : S8104458I  
Make & Model : Fiat Bravo 1.4A  
DOA : 19.11.2018  
Claim Type : Third Party

## REPAIR STATEMENT

Re: Vehicle Registration No:

SJP261K ✓

Cost Of Repair	\$	200.00
7% GST	\$	14.00
	<u>\$</u>	<u>214.00</u>

Accord Auto Services Pte Ltd

**ACCORD**  
AUTO SERVICES PTE LTD

---



**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735

### Third Party Insurer Enquiry

Our Ref No: GR-18-166010  
Date of Request: 25/10/2018

Your Ref No: Online Purchase

Accord Auto Services Pte Ltd  
10 Ang Mo Kio Ind Park 2A #03-11  
AMK Auto Point  
Singapore 568047

Dear Sir/Madam,

Enquiry Date: 25/10/2018  
Enquiry By: Soe Jie Yi  
TP Vehicle No: SLC8342C  
Accident Date: 19/10/2018

**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SLC8342C	AXA Insurance Pte Ltd	01/06/2018-31/05/2020	6338 7288

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18019521/Kjb3q2

8 SHENTON WAY #24-01  
AXA TOWERSINGAPORE 068811  
ATTN:YVONNE

Date : 17-06-2019



Code : ASM

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLC 8342C	Veh. Inspected	SJP 261K
Policy No.	P2130092	Coverage (\$)	0.00
Claim No.	S8M010PD	Excess (\$)	0.00
Assign From		Assign Date	26/10/2018

## 2. Vehicle Particulars & Condition

Make & Model	FIAT BRAVO (A)	c.c	1368
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	ZFA19800004204064	Colour	WHITE
Odometer	70151	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45Z R17	NEXEN	7 mm
L/H Front Tyre	225/45Z R17	NEXEN	7 mm
R/H Rear Tyre	225/45Z R17	NEXEN	8 mm
L/H Rear Tyre	225/45Z R17	NEXEN	8 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

## 5. General Information

Accident Date	19/10/2018	Inspection Date	29/10/2018
Survey held at	ACCORD AUTO SERVICES PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A AMK AUTO POINT #03-11 SINGAPORE 568047		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>1 Working Days</b>
-------------------------------------	-----------------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJP 261K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	SPRAY PAINTING ON ALL AFFECTED AREA.		300.00	200.00
	LABOUR REMOVE/REFIX ACCIDENT DAMAGES PARTS TO KNOCK ,JACK ,CUT WELD AND REALIGN ACCIDENT AFFECTED AREA.	NOT NECESSARY	300.00	-
	TO APPLY ANTI RUST TREATMENT.	NOT NECESSARY	50.00	-
			650.00	200.00
	<b>GRAND TOTAL</b>		<b>650.00</b>	<b>200.00</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>200.00</b>

Report Ref No. CC4/ASM18019521/Kjb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

## Service Request Details

Claim: SRM010FD  
 Reference: CCA/ASH18019521/0J0302  
 Loss Date: 19 October 2018  
 Report Date: 26 Oct 2018 8:39:48 AM  
 Request Date: 26 October 2018  
 Due Date:

Vendor Name: LKK AUTO CONSULTANTS PTE LTD (P)  
 Type of Loss: Third Party Vehicle Damage  
 Services: Pending verification - Direct Settlement

**Actions**

Next Step: Wait for Approve invoice

Add Invoice

**Vehicle Information**

Incident Vehicle Registration #: SJP281K  
 Make: TPVD FIAT  
 Model: BRAVO-1.4 (A)  
 Service Address: ...

**Primary Contact/Insured**

KOO GIN BOO  
 BLK 240 JALAN MEMBINA, #13-15B, 167026, Singapore  
 maykoo2003@yahoo.com

**Claim Handler**

ANG Yvonne  
 656804461  
 yvonne.lang@axa.com.sg

Additional Instructions: NON-REPORTED

Messages Invoices History Documents Assessment Metrics Notes

Document Type:

[+ Upload Documents](#)

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Accident Statement				
Reports & Statement				

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
■ LKInvoice1 (5).pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
■ PAYMENT BREAKDOWN_LKK.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
■ LKKinspection (2).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
■ LKKAdjustment1a (1).pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
■ GJA SEARCH.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
■ PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
■ AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
■ WORKSHOP INVOICE.pdf	Invoice	Regular	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
■ LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
■ SCENE PHOTO FROM ACCORD.jpg	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	19 March 2019
■ MANDATE IA - ACCORD.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 March 2019
■ SURVEY PHOTOS.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	5 March 2019
■ TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LKK AUTO CONSULTANTS PTE LTD (TP)	30 October 2018
■ PRI WORKSHOP WITH TP GJA SJF261K.mig	Forms / Claim Documents	Others	KUMAR Shalinda	26 October 2018