

22/03/2002

ASS. REC. BY:

REF: CS/LPC18019556/Kvd3

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

merimen

From (Person): Ong Li Li

of

LPC

Date/Time: 26/10/18 @ 4:13pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SJZ 7099P

Insured:

at Workshop m/s

SH Motor

Tel: 6453 4730

of

160 Sin Ming Drive #07-02

Policy No: Z/18/VP00/101945

Claim No:

18/18/18/VP05/020998

Sum Insured:

Excess:

\$500-00

Make of Veh:

D.O.A. 06/10/2018

(Client's Record)

29/10/2018

H.O.D. Endorsement:

CA / (REV) / REP. / REV 24 HRS

Date/Time: 26/10/18 @ 5:07pm

Person Contacted:

Cynthia

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate Request police investigation report / letter
	SJZ 7099P-CC1/LPC18018807/APB3 Date: 06/10/2018
30/10/18	Revert vehicle TLH via merimen, pending police investigation result / letter.
14/12/18	Recd from Ong Li Li to submit our report

REF: **lpc**

ASSIGNMENT

From: Date: **29/11/2018**

Estimated Cost:

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo inspect Vehicle No: **8JZ 7099P**
at Workshop m/s: **3 1/2 H Motor**
of **160 Sin Ming Drive # 07-02**

Insured:

Policy No:

Claims No:

Sum Insured: Excess: **\$500.00**

(Client's Record)

Make of Veh: **Request police investigation letter/ Report.**

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: **\$28K**

IDAC Accident Report: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: **8JZ 7099P** Yr Regn: **12 10**Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Niss Juke** C.C. **1618**Colour: **M. Grey** A/C: Insured / Std / NI / NA

Sp. Reading: T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: **JN1FAAF158 0005009**Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: **215/55R17**

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / ☒ YOKO or

Front

Rear

R/Bal. **4** mmR/Bal. **2** mmL/Bal. **4** mmL/Bal. **2** mmD.O.A: **6/10/18**D.O.I: **29/10/18**

Survey held at

Des. of Damages: ☒ Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

30/10 Flaps to confirm**14/12/18 Submit uneconomical T/L - mv: \$28K (Est) LTA: \$24,823 NV: \$3177
Est repair cost \$25,000/-**

RECEIVED 14 DEC 2018

Date/Time: File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time: File Return to?

2) **14/12 - typist**

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee: ☐ Site Insp (\$)

) S + RS \$

☐ Interview (\$)

) Photos

☐ Tech. Invs (\$)

) Others

☐ Weekend (\$)

)

TOTAL

Report Format: **merimen**

Lump Sum / I.B.I: (\$)

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Oct 2018 14:00 Sendback Est	26 Oct 2018 15:42 \$50.00	26 Oct 2018 16:13 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	SENG KONG PRODUCTION PTE LTD , Co. Reg. No.: 198502524K		
Vehicle Reg. No.:	SJZ7099P	Date of Loss:	06/10/2018 00:00 - :59 [93 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 18/18/18/VP05/020998	Policy/Cover Note No.:	Z/18/VP00/101945 (Comprehensive)
Vehicle Reg. No. (TP):	XB8747X	Policy No. (TP):	
		Excess:	S\$500.00
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730		
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Ong Li Li - 62799254]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 07/11/2018]		
Driver/Custodian:	TAN CHOON KHIM (), NRIC: S1748604G, Tel: +6593846668		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Received Message

This mail is associated with :

SJZ7099P (18/18/18/VP05/020998)
[XB8747X]

OD

Oct 6 2018 12:00AM
[SENG KONG PRODUCTION PTE LTD]
S & H Motor Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From Lonpac Insurance Bhd (HQ) (LONPAC_HQ), sent on 14/12/2018 15:02 PM.

To LKK_HQ

Subject Alert - Adj Mandate Revoked - SJZ7099P - Claim Handler: Ong Li Li

Revoked:PLEASE SUBMIT REPORT/BILL

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Li Li

Date: 30 Oct 2018

Preliminary Advice

Vehicle No	: SJZ7099P	Accident Date	: 06/10/2018
Make	: NISSAN JUKE	Policy No.	: Z/18/VP00/101945
Assignment Date	: 26/10/2018	Excess	: S\$500.00
Date of Inspection	: 29/10/2018	Est. Duration of Repair	: 0.00
Inspection At	: S & H MOTOR PTE LTD (SIN MING) 160 SIN MING DRIVE #07-02, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	25,000.00
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	28,000.00
COE / PARF Rebate	:S\$	24,823.00
Salvage Value	:S\$	
Margin for Repair	:S\$	3,177.00

Remarks

() The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

(X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : Pending police investigation result/ letter.

Celine Fong (LKKAUTO)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, 26 October 2018 4:31 PM
To: assignments; MT_Claim_SG; Admin-D (LKKAUTO)
Subject: RE: SJZ7099P Incoming OD Our Ref: 18/18/18/VP00/020998

Dear Catherine/Nivitha

Please refer to Merimen and arrange OD survey.

Kindly request for the Police Investigation result/letter.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Do-Not-Reply [mailto:do-not-reply@merimen.com]
Sent: Friday, 26 October, 2018 4:00 PM
To: MT_Claim_SG
Subject: SJZ7099P Incoming OD

This mail is associated with :

SJZ7099P

OD

Oct 6 2018 12:00AM

[SENG KONG PRODUCTION PTE LTD]

S & H Motor Pte Ltd

From: S & H Motor Pte Ltd
Date of Initiation: 26/10/2018
Vehicle No: SJZ7099P
Date of Loss: 06/10/2018
Claim No:

This is an auto-generated email. Do not reply to this email.

Sent by : Merimen Administrator (MERIMEN TECHNOLOGIES (SINGAPORE) PTE. LTD.)



This email has been checked for viruses by AVG antivirus software.
www.avg.com



Date : 26th October 2018

M/s Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555
The Motor Claims Department

RE : VEHICLE NO. SJZ7099P ACCIDENT DATE : 06.10.2018


Refers to the above vehicle was towed our workshop for repair, we hereby inform you that the vehicle is not economical for repair (Estimate more than S\$25,000.00). Kindly arrange for surveyor to survey vehicle.

Towing Charge

Towing from Traffic Police To WorkShop S\$80.00

Shall you require any assistance pertaining this matter, please do not hesitate to contact undersigned.

Yours faithfully
S & H Motor Pte Ltd


Doris Ang

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/10/2018 10:29
Date Of Accident	06/10/2018 02:30
Exact Location Of Accident	MCE TO KPE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJZ7099P
Insured/Policyholder	
Name Of Registered Owner	SENG KONG PRODUCTION PTE LTD
Co Reg No	-
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93846668
Alternative Phone No	OFFICE-93846668

Vehicle Particulars

Manufacturer	NISSAN
Model	-

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z/18/VP00/101945
Cover Note Number	

Driver

Name of Driver	TAN CHOON KHIM
NRIC No	S1748604G
Date Of Birth	05/12/1966
Occupation	OUTDOOR
Date Of Driving Pass	17/12/2014
Driving Experience	3 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93846668
Fax Number	
Contact Number	
Email Address	NOEMAIL

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	2524K

Vehicle Details

Vehicle No.:	SJZ7099P
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Oct 2018
Vehicle Make:	NISSAN
Vehicle Model:	JUKE 1.6 MCVT ABS D/AB 2WD 5DR HID
Primary Colour:	Grey
Manufacturing Year:	2010
Engine No.:	MR16018872A
Chassis No.:	JN1FAAF15Z0005009
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$25,165.00
Original Registration Date:	21 Dec 2010
First Registration Date:	21 Dec 2010
Transfer Count:	1
Actual ARF Paid:	\$25,165.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Dec 2020
PARF Rebate Amount:	\$15,099.00

Intended COE Rebate Details

COE Expiry Date:	20 Dec 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$46,001.00
COE Rebate Amount:	\$9,724.00
Total Rebate Amount:	\$24,823.00

The information contained herein is correct as at 26 Oct 2018

OK

Nissan Used Vehicle List (1 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availability
Nissan Juke 1.6A	\$28,888	\$8,390 /yr	16-Dec-2010	1,598 cc	123,000 km	Go-Go Carz Pte Ltd	Available

New Arrival! Offer Now. Cheapest In Market. One And Only 2010 In Market. Rare Model With A Pretty Red. Lady Owner Driver. Very Low Mileage Done. Superb Handling And Fuel Efficient. No Repairs Needed A...

Office No. - -

Kobi Sim - 88236623

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, trucks, hybrid cars, sports cars or stationwagons. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions, and also motoring advice, car reviews & car news on the latest models. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

© 2004-2018 sgCarMart. All rights reserved.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	26 Oct 2018 14:00	26 Oct 2018 15:42 S\$0.00	26 Oct 2018 16:13 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt	Pending for Survey Report

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	SENG KONG PRODUCTION PTE LTD, Co. Reg. No.: 198502524K		
Vehicle Reg. No.:	SJZ7099P	Date of Loss:	06/10/2018 00:00 - :59 [93 Months and 15 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 18/18/18/VP05/020998	Policy/Cover Note No.:	Z/18/VP00/101945 (Comprehensive)
Vehicle Reg. No. (TP):	XB8747X	Policy No. (TP):	
		Excess:	S\$500.00
Repairer:	S & H Motor Pte Ltd (Sin Ming) 160 Sin Ming Drive #07-02, Sin Ming AutoCity, 575722 Sin Ming - Tel: 6453 4730		
Handling Insurer:	Lonpac Insurance Bhd (HQ) - Tel: +65 62507388 ... [Handled by Ong Li Li - 62799254]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 07/11/2018]		
Driver/Custodian:	TAN CHOON KHIM (), NRIC: S1748604G, Tel: +6593846668		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- LONPAC_HQ (14/12/2018): **Alert - Adj Mandate Revoked - SJZ7099P - Claim Handler: Ong Li Li**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJZ7099P (18/18/18/VP05/020998)
[XB8747X]

OD

Oct 6 2018 12:00AM
[SENG KONG PRODUCTION PTE LTD]
S & H Motor Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
View
[View in Browser](#)

Letters/Correspondences

1 per page



No	Finalized On	Lonpac Insurance Bhd (HQ)	Thumbnail	Print
1	26/10/18 16:37	OD Letter	Load HTM	

Assessment Reports

1 per page



No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	26/10/18 15:42	Repairer Estimates	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/10/18 11:42	Adjuster Immediate Advice	Load HTM	

Photos/Images

3 per page



No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/10/18 11:45	General View	Load JPG	
2	30/10/18 11:45	General View	Load JPG	
3	30/10/18 11:45	General View	Load JPG	
4	30/10/18 11:45	General View	Load JPG	
5	30/10/18 11:45	General View	Load JPG	
6	30/10/18 11:45	General View	Load JPG	
7	30/10/18 11:45	General View	Load JPG	
8	30/10/18 11:45	General View	Load JPG	
9	30/10/18 11:45	General View	Load JPG	
10	30/10/18 11:45	General View	Load JPG	
11	30/10/18 11:45	General View	Load JPG	
12	30/10/18 11:45	General View	Load JPG	
13	30/10/18 11:45	General View	Load JPG	
14	30/10/18 11:45	General View	Load JPG	
15	30/10/18 11:45	General View	Load JPG	
16	30/10/18 11:45	General View	Load JPG	
17	30/10/18 11:45	General View	Load JPG	
18	30/10/18 11:45	General View	Load JPG	
19	30/10/18 11:45	General View	Load JPG	
20	30/10/18 11:45	General View	Load JPG	
21	30/10/18 11:45	General View	Load JPG	
22	30/10/18 11:45	General View	Load JPG	
23	30/10/18 11:45	General View	Load JPG	
24	30/10/18 11:45	General View	Load JPG	
25	30/10/18 11:45	General View	Load JPG	
26	30/10/18 11:45	General View	Load JPG	

Documentation

1 per page



Letters/Correspondences			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	Lonpac Insurance Bhd (HQ)		Thumbnail Print
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)		Thumbnail Print
1	26/10/18 14:04	uneconomical repair		Load TIF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	14/12/18 16:48	LTA REBATE		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse
Singapore 199555

Our File No: CS/LPC18019556/KVD3S2

Date: 14/12/2018

REFERENCE

Insured/Claimant: SENG KONG PRODUCTION PTE LTD

Policy No: Z/18/VP00/101945

Date of Loss: 06/10/2018

Nature of Claim: OD

Claim No: 18/18/18/VP05/020998

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJZ7099P

Make & Model: NISSAN JUKE, 1.6 MCVT (A)

Engine No: MR16018872A

Reg. Date: 21/12/2010 (Man. Year: 2010)

Chassis No: JN1FAAF15Z0005009

Colour: Metallic Grey

Odometer: 0 km

Engine Capacity: 1618 cc

Market Value/New Car Price: S\$28,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55R17

Rear Tyre Size: 215/55R17

Front Left Side: Yokohama 4 mm

Rear Left Side: Yokohama 2 mm

Front Right Side: Yokohama 4 mm

Rear Right Side: Yokohama 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	0.00	500.00	-500.00	
(S\$)	0.00	-500.00	500.00	
+ GST 7.00/7.00% (S\$)	0.00	-35.00	35.00	
Nett Amount (S\$)	0.00	-535.00	535.00	

INSPECTION

Date of Assignment: 26/10/2018

Date Inspected: 29/10/2018 Inspected At:

S & H Motor Pte Ltd (Sin Ming)
160 Sin Ming Drive #07-02, Sin Ming AutoCity
Singapore 575722

Estimated Period of Repair: 0.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$28,000.00
OMV :	\$25,165.00
PARF Rebate (1) :	\$15,099.00
Quota Premium Paid :	\$46,001.00
COE Rebate (2) :	\$9,724.00
Total Rebate (1) + (2) = :	\$24,823.00

The total amount incurred will be Market Value \$28,000.00 minus Total Rebate \$24,823.00 = \$3,177.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 14 Dec 2018)	
Parts:	N/A	NISSAN JUKE 1.6 MCVT (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ7099P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >