TEVING ASS. REC. BY	RE	F: CITEDISOIS	9565 Zc	Special Intraction:
Surveyor		ASSIGNME	CONTRACTOR OF THE PARTY OF THE	
From (Person)	Kansaliah Kamis	of CRE.		Date/Time: 36 10 3018
	st:	-115	Bill to:	1, 14
OD/TP/W	STIPRES / OD RES /	EVA/INV/MY/CS		9
To Inspect Ve	chicle No: STU 435	5X		_ Insured:
at Workphow Infa			Tel:	
of			V-	
Policy No	MHASPFO60000	26991	Claim No: _	TP 1P 57103 2018
Sum Insured:			Excess:	
Make of Veb.				D.O.A. 710 2018
(Climita Recent	51	15.		
	REP. / REV 24 HRS			11.O.D. Padorsement:
Date/14me		Person Contacted:		Vehicle INLOUT
Date/Time	Action/Instruction () Estimate		
	CTU 4355X -X			
				CART
				CS 1
				71
	100000000000000000000000000000000000000			



Rohaizal (LKKAuto)

SJU 4355x

From: Kamaliah KAMIS (SPF) < Kamaliah_KAMIS@spf.gov.sq>

Sent: Friday, 26 October 2018 12:31 PM
To: Robaixal (LKK Auto)

To: Rohaizal (LKKAuto)

Cc: Bryan Ang (LKKAuto); SPF-TP FAIT; Norashikin DAUD (SPF)

Subject: Mechanical Inspection Report Request

Hi Sirs,

May I seek your assistance to perform a detailed mechanical inspection of the 6 vehicles below:

a) Case IAFP-IB-20181025 - Mechanical Inspection of Motor Car, SKV6736A (TP/IP/21411/2018)

On 4 April 2018, sometime before 5.08 p.m., the motor car was exiting from Tampines Mall Carpark and made a left turn. While doing so, the motor car continued to surge forward despite him stepping on the brake. He then lost control of his vehicle and hit a pedestrian. The car continued to surge and collided onto the guard railings and finally stopped after colliding onto the metal structures (for Night Market Set-up). Driver of the said motor car claimed the brakes were faulty.

Vehicle to be inspected: SKV6736A - Potential Defendant

10 In-Charge: 10 Norashikin

b) Case IAFP-IB-20181025 - Mechanical Inspection of Motor Car, SJU4355X (TP/IP/57103/2018)

On 07 October 2018, sometime before 1.31 p.m., the driver of motor car SJU4355X was traveling along Upper Bukit Timah Road towards the direction of Clementi Road, when he lost control, skidded and hit a tree on the centre divider median. Due to impact, the front left passenger suffered fatal injuries and passed away at the accident scene. As for the driver, he was conscious, sustained serious injuries and was admitted in the hospital.

Vehicle to be inspected: SJU4355X - Driver (Accused) and front passenger (Deceased)

10 In-Charge: SIO Farhan

c) Case IAFP-IB-20181022 - Mechanical Inspection of Motorcycle, JRU5542 (TP/IP/59407/2018)

On 19.10.2018 at about 8.23 am, motorcycle was travelling on the lane 2 of 3 lanes road where due to unknown reason, he had skidded and fall onto the road along SLE (CTE) 6.5 km. Deceased was unconscious and conveyed to KTPH but however, he succumbed to his injuries on the same day at KTPH.

Vehicle to be inspected: JRU5542 - Rider (Deceased)

IO In-Charge: SIO Vilton

d) Case IAFP-IB-20181022 - Mechanical Inspection of Motor Van, GBH2532C (TP/IP/59537/2018)

On 20.10.2018 at about 3.08 am, motor van was travelling on the left most lane along Bt Tiimah Road where he had lost control of his vehicle for unknown reason, mounted up left kerb before collided onto a tree.

Front 2 passengers of the motor van were pronounced dead at the scene while driver was conveyed to TTSH in a non-critical state.

Vehicle to be inspected: GBH2532C - Driver (Accused) and 2 front passengers (Deceased)

IO In-Charge: SIO Vilton

e) Case IAFP-IB-20180925 - Mechanical Inspection of Motor Car, SLS9401A (TP/IP/52969/2018)

On 15 September 2018 (Saturday) at about 12.40 a.m., the motor car was travelling along the slip road of Changi South Avenue 3 and subsequently made a lane changed from the slip road into the main of PIE (Tuas), 1.4km. While the motor car was doing so, the right wing mirror of the said motor car side-swiped into the deceased's motorcycle that was travelling straight along PIE (Tuas), 1.4km on lane 3 of the 3-lanes road. Due to the impact, the Deceased fell face down and landed on lane 2. As a result of the accident, the Deceased sustained head injuries and was conveyed in critical condition to Changi General Hospital by an ambulance. However, the Deceased succumbed to his injuries and was pronounced dead by Dr Mathavan Valantina in hospital on the same day at 2.16 a.m.

Vehicle to be inspected: SLS9401A - Driver (Potential Defendant)

IO In-Charge: IO Kamaliah

f) Case IAFP-IB-20180925 - Mechanical Inspection of Mini Bus, PA8420Z (TP/IP/57061/2018)

On 6 October 2018 (Saturday) at about 7.20 p.m., video footage from the mini bus' built in-car camera revealed that the mini bus was travelling on lane 1 of 2 lanes road along Bedok Reservoir Road) towards Bedok North Avenue 3. While nearing Jalan Lembah Bedok, the Deceased (pedestrian) was seen walking across the road with a walking cane and subsequently the Deceased was knocked down by the mini bus' frontal left portion. As a result of the accident, the Deceased sustained head injuries and was conveyed in critical condition to Changi General Hospital by an ambulance. However, the Deceased succumbed to his injuries and was pronounced dead by Dr Rarnga in the said hospital on 23 October 2018 at 8.25 a.m.

Vehicle to be inspected: PA8420Z - Driver (Potential Defendant)

10 In-Charge: 10 Kamaliah

- These request has been approved by my management.
- Thank you Sirs.

Cc: Bryan Ang (LKK), FAIT Team & GIT IO Norashikin, fyip

Best regards,

Kamaliah Kamis (Miss) Investigation Officer | Fatal Accident Investigation Team Traffic Police | Singapore Police Force DID: (65) 6647 6435 | FAX: (65) 6647 6362