

22/03/2002

ASS. REC. BY:

REF: CS3/SNO18019596/RICD3⁹²

Special Instruction:

Surveyor
Meimien

Rasul

ASSIGNMENT (Office)

From (Person): Chan Shu hui

of

SMO

Date/Time 24/10/18 @ 11:30am

Estimated Cost:

Bill to:

OD/TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

YP 7769P

Insured:

GBE 4769P

at Workshop m/s

N-SI Automotive

Tel:

68420051

of

2 Kelki Bkt Ave 2 # 01-17/18

Policy No:

D18MTH CVE 000 238

Claim No:

CMTD 1803793

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

26/08/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time:

11:52am @ 24/10/18

Person Contacted:

Melody

Vehicle (IN) OUT

Date/Time	Action/Instruction (X) Estimate
	YP 7769P - X
	GBE 4769P - X.

REF: SMO

04430

ASSIGNMENT

From: Date: 29/10/18

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: 4P 7769P
at Workshop m/s N-SI Automotive
of 2 Kaki Bkt Ave 2 #01-17/18

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 7 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: 4P 7769P Yr Regn: 2017 / 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HINO GH8JMA C.C. 7684

Colour: WHITE A/C: Insured / Std / NI / NA

Sp. Reading: 110153 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: GH8JRM10386

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 10.00R20

R: 4

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or GOOD TYRE

Front

Rear

R/Bal. 7 mm R/Bal. 7/7 mm

L/Bal. 7 mm L/Bal. 7/7 mm

D.O.A. 26/08/18 D.O.I. 29/10/18

Survey held at N-SI

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

- Estimate repair range \$7,000 - \$9,000

31/10/2018

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 7

Resurvey No. of Trip: 1

Survey Fee:

Transportation

S + RS. SI

Photos

Others

Report Format: PRS

Lump Sum / I.B.I: (\$)

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Aug 2018		29 Oct 2018 11:30 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H		
Main Claimant:	RICHLAND LOGISTICS SERVICES PTE LTD, Co. Reg. No.: 199500443D		
Vehicle Reg. No.:	YP7769P	Date of Loss:	26/08/2018 15:00 - :59
Claim Type:	TP / CMTD1803793	Policy/Cover Note No.:	D18MTHCVE000238 (Third Party Only)
Vehicle Reg. No. (Insured):	GBE4769P	Policy No. (Claimant):	
		Excess:	
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/11/2018]		
Driver/Custodian (Insured):	MOHANRAJ MURUGAN (), NRIC: G8543010L, Tel: +6582466494		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Monday, 29 October 2018 11:29 AM
To: Chin Hui Xin; admin-d@lkkauto.com; assignments@lkkauto.com
Cc: Henry, Irene James; Chan, Shu Hui Agnes; Ye, Yong Kang Melvin
Subject: CMTD1803793/AGC - SUV(LKK)/ GBE4769P & YP7769P ACC ON 26.08.18- NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Our Reference: CMTD1803793/AGC
Your Reference: YP7769P

Without Prejudice

Date: 29th October 2018

Attention:
M/S N-51 AUTOMOTIVE PTE LTD

Dear Melody,

ACCIDENT INVOLVING GBE4769P & YP7769P ON 26.08.2018

We refer to your email reply of 26/10/18.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Yours faithfully,

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147



Innovation for Wellbeing

SOMPO

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompō SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompō Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Chin Hui Xin [mailto:huixin@n51.com.sg]

Sent: Friday, October 26, 2018 5:50 PM

To: Ye, Yong Kang Melvin

Cc: Teo, Grace; Henry, Irene James; Chan, Shu Hui Agnes

Subject: Re: YP7769P & GBE4769P - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

We refer to your list of motor surveyors proposed.

We do not agree to your list of motor surveyors.

Please see attached.

Thanks

Regards,

Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

www.n51.com.sg



On Fri, Oct 26, 2018 at 5:06 PM Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg> wrote:

Our Reference: CMTD1803793

Your Reference: YP7769P

Without Prejudice

Date: 26 OCTOBER 2018

Attention:

M/S N-51 AUTOMOTIVE PTE LTD

Dear Melody,

ACCIDENT INVOLVING YP7769P & GBE4769P ON 26.10.2018

We refer to your Notice of Accident dated 26/10/2018.

Please be informed that Ms Agnes Chan is the handler of this case.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	

		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffery Ong	
4	JP Knights Adjusters & Surveyors	Jason Lek	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Melvin Ye

Claims Division

D: 6322 4667 | T: 6461 6555 | F: 6221 3302



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹For Travel, Personal Accident & Home Insurance | ²For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Chin Hui Xin <huixin@n51.com.sg>

Sent: Friday, 26 October, 2018 3:27 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Subject: YP7769P & GBE4769P - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 3 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer attachment and:-

Kindly propose / provide your 10 surveyors.

Thank you...

Regards,

Melody Chin

N-51 Automotive Pte Ltd

Office : 6842 0051

Fax : 6741 0510

www.n51.com.sg



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/08/2018 21:20
Date Of Accident	26/08/2018 15:10
Exact Location Of Accident	ALONG JOO KOON CIRCLE OUTSIDE 5 JOO KOON CIRCLE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP7769P
Insured/Policyholder	
Name Of Registered Owner	RICHLAND LOGISTICS SERVICES PTE LTD
Co Reg No	199500443D
Email Address	GUNALAN.MARIMUTHU@RICHLANDLOGISTICS.COM
Mobile Phone No	(LOCAL) +65-81252292
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	HINO
Model	OTHERS
Exact Purpose for which vehicle was being used at time of accident	COMMERICAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5070270535-02
Cover Note Number	

Driver

Name of Driver	HU CHENQI
Work Permit No	G3010118P
Date Of Birth	04/02/1982
Occupation	OUTDOOR
Date Of Driving Pass	30/10/2014
Driving Experience	3 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81252292
Fax Number	
Contact Number	
Email Address	GUNALAN.MARIMUTHU@RICHLANDLOGISTICS.COM

Address 5 JOO KOON CIRCLE
SINGAPORE
Postcode 629118
Was driver an employee of the Insured's Company YES
If No, Relationship of the Driver with the Insured
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1
NAME: : CHAI YUE FEI
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
If Yes, Please state which Police Station
Police Station Name JURONG WEST NEIGHBOURHOOD POLICE CENTRE
Police Station Address ROAD: 700 CORPORATION ROAD , POSTCODE: 649818 , COUNTRY: SINGAPORE
Police Station Contact TEL NO: 1800-2689999 - FAX NO: 62672438
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER TO POLICE REPORT

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBE4769P
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver UNKNOWN
NRIC/Passport Number
Contact Number UNKNOWN
Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders;

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time: 27/02/2018
12:56:15



Reporting Centre Personnel's Signature
Name: Eugene Lee
NRIC/FIN No: 5791823

Sketch Plan #2

SKETCH PLAN



V1: YP 7764P
V2: GBE 4764P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report : T/20120226/2092

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 27/02/2012
12:15 h k



Reporting Centre Personnel's Signature
Name: Eugene Lee
NRIC/FIN No: 5971823

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20180826/2092

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

1 of 3
Report No. T/20180826/2092

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 26/08/2018 19:33		Vide Report No.: J/20180826/0151		Station Diary No.: 108	
Informant's Particulars					
Name of Informant: HU CHENGQI			Address: APT BLK 653A JURONG WEST STREET 61 #12-438 SINGAPORE 641653		
ID Type / ID No.: FIN NO / G3010118P			Contact No.: Home/Office: Mobile: 81252292		
Nationality: CHINESE			Email:		
Sex: Male	Age: 36	Date of Birth: 04/02/1982	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: DELIVERY MAN			Driving Licence Information: Class: 3,4 Date of Expiry: 13/02/2019		

General Information of the Accident				
Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 26/08/2018 15:10	Type of Location: Straight Road
Location: Along Road 1 JOO KOON CIRCLE				
OUTSIDE RICHLAND LOGISTIC				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control:	Traffic Volume: No Traffic	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
GBE4769P	Lorry				Seriously Damaged	0
YP7769P	Lorry				Slightly Damaged	1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA

POLICE REPORT



**SINGAPORE
POLICE FORCE**



T/20180826/2092

2 of 3

Report No. T/20180826/2092

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

CONTINUATION OF REPORT

Driver Name	Unknown Driver	ID No.	NIL
Related Vehicle	GBE4769P (Lorry)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Driver Name	HU CHENGQI	ID No.	G3010118P
Related Vehicle	YP7769P (Lorry)	Contact No.	81252292
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3,4 Date of Expiry: 13/02/2019
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On the 26/08/2018 at about 03:10pm, I was travelling along Joo Koon Circle from Benoi Road with my company lorry (YP7769P). As I was approaching my company, GLS Building, I then slower down in front of the main gate of my company before I inched forward for the turn. I have on my right signal light before I made my right turn.

Suddenly I felt an impact from the rear of my vehicle while I am focusing the traffic in front. I then alighted and realised that there was a small lorry (GBE4769P) has collided onto the rear side of my lorry. The said driver has stuck in his vehicle due to the collision.

My company staffs have called for ambulance which later conveyed the said driver who is in a conscious state to the hospital. Traffic police has attended to the accident and advised me to lodge a police report. under TP IO Abdillah, Tel: 65476246 referred to the case number of J/20180826/0151.

No in car camera footage recorded and I am not sure whether any CCTV around the vicinity.

POLICE REPORT



SINGAPORE
POLICE FORCE



T/20180826/2092

Police Station Of Origin:
Jurong West N.P.C
700 Corporation Road SINGAPORE 649818
Tel No: 1800-2689999

3 of 3

Report No. T/20180826/2092

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sgt 2 PERRY P NG WEE PHONG

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

26/08/2018 19:33

Officer In Charge Of Case:

TP / GIT /

SI MOHAMMAD ABDILLAH BIN PALIL

Contact No.: 65476246

Classification Of Case:

Authentication Stamp

NP168

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	0443D
Vehicle Details	
Vehicle No.:	YP7769P
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Oct 2018
Vehicle Make:	HINO
Vehicle Model:	HINO GH8JRM-QG5
Primary Colour:	White
Manufacturing Year:	2017
Engine No.:	J08EVD21904
Chassis No.:	GH8JRM10386
Maximum Power Output:	-
Open Market Value:	\$61,761.00
Original Registration Date:	06 Nov 2017
First Registration Date:	06 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$3,089.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	05 Nov 2027
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$42,801.00
COE Rebate Amount:	\$38,580.00
Total Rebate Amount:	\$38,580.00

The information contained herein is correct as at 31 Oct 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Aug 2018		29 Oct 2018 11:30 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	ETHOZ GROUP LTD, Co. Reg. No.: 198104531H		
Main Claimant:	RICHLAND LOGISTICS SERVICES PTE LTD, Co. Reg. No.: 199500443D		
Vehicle Reg. No.:	YP7769P	Date of Loss:	26/08/2018 15:00 - :59 [9 Months and 20 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1803793	Policy/Cover Note No.:	D18MTHCVE000238 (Third Party Only)
Vehicle Reg. No. (Insured):	GBE4769P	Policy No. (Claimant):	
		Excess:	
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by CHAN SHU HUI AGNES - 6329 5327]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 08/11/2018]		
Driver/Custodian (Insured):	MOHANRAJ MURUGAN (), NRIC: G8543010L, Tel: +6582466494		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*YP7769P (CMTD1803793)
[GBE4769P]

TP

RICHLAND LOGISTICS SERVICES PTE LTD

Aug 26 2018 3:00PM

[ETHOZ GROUP LTD]


N-51 Automotive Pte Ltd

[Upload Documents](#) [Upload Photos](#) [Compose New Letter](#)

View [View in Browser](#) ▼
































Assessment Reports

1 per page ▼ ☒

No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	29/10/18 11:21	Accident Statement From: SC - Reg. No: GBE4769P, Claimant: ETHOZ GROUP LTD	 Load HTM	<input checked="" type="checkbox"/>

Photos/Images

3 per page ▼ ☒

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
18	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
19	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
20	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
21	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
22	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
23	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
24	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
25	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
26	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
27	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
28	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
29	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
30	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
31	31/10/18 09:21	General View	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	✓
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
32	31/10/18 09:21	General View	 Load JPG	✓
33	31/10/18 09:21	General View	 Load JPG	✓
34	31/10/18 09:21	General View	 Load JPG	✓
35	31/10/18 09:21	General View	 Load JPG	✓
36	31/10/18 09:21	General View	 Load JPG	✓
37	31/10/18 09:21	General View	 Load JPG	✓
38	31/10/18 09:21	General View	 Load JPG	✓
39	31/10/18 09:21	General View	 Load JPG	✓
40	31/10/18 09:21	General View	 Load JPG	✓
41	31/10/18 09:21	General View	 Load JPG	✓
42	31/10/18 09:21	General View	 Load JPG	✓
43	31/10/18 09:21	General View	 Load JPG	✓
44	31/10/18 09:21	General View	 Load JPG	✓
45	31/10/18 09:21	General View	 Load JPG	✓
46	31/10/18 09:21	General View	 Load JPG	✓
47	31/10/18 09:21	General View	 Load JPG	✓
48	31/10/18 09:21	General View	 Load JPG	✓
49	31/10/18 09:21	General View	 Load JPG	✓
50	31/10/18 09:21	General View	 Load JPG	✓
51	31/10/18 09:21	General View	 Load JPG	✓
52	31/10/18 09:21	General View	 Load JPG	✓
53	31/10/18 09:21	General View	 Load JPG	✓
54	31/10/18 09:21	General View	 Load JPG	✓
55	31/10/18 09:21	General View	 Load JPG	✓
56	31/10/18 09:21	General View	 Load JPG	✓
Documentation			1 per page ▼	✓
No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	Thumbnail	Print
1	26/10/18 17:11	Third Party E-filed GIA report	 Load PDF	
2	29/10/18 11:30	Pre-Repair Survey ASSIGN LKK	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO18019596/R1CD3S2

Date: 02/11/2018

REFERENCE

Handling Insurer: Sompo Insurance Singapore Pte. Ltd. Policy No: D18MTHCVE000238
 Claimant Vehicle No : YP7769P Insured Vehicle No : GBE4769P
 Date of Loss: 26/08/2018 Nature of Claim: TP Claim No: CMTD1803793

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **YP7769P**
 Make & Model: HINO GH8JRKA, 7.7 D (M) Engine No: J08EVD21904
 Reg. Date: 06/11/2017 (Man. Year: 2017) Chassis No: GH8JRM10386
 Colour: White Odometer: 110153 km
 Engine Capacity: 7684 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 10.00 R20 Rear Tyre Size: 10.00 R20 (D)
 Front Left Side: GoodTyre 7 mm Rear Left Side: GoodTyre 7/7 mm
 Front Right Side: GoodTyre 7 mm Rear Right Side: GoodTyre 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/10/2018
 Date Inspected: 29/10/2018 Inspected At: N-51 Automotive Pte Ltd (HQ)
 BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB
 Singapore 417921
 Estimated Period of Repair: 7.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000.00 - \$9,000.00

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 02 Nov 2018)

Parts: N/A HINO GH8JRKA 7.7 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YP7769P)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >