CWS From (Person Estimated Co	st: Date/Time: -6/10/16@ 6:379
at Workshop	StTP RES / OD RES / EVA / INV / MV / CS SLV 9800P Insured: CHA 008EM
ofPolicy No:Sum Insured:	2 penden Crement Level 4 Claim No: D18007724 MFSH Excess:
Make of Veh: (Client's Record CA / REV / Date/Time: ((REP. / REV 24 HRS (DS)
Date/Time	Action/Instruction () Estimate SLV 9800R - X
29/10/18-	SHA 9088M-CF/AIG 07 062270/gw 20A: 8/7/2007
15/11/18-	vehicle not in vehicle shill nuth.
28/11/18-	VNI yet will armage.

REF:



MS First Capital Insurance Limited Co.Reg. No. 195000106C GST Reg. No. M2-0001676-9 6 Raffles Quay #21-00 Singapore 048580 Tel: (65) 6222 2311 Fax: (65) 6222 3547

Claims & Hotor Underwriting Dept: 36 Robinson Road #16-01 City House Singapore 068877 Tel: (65) 6507 3848 Fax: (65) 6507 3849 www.msfirstcapital.com.sg

MOTOR SURVEY ASSIGNMENT

Date

25-10-2018

Our Ref No. D18007724MFSH

Accident Date

24-10-2018

Claim Type. Third Party

Insured Vehicle

SHA9088M

Third Party Vehicle. SLV9800R

Survey Location

INCHCAPE BODYCARE CENTRE LEVEL 4 INCHCAPE CENTRE2 PANDAN

CRESCENT

Contact Person.

NABILAH

Contact No.

66311874/0

Fax No. 68727260

Survey Type

DIRECT SETTLEMENT:

Appointed

Surveyor

LKK AUTO CONSULTANTS PTE LTD

Contact Person

NA

Fax No. 68416315

Contact Number.

NA

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc: Workshop

BORNEO MOTORS

(SINGAPORE) PTE LTD

Attention, NIL

Cc: TP Solicitor

NA

TP Solicitor Fax No. NA

Officer Incharge

LURENE

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

oh Sheet (/C	laimWS/Surveyor/JobSheet/2	245515) 📐 PRI	Documents 🙆 Close 🗶		
ob Sheet (/ e		101	PRI Header Details		
Claim No	D18007724MFSH	Policy No	D-18088937MFSH	Claimant S.No & Name	1 & BORNEO I LTD
Workshop Name	BORNEO MOTORS (SINGAPORE) PTE LTD (Contact Person : NABILAH)	Survey Location & Contact Details	INCHCAPE BODYCARE CENT Mobile: 0 , Phone: 663118 EmailId: SITI.NABILAH@IN	74 , Fax: 68	727260
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHA9088M	TP Vehicle No	SLV9800R
PRI Recieved Date	25-10-2018 03:54:14 PM	Surveyor Appointed Date	26-10-2018 05:36:50 PM	Surveyor Accept Date	29-10-2018
			Survey Report Upload	98	
Surveyor Inspection Date *:		Surveyor Report Date	29-10-2018	Upload Survey Report *:	Choose File
			Vehicle Particulars		
Make	Please Select Make ▼	Model	Please Select Model 🔻	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			
Multiple [Documents Upload				
	ocuments opious	Upload Multip	le Documents		
File Na	me			Action	
Surveyor	Job Remarks				
	1				

Nivitha (LKK Auto)

From:

Aini Binte Md Min <Aini@msfirstcapital.com.sg>

Sent:

Thursday, 25 October 2018 9:18 AM

To:

IL Process Centre

Cc:

Lurene Jaw

Subject:

FW: Direct Settlement (ST) - Accident Involving SLV9800R & SHA9088M DOA

24.10.2018

Attachments:

SLV9800R 24102018_Est Inv.pdf; SLV9800R 24102018_SAS_Damaged Photos.pdf

Dear IL

New survey request for your handling.

Thanks & Regards

Aini

Motor Claims Department

MS First Capital Insurance Ltd | 36 Robinson Road, City House, #16-01 Singapore 068877 | TEL: 6507 3848 Fax: 6507 3849 | Company Reg. No. 195000106C

A Member of MS&AD INSURANCE GROUP

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: Harminder Kaur

Sent: Thursday, 25 October, 2018 8:14 AM

To: Aini Binte Md Min < Aini@msfirstcapital.com.sg>

Subject: FW: Direct Settlement (ST) - Accident Involving SLV9800R & SHA9088M DOA 24.10.2018

SURVEY

Best Regards, Harminder Kaur Motor Claims

MS First Capital Insurance Ltd

A Member of MS&AD Insurance Group

 \bowtie

Change of email address

harminder@msfirstcapital.com.sg

36 Robinson Road, #16-01 City House, Singapore 068877 | Tel: 6507 3848 | Fax: 6507 3849 | Reg. No. 195000106C

Personal Data Protection Act 2012 ("PDPA"):

Under the PDPA, there are various requirements that regulate the processing of your personal data. Please refer to http://www.msfirstcapital.com.sg for details of PDPA Personal Data Collection Statement.

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged. If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it. If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

From: ILPROCESSCENTRE //ICICILOMBARD/HYD [mailto:ilprocesscentre@icicilombard.com]

Sent: Wednesday, October 24, 2018 6:07 PM

To: Motor_Claims < Motor Claims@msfirstcapital.com.sg>

Subject: FW: Direct Settlement (ST) - Accident Involving SLV9800R & SHA9088M DOA 24.10.2018

From: Siti Nabilah PTCBC [mailto:Siti.Nabilah@inchcape.com.sq]

Sent: Wednesday, October 24, 2018 3:26 PM

To: Claim Workflow System Cc: Siti Nabilah PTCBC

Subject: Direct Settlement (ST) - Accident Involving SLV9800R & SHA9088M DOA 24.10.2018

Hi,

Reference to the above-mentioned.

Please find attached herein a copy of our client's Accident Report, Damaged Photos & Estimate Invoice for your kind perusal.

As our client is claiming against your insured SHA9088M thus would appreciate if you could revert to us on the liability urgently or we could settle the case under Direct Settlement with Car Rental of @ \$100 per day x no. of days as recommended by your appointed surveyor.

Kindly have your surveyor to contact our Motor Claim Assessor, <u>Shashi @ 9336 6875 / 6631 1864</u> located at <u>2</u> <u>Pandan Crescent – Level 4</u> for an appointment to inspect our client's vehicle soonest.

As for liability clearance, kindly revert to this email.

Your kind attention into the above is greatly appreciated.

Thank you

Best Regards,
Nabilah

TPR Team (Claims Accident Recovery Dpt)

DID 6631 1874 | FAX 6872 7260

Inchcape - Borneo Motors (S) Pte Ltd

Office Address: 2 Pandan Crescent, Inchcape Centre Level 4, Singapore 128462

www.borneomotors.com.sg 1 www.toyotasingapore.com.sg



This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

"Please note that this email, including any attachments, is intended solely for the individual (s) or entity

(ies) to whom they are addressed and may contain information that is private, confidential and privileged. In case you are not the intended recipient, request you to notify the sender by reply mail and delete this email, including any copies or attachments from your system. Any unauthorized dissemination, disclosure and/or use of the contents of this communication to anyone is strictly prohibited and punishable by law.

Opinions, conclusions and statements of intent expressed in this e-mail are of the sender and ICICI Lombard General Insurance Company Limited (Company) does not accept liability for the views expressed in this email unless confirmed by an authorized representative of the Company independently of this communication or for the consequences of any viruses that may be transmitted with this email."

THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER.	MCA: Shashi
AND AND ADDRESS OF A CONTROL OF	OR ACCIDENT REPORT
	7 Date Of Accident: 24 007 2018 Time: 10:559
xact Location Of Accident: Emerald Link	
	elangor Darul Ehsan 🗆 / Negeri Sembilan 🗀 / Melaka 🗀 / Pahang 🗀 /
	TAILS (INSURED/POLICY HOLDER)
Pehicle Registration Number: SLV 9800 R	Co. Reg. No(for Co. Vehicle)/NRIC/PP/FIN No : 88036988C
Name Of Registered Owner: LEE KUOK SONG	
Mobile Number: \$118 0988 Alternative No:	Email Address: LLE KWOK Song @ ginail com
/ehicle Particulars	电影中国的
Manufacturer : Toyota 🛭 Lexus 🗆 Suzuki 🗀 Hino 🗆	Model: Bienta
xact Purpose for which vehicle was being used at time of accident:	Normal Usage ☑ Other □ (please specify) :
Are you claiming under your own insurance policy for repair to your v	rehicle? Yes □ Reporting Only □ Third Party ♥
/ehicle Category: Private Car ☑ Commercial Vehicle ☐ Of	thers 🗆
nsurance Company	
Name of Insurance Company: AXA	
Type Of Coverage: Comprehensive 🗹 Third Party 🗆 Thir	rd Party Fire and/or Theft 🗆
leet Policy: Yes □ No ☑	Policy / Cover Note No:
DRIVER DETA	AILS AT POINT OF ACCIDENT
Name of Driver: Lee Kwok Song.	NRIC/ Passport / FIN No: SSO 36988C
Date Of Birth: 19 Nov 1980	Occupation: Indoor 🗹 Outdoor 🗆
Date Of Driving Pass: 28 Feb 2008	Gender: Male ☑ Female □
Mobile Number: \$118 0988 Fax No:	Alternative No:
Address: BIR 3174 YISHUN AVE 9 # 06-110	Postal Code: 761317
Email Address: Lee Ewol song & gunil.com	
	State relationship of the driver with the insured:
Vehicle Registration Number of Driver's Own Vehicle (if applicable):	
Insurance Company of Driver's Own Vehicle (if applicable):	
GENERAL INFO	ORMATION OF THE ACCIDENT
Type Of Accident: Rear collision	
Number of Passengers in the above vehicle (Including Driver):	/ / If more than 2 Pax Please fill ANNEX B
TOWN TO BE THE VIEW OF THE	PASSENGER 1
Name: Lee KWOK Song	Gender: Male-✓ Female □
	Gender: Male ✓ Female □ lease state condition):
Weather Conditions: Clear ☑ Raining □ Others □ (If others,pl	lease state condition):
Weather Conditions: Clear ☑ Raining ☐ Others ☐ (If others,pl Road Surface: Wet ☐ Dry ☑ Others ☐ (If others,please state of	lease state condition):
Weather Conditions: Clear ☑ Raining ☐ Others ☐ (If others,pl Road Surface: Wet ☐ Dry ☑ Others ☐ (If others,please state of Was any body injured in the Accident? No ☑ Yes ☐	lease state condition):
Weather Conditions: Clear ☑ Raining □ Others □ (If others,pl Road Surface: Wet □ Dry ☑ Others □ (If others,please state of Was any body injured in the Accident? No ☑ Yes □ Was any injured conveyed to hospital by ambulance? No ☑ Yes	lease state condition): condition):
Weather Conditions: Clear Raining Others (If others,pl Road Surface: Wet Dry Others (If others,please state of Was any body injured in the Accident? No Yes Was any injured conveyed to hospital by ambulance? No Yes Was any foreign vehicle involved in this accident? No Yes □	lease state condition): condition):
Weather Conditions: Clear ☑ Raining □ Others □ (If others,pl Road Surface: Wet □ Dry ☑ Others □ (If others,please state of Was any body injured in the Accident? No ☑ Yes □ Was any injured conveyed to hospital by ambulance? No ☑ Yes Was any foreign vehicle involved in this accident? No ☑ Yes □ Number of vehicles involved in the accident: 2	lease state condition): condition): es Vehicle No: Vehicle type:
Weather Conditions: Clear ☑ Raining □ Others □ (If others,pl Road Surface: Wet □ Dry ☑ Others □ (If others,please state of Was any body injured in the Accident? No ☑ Yes □ Was any injured conveyed to hospital by ambulance? No ☑ Yes Was any foreign vehicle involved in this accident? No ☑ Yes □ Number of vehicles involved in the accident: 2	lease state condition): condition): es Vehicle No: Vehicle type:
Weather Conditions: Clear Raining Others (If others,pl Road Surface: Wet Dry Others (If others,please state of Was any body injured in the Accident? No Yes Was any injured conveyed to hospital by ambulance? No Yes Was any foreign vehicle involved in this accident? No Yes Number of vehicles involved in the accident: 2 Was there any witness? No Yes If yes, please furnish w Witness Name: Contact No.:	lease state condition): condition): es Vehicle No: Vehicle type: vitness details column below Email:
Weather Conditions: Clear Raining Others (If others, place of the state of the stat	lease state condition): condition): es Vehicle No: Vehicle type: vitness details column below Email:
Weather Conditions: Clear Raining Others (If others, place of the state of the stat	lease state condition): condition): es Vehicle No: Vehicle type: vitness details column below Email: Are accident scene photos available for attachment? No Yes Yes
Weather Conditions: Clear Raining Others (If others, place of the state of the stat	lease state condition): condition): es Vehicle No: Vehicle type: vitness details column below Email: Are accident scene photos available for attachment? No Yes s,please state which Police Station):
Weather Conditions: Clear Raining Others (If others, place of the state of the stat	lease state condition): condition): es Vehicle No: Vehicle type: vitness details column below Email: Are accident scene photos available for attachment? No Yes s,please state which Police Station): es,please state against whom):
Weather Conditions: Clear Raining Others (If others, place of the state of the stat	lease state condition): condition): es Vehicle No: Vehicle type: vitness details column below Email: Are accident scene photos available for attachment? No s,please state which Police Station): es,please state against whom): cident claims assistance. No Yes
Weather Conditions: Clear Raining Others (If others, place of the state of the stat	lease state condition): condition): Vehicle No: Vehicle type: Vitness details column below Email: Are accident scene photos available for attachment? No Yes s,please state which Police Station): es,please state against whom): cident claims assistance. No Yes ERTY 1 (Please fill Annex A if more vehicles involved)
Weather Conditions: Clear Raining Others (If others, place Surface: Wet Dry Others (If others, please state of Was any body injured in the Accident? No Yes Was any injured conveyed to hospital by ambulance? No Yes Was any foreign vehicle involved in this accident? No Yes Was any foreign vehicle involved in this accident? No Yes Was there any witness? No Yes If yes, please furnish www. Witness Name: Contact No.: Was there any other vehicle or property damaged? No Yes Was there any video captured by Car Camera? No Yes (If yes Was the accident reported to the police? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes Was notice of intended by unknown person(s) soliciting/offering accompany of the North Registration Number: SHA GOSS M	lease state condition): condition): es Vehicle No: Vehicle type: vitness details column below Email: Are accident scene photos available for attachment? No s,please state which Police Station): es,please state against whom): cident claims assistance. No Yes
Weather Conditions: Clear Raining Others (If others, place of the state of Clear Raining Others (If others, place of Clear Raining	lease state condition): condition): Vehicle No: Vehicle type: Vitness details column below Email: Are accident scene photos available for attachment? No Yes s,please state which Police Station): es,please state against whom): cident claims assistance. No Yes ERTY 1 (Please fill Annex A if more vehicles involved)
Weather Conditions: Clear Raining Others (If others, place State of Conditions) Road Surface: Wet Dry Others (If others, please state of Was any body injured in the Accident? No Yes Was any injured conveyed to hospital by ambulance? No Yes Was any foreign vehicle involved in this accident? No Yes Number of vehicles involved in the accident: Was there any witness? No Yes If yes, please furnish witness Name: Was there any other vehicle or property damaged? No Yes Was there any video captured by Car Camera? No Yes Was the accident reported to the police? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes I have been approached by unknown person(s) soliciting/offering accidents of Properties Damage in Accident: Vehicle Category:	lease state condition): condition): Vehicle No: Vehicle type: Vitness details column below Email: Are accident scene photos available for attachment? No Yes s,please state which Police Station): es,please state against whom): cident claims assistance. No Yes ERTY 1 (Please fill Annex A if more vehicles involved)
Weather Conditions: Clear Raining Others (If others, place Surface: Wet Dry Others (If others, please state of Was any body injured in the Accident? No Yes Was any injured conveyed to hospital by ambulance? No Yes Was any foreign vehicle involved in this accident? No Yes Number of vehicles involved in the accident: 2 Was there any witness? No Yes If yes, please furnish witness Name: Contact No.: Was there any other vehicle or property damaged? No Yes Was there any video captured by Car Camera? No Yes Was there any video captured by Car Camera? No Yes (If yes Was notice of intended Prosecution given? No Yes (If y	lease state condition): condition): es Vehicle No: Vehicle type: vitness details column below Email: Are accident scene photos available for attachment? No Yes s,please state which Police Station): es,please state against whom): cident claims assistance. No Yes RTY 1 (Please fill Annex A if more vehicles involved) Vehicle Make/Model/Colour:
Weather Conditions: Clear Raining Others (If others, place of the state of the stat	lease state condition): condition): Vehicle No: Vehicle type: vitness details column below Email: Are accident scene photos available for attachment? No Yes s,please state which Police Station): s,please state against whom): cident claims assistance. No Yes RTY 1 (Please fill Annex A if more vehicles involved) Vehicle Make/Model/Colour:
Weather Conditions: Clear Raining Others (If others, place State of Conditions) Road Surface: Wet Dry Others (If others, please state of Was any body injured in the Accident? No Yes Was any injured conveyed to hospital by ambulance? No Yes Was any foreign vehicle involved in this accident? No Yes Number of vehicles involved in the accident: Was there any witness? No Yes If yes, please furnish witness Name: Was there any other vehicle or property damaged? No Yes Was there any video captured by Car Camera? No Yes Was there any video captured by Car Camera? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes Was notice of intended Prosecution given? No Yes (If yes	lease state condition): condition): Vehicle No: Vehicle type: vitness details column below Email: Are accident scene photos available for attachment? No Yes s,please state which Police Station): s,please state against whom): cident claims assistance. No Yes RTY 1 (Please fill Annex A if more vehicles involved) Vehicle Make/Model/Colour:

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time Sketch Plan	Driver's Signature (If driver is not the policyholder) / Date & Time	Witnessed by Reporting Centre Personnel
SHA9088M	SLV9800R - Timeral Link	

Describe Circumstances of the Accident way home my UE Square road Emerald Lving Stationary while Waiting green KNOCK rear - right car.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &


Time


Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre

Personnel









AXA INSURANCE PTE LTD 8 Shenton Way, #24-01 AXA Tower, Singapore 068811 Customer Service Centre #B1-01 Tel:(65)63387288 Fax:(65)63382522 Website:www.axa.com.sq GST Registration Number: 199903512M customer.service@axa.com.sg

. . . .



CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act. (Chapter 189) Motor Vehicles (Third-Party Risks and Compensation) Rules. 1960 Farty Risks) Rules, 1959 (Malaysia) Road Transport Act. 1987 (Malaysia) Motor Vehicles (Third-

Account No. : 14885 CERTIFICATE NO. : VPA/P2067808

Coverage : Comprehensive (SmartDrive Toyota Prestige)

: Market Value At The Time Of Loss Sum Insured

Name of Policy Holder : LEE KWOK SONG (LI GUOSONG)

Vehicle Registration No. : SLV9800R

Period of Insurance : From 31/01/2018 To 30/01/2020 (Both Dates Inclusive)

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*

(a) The Policyholder

The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employer or his partner

(b) Any other person who is driving on the Policyholder's order or with his permission Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE*

Use only for social, domestic and pleasure purposes and for the Policyholder's business The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary, in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

(01)

Basic Own Damage Excess

: SGD 500.00

An Additional Excess is applicable as follows: \$\$2,500.00 for Young or Inexperienced Driver.

Young or Inexperienced Driver is defined as any driver whom is aged below 23 years old and/or less than one year of driving experience.

(Please refer to your policy on the terms & conditions) * Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Farty Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Farty Risks and Compensation) Act, (Chapter 189) and Fart IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

Authorized Signature

Issued by - SGOAGPH on 09/02/2018

IMPORTANT :

Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189). The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement



Co Reg No : 196700086Z GST Reg No: MR-8500000-9

ESTIMATE

Online Service Booking:

Borneo Motors (Singapore) Pte Ltd

www.toyotasingapore.com.sg Toyota Bodycare Cer No. Z randan Cresc Singapore 128462

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items! Tel no.: 6631 1188 Account No Account Detail Customer Detail S1000020/TPCLAIM THIRD PARTY CLAIM Mr Lee Kwok Song Document No 317A Yishun Avenue 9 #06-110 Singapore 761317 Document Date Mobile: 81180988 24/10/2018 Year Make Model Veh Reg No Reg Date Kilometers WIP No Order No/Remarks 18 MWYQKT E3 NSP170R 31/01/2018 36840 6TP/SLV9800R/24101 Chassis No. Engine No TWC No Terms Service Engineer Vehicle In Collected On MHFZ28H3500050167 2NRX270864 Shashitharan --/--/--- 0.00 --/--/---L Cd Job/Parts Description Qty Unit Price Disc % Amount ZBP-SUNDRY SUNDRIES POLICY NO .: ACC DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON: В BP-LAB CHECK WIRING AND CONDUCT LEAK TEST B BP-LAB TRANSFER TAILGATE MECHANISM AND REVERSE CAMERA 4 B BP-WS REPL REAR WINDSCREEN 396.00 5 SUPPLY SOLAR FILM (PO# Ĺ BP-LPO 300.00 6 B BP-LAB DRILL HOLE AND INSTALL REVERSE SENSOR 154.00 7 REPL ACC AFF PARTS AND PANEL 8 BP-LAB 1232 2464.00 STRAIGHTEN AND REALLIGN ACC AFF AREA 10/2 8 B BP-RES RESRPAY ACC AFF AREA 2024.00 9 Z SUPPLY SEALANT (NETT BP-SLANT NU nu 108.00 SIKA 182010 SIKA TACK GO! (BLA 1.00 108.00 mu/ 1.00 SIKA 182010 SIKA TACK GO! 108.00 108.00 W/ 200.00 SIKA 207. G+P ADHESIVE PRIMER 1.00 de S52159-0U919 4 COVER, RR BUMPER, L 1.00 Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply For & on behalf of Customer's Signature Change Summary Borneo Motors Please acknowledge receipt of vehicle Parts LKK Auto Consultants hence notify 5-6den Labour the Repairer of the following: Materials · To resurvey before/after spray painting Lubrication/Fluid To display damaged part(s) during resurvey Others Parts prices are subject to confirmation Sur El Mantown. Amount Due Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and 3827069 PLEASE TEAR ALONG PERFORATED LINE is subject to final approval from Insurance Company TO SECURITY GUARD ACKNOWLEDGED by Repairer 3827069 DATE 24/10/2018 PLEASE ALLOW THE UNDERMENTIONED

VEHICLE NO

VEHICLE TO LEAVE THE COMPANY PREMISES

SLV9800R

TIME

14:39

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD





Co Reg No : 196700086Z GST Reg No : MR-8500000-9

ESTIMATE

Online Service Booking: www.toyotasingapore.com.sg Toyota Bodycare Centre No. 2 Pandan Crescent Singapore 128462 Tel no.: 6631 1188

Borneo Motors (Singapore) Pte Ltd

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

	Accou	nt Detail	Account No	S1000020/TPCLAIM		Customer Detail		
THIRD PARTY CLAIM		Docu		Document No 317A #06-1 Singa		Lee Kwok Song A Yishun Avenue 9 -110 Japore 761317		
			Document Date 24/10/		Mobi	le: 81180	988	
Year	Make Mod	lel Reg Date	Veh Reg No	Kilometers	WI	P No	Order N	o/Remarks
18 M	WYQKT E3	NSP170R 31/01/2018	SLV9800R	0	31	6840 -6	TP/SLV	9800R/24101:
Chas	sis No Engi	ine No TWC No	Terms	Service Engineer	r Ve	hicle In	Collecte	d On
MHFZ2	8H3500050167	2NRX270864	60 Sha	shitharan	/-	-/ 0.	00/	/ 0.00
L	od .	Job/Parts Desc	ription		Qty	Unit Price	Disc %	Amount
14 5 6 7 15 6 7 17 8 18 9 0 1 20 1 2 2 2 3	\$52151-0D010 \$64813-0D330 \$68105-0D260 \$67005-0D360 T90975-02086 \$75442-0D290 \$75441-0D070 \$81910-0D020	EXTENSION, R EXTENSION, R DAM, BACK WI GLASS SUB-AS PANEL SUB-AS TOYOTA SYMBO PLATE, BACK PLATE, BACK REFLECTOR AS	R BUMPER RH NDOW GLA SY, BACK SY, BACK L EMBLEM, DOOR NAM DOOR NAM SY, REFL		1.00 1.00 1.00 1.00 1.00 1.00 1.00	126.70 186.40 12.20 987.90 1110.70 72.20 34.80 52.10 58.60	9934	M × 126.70 de 186.40 nei 12.20 Dun 987.90 bt 1110.70 nu 72.20 nu 34.80 Nu 52.10 Nu 73.80 Nu 52.10 Nu 73.80
	For & on behalf of Borneo Motors	Customer's Signa	sture	Change Summary	6	Total		9,501.80
		Please acknowledge rece	eipt of vehicle Parts		367.80	GST 7.00	8	665.13
			Mater	ials	300.00	Less		0.00
			Lubrio	cation/Fluid s	0.00			

PLEASE TEAR ALONG PERFORATED LINE

3827070

TO SECURITY GUARD

3827070

PLEASE ALLOW THE UNDERMENTIONED

DATE 2

24/10/2018

VEHICLE TO LEAVE THE COMPANY PREMISES.

TIME 14:39

VEHICLE NO

SLV9800R

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD





Co Reg No : 196700086Z GST Reg No : MR-8500000-9

Borneo Motors (Singapore) Pte Lt

Online Service Booking: www.toyota.com.sg

Toyota Bodycare Centre No. Z Fandan Crescent

ESTIMATE E account & more! Download "My Toyota SG" app on Playstore or Appstore to access your Singapore 128462 Tel no.: 6631 1188 Account No Account Detail Customer Detail S1000005/ICFIC1 First Capital Insurance Ltd Mr Lee Kwok Song Document No 317A Yishun Avenue 9 36 Robinson Road #16-01 City House #06-110 Singapore 068877 Singapore 761317 Document Date Attn: Motor Claims Dept Mobile: 81180988 23/01/2019 Year Make Model Veh Reg No Kilometers WIP No Order No/Remarks Reg Date 18 MWYQKT E3 NSP170R 31/01/2018 SLV9800R 6TP/SLV9800R/24101: 36840 Chassis No. Engine No Service Engineer Vehicle In Collected On Terms MHFZ28H3500050167 2NRX270864 60 Shashitharan 18/01/2019 8.00 23/01/2019 18.00 L Cd Job/Parts Description Qty Unit Price Disc % Amount 1 Z BP-SUNDRY SUNDRIES 50.00 DATE-IN: 18/01/19 DATE SURVEY: 05/12/18 NO OF REPAIR DAYS:5 days BY:taufikh lkk AUTHORISED ON: 18/01/19 2 В BP-LAB CHECK WIRING AND CONDUCT LEAK TEST 154.00 3 B BP-LAB TRANSFER TAILGATE MECHANISM AND REVERSE 462.00 CAMERA В BP-WS REPL REAR WINDSCREEN 396.00 5 BP-LPO L SUPPLY SOLAR FILM (PO# 300.00 6 В BP-LAB DRILL HOLE AND INSTALL REVERSE SENSOR 154.00 7 BP-LAB B REPL ACC AFF PARTS AND PANEL 1232.00 STRAIGHTEN AND REALLIGN ACC AFF AREA 8 В BP-RES RESRPAY ACC AFF AREA 1012.00 9 Z BP-SLANT SUPPLY SEALANT (NETT) 80.00

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	Less
		Lubrication/Fluid	
		Others	

PLEASE TEAR ALONG PERFORATED LINE

3889931

108.00

108-00

186.40

993.70

12.20

31

TO SECURITY GUARD

3889931

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES. DATE 23/01/2019 TIME 09:27

SIKA 210002-0 TACK GO! (BLACK) SG

SIKA 210002-0 TACK GO! (BLACK) SG

COVER, RR BUMPER, L

EXTENSION, RR BUMPER

DAM, BACK WINDOW GLA

GLASS SUB-ASSY, BACK

VEHICLE NO

SLV9800R

SIGNATURE

FOR BORNEO MOTORS (SINGAPORE) PTE LTD



1.00

1.00

1.00

1.00

1.00

1.00

108.00

108.00

310.20

186.40

12.20

993.70

Borneo Moto

10 1

11

12

13 4

14 5

15 6

2

T21000-20

T21000-20

S52159-0U919

S52151-0D010

S64813-0D330

S68105-0D261



Engine No

Co Reg No : 196700086Z GST Reg No : MR-8500000-9

Chassis No

Vehicle In

Service Engineer

Borneo Motors (Singapore) Pte Lt

Collected On

Online Service Booking: www.toyota.com.sg

Toyota Bodycare Centre No. 2 Pandan Crescent Singapore 128462

	Account Detail		Account No		Tel no.: 6631 1188 Customer Detail		
First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept		S1000005 / ICFIC1 Document No 0 Document Date 23/01/2019		Mr Lee Kwok Song 317A Yishun Avenue 9 #06-110 Singapore 761317 Mobile: 81180988			
Year Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks	
8 MWYQKT E3	NSP170R	31/01/2018	SLV9800R	0	36840	6TP/SLV9800R/24101	

MHF	Z28	Н3500050167	2NRX270864 60 Shashitha	ran 18/0	1/2019 8.	00 23/01	/2019 18.00
L	Cd		Job/Parts Description	Qty	Unit Price	Disc %	Amount
16	7	s67005-0D360	PANEL SUB-ASSY, BACK	1.00	1110.70		1110.70
17	8	T90975-02086	EMBLEM, SYMBOL	1.00	72.20		72.20
18	9	S75442-OD290	PLATE, BACK DOOR NAM	1.00	34.80		34.80
19	0	S75441-0D070	PLATE, BACK DOOR NAM	1.00	52.10		52.10

Terms

For & on behalf of Borneo Motors	Customer's Signature	Change S	ummary	Total	6,828.30
20110011001	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid	2,988.30 3,540.00 300.00	GST 7.00% Less	477.98
	-	Others	0.00	Amount Due	7,306.2

PLEASE TEAR ALONG PERFORATED LINE

3889938

TO SECURITY GUARD

3889932

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES. DATE TIME

23/01/2019 09:27

VEHICLE NO

SLV9800R

SIGNATURE

FOR RORNEO MOTORS (SINGAPORE) PTE ITO



Borneo Moto



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Auto

Ref: CS/FCI18019605/T1td3e2 MS FIRST CAPITAL INSURANCE LTD



	OBINSON ROAD	INGAPORE 068877	Date: 15-02-2019	
, , ,	0,011,1100020		Code: FCI2	
		Policy Particula	rs :- THIRD PARTY CLAIR	M.
	Insured Veh.	SHA 9088M	Veh. Inspected	SLV 9800R
	Policy No.	D-18088937MFSH	Coverage (\$)	0.00
	Claim No.	D18007724MFSH	Excess (\$)	0.00
	Assign From	LURENE JAW	Assign Date	26/10/2018
2.		Vehicle Pa	rticulars & Condition	
	Make & Model	TOYOTA SIENTA E	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	MHFZ28H3500050167	Colour	GREY
	Odometer	14664	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
i		Cond	litions of Tyres	
		Size	Make	Balance
	R/H Front Tyre	195/50 R16	BRIDGESTONE	6 mm
	L/H Front Tyre	195/50 R16	BRIDGESTONE	6 mm
	R/H Rear Tyre	195/50 R16	BRIDGESTONE	6 mm
	L/H Rear Tyre	195/50 R16	BRIDGESTONE	6 mm
		Descrip	otion of Damages	Market Market Service
	THE VEHICLE SU	STAINED DAMAGES AT THE I	REAR O/S PORTION.	
	DAMAGES SEE D	ETAILS.		
5,		Gene	eral Information	
	Accident Date	24/10/2018	Inspection Date	03/12/2018
	Survey held at	BORNEO MOTORS (S) PTE	LTD	
	Out:	2 PANDAN CRESCENT SINGAPORE 128462		
ā.			Remarks	THE PARTY OF THE P
	B)THE INSPECTION	ISISTENT TO ACCIDENT REP ON WAS CONDUCTED ON A"V CE TO YOUR INSTRUCTIONS	WITHOUT PREJUDICE" BAS	
5b.		Estima	te Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	5 Working Day	S



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 9800R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	SUNDRIES (SN)	NECESSARY	100.00	50.00
1	SEALANT (SN)	NECESSARY	80.00	80.00
1	SIKA 182010 SIKA TACK GO! (BLA (SN)	NECESSARY	108.00	108.00
1	SIKA 182010 SIKA TACK GO! (BLA (SN)	NECESSARY	108.00	108.00
1	SIKA 207. G+P ADHESIVE PRIMER (SN)	NOT NECESSARY	200.00	-
1	COVER, RR BUMPER, L (SN)	DEFORMED	310.20	310.20
1	EXTENSION, RR BUMPER LH (SN)	NOT NECESSARY	126.70	-
1	EXTENSION, RR BUMPER RH (SN)	DEFORMED	186.40	186.40
1	DAM, BACK WINDOW GLA (SN)	NECESSARY	12.20	12.20
1	GLASS SUB-ASSY, BACK (SN)	NECESSARY	993.70	993.70
1	PANEL SUB-ASSY, BACK (SN)	BENT	1,110.70	1,110.70
1	TOYOTA SYMBOL EMBLEM (SN)	NECESSARY	72.20	72.20
1	PLATE, BACK DOOR NAM (SN)	NECESSARY	34.80	34.80
1	PLATE, BACK DOOR NAM (SN)	NECESSARY	52.10	52.10
1	REFLECTOR ASSY, REFL (SN)	NOT NECESSARY	58.60	-
			3,553.60	3,118.30
	LABOUR			
	CHECK WIRING AND CONDUUCT LEAK TEST.		154.00	154.00
	TRANSFER TAILGATE MECHANISM AND REVERSE CAMERA.		462.00	462.00
	REPL REAR WINDSCREEN.		396.00	396.00
	SUPPLY SOLAR FILM (PO#)		300.00	300.00
	DRILL HOLE AND INSTALL REVERSE SENSOR.		154.00	154.00
	REPL ACC AFF PARTS AND PANEL STRAIGHTEN AND REALLIGN ACC AFF AREA.		2,464.00	1,232.00
	RESPRAY ACC AFF AREA.		2,024.00	1,012.00
			-	-
			-	
			-	-
			5,954.00	3,710.00
	GRAND TOTAL		9,507.60	6,828.30

Report Ref No. CS/FCI18019605/T1td3e2





RECOMMENDED COST OF REPAIRS 6,828.30

Report Ref No. CS/FCI18019605/T1td3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

St. S.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.