## SINGAPORE ACCIDENT STATEMENT

# IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

aforesaid.	
	ACCIDENT STATEMENT
Date Of Report	29/10/2018 14:08
Date Of Accident	27/10/2018 12:05
Exact Location Of Accident	PIE (TUAS) BEFORE KALLANG BAHRU EXIT
Country/State of Loss	SINGAPORE
D	ETAILS OF OWN VEHICLE
Vehicle Registration Number	SLW9880D
Insured/Policyholder	
Name Of Registered Owner	YEE XIAN JUN (YU XIANJUN)
NRIC No	S9021732A
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97337258
Alternative Phone No	OFFICE-97337258
Vehicle Particulars	
Manufacturer	MITSUBISHI
Model	ECLIPSE CROSS 1.5 CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1800023971
Cover Note Number	
Driver	

Name of Driver YEE XIAN JUN (YU XIANJUN)

NRIC No S9021732A Date Of Birth 21/06/1990 Occupation **INDOOR** Date Of Driving Pass 08/06/2009

**Driving Experience** 9 YEARS AND 4 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-97337258

Fax Number

**Contact Number** OFFICE-97337258

**EMail Address NOEMAIL**  Address BLK 154 JALAN TECK WHYE

#13-89

Postcode 680154

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own

Vehicle

.

Insurance Company of Driver's Own Vehicle

-

### **General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR
Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? YES
Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

### **Details of Police Action**

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

# **Circumstances of Accident**

# REFER TO STATEMENT.

# Attachment(s)

Are accident photos available for attachment? YES Was there any video captured by Car Camera? YES

Remarks/ Reasons: VIDEO FOOTAGE WITH DRIVER

Was there any audio recorded? NO

# **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SLX8782E

Vehicle Make/Model/Colour

**Details Of Properties** 

Vehicle Category PRIVATE CAR

Name of Driver

NRIC/Passport Number

**Contact Number** 

Address Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

# **DETAILS OF INJURED PERSON 1**

YEE XIAN JUN (YU XIANJUN) Name

Approximate Age

Injuries Sustain

Injured person in which vehicle? SLW9880D

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

BODY

YES

NO

### Accident Sketch Plan

# SKETCH PLAN

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (Iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud. regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

Reporting Centre Perso nel's Signature

Name

NRIC/FIN NO.

# **Accident Sketch Plan**

The second secon	
	towards that defort
CEX	(7 12) harris garden
	A
Winscort A	Sev. o S
- 5	CM 9870 9
CHAMICON B	
_ 5	LX 8782 BDIAD
ECCDIDE CIDCIINACTA	NCES OF THE ACCIDENT
ESCRIBE CIRCUMSTA	ACES OF THE ACCIDENT
I was To	evaluate promis pie towards that pikection. I
was on	THE EXTRAME RIGHT LAVE.
	WELL ELLS OF SING CAD CHARMS IN
TRAFFIC, TO	the value increase graces to compute stop,
ano so	I TOO APPLIED BRANCE TO COMPLETE STOP.
SUDDENLY	AFTER A FEW SECONDS, I FELT A GREAT
	AFTER A FEW SECONDS, I FELT A GREAT
	AFTER A FEW SECONDS, I FELT A GREAT OF MY VEHICLE.
	The state of the s
impact ce	on the rear of my vertice.
ALIGHTED	prom my verticus and reactived it was
ALIGHTED	on the rear of my vertice.
ALIGHTED Q VILLIGIA	FROM MY URHICUS AND REALIZED IT WAS
ALIGHTED Q VILLIGIA	prom my verticus and reactived it was
ALIGHTED Q VILLIGHE COLLIDIED	PROM MY LIBHICUS AND REALIZED IT WAS  WITH LICENCE PLATE (SLX 8782 12) THAT  TO THE REAR OF MY VEHICLE.
ALIGHTED Q VILLIGA	PROM MY LEHICUE AND REALIZED IT WAS  WITH LICENCE PLATE (SLX 8782 12) THAT  TO THE REAL OF MY VEHICLE.
ALIGHTED  Q VILLIGHE  COLLIDIED  THE WHOLE	PROM MY LEHICUE AND REALIZED IT WAS  WITH LICENCE PLATE (SLX 8782 12) THA  TO THE REAL OF MY VEHICLE.
ALIGHTED  Q VILLIGHE  COLLIDIED  TIME WHOLE	FROM MY VEHICUE AND REALIZED IT WAS  WITH LICENCE PLATE (SLX 8782 12) THAT  TO THE REAL OF MY VEHICUE.
ALIGHTED  Q VILLIGHE  COLLIDIED  THE WHOLE	PROM MY LEHICUE AND REALIZED IT WAS  WITH LICENCE PLATE (SLX 8782 12) THA  TO THE REAL OF MY VEHICLE.
ALIGHTED  QUANTICUE  COLLIDIED  TIME WHOLE  INCOME CA	FROM MY LEHICULE AND REALIZED IT WAS  WITH LICENCE PLATE (SLX 9782 %) THAT  TO THE REAR OF MY VEHICLE.  E ACCIDANT FOOTAGE WAS COPTURED BY  MERA.
ALIGHTED  Q VILLICUS  COLLIDIED  TIME WHOLE  IACOR CA	PROM MY LEHICUE AND REALITIED IT WAS  WITH LICENCE PLATE (SLX 8782 NE) THAT  TO THE REAL OF MY VEHICUE.  E ACCIDANT FOOTAGE WAS COATURED BY  MERA.  - SLW 98801)
ALIGHTED  QUALICUE COLLIDIED  THE WHOLE  INCORR CA	PROM MY LEHICUE AND REALITIED IT WAS  WITH LICENCE PLATE (SLX 8782 NE) THAT  TO THE REAL OF MY VEHICUE.  E ACCIDANT FOOTAGE WAS COATURED BY  MERA.  - SLW 98801)
ALIGHTED  Q VILLICUS  COLLIDIED  TIME WHOLE  IACOR CA	PROM MY LEHICUE AND REALITIED IT WAS  WITH LICENCE PLATE (SLX 8782 NE) THAT  TO THE REAL OF MY VEHICUE.  E ACCIDANT FOOTAGE WAS COATURED BY  MERA.  - SLW 98801)
ALIGHTED  Q VILLICUS  COLLIDIED  TIME WHOLE  INCORR CA	PROM MY LEHICUE AND REALITIED IT WAS  WITH LICENCE PLATE (SLX 8782 NE) THAT  TO THE REAL OF MY VEHICUE.  E ACCIDANT FOOTAGE WAS COATURED BY  MERA.  - SLW 98801)
ALIGHTED  Q VILLICUS  COLLIDIED  TIME WHOLE  IACOR CA	PROM MY LEHICUE AND REALITIED IT WAS  WITH LICENCE PLATE (SLX 8782 NE) THAT  TO THE REAL OF MY VEHICUE.  E ACCIDANT FOOTAGE WAS COATURED BY  MERA.  - SLW 98801)
ALIGHTED  Q VILLICUS  COLLIDIED  TIME WHOLE  INCORR CA	PROM MY LEHICUE AND REALITIED IT WAS  WITH LICENCE PLATE (SLX 8782 NE) THAT  TO THE REAL OF MY VEHICUE.  E ACCIDANT FOOTAGE WAS COATURED BY  MERA.  - SLW 98801)
ALIGHTED  Q VILLICUS  COLLIDIED  TIME WHOLE  INCORR CA	PROM MY LEHICUE AND REALITIED IT WAS  WITH LICENCE PLATE (SLX 8782 NE) THAT  TO THE REAL OF MY VEHICUE.  E ACCIDANT FOOTAGE WAS COATURED BY  MERA.  - SLW 98801)
ALIGHTED  QUANICUE COLLIDIED  THE WHOLE  IA-CAR CA  USMICUE A  USMICUE B	PROM MY LEHICUE AND REALITIED IT WAS  WITH LICENCE PLATE (SLX 8782 NE) THAT  TO THE REAL OF MY VEHICUE.  E ACCIDANT FOOTAGE WAS COATURED BY  MERA.  - SLW 98801)
ALIGHTED  QUANICUE COLLIDIED  THE WHOLE  IA-CAR CA  USMICUE A  USMICUE B	PROM MY LEHICUE AND REACITIED IT WAS  , WITH LICENCE PLATE (SLX 9782 E) THAT  TO THE REAR OF MY VEHICLE.  E ACCIDANT FOUTHER WAS CONTURED BY  MERLA.  - SLW 98801)  - SLX 8782 B
ALIGHTED  QUANICUE COLLIDIED  THE WHOLE  IA-CAR CA  USMICUE A  USMICUE B	PROM MY LEHICUE AND REACITIED IT WAS  , WITH LICENCE PLATE (SLX 9782 E) THAT  TO THE REAR OF MY VEHICLE.  E ACCIDANT FOUTHER WAS CONTURED BY  MERLA.  - SLW 98801)  - SLX 8782 B
ALIGHTED  QUANICUE COLLIDIED  THE WHOLE  INCAR CA  USINICUE A  WITHICLE B	PROM MY LEMICULE AND REALITIED IT WAS  WITH LICENCE PLATE (SLX 9782 R) TIMP  TO THIE REAR OF MY VEHICLE.  E ACCIDANT FOOTAGE WAS CORTURED BY  MERA.  SLW 98801)  SLX 8782 R
ALIGHTED  QUANICUE COLLIDIED  THE WHOLE  IA-CAR CA  USMICUE A  USMICUE B	PROM MY LEHICUE AND REACITIED IT WAS  , WITH LICENCE PLATE (SLX 9782 E) THAT  TO THE REAR OF MY VEHICLE.  E ACCIDANT FOUTHER WAS CONTURED BY  MERLA.  - SLW 98801)  - SLX 8782 B





# Accident Photo Res Austri Cross SLIGBBO

















