Our Ref : 305230584

Date: 26.10.2018

Time of Fax : 10354

LONPAC

Your Insured: CBC 833

Date of Acc: 25.10.2018

COMFORTDELGRO Engineering

> ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

> > Mainline +65 6383 6280 Facsimilie +65 6280 9755

> > > www.cdge.com.sg

Company Registration No: 199508048W

Workshop

Attn: Motor Claims Dept.

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO SHA (690 18

59 Loyang Drive Singapore 508969

- 1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.
- 2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.
- 3 Enclosed, please find:
  - 1) Our initial estimate of repairs of the damaged vehicle.
  - II) Accident report made by our client.
- 4 I would appreciate it if you could call us to arrange for the survey of the vehicle

Lim Kwok Eng Tel no. 62148355 or Hp no. 98240811 Jumani Bin Masudin Tel no. 62148315 or Hp no. 96355305 Lim Tlen Slong Tel no. 62148398 or Hp no. 96358546 Chiang Liat Choon Tel no. 62148314 or Hp no. 92966006

Fauzy Bin Mokhtar Tel no: 62148319 or Hp no: 81259176

Larry Ng Tel: 6214 8316

- 5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage Independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.
- 6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.
- 7 Thank you.

Yours faithfully

Larry Ng

for Vice President Crash Repairs & Claims Recovery

# COMFORTDELGRO ENGINEERING PTE LTD

# REPAIR ESTIMATE\*

VEHICLE NO: SHA 1690B

DATE 26/10/2018 9:22

MAKE

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Туре	Ţ	Unit Price	1	Amount	
	Boot Lid				S	2,174.90	
	Boot Lid Lock Upper				\$	102.60	
	Boot Lid Lock Lower				\$	31.70	
	Boot Lid 'H' Emblem				\$	28.70	
	Boot Lid CRDI Plate				\$	27.90	
	Bootlid Moulding				\$	227.90	
	Bootlid i40 Emblem				\$	27.90	
	Bootlid Lower Gamish				\$	227.90	
	Rear Bumper		<u> </u>		\$	553.00	l
	Rear Bumper Reinforcement		ŀ		\$	428.40	
	Rear Bumper Reinforcement Bracket (LH/RH)		\$	80.30	\$	160.60	
	Rear Bumper Clip 10 pcs				\$	22,00	
	Rear Bumper Bracket		\$	35.60	\$	71.20	
	Rear Bumper Sponge		ŀ		\$	103.50	
	Rear Bumper Under Cover	•	•		\$	228.00	1
	Rear Panel				\$	526.70	
	Rear Panel Garnish				\$	57.70	
	Rear Panel Lower Panel				\$	89.40	
	SUB TOTAL				\$	5,090.00	
	LESS 20%				\$	1,018.00	
	DISCOUNTED TOTAL				\$	4,072.00	
						·	
	Boot Lid Comfort Logo & Tel No. Sticker				\$	30.00	Nett
	Rear Bumper Reverse Sensor				\$	135.70	
	Rear Bumper Rubber Mat				S	50.00	
	Rear Bumper Advertisement Logo				\$	50.00	Nett
	Rear Fender Advertisement Logo (LH/RH)		\$	100.00	\$	200.00	Nett
						···	
					\$	465.70	-
	Labour Charge						
	Panel Beating				\$	800.00	
	Spray Painting Charge				\$	900.00	
	Wiring Charge				\$	30,00	
	Tuff Kote	t			\$	50.00	
	Remove/Refix Reverse Sensor				\$	80.00	
	TOTAL LABOUR				<u> </u>	1,860.00	
	ESTIMATE TOTAL	·			\$	6,397.70	4
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a proton Surveyor appointed by the insurance company.						
	be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.						ل

MCD818130081 / ComfortDelGro Engineering Pie Ltd - Loyang ENTRY DATE & TIME: 28/10/2018 18:48 SUBMITTED BY: Huang XlaoYan

### SINGAPORE ACCIDENT STATEMENT

- 1. Please report correctly the details of the accident to speed up the claims process.

  2. This Form must be completed by the Policyholder and/or the Authorised Driver.

  3. Information profiled must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for Investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by inferested parties.
- 7. By the ladgement of this report to the insurers, you horoby consent to the archiving of this report at the centre and to copies of the report being made available

	ACCIDENT STATEMENT					
Date Of Report	25/10/2018 16:46					
Date Of Accident	25/10/2018 14:30					
Exact Location Of Accident	GEYLANG RD NEAR HAIG RD FOOD CENTRE					
Country/State of Loss	SINGAPORE					
	DETAILS OF OWN VEHICLE					
Vehicle Registration Number	SHA1690B					
Insured/Policyholder	* professional and the second of the professional and the second of the					
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD					
Co Reg No	199303821R					
Email Address	FLEETSAFETY@CDGTAXI.COM.\$G					
Mobile Phone No						
Alternative Phone No  Vehicle Particulars	OFFICE-65508768					
Manufacturer	HYUNDAI					
Model	140					
Exact Purpose for which vehicle was being used a time of accident	t					
Are you claiming under your own insurance policy for repair to your vehicle?	NO					
If No, Please state action to be taken	THIRD PARTY					
Vehicle Category	TAXI					
Insurance Company						
Name of insurance Company	MS FIRST CAPITAL INSURANCE LTD					
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT					
Fleet Policy	YES					
Policy Number	D-18088936MFSH					
Cover Note Number						
Driver						
Name of Driver	TAJUDDIN BIN BADRUDDIN					
NRIC No	S1769561D					
Date Of Birth	11/03/1966					
Occupation	OUTDOOR					
Date Of Driving Pass	11/12/2001					
Driving Experience	16 YEARS AND 10 MONTHS					
Gender	MALE					
Mobile Number	(LOCAL) +65-90121627					
Fax Number						
Contact Number						
EMail Address	TAJUDDINBADRUDDIN@GMAIL.COM					

26-10-18:10:30

Address BLK 856F TAMPINES STREET 82 #03-214

Postcode 526856

NO Was driver an employee of the Insured's Company

If No, Relationship of the Driver with the insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

COLLISION - HEAD TO REAR Type Of Accident

ΝΦ

NO

NO

NO

NO

GBC833Z

Weather Conditions CLEAR Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by

ambulance?

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

**Details of Police Action** 

Was the accident reported to the police?

If Yes, Please state which Police Station

Was notice of Intended Prosecution given?

If Yes, against whom?

Circumstances of Accident

PLS REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment? YE\$ Was there any video captured by Car Camera? YE\$

Remarks/ Reasons:

Was there any audio recorded?

**DETAILS OF OTHER VEHICLE PROPERTY 1** 

Vehicle Registration Number

Vehicle Make/Model/Colour

**Details Of Properties** 

COMMERCIAL VEHICLE Vehicle Category

NG KING HOCK Name of Driver S0994494Z NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name LONPAC INSURANCE BHD

FRT Nature Of Damage

No. Of Passenger (Including Driver)

The suggestion of the second and an elementary of the second of the seco

No. of the second secon

26-10-18:10:30 :

# 5/ 6

## Sketch Plan Pg. 1

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the cialms process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The Issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any faire reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8, Consont under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapora ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal information") and disclose and transfer such Personal information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident (all insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or doaling with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (III) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, involces, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable ligw in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD

CO. REG NO. 199203821R

Policyholder's Signature Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time;

Reporting Centre Personnol's Signature

Name:

NRIC/FIN No.:

GIARMC SketchPlanForm\_V3

¥ ... \$

4---

GIATITAC SkatchPlanForm\_V3

# Sketch Plan Pg. 2

KETCH PLAN	•
	and Read Wear Age Vocal Took Control A 15-1-16-10
<u> </u>	
<del>╎</del> ┤┤┼┼┼┼┼┼	TRANSPORT
┍┩╸╖┡╶╖┞╼╾┞╼╾┞╴╺ <del>┩╴┍┡</del> ╸ <del>┋┍┑╏╸╸</del> ┠╸╾╏╸	╼╃╾┩╼┦╼┸╍┦╍┦╍┦╌┋╼┋╼ <u>┡╴┞╾╢╍╫╸</u> ┋╌╃╸╀╸ <u>┇╸╃╌┧╸┨╼╟╸┠╍╂╍╬╍╬╌╏╌╏╌╏╴╏╴╏╴╂╴╂╌</u> ╏╌
	<del>┍</del> ┩╸╏╸╏ <del>╸</del> ┇╼┢╍╫╺╬ <del>╒╬╸</del> ┣╸╬╍┢╍╟╌╬╴┡╍╇═┦╴┥╍╊╌╏╌┡╸╏╸╏╼╿╸╀╴╫╌╠┅╟╴╏╶╏┄╏┈╏┈╏┄╏┄╟╸╏
╌╎═┼╍┼╍┼╸┟╍┞═╃═╬╌┤╒┦╌╎╌╏	<del>╶╎╸╎╸╣╸╣╸┩╸┩╸┋╸┋╸┩╸┪╻┋╸</del> ┝╸╬╶┫╼ <del>┋╸</del> ┢╸╎╸┩╸┪╸╬╸╏╸╟╸┩╺┡╸┋╸┩╸┪╸╋╸┩╸╬╸┥
ESCRIBE CIRCUMSTANCES O	F THE ACCIDENT
A state	at along 11.22 he who to I lob It was
Ch 25/10/18 0	et about 1430 hm white I Veh 14 was
1	
dring storyly	near the long, Well" B collided
J	near the low, Weling collided
on the rear	of my chicle.
	A
	^ /
DECLARATION	SR MyCoun,
I/We declare the foregoing partic COMFORT TRANSPORTATION	culars are true in every respect, '
COMPORT TRANSPORTATION CO. REG. NO. 199303	301R 101
	<u> </u>
Policyholder's Signature	Driver Signature Reporting Centre Personner d Signature
Date & Time;	(if driver is not the policyholder)  Name:  NRIC/FIN No.: