

22/03/2002

ASS. REC. BY:

REF: CS3/AG18019627/R1cd362

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

11:2am @ 29/10/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLE 3692P

Insured:

SLB 4060Y

at Workshop m/s

JL Auto

Tel:

9188 5495

of

Blk 3006 ubi Rd | # 01-346

Policy No:

2100457681

Claim No:

6085240840SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

25/10/2018

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

11:45am @ 29/10/18

Person Contacted:

Anthony

Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (x) Estimate	
	SLE 3692P - NA / MSG18019464 / 24	DOA: 25/10/18
	SLB 4060Y - NA / MSG18019464 / 24	DOA: 25/10/18
	Disassemble: 30/10/2018	

Your password will expire in 14 days. [Click here to change it.](#)

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying
To: assignments, admin-a@lkkauto.com
Cc: Fong, Andy-SY
Sent: 29/10/2018 11:12:41 AM
Attachments:  [tmp95D4.tif](#)

Hi LKK,

Kindly assist to survey, vehicle in workshop.

Thanks.

Best Regards
Lee Ying, Chin
AIG
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

YOGARAJAH LLC

ADVOCATES & SOLICITORS

Our Ref : CY.SLE3692P.18.JLA(HW).wp(Lh)

Your Ref : Your insured vehicle SLB 4060Y

25 October 2018

AMIT KUMAR GARG

c/o The Motor Claims Department
 AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way #07-16
 Singapore 079120

883 North Bridge Road
 #11-03 Southbank
 Singapore 198785
 T: 6292 5838
 F: 6292 5838
 (UEN No. 201333127N)
 (GST Reg No. 201333127N)

By Fax No: 6835 7416

Dear Sirs

NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS PURSUANT TO PRE-ACTION PROTOCOL FOR NON INJURY MOTOR ACCIDENT CASES ROAD TRAFFIC ACCIDENT INVOLVING MOTOR VEHICLES SLE 3692P & SLB 4060Y ON 25.10.2018 @ 09:15HRS ALONG JUNCTION BEDOK NORTH ROAD & BEDOK RESERVOIR ROAD

We are instructed by WONG SOO NEONG to notify you of a road traffic accident on 25.10.2018 @ 09:15hrs along Junction Bedok North Rd & Bedok Reservoir Rd involving our client's customer's vehicle registration number SLE 3692P and vehicle registration number SLB 4060Y driven by you at the material time. A copy of the Singapore accident statement report is enclosed.

As the result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully,

C. Yogarajah LLC
 Enc

Cc: M/s JL Auto Service Pte Ltd
 Block 3006 Ubi Road 1
 #01 - 346
 Mr. Ah Tay (9188 5495)
 Fax no : 6310 7269

Confidentiality & Privilege: This message is intended for the recipient to whom it is addressed. It may contain confidential or privileged information. If you are not the intended recipient, please notify the sender immediately by replying to this message and then delete it from your system. Do not read, copy, use or circulate this communication. Disclaimer: Mail/Fax/Internet communications are not secure. While every reasonable effort has been made to ensure that this communication has been securely transmitted and not been tampered with, C. Yogarajah LLC cannot be responsible for alterations made to the contents of this message without its express consent. If you wish to receive a hard copy of this communication for comparison or should you require any other form of confirmation of the contents of this message, please contact the sender. Opinions, conclusions and other information in this message that do not relate to the official business of the firm shall be understood as neither given nor endorsed by C. Yogarajah LLC Advocates & Solicitors. Thank you

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8782J
Vehicle Details	
Vehicle No.:	SLE3692P
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Oct 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS CLASSIC 1.6 CVT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	1ZR575754
Chassis No.:	MR053REH104551592
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$17,982.00
Original Registration Date:	19 Jul 2016
First Registration Date:	19 Jul 2016
Transfer Count:	0
Actual ARF Paid:	\$17,982.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jul 2026
PARF Rebate Amount:	\$13,486.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jul 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$52,301.00
COE Rebate Amount:	\$40,350.00
Total Rebate Amount:	\$53,836.00

The information contained herein is correct as at 31 Oct 2018

OK

97507472

64191947

AF 3.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/10/2018 11:42
Date Of Accident	25/10/2018 09:15
Exact Location Of Accident	JUNC BEDOK NORTH RD & BEDOK RESERVOIR RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLE3692P
Insured/Policyholder	
Name Of Registered Owner	WONG SOO NEONG
NRIC No	S2168782J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98506957
Alternative Phone No	OFFICE-98506957
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA ALTIS CLASSIC 1.6 CVT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A80458918QMY
Cover Note Number	

Driver

Name of Driver	LOH NGAP KEE
NRIC No	S0096831E
Date Of Birth	05/08/1950
Occupation	INDOOR
Date Of Driving Pass	28/07/1976
Driving Experience	42 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97507472
Fax Number	
Contact Number	OFFICE-97507472
Email Address	NOEMAIL

Address	BLK 636 BEDOK RESERVOIR ROAD #09-31
Postcode	410636
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting offering accident claims assistance	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: WONG, SOO, NEONG
	GENDER: FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

ON STATED DATE AND TIME, MY VEHICLE WAS STATIONARY STOPPED ALONG LANE 2 AS THERE WAS INCOMING VEHICLES TRAVELLING VERY FAST ALONG OPPOSITE DIRECTION OF BEDOK NORTH RD. SUDDENLY I FELT AN IMPACT OF MY VEHICLE. I ALIGHT FROM MY VEHICLE AND REALIZE THAT VEHICLE B HIT ONTO MY VEHICLE REAR PORTION.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB4060Y
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	AMIT KUMAR GARG
NRIC/Passport Number	S7285638D
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. The sketch must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The completion and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. In the completion of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of drawings, drawings made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I, the Policyholder, do hereby agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data, personal information set out in this form and any other personal information provided by me or possessed by my insurer, collectively the "Personal Information"; and disclose and transfer such Personal Information to an insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"); the Insurers' lawyers/law firms, the Ministry of Home Affairs of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) assessing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigation relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) acting, negotiating and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) conducting my claims, including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope, final packages and/or
 - (v) complying with requests from authorities for processing, handling and/or dealing with my claims (collectively the "Purposes");
- (b) the Insurers who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) the Personal Information may/are disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information collected under (d) above may be shared / disclosed:
 - (i) to the Insurers and/or any third parties that assist in evaluating, investigating, controlling or managing fraud, claims, claims law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) to the relevant regulatory authorities under any regulations, laws or court orders.

Policyholder's Signature
Date & Time

Insurer's Signature
Driver's Name (Policyholder)
Date & Time

Reprinting Centre Personnel's Signature
Name
NRIC/FIN No

Accident Sketch Plan

SKETCH PLAN



A. 315 3692P

B. 315 3692P

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Statement

DECLARATION

I/We declare the foregoing particulars to be true and correct.

[Signature]
 Name: *[Name]*
 Title: *[Title]*

[Signature]
 Name: *[Name]*
 Title: *[Title]*
 (policyholder)

[Signature]
 Reporting Centre Personnel's Signature
 Name: *[Name]*
 NRIC/ID No: *[ID No]*

MOTORCAR (Rear)

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
1139	993630	Rear Number Plate Garnish			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper	CR	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	
1147	992976	Rear Bumper Bracket	DD	✓	2
1148	993068	Rear Bumper Side Retainer	DIS	✓	2
1149	993045	Rear Bumper Reinforcement	BT	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge			
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector	CR	✓	1
1157	993023	Rear Bumper Lower Spoiler			
1158	994023	Reverse Sensor	BR	✓	
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish	BR	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp	CR	✓	
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp	CR	✓	
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DD	✓	
1171	991328	Bootlid Emblem	NEC	✓	3
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding	CUT	✓	
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH	CR	✓	
1176	992899	Bootlid Lamp RH	CR	✓	
1177	995243	Bootlid Lock	BT	✓	
1178	990377	Bootlid Rubber	CUT	✓	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

Vehicle No: SLE 3692P

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe	DD	✓	2
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting	DIS	✓	
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: 15

Assessor:

T Gum
5/11/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Oct 2018 Edit Reg		29 Oct 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

AMIT KUMAR GARG, ID: S7285638D

Main Claimant:

WONG SOON LEONG

Vehicle Reg. No.:

SLE3692P

Claim Type:

TP / 6085240840SG

Vehicle Reg. No. (Insured):

SLB4060Y

Repairer:

Ji Auto Services Pte Ltd (HQ) Blk 3006 UBI ROAD 1 #01-346, 408700 Ubi - Tel:

Handling Insurer:

AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ]
BernardJiQian.Ler@aig.com

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 08/11/2018]

Claimant's Solicitor:

C YOGARAJAH LLC - Tel: 62925838

Date of Loss:

25/10/2018 00:00 - :59
[27 Months and 6 Days From LTA Reg Date (Man Yr)]

Policy/Cover Note No.:

2100457681 (Comprehensive)

Policy No. (Claimant):

Excess:

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- AIG_SG (30/10/2018): Request to upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLE3692P (6085240840SG)**
[SLB4060Y]
TP
WONG SOON LEONG
Oct 25 2018 12:00AM
[AMIT KUMAR GARG]
JI Auto Services Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View		View in Browser	
Photos/Images															3 per page		v	☒
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)											Thumbnail	Print			
1	31/10/18 08:44		General View											Load JPG	☒			
2	31/10/18 08:44		General View											Load JPG	☒			
3	31/10/18 08:44		General View											Load JPG	☒			
4	31/10/18 08:44		General View											Load JPG	☒			
5	31/10/18 08:44		General View											Load JPG	☒			
6	31/10/18 08:44		General View											Load JPG	☒			
7	31/10/18 08:44		General View											Load JPG	☒			
8	31/10/18 08:44		General View											Load JPG	☒			
9	31/10/18 08:44		General View											Load JPG	☒			
10	31/10/18 08:44		General View											Load JPG	☒			
11	31/10/18 08:44		General View											Load JPG	☒			
12	31/10/18 08:44		General View											Load JPG	☒			
13	31/10/18 08:44		General View											Load JPG	☒			
14	31/10/18 08:44		General View											Load JPG	☒			
15	31/10/18 08:44		General View											Load JPG	☒			
16	31/10/18 08:44		General View											Load JPG	☒			
17	31/10/18 08:44		General View											Load JPG	☒			
18	31/10/18 08:44		General View											Load JPG	☒			
19	31/10/18 08:44		General View											Load JPG	☒			
20	31/10/18 08:44		General View											Load JPG	☒			
21	31/10/18 08:44		General View											Load JPG	☒			
22	31/10/18 08:44		General View											Load JPG	☒			
23	31/10/18 08:44		General View											Load JPG	☒			
24	31/10/18 08:44		General View											Load JPG	☒			
25	31/10/18 08:44		General View											Load JPG	☒			
26	31/10/18 08:44		General View											Load JPG	☒			
27	31/10/18 08:44		General View											Load JPG	☒			
28	31/10/18 08:44		General View											Load JPG	☒			
29	31/10/18 08:44		General View											Load JPG	☒			
30	31/10/18 08:44		General View											Load JPG	☒			
31	31/10/18 08:44		General View											Load JPG	☒			
32	31/10/18 08:44		General View											Load JPG	☒			
33	31/10/18 08:44		General View											Load JPG	☒			
34	31/10/18 08:44		General View											Load JPG	☒			
35	31/10/18 08:44		General View											Load JPG	☒			
36	31/10/18 08:44		General View											Load JPG	☒			
37	31/10/18 08:44		General View											Load JPG	☒			

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	31/10/18 08:44	General View	 Load JPG	☒
39	31/10/18 08:44	General View	 Load JPG	☒
40	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
41	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
42	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
43	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
44	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
45	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
46	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
47	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
48	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
49	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
50	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
51	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
52	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
53	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
54	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
55	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
56	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
57	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
58	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
59	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
60	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
61	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
62	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
63	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
64	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
65	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
66	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
67	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
68	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
69	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
70	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
71	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
72	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
73	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
74	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
75	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
76	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
77	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
78	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
79	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
80	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
81	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
82	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
83	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
84	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
85	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
86	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
87	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
88	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
89	31/10/18 08:45	Photographs of Damaged Parts	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	30/10/18 10:30	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18019627/R1CD3E2

Date: 14/11/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100457681
Claimant Vehicle No : SLE3692P **Insured Vehicle No :** SLB4060Y
 Date of Loss: 25/10/2018 Nature of Claim: TP Claim No: 6085240840SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLE3692P**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZRX575754
 Reg. Date: 19/07/2016 (Man. Year: 2016) Chassis No: MR053REH104551592
 Colour: Grey Odometer: 53204 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/10/2018
 Date Inspected: 29/10/2018 Inspected At: JI Auto Services Pte Ltd (HQ)
 B1k 3006 UBI ROAD 1 #01-346
 Singapore 408700
 Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER BRACKET	Dented	0.00 F	*- F
4	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F
5	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F
6	1		*REAR BUMPER REFLECTOR RH	Cracked	0.00 F	*- F
7	1		*REVERSE SENSOR	Broken	0.00 F	*- F
8	1		*REAR END PANEL	Dented	0.00 F	*- F
9	1		*REAR END PANEL TOP GARNISH	Broken	0.00 F	*- F
10	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
11	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
12	1		*BOOTLID	Dented	0.00 F	*- F
13	3		*BOOTLID EMBLEM	Necessary	0.00 F	*- F
14	1		*BOOTLID MOULDING	Cut	0.00 F	*- F
15	1		*BOOTLID LAMP LH	Cracked	0.00 F	*- F
16	1		*BOOTLID LAMP RH	Cracked	0.00 F	*- F
17	1		*BOOTLID LOCK	Bent	0.00 F	*- F
18	1		*BOOTLID RUBBER	Cut	0.00 F	*- F
19	1		*REAR EXHAUST PIPE	Repair	0.00 F	*- F
20	1		*REAR EXHAUST MOUNTING	Distorted	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)	0.00	0.00
--------------------------	-------------	-------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >