

ASS. REC. BY:

REF: CS3/AIG18019629/Rcd36

Special Instruction:

Surveyor: RASHI
Menren

ASSIGNMENT (Office)

From (Person): Chin Lee Xing

of AIG

Date/Time: 29/10/2018 @ 11.11am

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGE 3415H

Insured: SLU 4765Y

at Workshop m/s: teck wong motor

Tel: 9734 1991

of Blk 3006 Ubi Rd 1 #01-338

Policy No: 17000 85074

Claim No: 16030 75774 8G

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 28/10/2018

CA / REV / REP. / REV 24 HRS (up)

H.O.D. Endorsement:

Date/Time: 29/10/2018

Person Contacted: Ah wong

Vehicle IN / OUT

Date/Time	Action/Instruction (X) Estimate
	SGE 3415H - X
	SLU 4765Y - X
	Dismantle: 30/10/2018
	After repair: 2/11/2018

Your password will expire in 14 days. [Click here to change it.](#)

- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying

To: assignments, admin-a@lkkauto.com

Cc: Fong, Andy-SY

Sent: 29/10/2018 11:11:27 AM

Attachments:  [tmp6D7A.tif](#)

Hi LKK,

Please assist to survey, vehicle in workshop.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



Daniel Poon & Co.
Advocates & Solicitors
Commissioners for Oaths

133 New Bridge Road
#11-02 Chinatown Point
Singapore 059413
Tel: +65 6227-2469
Fax: +65 6225-2579
Email: law@dpco.com.sg
(UEN: 53130838C)

Daniel Poon Choon Kow
LL. B. (Hons), LL.M

Our Ref: DP.sl.isk.10734.18.TWM
Your Ref: ----
Please quote our reference number when replying

Date: 24 OCTOBER 2018

M/S AIG ASIA PACIFIC INSURANCE PTE. LTD.
AIG BUILDING
78 SHENTON WAY
#08-16
SINGAPORE 079120
ATTN: MOTOR CLAIMS DEPARTMENT

FAX (6835-7416) ONLY

DEAR SIRs,

PRE-REPAIR INSPECTION

**YOUR INSURED VEHICLE REGISTRATION NO: SLU 4765Y
ACCIDENT ON 23 OCTOBER 2018 INVOLVING SGE 3415H AND SLU 4765Y
ALONG HOLLAND ROAD AT THE FILTER LANE INTO COMMONWEALTH AVENUE**

We are instructed by Yee Peng Fei to notify you of a road traffic accident on 23rd October 2018 at about 11:10 along Holland Road at the filter lane into Commonwealth Avenue involving our client's vehicle registration number SGE 3415H and vehicle registration number SLU 4765Y driven by your insured at the material time. A copy of the Singapore accident statement /traffic police report filed is enclosed.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you would like to conduct a pre-repair inspection of the vehicle, by the attached list of ten (10) surveyor which our client deemed suitable to be appointed.

If the aforesaid is not agreeable, kindly therefore instruct your appointed surveyor for a pre-repair inspection of our client's vehicle at by making a prior appointment with the repairer stated below:-

M/S TECK WANG MOTOR WORKSHOP
BLK 3006 UBI ROAD 1
#01-338
SINGAPORE 408700
ATTN: AH WANG (9734-1991)

... 2/-

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8754H
Vehicle Details	
Vehicle No.:	SGE3415H
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Oct 2018
Vehicle Make:	SEAT
Vehicle Model:	TOLEDO 1.4 TDI 90 STYLE 7AT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	CUS296804
Chassis No.:	VSSZZZNHZH1012306
Maximum Power Output:	66.0 kW (88 bhp)
Open Market Value:	\$22,029.00
Original Registration Date:	20 Jan 2017
First Registration Date:	20 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$7,841.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Jan 2027
PARF Rebate Amount:	\$5,880.00
Intended COE Rebate Details	
COE Expiry Date:	19 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$49,751.00
COE Rebate Amount:	\$40,884.00
Total Rebate Amount:	\$46,764.00

The information contained herein is correct as at 31 Oct 2018

OK

MBHH18137735 / Ajax Mars Pte Ltd - Bukit Merah
 ENTRY DATE & TIME: 23/10/2018 16:25
 SUBMITTED BY: Chai MLIn

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	23/10/2018 16:25
Date Of Accident	23/10/2018 11:10
Exact Location Of Accident	8 HOLLAND AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGE3415H
Insured/Policyholder	
Name Of Registered Owner	YEE PENG FEI
NRIC No	S1788754H
Email Address	YEENPENGFEI@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96818850
Alternative Phone No	OFFICE-96818850
Vehicle Particulars	
Manufacturer	SEAT
Model	TOLEDO 1.4 TDI 90 STYLE 7AT
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2018-00000168
Cover Note Number	
Driver	
Name of Driver	YEE PENG FEI
NRIC No	S1788754H
Date Of Birth	24/03/1967
Occupation	INDOOR
Date Of Driving Pass	08/08/1988
Driving Experience	30 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96818850
Fax Number	
Contact Number	OFFICE-96818850
Email Address	YEENPENGFEI@GMAIL.COM

Address HDB MARINE DRIVE VIEW, 73 MARINE DRIVE 440073
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles involved in the accident
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1
 NAME: : SYLVIA LIM
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of Intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

Was driving along Holland ave making a left turn at the filter lane into Commonwealth ave. I stopped at the giveaway line for oncoming traffic, i noticed a cyclist. While waiting for the cyclist to past, I felt an impact from my rear, vehicle b driving on the rear unable to stop in time. The front portion of vehicle b rear ended onto my vehicle.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLU4765Y
 Vehicle Make/Model/Colour SUBARU XV1.6I-SAWD CVT BLK
 Details Of Properties
 Vehicle Category PRIVATE CAR
 Name of Driver TOMOKO OKAZAKI
 NRIC/Passport Number S2197097B
 Contact Number 96722945
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

IMPORTANT NOTICE

Please report correctly the details of the accident to speed up the claims process.
 This Form must be completed by the Policyholder and/or the Authorised Driver.
 Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
 The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies. Any false reporting may be referred to the Police for investigation.
 The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA) understand, acknowledge, agree and consent that:

a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- i) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- ii) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS
 REPORTING OFFICER
 MOHAMAD HELMY BIN
 ALEHAM

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Common Statement Pg. 1

ACCIDENT STATEMENT (2000 characters)

Was driving along Holland ave making a left turn at the filter lane into Commonwealth ave. I stopped at the giveaway line for oncoming traffic, i noticed a cyclist. While waiting for the cyclist to past, I felt an impact from my rear, vehicle b driving on the rear unable to stop in time. The front portion of vehicle b rear ended onto my vehicle.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER - MOHAMAD HELMY BIN ALEHAM

MARS Officer

Registered Owner or Driver's Signature

Job Complete Date/Time

Date/Time:

(01) Deformed (02) Shifted (03) Buckled (04) Broken (11) Necessary
 (12) Missing (13) Torn (14) Unconfirmed (15) Not Working

MOTORCAR (Rear)

(1) Replace (✓) (2) Repaired (3) Check (F)
 (4) Not Consistent (C)

Vehicle No: **SGE 3415H**

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base	DD	✓	
1139	993630	Rear Number Plate Garnish	CUT	✓	
1140	993632	Rear Number Plate Lamp	CRA	✓	
1141	992958	Rear Bumper	QIT	✓	
1142	993085	Rear Bumper Upper			
1143	993017	Rear Bumper Lower	?		
1144	993054	Rear Bumper Side			
1145	993103	Rear Bumper Tow Cover			
1146	992341	Rear Bumper Clips	NEC	✓	6
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer	DIS	✓	2
1149	993045	Rear Bumper Reinforcement	BT	✓	
1150	992970	Rear Bumper Beam			
1151	993077	Rear Bumper Sponge	CRA	✓	
1152	992999	Rear Bumper Damper			
1153	993040	Rear Bumper Protector			
1154	993036	Rear Bumper Pad			
1155	993026	Rear Bumper Moulding			
1156	993044	Rear Bumper Reflector			
1157	993023	Rear Bumper Lower Spoiler	DIS	✓	
1158	994023	Reverse Sensor	DM	✓	
1159	993327	Rear End Panel	DD	✓	
1160	993339	Rear End Panel Top Garnish	DL	✓	
1161	993333	Rear End Panel Inner Trim			
1162	990333	Boot Compartment Inner Trim			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1170	992895	Bootlid	DD	✓	
1171	991328	Bootlid Emblem	NEC	✓	2
1172	990356	Bootlid Handle			
1173	995250	Bootlid Moulding			
1174	990376	Bootlid Reflector			
1175	995222	Bootlid Lamp LH	CRA	✓	
1176	992899	Bootlid Lamp RH	CRA	✓	
1177	995243	Bootlid Lock	BT	✓	
1178	990377	Bootlid Rubber	DD	✓	
1179	990382	Bootlid Hinge			
1180	993877	Bootlid Spoiler			
1181	994543	Tailgate			
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1184	994640	Tailgate Moulding			
1185	994545	Tailgate Garnish			
1186	994648	Tailgate Reflector			
1187	994549	Tailgate Lamp			
1188	994646	Tailgate Protector			
1189	994676	Tailgate Wiper Arm			
1190	994677	Tailgate Wiper Blade			
1191	994679	Tailgate Wiper Nozzle			
1192	994555	Tailgate Wiper Motor			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
1197	994629	Tailgate Lock			
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge			
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			

NAC	INC	Item	CON	AC	Qty
1202	993784	Spare Tyre Board			
1203	994328	Spare Tyre Panel			
1204	995065	Spare Tyre			
1205	994326	Spare Tyre Lock Screw			
1206	993787	Spare Tyre Cover			
1207	995323	Triangle Breakdown Sign			
1208	990507	CD Changer Assy			
1209	990164	Antenna			
1210	990534	Centre Exhaust Pipe Assy			
1211	990532	Centre Exhaust Mounting			
1212	993364	Rear Exhaust Pipe			
1213	993357	Rear Exhaust Chrome Pipe			
1214	993361	Rear Exhaust Mounting			
1215	993358	Rear Exhaust Heat Shield			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			
1218	993436	Rear LH Fender			
1219	993449	Rear LH Fender Protector			
1220	993420	Rear LH Fender Inner Panel			
1221	993431	Rear LH Fender Inner Trim			
1222	993415	Rear LH Fender Inner Garnish			
1223	993425	Rear LH Fender Inner Shield			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1228	993456	Rear RH Fender			
1229	993450	Rear RH Fender Protector			
1230	993420	Rear RH Fender Inner Panel			
1231	993431	Rear RH Fender Inner Trim			
1232	993415	Rear RH Fender Inner Garnish			
1233	993425	Rear RH Fender Inner Shield			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1238	995162	Rear Fender Extension Panel LH			
1239	993401	Rear Fender Extension Panel RH			
1240	993430	Rear Fender Inner Top Garnish			
1241	993673	Rear Fender 1/4 Glass			
1242	993452	Rear Fender 1/4 Glass Rubber			
1243	993453	Rear Fender 1/4 Glass Sealant			
1244	993949	Rear Windscreen Glass			
1245	993976	Rear Windscreen Rubber			
1246	993961	Rear Windscreen Moulding			
1247	993955	Rear Windscreen Sealant			
1248	994729	Third Brake Light			
1249	993385	Rear Fender Air Grille			
1250	992167	Fuel Lid			
1251	992168	Fuel Neck			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1254	992191	Fuel Tank Float			
1255	990247	Sticker			

No of Items: 15

Assessor: _____

TGim
 1/11/18

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Oct 2018 Edit Reg		29 Oct 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	TOH KENG CHONG , ID: S0134257F, Tel: +6599999999								
Main Claimant:	YEE PENG FEI , ID: S1788754H								
Vehicle Reg. No.:	SGE3415H	Date of Loss:	23/10/2018 00:00 - :59 [21 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1603075774SG	Policy/Cover Note No.:	1700085074 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLU4765Y	Policy No. (Claimant):							
		Excess:							
Repairer:	Teck Wang Motor Workshop (HQ) BLK 3006 UBI ROAD 1 #01-362, 408700 Ubi - Tel: 67428221								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 08/11/2018]								
Claimant's Solicitor:	DANIEL POON & CO - Tel: 62272469								
ASSOCIATED MAIL RECEIVED			View All	Compose Case Mail					
<ul style="list-style-type: none"> AIG_SG (30/10/2018): Request to upload TP GIA Report 									
ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGE3415H (1603075774SG)**
[SLU4765Y]
TP
YEE PENG FEI
Oct 23 2018 12:00AM
[TOH KENG CHONG]
Teck Wang Motor Workshop

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View <input type="button" value="View in Browser"/>
Assessment Reports					1 per page <input type="button" value="v"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	30/10/18 09:37	Accident Statement From: SC - Reg. No: SLU4765Y, Claimant: TOH KENG CHONG		Load HTM	<input type="checkbox"/>
Photos/Images					3 per page <input type="button" value="v"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
2	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
3	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
4	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
5	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
6	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
7	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
8	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
9	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
10	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
11	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
12	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
13	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
14	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
15	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
16	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
17	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
18	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
19	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
20	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
21	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
22	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
23	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
24	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
25	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
26	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
27	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
28	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
29	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
30	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
31	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
32	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>
33	31/10/18 08:49	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
34	31/10/18 08:49	General View	 Load JPG	<input checked="" type="checkbox"/>
35	31/10/18 08:49	General View	 Load JPG	<input checked="" type="checkbox"/>
36	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
37	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
38	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	07/11/18 15:35	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
63	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
64	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
65	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
66	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
67	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
68	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
69	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
70	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
71	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
72	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
73	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
74	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
75	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
76	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
77	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
78	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
79	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
80	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
81	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
82	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
83	07/11/18 15:35	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
84	07/11/18 15:35	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
85	07/11/18 15:35	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
86	07/11/18 15:35	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>
87	07/11/18 15:35	Photo After Spray		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18019629/R1CD3E2

Date: 14/11/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700085074
Claimant Vehicle No : SGE3415H **Insured Vehicle No :** SLU4765Y
 Date of Loss: 23/10/2018 Nature of Claim: TP Claim No: 1603075774SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGE3415H**
 Make & Model: SEAT TOLEDO, 1.4 D TDI (A) Engine No: CUS296804
 Reg. Date: 20/01/2017 (Man. Year: 2016) Chassis No: VSSZZNHZH1012306
 Colour: Blue Odometer: 39546 km
 Engine Capacity: 1422 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 215/45 R16 Rear Tyre Size: 215/45 R16
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/10/2018
 Date Inspected: 29/10/2018 Inspected At: Teck Wang Motor Workshop (HQ)
 BLK 3006 UBI ROAD 1 #01-362
 Singapore 408700

Estimated Period of Repair: 6.0 days

Adjuster: MOHD RASUL

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR NUMBER PLATE BASE	Dented	0.00 F	*- F	
2	1		*REAR NUMBER PLATE GARNISH	Cut	0.00 F	*- F	
3	1		*REAR NUMBER PLATE LAMP	Cracked	0.00 F	*- F	
4	1		*REAR BUMPER	Cut	0.00 F	*- F	
5	1		*REAR BUMPER LOWER	* Check	0.00 F	*- F	
6	6		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F	
7	2		*REAR BUMPER SIDE RETAINER	Distorted	0.00 F	*- F	
8	1		*REAR BUMPER REINFORCEMENT	Bent	0.00 F	*- F	
9	1		*REAR BUMPER SPONGE	Cracked	0.00 F	*- F	
10	1		*REAR BUMPER LOWER SPOILER	Distorted	0.00 F	*- F	
11	1		*REVERSE SENSOR	Damaged	0.00 F	*- F	
12	1		*REAR END PANEL	Dented	0.00 F	*- F	
13	1		*REAR END PANEL TOP GARNISH	Dislodged	0.00 F	*- F	
14	1		*BOOTLID	Dented	0.00 F	*- F	
15	2		*BOOTLID EMBLEM	Necessary	0.00 F	*- F	
16	1		*BOOTLID LAMP LH	Cracked	0.00 F	*- F	
17	1		*BOOTLID LAMP RH	Cracked	0.00 F	*- F	
18	1		*BOOTLID LOCK	Bent	0.00 F	*- F	
19	1		*BOOTLID RUBBER	Dented	0.00 F	*- F	
					Total Parts (S\$)	0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >