



T 1018/ SHA5376H /WT(st) Our Ref :

Your Ref:

Dear Sir

Date 01-Nov-18 CDGE Taxi Claims Dept 59 Loyang Drive 4th Fir

Singapore 508969

AXA Insurance Pte Ltd

8 Shenton Way #24-01, AXA Tower Singapore 068811

WITHOUT PREJUDICE Attn: Motor Claims Department

ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701

> Mainline +65 6383 6280 Facsimilie +65 6280 9755

> > www.cdge.com.sq

Workshops

Braddell 205 Braddell Road Singapore 579701

Loyang

59 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

Pandan 45 Pandan Road Singapore 609286

320 Ubi Road 3 Singapore 408649

Senoko 24 Senoko Loop Singapore 758156

Sungei Kadut 7 Sungei Kadut Way Singapore 728791

Yishun Industrial Park A Singapore 768732

ACCIDENT INVOLVING OUR TAXI SHA5376H YOUR INSURED SME5005Z ON 28.10.18 AND OTHER

We are the authorised repair workshop for Comfort Transportation Pte Ltd, the owner SHA5376H which was involved in the captioned accident with your of motor vehicle No: insured vehicle. The vehicle owner and the taxi driver conderned have requested and authorized us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage to the vehicle.

As the accident was caused by the negligent act of your insured driving : SME5005Z we are submitting these claim for your consideration on behalf of the claimants.

TAXI OWNER'S CLAIM

1	Cost of Repair	\$ 2,247.00
2	4 days Loss of Rental @ \$ 106.81 per day	\$ 427.24
3	Survey Report Fees (Surveyed by M/s LKK)	\$
4	GIA / LTA Search Fee	\$ 7.49
5	GIA / Police Report Fees	\$ -
6	Towing Fees	\$ -
	Sub Total :	\$ 2,681.73

HIRER'S CLAIM

320.00 80.00 per days \$ days Loss of Income @ Total Claims: \$ 3,001.73

We enclose herewith the following documents to support the claims: -

Original repair bill and photocopies of photographs

SME5005Z LTA search slip/s of: b)

SHA5376H c) GIA / Police report/s of :

Letter of authority from owner / hirer / operator d)

(X) Photocopie/s of Accident Scene Photo/s () Traffic Compound () PIR

() Witness statement/s (x) Rental Rate letter (x) Downtime/Mileage record

Kindly look into the matter and let us hear from you on the settlement of the said claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours faithfully

William Tan

CDGE Claims Department

Tel: 6214 8737 Fax: 6214 1843 Email: williamtan@cdge.com.sg

This is a computer generated letter. No signature is required.





6

pcs





LETTER OF AUTHORISATION

(NAF / PAF)

ACCIDENT INVOLVING

SONATA SHA5376H , SME5005Z

ON 28-Oct-18 09:40

ALONG

MOUNTBATTEN RD TOWARDS NICOLL HWY

I / We

YEO BOON NGEE

(Hirer) NRIC No.: **\$1775761Z**

and/or

(Relief) NRIC No.:

Taxi Number

SHA5376H

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

- 1. To submit my/our claims for damages, costs and expense, including loss of income, loss of rental, medical fee and legal costs.
- 2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
- 3. To sign Discharge Voucher on my/our behalf.
- 4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of "ComfortDelGro Engineering Pte Ltd".

Date

28-Oct-2018

Name of Hirer

YEO BOON NGEE

Hirer NRIC

S1775761Z

Signature:

Here

Address

524-B TAMPINES CENTRAL 7 #07-63

522524

Contact No.

98699153



A member of COMFORTDELGRO

GST REG. NO. M2-8921817-3

TAX INVOICE

205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755 Workshops 59 Loyang Drive Singapore 508969 383 Sin Ming Drive Singapore 575717 45 Pandan Road Singapore 609286 24 Senoko Loop Singapore 758156

7 Sungei Kadut Way Singapore 728791 501 Yishun Industrial Park A Singapore 768732 320 Ubi Road 3 Singapore 408649 REG. NO.: 199506048W

ComfortDelGro Engineering Pte Ltd

Page: 1

8010010

AXA INSURANCE PTE LTD

8 SHENTON WAY AXA TOWER #24-01 SINGAPORE 068811

CONTACT NO: 63387288

VEHCLE NO SHA5376H

NO/DATE 91405326 31.10.2018

MAKE HYUNDAI 305231603

MODEL SONATA ODOMETER READING

DATE OF REG 19.04.2012

CHASSIS CODE

JOB TYPE KMHET41VMCA822917

Description: 3P 28.10.2018

Invoice for Lump Sum Repair

2,100.00 Total Lump Sum Repair Amt 7.000 % Add GST @

2,247.00 Total Invoice amount

: CHEWBEELENG 01.11.2018 16:28:59 Issued by Repair Type

Payment Type/Term : /Credit 30 days

ComfortDelGro Engineering Pte Ltd A member of COMFORTDELGRO

Head Office: 205 Braddell Road Singapore 579701

BANK/CHQ No. ACCOUNT No. INVOICE No. **AMOUNT**

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

Our Ref: CT18100872

Date: 01 November 2018



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON

28/10/2018 @ 09:40 hrs

ALONG

MOUNTBATTEN RD TOWARDS NICOLL HIGHWAY

INVOLVING

SME5005Z

We refer to the above-mentioned accident and wish to inform that Comfort Transportation Pte Ltd is the registered owner of the taxi bearing vehicle registration number SHA5376H (the "Taxi"). The Taxi was hired to YEO BOON NGEE IC NO S1775761Z a registered hirer-operator of Comfort Transportation Pte Ltd at the time of occurrence of the aforementioned accident at a rental rate \$106.81 per day (inclusive of GST).

Please be advised that the Taxi was insured with **MS First Capital Insurance Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Christine Tay Assistant Manager, Fleet Safety

This is a computer generated letter. No signature is required.

00-00	T 0 4 T			21162764		MILEAGE	HOURS OPERATED (TIME)	ATED (TIME)
FROM TO 23/10 245 180660 274 ales. 25/10 25 16 02 160 275 ales. 25/10 25 16 16 2 20 ales. 25/10 25 16 16 2 20 ales. 25/10 25 16 16 2 20 ales. 25/10 25 16 16 2 2 2 1 0 0 ales. 25/10 25/10 25 1/4 3 ales. 25/10 18 Repair 3 for soon year 1040	WELLED	HOURS OPERATED (TIN	ر مثا	NAME OF DRIVER	MILEAGE READING	TRAVELLED (KM)	FROM	TO
25. 180662 202. 225. 225. 225. 225. 225. 225. 225	(KM)		2			1 of La Com	0700	15K
Repair Just 102 1 160 202.			0/10	24.50	0	400	6753.	
200 161021160 222 200 210 0648. 200 21032 211 0648. 200 21032 300 2703 200 21032 300 2703 Repair 181675 143 0685. Repair 1800 year 1040.			18/0	Carlo Carlo	1040	200		1540
The son mer. 1040.			24/10			1/3	200	1221
22 1 8 2 3 2 211 0648. The son year 1040. Repair 16 500 0703			0/ /20	0	1 2 7 7	100	100	1
Repair Just 1040			3	П	181222	112	0648.	1305
Repair Jesson ver Day			1	2	0 0	200	2020	1269
Repair Jason me 1040.			24/10		1 5 5 0		2067	
Repair Jerson ver. Organg 1040.		,	100		181675	747	5290	07/1
Repair Jessen new Tolling			187	8	W. X.	0 0000		
Repair Jes seen me			28/10/182	Fee		1	-	1000
			3110118	-		7		

Insurance Particulars Enquiry By Agents Detail

https://vrl.lta.gov.sg/lta/vrl/action/insPartDetailByAA?FUNCTIO...

Enquire Vehicle Insurer Vehicle No. Incident Date/Time

Search Status

Insurance Company Code

Insurance Company Name

SME5005Z

28 Oct 2018 / 09:40:00

Successful

A12

AXA INSURANCE PTE LTD

Previous

OK











