

ASS. REC. BY:

REF: CS3/SMO/8019657/Ncd3² Special Instruction:Surveyor: NAZ ASSIGNMENT (Office)From (Person): Menmen Groh puu tang of SMO Date/Time: 29/10/2018 2:33pm

Estimated Cost: _____ Bill to: _____

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SDH 8388P Insured: YN 4427Gat Workshop m/s Lim Joo Kim Tel: 63671772of Blk 6, Kranji Loop #01-27Policy No: D17MTPCVE002775 Claim No: CMTD1804657

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 23/10/2018(Client's Record) _____ H.O.D. Endorsement: 30/10/2018CA / REV / REP. / REV 24 HRS (up)Date/Time: 4:49pm @ 29/10/18 Person Contacted: Irene Vehicle: IN/OUT

Date/Time	Action/Instruction (X) Estimate
	<u>SDH 8388P - X</u>
	<u>YN 4427G - X</u>
	<u>After repair: 31/10/2018</u>

PRELIMINARY

REF:

Surveyor: NAZ

C.M.D

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

CIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 1 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SDH 8388P Yr Regn: 20 SEP 2016Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: HONDA VEZEL 1.5X CVT C.C. - 1,496Colour: BROWN A/C: Insured / Std / NI / NASp. Reading: 45, 547 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU11201235Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 215 / 60 / R16R: 11BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 23/10/18 D.O.I. 30/10/18Survey held at LIM JOO KIMDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orfront windscreen

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

Date/Time, File Pass to?

☐ : Preli Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Report Format: PRE

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 1Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

TOTAL

Range \$1,500/2 - \$1,800/2

Repair days 1-2

RECEIVED 13 NOV 2018

9/11/2018

9/11/18

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Oct 2018		29 Oct 2018 14:33 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	GEE HO SENG TRANSPORT/WASTE PAPER DEALER, Co. Reg. No.: 24984900C		
Main Claimant:	BEAUTY WOOD MATERIAL AND HARDWARE PTE LTD, Co. Reg. No.: 199906968H		
Vehicle Reg. No.:	SDH8388P	Date of Loss:	23/10/2018 14:00 - :59
Claim Type:	TP / CMTD1804657	Policy/Cover Note No.:	D17MTPCVE002775 (Comprehensive)
Vehicle Reg. No. (Insured):	YN4427G	Policy No. (Claimant):	
		Excess:	
Repairer:	Lim Joo Kim Trading Co (HQ) Blk 6, Kranji Loop, #01-27, 739542 Kranji - Tel: 63671772		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/11/2018]		
Driver/Custodian (Insured):	JOSEPH XAVIOR (), NRIC: G7660382R, Tel: +6591839915		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
----------	----------	------	------------	---------	---------	-------------	--------------	------------	-------

No results.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/10/2018 12:10
Date Of Accident	23/10/2018 14:50
Exact Location Of Accident	NORTH LINK BLDG CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SDH8388P
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	BEAUTY WOOD MATERIAL AND HARDWARE PTE LTD
Co Reg No	199906968H
Email Address	BEAUTYWOODNL@OUTLOOK.COM
Mobile Phone No	
Alternative Phone No	OFFICE-65555244

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL-1.5 1.5X CVT (A)
Exact Purpose for which vehicle was being used at time of accident	PARKED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D18MTPV01015434
Cover Note Number	20/09/18 - 19/09/19

Driver

Name of Driver	NG BOON LIANG
NRIC No	S6917128A
Date Of Birth	16/05/1969
Occupation	INDOOR
Date Of Driving Pass	21/12/1998
Driving Experience	19 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91449519
Fax Number	
Contact Number	
Email Address	BEAUTYWOODNL@OUTLOOK.COM

Address	BLK 273 BAKIT ROAD #08-160
Postcode	670273
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	YN4427G
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

VEHICLE NO.: SDH 8388 P
INSURER : Sampo Ins
DATE & TIME: 23/10/18 @ 14:50

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
- (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: (YS)
NRIC/FIN No.:

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My car was parked at the above compound when someone notified me that my car was hit by another vehicle - YN44276. I rushed to the scene and the said driver was there and he claimed that there was gust of wind blow causing his loaded scrap to fly and hit onto my car front windscreen causing a crack on it.

Note: Please note that your insurer may have 14days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SDH8388P, Model Plan 1000, 03

() Claim Own Policy () Claim Third Party () Reporting Only
(✓) Claim OD/TP at other workshop (by own workshop)

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6968H
Vehicle Details	
Vehicle No.:	SDH8388P
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Nov 2018
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5X CVT
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	L15B4401235
Chassis No.:	RU11201235
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$20,849.00
Original Registration Date:	20 Sep 2016
First Registration Date:	20 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$11,189.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Sep 2026
PARF Rebate Amount:	\$8,391.00
Intended COE Rebate Details	
COE Expiry Date:	19 Sep 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,506.00
COE Rebate Amount:	\$40,518.00
Total Rebate Amount:	\$48,909.00

The information contained herein is correct as at 07 Nov 2018

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	24 Oct 2018		29 Oct 2018 14:33 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GEE HO SENG TRANSPORT/WASTE PAPER DEALER , Co. Reg. No.: 24984900C		
Main Claimant:	BEAUTY WOOD MATERIAL AND HARDWARE PTE LTD , Co. Reg. No.: 199906968H		
Vehicle Reg. No.:	SDH8388P	Date of Loss:	23/10/2018 14:00 - :59 [25 Months and 3 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / CMTD1804657	Policy/Cover Note No.:	D17MTPCVE002775 (Comprehensive)
Vehicle Reg. No. (Insured):	YN4427G	Policy No. (Claimant):	
		Excess:	
Repairer:	Lim Joo Kim Trading Co (HQ) Blk 6, Kranji Loop, #01-27, 739542 Kranji - Tel: 63671772		
Handling Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555 ... [Handled by GNOH PAU LOONG - 63295217]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 08/11/2018]		
Driver/Custodian (Insured):	JOSEPH XAVIOR (), NRIC: G7660382R, Tel: +6591839915		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SDH8388P (CMTD1804657)**
[YN4427G]

TP

BEAUTY WOOD MATERIAL AND HARDWARE PTE LTD

Oct 23 2018 2:00PM

[GEE HO SENG TRANSPORT/WASTE PAPER DEALER]

Lim Joo Kim Trading Co

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[View](#) [View in Browser](#) ▼

Assessment Reports

No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	1 per page ▼	Thumbnail	Print
1	29/10/18 14:33	Accident Statement From: SC - Reg. No: YN4427G, Claimant: GEE HO SENG TRANSPORT/WASTE PAPER DEALER		Load HTM	

Photos/Images

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per page ▼	Thumbnail	Print
1	30/10/18 17:49	General View		Load JPG	<input checked="" type="checkbox"/>
2	30/10/18 17:49	General View		Load JPG	<input checked="" type="checkbox"/>
3	30/10/18 17:49	General View		Load JPG	<input checked="" type="checkbox"/>
4	30/10/18 17:49	General View		Load JPG	<input checked="" type="checkbox"/>
5	30/10/18 17:49	General View		Load JPG	<input checked="" type="checkbox"/>
6	30/10/18 17:49	General View		Load JPG	<input checked="" type="checkbox"/>
7	30/10/18 17:49	General View		Load JPG	<input checked="" type="checkbox"/>
8	30/10/18 17:49	General View		Load JPG	<input checked="" type="checkbox"/>
9	30/10/18 17:49	General View		Load JPG	<input checked="" type="checkbox"/>
10	30/10/18 17:49	General View		Load JPG	<input checked="" type="checkbox"/>
11	30/10/18 17:49	General View		Load JPG	<input checked="" type="checkbox"/>
12	31/10/18 18:35	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
13	31/10/18 18:35	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
14	31/10/18 18:35	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
15	31/10/18 18:35	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
16	31/10/18 18:35	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
17	31/10/18 18:35	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
18	31/10/18 18:35	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Documentation

No	Finalized On	Sompo Insurance Singapore Pte. Ltd. (HQ)	1 per page ▼	Thumbnail	Print
1	29/10/18 14:32	PRI - LIM JOO KIM TRADING CO		Load PDF	
2	29/10/18 14:37	Third Party E-filed GIA report(I)		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

There are no document checklists configured.

[Reset](#)
[Save](#)
[Print](#)

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/SMO18019657/NCD3S2

Date: 16/11/2018

REFERENCE

Handling Insurer:	Sompo Insurance Singapore Pte. Ltd.	Policy No:	D17MTPCVE002775
Claimant Vehicle No :	SDH8388P	Insured Vehicle No :	YN4427G
Date of Loss:	23/10/2018	Nature of Claim:	TP
		Claim No:	CMTD1804657

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDH8388P	Engine No:	L15B4401235
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11201235
Reg. Date:	20/09/2016 (Man. Year: 2016)	Odometer:	45547 km
Colour:	Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	29/10/2018		
Date Inspected:	30/10/2018	Inspected At:	Lim Joo Kim Trading Co (HQ) Blk 6, Kranji Loop, #01-27 Singapore 739542
Estimated Period of Repair:	1.0 days		

Adjuster: Muhammad Nazril Bin Abdullah

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$1,500.00 - \$1,800.00

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Nov 2018)
Parts:	M1-SUV	HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDH8388P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >