

ASS. REC. BY:

REF:

CS3 / A1G18019661 / Ucd302

Special Instruction:

Surveyor

Menthen

ASSIGNMENT (Office)

From (Person):

Chin lee Ying

of

AIG

Date/Time:

29/10/18 @ 3:08pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

SKA 2874X

Insured:

SLK 8622C

at Workshop m/s

Alpha Car Services

Tel:

6509 8258

of

1 kaki Bkt Ave 6 # 01-59

Policy No:

2100497394

Claim No:

634514226856

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/10/2018

CA / REV / REP. / REV 24 HRS

cup

30/10/18 @ Morning

H.O.D. Endorsement:

Date/Time:

3:00pm @ 29/10/18

Person Contacted:

Cai Ling

Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	SKA 2874X - X
	SLK 8622C - X
	Dismantle: 30/10/2018

REF: A1G

ASSIGNMENT

From: Date: 30/10/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKA 2874X

at Workshop m/s

of 1 Kaki Bkt Ave 6 #01-59 Autobay

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up' LTA 40878

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

SKA 2874X Yr Regn: 211

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (A/

Make:

VOLVO 580 c.c 1999

Colour:

Grey A/C: Insured / Std / NI / NA

Sp.Reading

124134 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

YV1AS 445B131138380

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 235/40ZRF R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6 mm

Rear

R/Bal.

6 mm

L/Bal.

6 mm

L/Bal.

6 mm

D.O.A.

19/10/18

D.O.I.

30/10/18

Survey held at

@ 9.00am

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

no setting. @

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Report Format: PAR

Lump Sum / I.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

180

20

200

Your password will expire in 13 days. [Click here to change it.](#)



- PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURE...

From: Chin, Lee-Ying

To: assignments, admin-a@lkkauto.com

Cc: Fong, Andy-SY

Sent: 29/10/2018 3:08:42 PM

Attachments:  [ALL - AIG - Letter - 2018 Oct 26 - Proposed Surveyor\(s\).pdf](#)
 [tmpFF3B.TIF](#)

Hi LKK,

Kindly assist to survey, vehicle in Kaki Bukit Autobay, #01-59.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947 | Fax +(65) 6835 7416

Lee-Ying.Chin@aig.com | www.aig.com.sg

From: sihoe@actus.sg [mailto:sihoe@actus.sg]

Sent: Monday, October 29, 2018 1:27 PM

To: Chin, Lee-Ying

Cc: sihoe@actus.sg

Subject: RE: - PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLK8622C AND SKA2874X ON 19/10/2018

Dear Lee Ying

With apologies, please try using the contact details as follows:

Hoo Yeong Hwa, Manager

Tel 6509 8258

Mob 9136 8884

Mob 8226 5945

Regards

Si Hoe

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Your Ref: 6345142268SG003

Our Ref: BN/019/2018

26 October 2018

URGENT

AIG ASIA PACIFIC INSURANCE PTE LTD
78 Shenton Way
#07-16
Singapore 079120

By Email & Fax
Fax 6835 7416
Email Aashweenjeetkaur.Mithoosingh@aig.com

Dear Sirs

MOTOR ACCIDENT
ON 19 OCTOBER 2018, 8:40 AM
AT QUEENSWAY (TOWARDS PORTSDOWN AVENUE)
INVOLVING VEHICLES NO SKA 2874X AND SLK 8622C

1. We refer to your electronic correspondence dated, "Thursday, October 25, 2018 4:46 PM".
2. We are instructed that our client does not agree to your proposed motor surveyors.
3. **Mr Alan Cheong of Messrs C L Appraiser Pte Ltd** ("Motor Surveyor") is instead proposed for the purposes of a pre-repair inspection.
4. Pursuant to the applicable State Courts protocol, please let us hear from you within 2 working days from the date of this letter, failing which it will be taken that you have no objection to the Motor Surveyor acting as Single Joint Expert (SJE) and our client will proceed accordingly for the purposes of his claim.
5. In the event you object to the proposed Motor Surveyor, our client will instruct his choice of motor surveyor to conduct a pre-repair survey.

6. Please be informed that the subject vehicle may by prior appointment be inspected by at:

Workshop Alpha Car Services Pte Ltd
Address 1, Kaki Bukit Avenue
#01-05
Kaki Bukit Autobay
Singapore 123456
Contact Ah Hua
Mob 9123 4444

Yours faithfully



T Si Hoe
ACTUS LEGAL LLP

cc Client(s)

> **Back to OneMotoring****Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 0947C

Vehicle Details

Vehicle No.: SKA2874X

Vehicle to be Exported: No

Intended Deregistration Date: 30 Oct 2018

Vehicle Make: VOLVO

Vehicle Model: S80 2.0T AT ABS D/AB 2WD 4DR TURBO

Primary Colour: Grey

Manufacturing Year: 2010

Engine No.: B4204T64000745

Chassis No.: YV1AS445BB1138380

Maximum Power Output: 149.0 kW (199 bhp)

Open Market Value: \$41,913.00

Original Registration Date: 10 Feb 2011

First Registration Date: 10 Feb 2011

Transfer Count: 2

Actual ARF Paid: \$41,913.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 09 Feb 2021

PARF Rebate Amount: \$25,147.00

Intended COE Rebate Details

COE Expiry Date: 09 Feb 2021

COE Category: B - Car (1601cc & above)

COE Period(Years): 10

QP Paid: \$69,000.00

COE Rebate Amount: \$15,728.00

Total Rebate Amount: \$40,875.00

The information contained herein is correct as at 30 Oct 2018

OK



Volvo S80 T5

\$55,800**\$11,090 /yr****29-Nov-2011****1,999 cc****124,121 km****Luxury****Available**

Sell \$3k Above Paper Value Only! Powerful Luxurious Sedan/Well Kept In Rare Condition That You Not To Be Missed! Gigantic Boots Space! Extended Warranty Available. Professional Evaluation And Grooming...

Dickson Automobile

Posted: 14-Sep-2018 Tags: 2011 Volvo S80, 2011 volvo s80, Volvo S80, volvo s80, Volvo, S80, s80, Used Volvo



Volvo S80 T4

\$49,000**\$11,810 /yr****21-Apr-2011****1,596 cc****60,000 km****Luxury****Available**

Nice 3 Digit Number! 1 Owner Only! High Loan Up To 80%-90% Available! Lowest Depreciation In Market! Agent's Wearnes Unit. Low Mileage Done. No Expenses Spared, Pristine Condition. Low Depreciation Of...

Posted: 07-Sep-2018 Tags: 2011 Volvo S80, 2011 volvo s80, Volvo S80, volvo s80, Volvo, S80, s80, Used Volvo

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

Home

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Article

Forum

Resources

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Volvo S80, Volvo S80 Singapore, used Volvo S80 Singapore, used Volvo S80, used vehicles Singapore or even buy used Volvo S80 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

About Us

Careers

Contact Us

Sitemap

Terms of Service

Privacy Policy

Personal Data Protection Statement

©2004-2018 sgCarMart. All rights reserved.

Compare

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/10/2018 13:29
Date Of Accident	19/10/2018 08:40
Exact Location Of Accident	QUEENWAY TWDS PORTSDOWN AVE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKA2874X
Insured/Policyholder	
Name Of Registered Owner	NG WHYE JHUN
NRIC No	S8030947C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-84689988
Alternative Phone No	OFFICE-84689988

Vehicle Particulars

Manufacturer	VOLVO
Model	S80
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VA1/GA319259
Cover Note Number	

Driver

Name of Driver	NG WHYE JHUN
NRIC No	S8030947C
Date Of Birth	07/10/1980
Occupation	INDOOR
Date Of Driving Pass	21/10/1999
Driving Experience	18 YEARS AND 11 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-84689988
Fax Number	
Contact Number	OFFICE-84689988
EMail Address	NOEMAIL

Address	BLK 3 HOLLAND CLOSE #08-49
Postcode	271003
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	TOO LARGE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLK8622C
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



Queenway
Towards portstown AVE

Vehicle A: SKA 2874 X


Vehicle B: SLK 8622 C


DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along queenstown towards Portstown Ave and was at a stationary position when waiting for the traffic light to turn green. Suddenly vehicle B collided with my rear of my vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN NO:

SKA2874X

Boothid	Dented
Boothid 'volvo' emblem	nee —
Boothid inner lock	8vcx
Boothid weatherstrip	nee —
Boothid wrap sticker	nee —
Rear bumper	do/ce —
Rear bumper lower	re —
Rear bumper sensor	shut —
Rear bumper reinforcement	do —
Rear bumper top retain	cracked —
1 set Rear bumper clips	nee —
Rear end panel	do —
Rear end panel top garnish	tw —
tail lamp	cracked —
Rear bumper wrap sticker	nee —

4/4

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 Oct 2018 Edit Reg		29 Oct 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case
















Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	WEE SIEW HOON , ID: S1729186F								
Main Claimant:	NG WHYE JHUN , ID: S8030947C								
Vehicle Reg. No.:	SKA2874X	Date of Loss:	19/10/2018 00:00 - :59 [92 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6345142268SG	Policy/Cover Note No.:	2100497394 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLK8622C	Policy No. (Claimant):							
		Excess:							
Repairer:	Alpha Car Services Pte Ltd (HQ) Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit Autobay, 417883 Kaki Bukit - Tel: 65098258								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Foo, Chit Yan] Chityan.Foo@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 08/11/2018]								
Claimant's Solicitor:	ACTUS LEGAL LLP - Tel: 67882088								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> AIG_SG (30/10/2018): Request to upload TP GIA Report 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKA2874X (6345142268SG)**
[SLK8622C]
TP
NG WHYE JHUN
Oct 19 2018 12:00AM
[WEE SIEW HOON]
Alpha Car Services Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <div>View in Browser</div>			
Photos/Images											3 per page		<div></div>	<div></div>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
2	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
3	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
4	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
5	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
6	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
7	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
8	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
9	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
10	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
11	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
12	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
13	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
14	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
15	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
16	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
17	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
18	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
19	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
20	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
21	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
22	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
23	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
24	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
25	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
26	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
27	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
28	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
29	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
30	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
31	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
32	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
33	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
34	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
35	31/10/18 12:52	General View									<div>1</div>	Load JPG	<div></div>	
36	31/10/18 12:52	Photographs of Damaged Parts									<div>1</div>	Load JPG	<div></div>	
37	31/10/18 12:52	Photographs of Damaged Parts									<div>1</div>	Load JPG	<div></div>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
39	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	31/10/18 12:52	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
82	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	07/11/18 17:18	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	30/10/18 08:54	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18019661/UCD3E2

Date: 13/11/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100497394
 Claimant Vehicle No: SKA2874X Insured Vehicle No: SLK8622C
 Date of Loss: 19/10/2018 Nature of Claim: TP Claim No: 6345142268SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKA2874X
 Make & Model: VOLVO S80, 2.0 T (A) Engine No: B4204T64000745
 Reg. Date: 10/02/2011 (Man. Year: 2010) Chassis No: YV1AS445BB1138380
 Colour: Grey Odometer: 124134 km
 Engine Capacity: 1999 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 235/40Z R18 Rear Tyre Size: 235/40Z R18
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 29/10/2018
 Date Inspected: 30/10/2018 Inspected At: Alpha Car Services Pte Ltd (HQ)
 Blk C, Kaki Bukit Ave 6 #01-59, Kaki Bukit
 Autobay
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	0.00 F	*- F
2	1		*BOOTLID VOLVO EMBLEM	Necessary	0.00 F	*- F
3	1		*BOOTLID INNER LOCK	Serviceable	0.00 F	*- F
4	1		*BOOTLID WEATHERSTRIP	Necessary	0.00 F	*- F
5	1		*BOOTLID WRAP STICKER	Necessary	0.00 F	*- F
6	1		*REAR BUMPER	Dented / Deformed	0.00 F	*- F
7	1		*REAR BUMPER LOWER	Deformed	0.00 F	*- F
8	1		*REAR BUMPER SENSOR	Shorted	0.00 F	*- F
9	1		*REAR BUMPER REINFORCEMENT	Dented	0.00 F	*- F
10	1		*REAR BUMPER TOP RETAINER	Cracked	0.00 F	*- F
11	1		*SET REAR BUMPER CLIPS	Necessary	0.00 F	*- F
12	1		*REAR END PANEL	Dented	0.00 F	*- F
13	1		*REAR END PANEL TOP GARNISH	Twisted	0.00 F	*- F
14	1		*TAILLAMP	Cracked	0.00 F	*- F
15	1		*REAR BUMPER WRAP STICKER	Necessary	0.00 F	*- F
Total Parts (\$\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >