

ASS. REC. BY:

REF:

CS/CT118019671 / Ggber

Special Instruction:

Survivor

ASSIGNMENT (Office)

From (Person):

Irene Tay

of

CTL

Date/Time:

21.10.2018 4.51pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBN 4386M

Insured:

CB 7516L

at Workshop m/s

Pan Eun Bike

Tel:

6299 4929

of

21 Moonstone Lane #01-01

Policy No:

DMB15N15034818US

Claim No:

SNM18D05103103.

Sum Insured:

Excess:

Make of Veh:

D.O.A.

25.10.2018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

31.10.2018 @ after 10am

H.O.D. Endorsement:

Date/Time:

21.10.2018 5.36pm

Person Contacted:

Kin Wah

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

FBN 4386M - NA / LP15019461 / ZU

Ddt: 05.10.18

CB 7516L - NA / CT118019502 / ZU

Ddt: 15.10.18

15/3/19 @

Kin Wah informed that the owner already consent to claim CD. by email.

15/3/19

Submit prelim. report.

meimur

Xme

REF: CTI

8010C

ASSIGNMENT

From: Date: 31.10.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBN 4386m

at Workshop m/s

of 21 moonstone lane #01-01

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

after 10am

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

FBN 4386m Yr Regn: 01 Oct 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Triumph speed Triple Rs

Colour:

black

A/C: Insured / Std / NI / NA

Sp.Reading

462

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SM TTPN 275 CJ 89504

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

120/70ZR17

R:

190/55ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / FIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

D.O.I.

31-10-18

Survey held at

W/S

5:30pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

\$ 5236.6

RECEIVED 20 MAR 2019

Date/Time: File Pass to?



Preli. Report

1) 20/3/2019



Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee

Transportation

) S + PS SI

) Photos

) Others

TOTAL

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	29 Oct 2018		29 Oct 2018 16:51 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:

MS NG SIEW TIN, ID: S1734854Z

[Created by insurer]

Main Claimant:

MICHAEL SCOTT BERTRAND, ID: S7658010C

Vehicle Reg. No.:

FBN4386M

Date of Loss:

25/10/2018 09:00 - :59

Claim Type:

TP / SNM18D05103C02

Policy/Cover Note No.:

DMB1SN1503981803
(Comprehensive)

Vehicle Reg. No. (Insured):

CB7516L

Policy No. (Claimant):

SD18V11097/VMS/R00

Excess:

S\$0.00

Repairer:

Pan Euro Bikes Pte Ltd (HQ) 21 Moonstone Lane #01-01 Poh Leng Building, 328462 Serangoon - Tel: 62994929

Handling Insurer:

China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]

Claimant's Insurer:

Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 08/11/2018]

Driver/Custodian (Insured):

NG KOK HUA (54 / Male), NRIC: S1624535F, Tel: +6581582455

Adj Asg. Remarks:

EST \$6033.73, CASE WITH SJE.

ASSOCIATED MAIL RECEIVED

[View All](#)

[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)

[Search Tasks](#)

[Create New Task](#)

[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAuto)

From: PanEuroBikes <paneurobikes@singnet.com.sg>
Sent: Friday, 15 March 2019 10:11 AM
To: Shiau Chan (LKKAuto)
Subject: RE: TP MOTORBIKE FBN 4386M / OI VEHICLE CB 7516L (CHINA-TP) DOA: 25/10/2018)

Hi Shiau Chan,

Can just close it at that on your end and close the file. My client has converted to OD claim as Chinas' insured driver has made a conflicting report.

Thank You, & Best Regards,
Kin Wah
Pan Euro Bikes Pte Ltd
Tel : +65 6299-4929
Fax : +65 6299-4430
Mobil : +65 9731-7133, +65 8121-2173
Email : paneurobikes@singnet.com.sg

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]
Sent: Thursday, March 14, 2019 5:05 PM
To: paneurobikes@singnet.com.sg
Subject: RE: TP MOTORBIKE FBN 4386M / OI VEHICLE CB 7516L (CHINA-TP) DOA: 25/10/2018)

Dear Kin Wah,

Re-send.

WITHOUT PREJUDICE

Offer final fig \$5,336.60 before GST and 3 repair days.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 27 February 2019 4:11 PM
To: 'paneurobikes@singnet.com.sg' <paneurobikes@singnet.com.sg>
Subject: TP MOTORBIKE FBN 4386M / OI VEHICLE CB 7516L (CHINA-TP) DOA: 25/10/2018)

Dear Kin Wah,

WITHOUT PREJUDICE

Offer final fig \$5,336.60 before GST and 3 repair days.

Kindly confirm.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8010C
Vehicle Details	
Vehicle No.:	FBN4386M
Vehicle to be Exported:	No
Intended Deregistration Date:	01 Nov 2018
Vehicle Make:	TRIUMPH
Vehicle Model:	SPEED TRIPLE RS
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	5893457
Chassis No.:	SMTTPN275CJ893504
Maximum Power Output:	-
Open Market Value:	\$15,126.00
Original Registration Date:	01 Oct 2018
First Registration Date:	01 Oct 2018
Transfer Count:	1
Actual ARF Paid:	\$8,376.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Sep 2028
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$4,214.00
COE Rebate Amount:	\$4,177.00
Total Rebate Amount:	\$4,177.00

The information contained herein is correct as at 01 Nov 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	25/10/2018 15:13
Date Of Accident	25/10/2018 09:35
Exact Location Of Accident	SLIP RD GEYLANG BAHRL TWDS BENDEMEER RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	FBN4386M
Insured/Policyholder	
Name Of Registered Owner	MICHAEL SCOTT BERTRAND
NRIC No	S7658010C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-85710512
Alternative Phone No	OFFICE-85710512

Vehicle Particulars

Manufacturer	TRIUMPH
Model	SPEED TRIPLE RS
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V11097/VMS/R00
Cover Note Number	

Driver

Name of Driver	MICHAEL SCOTT BERTRAND
NRIC No	S7658010C
Date Of Birth	22/10/1976
Occupation	INDOOR
Date Of Driving Pass	27/09/2018
Driving Experience	0 YEAR AND 0 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-85710512
Fax Number	
Contact Number	OFFICE-85710512
Email Address	NOEMAIL

Address	20 TANAH MERAH KECHIL LINK #14-42
Postcode	465426
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	CB7516L
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	BUS
Name of Driver	BENSON NG KOK HUA
NRIC/Passport Number	
Contact Number	81582455
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2
Passenger 1	NAME: : GENDER: :

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be furnished by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the signature of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available elsewhere.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer(s), my workshop and the General Insurance Association of Singapore ("GIA"), may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Ministry of Transport of Singapore and any relevant government agency/authority (such as the police), for the purposes of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages; and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/ can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (a) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/ID No.:

Accident Sketch Plan

SKETCH PLAN

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

refer to investment

DECLARATION

We define the foregoing pathologies are true in every respect

Date & Time

Driver's signature
(if driver is not the policyholder)
Date & Time

Reporting Center Personnel's Signature
Name: _____
NRIC/FIN No: _____

Accident Sketch Plan

ON STATED DATE AND TIME, I WAS STOPPED BEHIND ANOTHER VEHICLE WAITING FOR TRAFFIC TO CLEAR. WHEN IT WAS MY TURN, I MOVED SLOWLY TO THE STOP LINE AND STOPPED AS THERE WAS ON COMING TRAFFIC. MY VEHICLE WAS STATIONARY STOPPED BEFORE THE STOPPING LINE OF GEYLANG BAHRU TWDS BENDEMEER RD TO CHECK INCOMING VEHICLES ALONG THE MAIN RD. SUDDENLY I FELT AN IMPACT OF MY VEHICLE AND THE VAN BEHIND ME KEPT MOVING FORWARD. I HAD TO HIT THE WINDSCREEN WITH MY HAND FOR HIM TO STOP. THE VAN THEN REVERSED TO UNTANGLE THE TWO VEHICLES AS THE REAR OF MY VEHICLE (A) WAS WEDGED IN THE OTHER VEHICLE (B) FRONT PORTION. AS I WAS STOPPED WITH FEET ON THE GROUND I MANAGED TO HOLD THE BIKE STRAIGHT AND NOT FALL.

PAN EURO BIKES PTE LTD

21 Moonstone Lane #01-01 Poh Leng Building Singapore 328462
Tel: 62994929 Fax: 62994430 Email: paneurobikes@singnet.com.sg
Biz/GST Reg: 200916151R

PAGE 1

TO: MOTOR CLAIMS DEPARTMENT

DATE: 26.10.2018

CHINA TAIPING INSURANCE (S) PTE LTD

ESTIMATED COST OF REPAIRS TO TRIUMPH SPEED TRIPLE RS

ENGINE NO : CHASSIS NO :
VEHICLE NO : FBN 4386M ACCIDENT ON : 25.10.2018
INSURED : MICHAEL SCOTT BERTRAND

1 PC	REAR NO. PLATE LIGHT	/ cut	\$	55.00	/
1 PC	REAR NO PLATE HOLDER	/ CPA	\$	79.00	/
1 PC	REFLECTOR, RED, RH, REAR NUMBER PLATE	x 5mm	\$	8.00	x
1 PC	REFLECTOR, RED, LH, REAR NUMBER PLATE	x	\$	8.00	x
1 PC	LH REAR SIGNAL, LED	/ cut	\$	115.00	/
1 PC	RH REAR SIGNAL, LED	/ cut	\$	115.00	/
1 PC	REAR NUMBER PLATE HOLDER STAY	/ cut	\$	102.00	/
1 PC	TAILLAMP, LED	/ cut	\$	295.00	/
1 PC	TAILLAMP SHROUD, MATT	/ cut	\$	177.00	/
1 PC	SUBFRAME, SILVER	/ BT	\$	1,116.00	/
TOTAL			\$	2,070.00	2054
LESS 10%			\$	207.00	

SUB TOTAL

\$ 1,863.00 1848.6

NETT ITEMS:

1 PC	REAR NO. PLATE, ACRYLIC	/ cut	\$	18.00	/
1 SET	ARROW EXHAUST SYSTEM	/ BT	\$	2,880.00	/
1 SET	EXHAUST PLATE, RH EXHAUST, CARBON	x 8mm	\$	118.00	x
	REAR TIRE 190/55-17, PIRELLI DIABLO SUPERCORSA	/ cut	\$	280.00	240
	LABOUR CHARGE		\$	480.00	350
TOTAL			\$	5,639.00	3488

ADD 7% GST

\$ 394.73

GRAND TOTAL

\$ 6,033.73

REMARKS:

Kindly send a surveyor down for 3rd Party claim against your insured CB 7516L.

Thank You.

Kin Wah: 9731-7133

3 Days.
part by part.

After repair photos.

Guo Qiao - 82880282
31/10/18.

LKK Auto Consultants hence notify
the Employer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	29 Oct 2018		29 Oct 2018 16:51 Edit Adj Rpt	\$55,336.60 Edit Estimates	\$55,336.60 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	MS NG SIEW TIN , ID: S1734854Z		
Main Claimant:	MICHAEL SCOTT BERTRAND , ID: S7658010C		
Vehicle Reg. No.:	FBN4386M	Date of Loss:	25/10/2018 09:00 - :59 [24 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM18D05103C02	Policy/Cover Note No.:	DMB1SN1503981803 (Comprehensive)
Vehicle Reg. No. (Insured):	CB7516L	Policy No. (Claimant):	SD18V11097/VMS/R00
		Excess:	\$0.00
Repairer:	Pan Euro Bikes Pte Ltd (HQ) 21 Moonstone Lane #01-01 Poh Leng Building, 328462 Serangoon - Tel: 62994929		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 08/11/2018]		
Driver/Custodian (Insured):	NG KOK HUA (54 / Male), NRIC: S1624535F, Tel: +6581582455 Email: NOEMAIL		
Adj Asg. Remarks:	EST \$6033.73, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***FBN4386M (SNM18D05103C02)**
[CB7516L]

TP

















































MICHAEL SCOTT BERTRAND

Oct 25 2018 9:00AM

[MS NG SIEW TIN]

Pan Euro Bikes Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View View in Browser <input type="button" value="v"/>	
Assessment Reports				1 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	25/10/18 15:19	Accident Statement		Load HTM	
Photos/Images				3 per page <input type="button" value="v"/>	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	25/10/18 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	25/10/18 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	25/10/18 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	25/10/18 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	25/10/18 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	25/10/18 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	25/10/18 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
8	25/10/18 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
9	25/10/18 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
10	25/10/18 15:17	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	19/11/18 10:08	General View		Load JPG	<input checked="" type="checkbox"/>
2	19/11/18 10:08	General View		Load JPG	<input checked="" type="checkbox"/>
3	19/11/18 10:08	General View		Load JPG	<input checked="" type="checkbox"/>
4	19/11/18 10:08	General View		Load JPG	<input checked="" type="checkbox"/>
5	19/11/18 10:08	General View		Load JPG	<input checked="" type="checkbox"/>
6	19/11/18 10:08	General View		Load JPG	<input checked="" type="checkbox"/>
7	19/11/18 10:08	General View		Load JPG	<input checked="" type="checkbox"/>
8	19/11/18 10:08	General View		Load JPG	<input checked="" type="checkbox"/>
9	19/11/18 10:08	General View		Load JPG	<input checked="" type="checkbox"/>
10	19/11/18 10:08	General View		Load JPG	<input checked="" type="checkbox"/>
11	19/11/18 10:08	General View		Load JPG	<input checked="" type="checkbox"/>
12	19/11/18 10:08	General View		Load JPG	<input checked="" type="checkbox"/>
13	19/11/18 10:08	General View		Load JPG	<input checked="" type="checkbox"/>
14	19/11/18 10:08	General View		Load JPG	<input checked="" type="checkbox"/>
15	19/11/18 10:08	General View		Load JPG	<input checked="" type="checkbox"/>
16	19/11/18 10:08	General View		Load JPG	<input checked="" type="checkbox"/>
17	19/11/18 10:08	General View		Load JPG	<input checked="" type="checkbox"/>
18	19/11/18 10:08	General View		Load JPG	<input checked="" type="checkbox"/>
19	19/11/18 10:08	General View		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)	Thumbnail	Print
20	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
21	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
22	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
23	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
24	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
25	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
26	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
27	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
28	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
29	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
30	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
31	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
32	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
33	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
34	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
35	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
36	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
37	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
38	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
39	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
40	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
41	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
42	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
43	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
44	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
45	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
46	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
47	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
48	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
49	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
50	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
51	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
52	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
53	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
54	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
55	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
56	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
57	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
58	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
59	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
60	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
61	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
62	19/11/18 10:08	General View	 Load JPG	<input checked="" type="checkbox"/>
63	19/11/18 10:09	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
64	19/11/18 10:09	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	29/10/18 16:50	REPAIR EST	 Load PDF	
2	29/10/18 16:50	TP GIA	 Load PDF	
3	29/10/18 16:50	OI GIA	 Load PDF	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	25/10/18 15:18	Accident Sketch Plan [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	25/10/18 15:18	Accident Sketch Plan [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	25/10/18 15:18	Accident Sketch Plan [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports				View	View in Browser
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	25/10/18 15:19	Accident Statement		Load HTM	
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	25/10/18 15:17	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	25/10/18 15:17	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	25/10/18 15:17	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	25/10/18 15:17	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	25/10/18 15:17	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	25/10/18 15:17	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	25/10/18 15:17	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	25/10/18 15:17	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	25/10/18 15:17	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	25/10/18 15:17	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Ubi)		Thumbnail	Print
1	25/10/18 15:18	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	25/10/18 15:18	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
3	25/10/18 15:18	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18019671/GQBE2

Date: 20/03/2019

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMB1SN1503981803

Claimant Vehicle No: FBN4386M Insured Vehicle No: CB7516L

Date of Loss: 25/10/2018 Nature of Claim: TP Claim No: SNM18D05103C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBN4386M**

Make & Model: TRIUMPH SPEED TRIPLE RS, 1.1 Engine No: 5893457

Reg. Date: 01/10/2018 (Man. Year: 2018) Chassis No: SMTTPN275CJ893504

Colour: Black Odometer: 462 km

Engine Capacity: 1050 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/70Z R17 Rear Tyre Size: 190/55Z R17

Front Left Side: Pirelli 8 mm Rear Left Side: Pirelli 8 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,159.00	4,986.60	172.40	3.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	480.00	350.00	130.00	27.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,639.00	5,336.60	302.40	5.36
+ GST 7.00/7.00% (S\$)	394.73	373.56	21.17	5.36
Nett Amount (S\$)	6,033.73	5,710.16	323.57	5.36

INSPECTION

Date of Assignment: 29/10/2018

Date Inspected: 31/10/2018 Inspected At: Pan Euro Bikes Pte Ltd (HQ)
21 Moonstone Lane #01-01 Poh Leng Building
Singapore 328462

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

REPAIR DETAILS

Reference		
Part Source:		(Last Synchronised: 20 Mar 2019)
Parts:	N/A	TRIUMPH SPEED TRIPLE RS 1.1 (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN4386M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR NO. PLATE LIGHT	Cut	55.00 FL	*55.00 FL
2	1		*REAR NO PLATE HOLDER	Cracked	79.00 FL	*79.00 FL
3	1		*REFLECTOR, RED, RH, REAR NUMBER PLATE	Not Necessary	8.00 FL	*- FL
4	1		*REFLECTOR, RED, LH, REAR NUMBER PLATE	Not Necessary	8.00 FL	*- FL
5	1		*LH REAR SIGNAL, LED	Cut	115.00 FL	*115.00 FL
6	1		*RH REAR SIGNAL, LED	Cut	115.00 FL	*115.00 FL
7	1		*REAR NUMBER PLATE HOLDER STAY	Cracked	102.00 FL	*102.00 FL
8	1		*TAILLAMP, LED	Cut	295.00 FL	*295.00 FL
9	1		*TAILLAMP SHROUD, MATT	Cut	177.00 FL	*177.00 FL
10	1		*SUBFRAME, SILVER	Bent	1,116.00 FL	*1,116.00 FL
11	1		*REAR NO. PLATE, ACRYLIC	Cut	18.00 FS	*18.00 FS
12	1		*SET ARROW EXHAUST SYSTEM	Bent	2,880.00 FS	*2,880.00 FS
13	1		*SET EXHAUST PLATE, RH EXHAUST, CARBON	Not Necessary	118.00 FS	*- FS
14	1		*REAR TIRE 190/55-17, PIRELLI DIABLO SUPERCORSA	Cut	280.00 FS	*240.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,366.00	5,192.00
- List Item Discount on L Items 10.00/10.00% (S\$)	207.00	205.40
Total Parts (S\$)	5,159.00	4,986.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGE	New	480.00	350.00
Gross Labour Cost (S\$)			480.00	350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >